



To
HDFC BANK LTD., Bhubaneswar
 Date of valuation report: -10/07/2026
 Ref: -SMA/07-26/22

• STANDARD VALUATION REPORT FORMAT		
GENERAL DETAILS		
Type of property	Residential	Residential
	Commercial	
	Residential cum commercial.	
	Industrial	
	Vacant Plot	
Name of the Customer(s): - "SUJIT KUMAR NAYAK"		
Property Address with pin code:-Khata No-390/116,Plot No-1145(Area=AC.0.300Decs, Homestead), Mouza-Kantapada, PS/Tahasil-Astarang, Dist-Puri, Odisha, Pin-752109		
Landmark: - Near Kantapada UP School, Astarang		
Loan Application number: - 803702563		
Name of Document holder: Mr. Sujit Kumar Nayak		
Legal address of property (Hissa No / Survey no / khasra No : - Khata No-390/116,Plot No-1145 (Area=AC.0.300Decs, Homestead), Mouza-Kantapada, PS/Tahasil-Astarang, Dist-Puri, Odisha, Pin-752109		
Date of Inspection: -08/07/2026		
SURROUNDING LOCALITY DETAILS		
Ward No/ Municipal land No: -Within GP limit & coming under RURAL area		
Vicinity- Slum/ Residential / Commercial/ Mixed/Industrial		
Locality Type	Elite/Posh/High Class	Middle Class
	Upper Middle Class	
	Middle Class	
	Lower Middle Class	
Approach Road Width	>=60 feet Road	20-Feet Road
	60-40 Feet Road	
	40-20 Feet Road	
	<20 Feet Road	
Plot Demarcated at site- Yes/No		
Proximity to Civic Amenities	1. Nearest Railway Station	1. 58-kms from Puri Railway Station
	2. Nearest Bus Stop	2. 7-km from Kakatpur Bus Stop
	3. Nearest Hospital	3. 45-kms from Kakatpur Govt. Hospital
Property Identification	Easy to Identify	Identification by documents & With Help of customer, Mr. Sujit Kumar Nayak
	Identification by documents	
	Additional documents required for Identification	
	Difficult to identify	



S MOHANTY ASSOCIATES

Delivering Solutions ...

VALUER & CHARTERED ENGINEER

Proximity to necessities and facilities like Educational, Recreational.	<1 Km	1-3 Kms
	1-3 Kms	
	3- 5 Kms	
	>5 Kms	
Landmark Details	Nearest Railway Station	1. 58-kms from Puri Railway Station
	Nearest Bus Stop	2. 7-km from Kakatpur Bus Stop
	Nearest Hospital	3. 45-kms from Kakatpur Govt. Hospital
	Nearest Landmark	4. Near Kantapada UP School, Astarang
PROPERTY DETAILS		
Type of Usage of entire property- Residential / Commercial/Residential cum Commercial/ Industrial/Vacant plot		
Additional Amenities-----Garden/ Swimming Pool/ Not Applicable		
Legal status of Property	Freehold	Freehold
	Lease hold >30 yrs.	
	Lease hold 15-30 yrs.	
	Lease hold <15 yrs.	
SUBJECT PROPERTY DETAILS		
Type of Premises---- Residential flat/Gala/ Shop/Bungalow/ Row House /office/ Chawl/ Open Plot/ Showroom/Duplex Flat /Pent House		
Occupied by Name of Occupant / is property vacant: Self Occupied		
Is property rented: NA		
If rented list of occupants: NA		
Property Taxation/Maintenance cost	Low	Average
	Average	
	High	
	Very High	
Boundary Details- As per Sketch map	NORTH EAST	Rest part of the plot Plot No-1146 & 1150
	SOUTH WEST	Road Plot No-1144
Boundary Details –At site	NORTH EAST	Vacant Plot Vacant Plot
	SOUTH WEST	Road Road
STRUCTURAL DETAILS		
Type of Structure- RCC / Load Bearing/ Steel Structure/Composite structure/ Industrial Shed/Structure with A/C sheet / G/I SHEET/Asbestos Roofing		
No. of Floors: -2 (G+1)		
No of wings: -NA		
No. of units on each floor: -NA		
Internal Composition of property: Good		
No. of lifts in each wing: NA		

Regd. Valuer : SBI, PNB, UNION BANK, IDBI BANK, BOB, BOM, BOI, UCO, CANARA BANK, LIC, HDFC BANK, YES BANK, ICICI BANK, KOTAK MAHINDRA BANK, AXIS BANK

Regd. Office : Plot No. 858(P) & 859(P), Near Astha Binodini Apartment, Siba Nagar, Rajarani, Tankapani Road, Bhubaneswar - 751018, Odisha
Ph.: 0674-3134245, Mob : 9937023855, 9437074855, E-mail : smohantyassociates@gmail.com



S MOHANTY ASSOCIATES
Delivering Solutions ...
VALUER & CHARTERED ENGINEER

Age of the Property	1-10 years	8-Years
	11-25 years	
	26-50 years	
	>50 years	
Estimated Future Life: 52-Years		
Exteriors		
Beam & Column Structure		
Quality of Construction Appearance & Maintenance of Building.	Very Good	Good
	Good	
	Average	
	Poor	
Common Areas Remarks: Normal		
Other Observations: As visually observed, there was no appearance of cracks or any major defect.		
Interiors		
Flooring & finishing: Tile Flooring		
Roofing and terracing: RCC Roofing		
Quality of fixtures and fittings: Good Quality Fittings		
Plan Approvals		
Construction as per approved/ sanctioned plans-----Yes/No		
Details of approved plan with approval no and date: Yes (Plan has been approved by Sarapanch for G+1 storied residential building.)		
Construction permission Number and date: Not mentioned		
Violations Observed if Any Or is there any risk of Demolition in case of violation: Low		
If plans not available then is the structure firming to the local byelaws: NA (Plan available)		
Other Documents Verified: Xerox copy of Sale deed, ROR, Sketch map & approved plan verified by us.		
VALUATION		
Individual Apartments / flats		
Carpet Area (Sqft) Floor-wise: NA		
Loading for BUA- NA		
Approved BUA / SBUA(Sqft) in Apartment Floor-wise: NA		
Current Govt. Approved rates: NA		
Recommended Rate and basis for recommendation: NA		
Final Market value.	NA	
Total	NA	
Forced Sale %	NA	NA
For Land and building valuation.		
Land Area=13,068sqft (AC.0.300Decs)		
Current Government Approved Rates for land: Rs.23/- Per sqft of land		
Recommended Rate and Basis for recommendation: -Rs.450/- Per sqft of land (As per local feedback)		
Land value=13,068sqft X Rs.450/- per sqft land=Rs.58,80,600/-		
Actual BUA of the premises(Sqft) RCC {G+1}: - GF-1537sqft + FF-1287sqft=2824sqft		
BUA as per the Approvals(Sqft) RCC (G+1): -2 X 1600sqft=3200sqft		
Construction cost as per the Amenities provided: Rs.1800/- per sqft of BUA		

Regd. Valuer : SBI, PNB, UNION BANK, IDBI BANK, BOB, BOM, BOI, UCO, CANARA BANK, LIC, HDFC BANK, YES BANK, ICICI BANK, KOTAK MAHINDRA BANK, AXIS BANK

Regd. Office : Plot No. 858(P) & 859(P), Near Astha Binodini Apartment, Siba Nagar, Rajarani, Tankapani Road, Bhubaneswar - 751018, Odisha
 Ph.: 0674-3134245, Mob : 9937023855, 9437074855, E-mail : smohanlyassociates@gmail.com



S MOHANTY ASSOCIATES
Delivering Solutions ...
VALUER & CHARTERED ENGINEER

Total value of construction (Actual BUA) RCC {G+1}: -2824sqft X Rs.1800/-=Rs.50,83,200/-		
Depreciated value of Construction (1% per year) (Less-8%): -Rs.46,76,544/-		
Market Value	Land value+ Depreciated constructed value (in figures)	Land Rs.58,80,600/- + Cons. Rs.46,76,544/- Total Rs.1,05,57,144/- Or Say Total Rs.1,05,00,000/- (Rupees One Crore & Five Lakhs Only)
Realisable value: -Rs.95,01,429/-		
Forced Sale %	80 %	
Forced sale value -		Rs.84,45,715/- Or Say Rs.84,45,000/- (Rupees Eighty-Four Lakhs & Forty-Five Thousand Only)
	Rs. In figures	
	Rs. In words	
Marketability	Excellent	Good
	Very Good	
	Good	
	Difficult	
Valuation result-----Positive/negative		
Replacement cost / Insurance Value: -Rs.39,75,062/-		
Deviations in the property- NA		
Remarks if any: -Subject property is G+1 storied residential building land extent of 13,068sqft (AC.0.300Decs), total actual area of 2824sqft & constructed about 8-years back. Plan has been approved by Sarapanch for G+1 storied residential building. Entire building is occupied by the customer for residential use. All the civic amenities are present 1-2-Kms & about 50-kms from Puri city center. This property is coming under GP limit. Valuation has been done for land & actual BUA of single storied residential building.		
Declaration		
I hereby declare that:		
I have deputed my representative Mr. Dinesh Das inspect the property. My representative has personally inspected the property on 08/07/2026. I have no direct or indirect interest in the property valued The information furnished in the report is true and correct to the best of my knowledge and belief. Signature of Valuer (All pages to be signed) Name of Valuer Er. Satyajit Mohanty Date 09/07/2026		

Regd. Valuer : SBI, PNB, UNION BANK, IDBI BANK, BOB, BOM, BOI, UCO, CANARA BANK, LIC, HDFC BANK, YES BANK, ICICI BANK, KOTAK MAHINDRA BANK, AXIS BANK

Regd. Office : Plot No. 858(P) & 859(P), Near Astha Binodini Apartment, Siba Nagar, Rajarani, Tankapani Road, Bhubaneswar - 751018, Odisha
 Ph.: 0674-3134245, Mob : 9937023855, 9437074855, E-mail : smohantyassociates@gmail.com



PROPERTY PHOTOGRAPHS

S MOHANTY ASSOCIATES

Delivering Solutions ...

VALUER & CHARTERED ENGINEER



Regd. Valuer : SBI, PNB, UNION BANK, IDBI BANK, BOB, BOM, BOI, UCO, CANARA BANK, LIC, HDFC BANK, YES BANK, ICICI BANK, KOTAK MAHINDRA BANK, AXIS BANK

Regd. Office : Plot No. 858(P) & 859(P), Near Astha Binodini Apartment, Siba Nagar, Rajarani, Tankapani Road, Bhubaneswar - 751018, Odisha
Ph.: 0674-3134245, Mob : 9937023855, 9437074855, E-mail : smohantyassociates@gmail.com




SKETCH MAP

S MOHANTY ASSOCIATES

Delivering Solutions ...

VALUER & CHARTERED ENGINEER



Regd. Valuer : SBI, PNB, UNION BANK, IDBI BANK, BOB, BOM, BOI, UCO, CANARA BANK, LIC, HDFC BANK, YES BANK, ICICI BANK, KOTAK MAHINDRA BANK, AXIS BANK

Regd. Office : Plot No. 858(P) & 859(P), Near Astha Binodini Apartment, Siba Nagar, Rajarani, Tankapani Road, Bhubaneswar - 751018, Odisha
Ph.: 0674-3134245, Mob : 9937023855, 9437074855, E-mail : smohantyassociates@gmail.com




LOCATION MAP

S MOHANTY ASSOCIATES

Delivering Solutions ...

VALUER & CHARTERED ENGINEER



Regd. Valuer : SBI, PNB, UNION BANK, IDBI BANK, BOB, BOM, BOI, UCO, CANARA BANK, LIC, HDFC BANK, YES BANK, ICICI BANK, KOTAK MAHINDRA BANK, AXIS BANK

Regd. Office : Plot No. 858(P) & 859(P), Near Astha Binodini Apartment, Siba Nagar, Rajarani, Tankapani Road, Bhubaneswar - 751018, Odisha
Ph.: 0674-3134245, Mob : 9937023855, 9437074855, E-mail : smohantyassociates@gmail.com