

Vehicle Damage Inspection Report

Generated On : 07 July 2026, 03:41 PM

Vehicle Summary

Total Damages	5
Overall Severity	Medium
Vehicle Health	Fair
Risk Score	48
Inspection Status	Needs Inspection

Damage Details

Damage	Severity	Location	Confidence	Priority	Estimated Cost
Lamp Broken	Medium	Rear Center Lamp	89.8%	Medium	■3,000 - ■12,000
Dent	Medium	Rear Bumper	65.4%	Medium	■5,000 - ■15,000
Scratch	Medium	Rear Bumper	55.0%	Medium	■2,000 - ■6,000
Scratch	Medium	Rear Bumper	53.9%	Medium	■2,000 - ■6,000
Dent	Minor	Front Bumper	48.2%	Low	■5,000 - ■15,000

Damage Recommendations

Damage #1

Damage Type : **Lamp Broken**

Severity : **Medium**

Location : **Rear Center Lamp**

Estimated Cost : **■3,000 - ■12,000**

Repair Priority : **Medium**

Recommendation : Replace the damaged lamp assembly.

Damage #2

Damage Type : **Dent**

Severity : **Medium**

Location : **Rear Bumper**

Estimated Cost : **■5,000 - ■15,000**

Repair Priority : **Medium**

Recommendation : Dent removal and panel inspection recommended.

Damage #3

Damage Type : **Scratch**

Severity : **Medium**
Location : **Rear Bumper**
Estimated Cost : **■2,000 - ■6,000**
Repair Priority : **Medium**
Recommendation : Buffing and repainting recommended.

Damage #4
Damage Type : **Scratch**
Severity : **Medium**
Location : **Rear Bumper**
Estimated Cost : **■2,000 - ■6,000**
Repair Priority : **Medium**
Recommendation : Buffing and repainting recommended.


Damage #5
Damage Type : **Dent**
Severity : **Minor**
Location : **Front Bumper**
Estimated Cost : **■5,000 - ■15,000**
Repair Priority : **Low**
Recommendation : Dent removal and panel inspection recommended.

Overall Recommendation

- Total detected damages : **5**
- Overall Severity : **Medium**
- Vehicle Health : **Fair**
- Inspection Status : **Needs Inspection**

Professional inspection is recommended before insurance claim approval.

Detected Damage Image



Disclaimer

This report has been generated automatically using the Vehicle Damage Detection System powered by YOLOv8. The assessment is AI-assisted and should be verified by a qualified vehicle inspector before insurance claim approval or repair estimation.