

PAVED ROADS



Palisa-Kumi road is in very good condition since its upgrade



Busitema junction-Busia has wide cracks on over 90% of the road width



Newly constructed section at Km 12 + 800 of Busia-Majanji road



Ponding section along Kisoga-Katosi road



Busumba- Munamba road in very good condition



Tororo-Magodes-Nabumali road in poor condition



Section on Kiganda-Kitenga (A005_Link05) at Km 122 (between Mityana and Mubende) in very poor condition



Rutting at Km 3+ 100 from Moroto to Ariamoi



Water ponding at Km 18 + 000 along Arapai-Katakwi-Iriri road. If the road drainage is not worked on, it will lead to pavement failures.

UNPAVED ROADS



Katikamu-Kikyusa road with deep erosion gulleys



Km 17 + 600 along Kakooge-Wabusana road has poor drainage



Figure 1 Kakiri-Masulita-Kapeeka at Km 11+700 the road is in good condition



Nazigo-Kitimbwa at Km 24+020. A section of the road (19km) is swallowed by River Nile



Zirobwe-Bamunanika road with water ponding and deep potholes at 0+40 from Bamunanika



Nazigo-Kitimbwa at Km 34+000 in good condition



Kagusa-Buikwe(Makindu) road with deep gullies



Gobero-Kakonda at Km 9+ 600 where a river crosses the road



Nawantale - Bukungu (B307_Link04) coved by water from Lake Kyoga




Nabirumbi- Buyende - Nkondo - Kidera (C812_Link01) with severe edge breaks

BRIDGES



Oluffe Bridge (B121) along Manibe - Maracha – Koboko (A008_Link06) in very good condition



Omposo Bridge (B333) along Moyo – Obongi (C722_Link01) road in very poor condition



Yadalala Bridge (B177) along Kotido - Apaán – Kabong road, Kotido station in good condition



Lakapelot bridge (B176) along Kotido - Apaan - Kabong (B301_Link03) in a critical state