



MINISTRY OF WORKS AND TRANSPORT
DEPARTMENT OF NATIONAL ROADS
DIVISION OF DESIGN AND NETWORK ENGINEERING
NETWORK ENGINEERING UNIT

National Road Network Situation Analysis Report

JULY 2024 – JUNE 2025

JULY 2025

TABLE OF CONTENTS

LIST OF TABLES	iii
LIST OF FIGURES	v
LIST OF ABBREVIATIONS	vi
EXECUTIVE SUMMARY	viii
1. INTRODUCTION	9
2. THE UGANDA NATIONAL ROAD NETWORK	10
2.1 Network Classification and Length	10
2.2 Length Investigated	13
2.3 Bridges and Structures.	13
3. ROADS INVENTORY	15
3.1 Background to Road Inventory	15
3.2 Line features	16
3.3 Point features	19
4. TRAFFIC INFORMATION	23
4.1 Traffic on the network	23
4.2 Average Traffic per Maintenance Station	25
5. MAINTENANCE STATIONS	26
5.1 Central Region	27
5.2 Eastern Region	42
5.3 Northern Region	52
5.4 Western Region	61
5.5 Southern Region	68
5.6 North Eastern Region	78
6. PAVED ROADS NETWORK CONDITION	84
6.1 Background to paved VCI	84
6.2 Visual Assessment and Distress Graphs for Paved Road Network	84
6.3 Comparison of the condition of Paved roads	88
6.4 Average VCI for Paved roads	92
6.5 Condition distribution graphs for VCI of Paved Roads	93
6.6 Condition trends for Paved roads	93
6.7 Performance of the paved road network per station	95
7. UNPAVED ROAD NETWORK CONDITION	98
7.1 Background to Unpaved VCI	98
7.2 Visual assessment of the Unpaved Road network	98
7.3 Condition of Unpaved Roads	101

7.4	Condition distribution graph for the VCI of Unpaved roads	102
7.5	Condition trends for Unpaved roads	103
7.6	Performance of the unpaved road network per station, 2025	105
8.	CONCLUSION	108
9.	RECOMMENDATIONS	108

LIST OF TABLES

Table 1: Classification of the Uganda National Road Network	10
Table 2: Changes in Length (2008 – 2025)	11
Table 3: Length of line features on the paved road network	17
Table 4: Line features on the paved road network.....	18
Table 5: Number of point features on the paved road network	20
Table 6: Number of point features on the unpaved road network	22
Table 7: Maintenance Stations Central Region	27
Table 8 : Length per Functional Class	28
Table 9: Kampala Station	34
Table 10: Luwero station	36
Table 11: Masaka Station	38
Table 12: Mpigi Station	40
Table 13: Mubende Station.....	42
Table 14: Eastern Region Maintenance Stations.....	43
Table 15 : Length per Functional Class	44
Table 16: Jinja Station	47
Table 17: Mbale Station.....	49
Table 18: Tororo Station	51
Table 19: Northern Region Maintenance Stations	52
Table 20 : Length per Functional Class	53
Table 21: Arua Station	55
Table 22: Gulu Station	56
Table 23: Kitgum Station	57
Table 24: Lira Station	59
Table 25: Moyo Station.....	60
Table 26: Western Region Maintenance Stations.....	61
Table 27 : Length per Functional Class	62
Table 28: Fort Portal Station.....	64
Table 29: Masindi Station	65
Table 30: Hoima Station	67
Table 31: Southern Region Maintenance Station	68
Table 32 : Length per Functional Class	69

Table 33: Ibanda Station	71
Table 34: Kabale Station	74
Table 35: Kasese Station.....	75
Table 36: Mbarara Station	77
Table 37: North Eastern Region Maintenance Stations	78
Table 38 : Length per Functional Class	79
Table 39: Kotido Station	80
Table 40: Moroto Station	81
Table 41: Soroti Station	83
Table 42: VCI ratings on paved roads.	84
Table 43: Comparison of the condition of Paved roads	92
Table 44: Condition of paved roads from 2009/10 to 2024/25	94
Table 45 : Station VCI	95
Table 46: VCI ratings on unpaved roads	98
Table 47: Condition of Unpaved Roads	102
Table 48 : Trend of the condition of unpaved roads over the years	104

LIST OF FIGURES

Figure 1: Split between Paved (29%) and Unpaved (71%) Road lengths of the MOWT Network (2025).....	10
Figure 2: Functional Classification of the National Road Network	11
Figure 3: Changes in Length (2008 - 2025).....	12
Figure 4: Paved and Investigated Road lengths (km), 2025	13
Figure 5: Split between Bridges and Major Culverts on the National Network, 2025	13
Figure 6: Split between Bridges and Major Culverts on the Paved and Unpaved Network, 2025	14
Figure 7: Split between Bridges and Major Culverts per region, 2025.....	14
Figure 8: Length of line features on the paved road network, 2025.....	16
Figure 9: Length of line features on the unpaved road network, 2025.....	17
Figure 10: Number of point features on the paved road network, 2025.....	19
Figure 11: Number of point features on the unpaved road network, 2025.....	21
Figure 12: Average Daily Traffic	23
Figure 13: Average Daily Traffic inclusive of motorcycles per Vehicle Type, 2025...	23
Figure 14: Traffic per Maintenance Station.....	25
Figure 15: Distress ratings of defects on paved roads, 2025.....	87
Figure 16: Average Paved VCI comparison.....	92
Figure 17: Paved VCI for 2025	93
Figure 18: Condition trend for the paved roads from 2009/10 to 2024/25	93
Figure 19: VCI rating of the paved road network per station.....	96
Figure 20: Distress, characteristic and condition ratings of unpaved roads, 2025..	100
Figure 21: VCI distribution for the unpaved road network.....	102
Figure 22: Condition trend for the unpaved roads over the Years	103
Figure 23: Condition rating of the unpaved road network per station	106

LIST OF ABBREVIATIONS

AADT	Annual Average Daily Traffic
AC	Assistant Commissioner
ANPR	Automatic Number Plate Recognition
ATC	Automatic Traffic Counter
BMS	Bridge Management System
CoB	Centre of Balance
COTS	Commercial Off-The-Shelf
DCL	Data Collection Limited
DNE	Design and Network Engineering
DRM	Directorate of Road Maintenance
FY	Financial Year
GIS	Geographic Information System
GPS	Global Positioning System
HDM-4	Highway Development and Management Model, Version 4
HS-WIM	High-Speed Weigh-In-Motion
ICT	Information and Communication Technology
IRI	International Roughness Index
ITS	Intelligent Transport Systems
km	Kilometre
MoWT	Ministry of Works and Transport
MSSQL	Microsoft Structured Query Language
O&M	Operation and Maintenance
OPRC	Output and Performance-Based Road Contract
PCU	Passenger Car Unit
PXE	Principal Engineer
RHD	Road Hierarchy Designation
RM	Road Maintenance
ROMDAS	Road Measurement Data Acquisition System
ROW	Right of Way
TIS	Traffic Information System
UNRA	Uganda National Roads Authority

UTM	Universal Transverse Mercator
VOC	Vehicle Operating Cost
WGS84	World Geodetic System 1984
WIM	Weigh-In-Motion

EXECUTIVE SUMMARY

The National Road Network Situation Analysis Report presents a comprehensive assessment of the status of Uganda's national road infrastructure as of the end of the 2024/25 Financial Year. Prepared by the Division of Design and Network Engineering under the Department of National Roads, the report provides an evidence-based overview of the extent, composition, condition, traffic performance, and asset inventory of the national road network to support informed planning, maintenance prioritisation, and investment decision-making.

Uganda's national road network currently totals 21,292 km, of which 29% (6,312 km) is paved, and 71% (14,979 km) is unpaved. The network plays a critical role in national and regional mobility, carrying the majority of passenger and freight traffic and underpinning economic activities such as trade, agriculture, tourism, and oil and gas development. The assessment covered approximately 95% of the paved road network and extensive sections of the unpaved network, ensuring a robust representation of current network conditions.

The analysis indicates that, on average, both paved and unpaved roads are in "Good" condition based on Visual Condition Index (VCI) ratings. However, emerging deterioration trends are evident, particularly on heavily trafficked corridors and in regions dominated by unsealed roads. Traffic analysis shows that motorcycles, light goods vehicles, and minibuses constitute a significant proportion of daily traffic, placing increasing pressure on pavement performance and accelerating wear on both paved and unpaved assets.

The report also documents the condition and distribution of 816 bridges and major culverts, highlighting regional disparities that have implications for maintenance funding and asset management planning. Inventory surveys of road features, including drainage, safety devices, pavement markings, and roadside structures, reveal significant maintenance obligations necessary to preserve road safety and functionality.

Overall, the findings highlight the need for proactive asset management, sustained and predictable maintenance funding, and targeted upgrading of strategic corridors. The Situation Analysis forms a foundational input into the National Roads Investment Plan, guiding the prioritization of preventive maintenance, rehabilitation, and upgrading interventions to ensure a safe, reliable, and resilient national road network.

1. INTRODUCTION

The National Road Network Situation Analysis constitutes the first and foundational component of the National Roads Investment Plan (NRIP). Its primary purpose is to establish a clear understanding of the current state of the national road network in terms of network extent, asset inventory, traffic demand, and infrastructure condition. Such an assessment is essential for effective infrastructure planning, as sound investment decisions must be grounded in a reliable understanding of existing assets and their performance.

Uganda's national road network is the backbone of the country's transport system, supporting over 95% of passenger and freight movements. As a landlocked country with growing regional trade responsibilities, the performance and sustainability of the national road network are critical to economic growth, social development, and regional integration. Consequently, maintaining the network in a serviceable condition while optimising lifecycle costs remains a key policy and operational objective of the Ministry of Works and Transport.

This analysis draws on data collected during the 2024/25 Financial Year, including road inventory surveys, traffic counts, and visual condition assessments of paved and unpaved roads, bridges, and major culverts. The assessment was conducted using programmable spreadsheets and dTIMS version 9.5, incorporating HDM-4 pavement performance algorithms to ensure consistency with national and international best practices in road asset management.

The findings of this Situation Analysis inform the subsequent needs analysis, which identifies maintenance, rehabilitation, and upgrading requirements across the network. These outputs directly support the development of prioritised, cost-effective investment programmes aimed at preserving asset value, improving safety, responding to growing traffic demand, and enhancing the long-term resilience of Uganda's national road network.

2. THE UGANDA NATIONAL ROAD NETWORK

- *The National Network is 21,292 km in total.*
- *29% (6,312km) is paved, and 71 % (14,979km) is unpaved.*
- *6,026km (96%) of paved roads were analysed in this report (Roads with ongoing works were not assessed).*
- *The national network comprises 816 bridges and major structures.*

2.1 Network Classification and Length

The total length of the national road network is 21,292 km, of which 6,312 km are paved, and 14,979 km are unpaved. Furthermore, according to functional classification, 12% of this network is Class A, 13% Class B, 74% is Class C, and 1% is Class M, as indicated in Table 1 below.

Functional Classification	Paved	Unpaved	Length (Km)	%	Description
A	2605	0	2605	12	International Trunk Roads
B	1740	1105	2845	13	National Trunk Roads
C	1823	13874	15697	74	Primary Roads
M	145	0	145	1	Expressways
Total	6312	14979	21292		

Table 1: Classification of the Uganda National Road Network




Figure 1: Split between Paved (29%) and Unpaved (71%) Road lengths of the MOWT Network (2025)




Figure 2: Functional Classification of the National Road Network

Table 2: Changes in Length (2008 – 2025)

Year	Paved (Km)	Unpaved (Km)	Total
2008/09	2916	7137	10053
2009/10	3119	7311	10430
2010/11	3264	17120	20384
2011/12	3317	17683	21000
2012/13	3490	17510	21000
2013/14	3795	16749	20544
2014/15	3919	16625	20544
2015/16	4157	16387	20544
2016/17	4257	16287	20544
2017/18	4636	15908	20544
2018/19	5015	15841	20856
2019/20	5398	15612	21010
2020/21	5528	15492	21020
2021/22	5745	15375	21120
2022/23	6056	15144	21200
2023/24	6,306	14,982	21,288
2024/25	6312	14979	21292




Figure 3: Changes in Length (2008 - 2025)

2.2 Length Investigated

The total length investigated in this analysis is based on the length of roads with complete assessment data in 2024/25. 6,029km of paved roads have complete assessment data. In total, 6,029 km (28%) of the total road length, which is 95% of the total paved road network, was investigated.

The graph below details the length investigated for FY 2024/25.




Figure 4: Paved and Investigated Road lengths (km), 2025

2.3 Bridges and Structures.

Based on the FY 2024/25 assessment, the total number of structures on the network is 816. These are categorised as Bridges and Major Culverts because they have distinct maintenance requirements and service lifespans.

The graphs below detail the number of structures on the network.




Figure 5: Split between Bridges and Major Culverts on the National Network, 2025




Figure 6: Split between Bridges and Major Culverts on the Paved and Unpaved Network, 2025




Figure 7: Split between Bridges and Major Culverts per region, 2025

The Northern region, followed by the Eastern region, has the highest number of structures, whereas the Central region has the fewest, which affects routine maintenance funding by region.

3. ROADS INVENTORY

3.1 Background to Road Inventory

The road inventory surveys entail identifying the physical characteristics of the road and its features, detailing their chainage and location. Road inventory is conducted for both paved and unpaved roads and is categorised into line and point features. Line features are defined by a specific start and end point, whereas a single location defines point features. Line and point features are further broken down into the categories listed below.

Line features

- Drainage
- Footways
- Number of lanes
- Median
- Roadside structures
- Terrain
- Side slope
- Safety devices
- Pavement markings
- Climbing Lanes

Point features

- Road sign
- Railway crossing
- Junctions
- Drifts
- Speed Restriction
- Pedestrian crossing
- Roadside structure
- Road marker post
- Pavement marking
- Drainage structures

Road inventory surveys were conducted on 80% (4,775km) of the paved road network and 69% (10,420km) of the unpaved road network. Data verification is a recurring process that requires input from regional stations to ensure an accurate and comprehensive representation of the network. Continuous updates and verification are essential for incorporating new changes and maintaining data precision.

3.2 Line features

3.2.1 Paved road network




Figure 8: Length of line features on the paved road network, 2025

Pavement markings are the most significant line feature on the network, present in 7,622km, followed by drainage, which covers 1,865km. Adequate and timely resources should be allocated to sustain these features, ensuring safety, compliance, and efficient traffic flow.

The table below presents a detailed breakdown of lengths for various line feature categories on the paved road network.

INVENTORY FEATURES	LENGTH (KM)
Drainage	1864.84
a. Lined open	1499.02
b. Lined covered	116.94
c. Unlined	246.90
d. Storm drain	1.98
Footways	146.86
Median	147.69
a. Depressed	2.62
b. Flush	0.84
c. Raised	144.23
Roadside structures	1263.15
a. Kerb	754.30
b. Retaining wall	0.00

INVENTORY FEATURES	LENGTH (KM)
c. Island	12.86
d. Layby	495.62
e. Edge Marker Posts	0.37
Side slope	124.69
a. Embankment	229.51
b. Cutting	124.69
Safety Devices	831.68
a. Streetlights	123.66
b. Road studs	0.00
c. Bollards	236.51
d. Guard Rail	471.51
Pavement Markings	7621.75
a. Dividing Centrelines	3261.82
b. Lane Lines	1987.88
c. Edge Lines	2058.76
d. None	313.29
Climbing Lanes	94.46

Table 3: Length of line features on the paved road network

3.2.2 Unpaved road network




Figure 9: Length of line features on the unpaved road network, 2025

Fewer categories of line features were observed on unpaved roads than on paved roads, owing to their nature. From the analysis, drainage is by far the largest with 44,147km, followed by side slopes with 8,295km.

The table below provides a detailed breakdown of lengths for various line-feature categories in the unpaved road network.

INVENTORY FEATURES	LENGTH (KM)
Drainage	44147
a. Lined open	29976

INVENTORY FEATURES	LENGTH (KM)
a. Lined covered	4
b. Unlined	14194
c. Storm drain	13
Footways	None
Median	5
a. Depressed	0
b. Flush	0
c. Raised	5
Roadside structures	30
a. Kerb	26
b. Retaining wall	1
c. Island	4
d. Layby	1
e. Edge Marker Posts	0
Side slope	8295
a. Embankment	530
b. Cutting	7650
Safety Devices	44
a. Streetlights	0
b. Road studs	0
c. Bollards	22
d. Guard Rail	22
Pavement Markings	None
a. Dividing Centrelines	0
b. Lane Lines	0
c. Edge Lines	0
d. None	0
Climbing Lanes	None

Table 4: Line features on the paved road network

3.3 Point features

3.3.1 Paved road network




Figure 10: Number of point features on the paved road network, 2025

The table presents a detailed breakdown of the counts for various point-feature categories on the paved road network.

S/N	INVENTORY FEATURES	TOTAL COUNT
1.	Road sign	22855
2.	Regulatory	11
3.	Informative	4089
4.	Guidance	3016
5.	Prohibitory	3304
6.	Warning	8785
7.	Mandatory	275
8.	Hazard marker	3099
9.	Supplementary	276
10.	Railway crossing	11
11.	Barrier	2
12.	No barrier	9
13.	Junction	2083
14.	Access	1296
15.	Cross	167
16.	Roundabout	75
17.	T junction	466
18.	Y junction	79
19.	Drift	0
20.	Speed restriction	7319
21.	Road humps	1016
22.	Rumble strips	4898
23.	Speed tables/Cushions	1399
24.	Road narrowing (chicanes & pinch points)	4
25.	Psychological Traffic calming (speed bars, dragon teeth)	2
26.	Pedestrian crossing	787
27.	Non-light-controlled	783
28.	Light controlled	4
29.	Roadside structures	43
30.	Waiting shed	43
31.	Road marker post	33951
32.	Kilometre post	2846
33.	Road reserve post	25829
34.	Culvert marker post	5276
35.	Pavement marking	1525
36.	Transverse Markings	1135
37.	Other markings	390
38.	Drainage Structure	6882
39.	Bridge	120
40.	Major Culvert	303
41.	Minor Culvert	6459

Table 5: Number of point features on the paved road network

3.3.2 Unpaved road network




Figure 11: Number of point features on the unpaved road network, 2025

The table below provides a detailed breakdown of the counts for various point-feature categories on the unpaved road network.

S/N	INVENTORY FEATURES	TOTAL COUNT
1.	Road sign	2116
2.	Regulatory	95
3.	Informative	62
4.	Guidance	313
5.	Prohibitory	150
6.	Warning	1201
7.	Mandatory	123
8.	Hazard marker	9
9.	Supplementary	7
10.	Railway crossing	25
11.	Barrier	0
12.	No barrier	25
13.	Junction	6653
14.	Access	3965
15.	Cross	729
16.	Roundabout	58
17.	T junction	1497
18.	Y junction	404
19.	Drift	28
20.	Speed restriction	74
21.	Road humps	13
22.	Rumble strips	61
23.	Speed tables/Cushions	0

S/N	INVENTORY FEATURES	TOTAL COUNT
24.	Road narrowing (chicanes & pinch points)	0
25.	Psychological Traffic calming (speed bars, dragon teeth)	0
26.	Pedestrian crossing	None
27.	Non-light-controlled	0
28.	Light controlled	0
29.	Roadside structures	None
30.	Waiting shed	0
31.	Road marker post	68
32.	Kilometre post	7
33.	Road reserve post	61
34.	Culvert marker post	0
35.	Pavement marking	None
36.	Transverse Markings	0
37.	Other markings	0
38.	Drainage structure	16863
39.	Bridge	210
40.	Major Culvert	183
41.	Minor culvert	16470

Table 6: Number of point features on the unpaved road network

4. TRAFFIC INFORMATION

Traffic data was collected using manually classified counts, analysed and expressed as Average Daily Traffic (ADT) for each road link surveyed, representing vehicle traffic.




Figure 12: Average Daily Traffic

4.1 Traffic on the network




Figure 13: Average Daily Traffic inclusive of motorcycles per Vehicle Type, 2025

It is observed that traffic on the network is dominated by Motorcycles & Scooters and Light Goods vehicles, as shown in the figure above.

4.2 Average Traffic per Maintenance Station

Maintenance Stations	Motorcycles & Scooters	Saloon Cars & Taxi's	Light Goods	Small Buses	Medium Buses	Large Buses	Light Trucks	Medium Trucks	Truck Trailer/Semi Trailer	Bicycles
Kampala	3900	1049	1469	1553	90	53	487	508	326	454
Mpigi	1694	409	540	371	25	49	207	184	69	169
Masaka	1642	420	377	177	20	56	152	118	62	302
Mubende	1550	228	224	185	8	14	149	102	43	172
Luwero	1540	377	466	366	28	28	224	130	42	427
Mbarara	1015	407	289	145	20	19	149	114	50	343
Ibanda	847	214	127	34	4	1	69	41	8	202
Kabale	702	228	197	98	17	8	94	75	38	248
Kasese	1089	154	315	112	2	20	89	80	59	127
Fort Portal	1672	148	189	98	3	11	59	68	26	342
Hoima	1034	112	101	81	3	5	71	52	9	214
Masindi	488	66	130	63	3	11	55	43	16	158
Lira	734	79	118	24	6	9	68	37	46	852
Gulu	1079	114	256	44	5	24	82	87	60	456
Kitgum	478	47	82	16	4	6	38	31	10	288
Moyo	971	100	145	15	2	3	64	30	7	703
Arua	686	103	166	19	5	7	57	63	32	313
Jinja	2414	277	351	427	27	14	124	152	168	593
Tororo	2340	251	283	253	9	10	112	130	187	888
Mbale	2560	243	322	217	5	14	127	96	92	530
Soroti	1169	63	103	38	1	3	44	24	13	811
Moroto	190	14	54	8	1	1	15	33	3	151
Kotido	158	6	35	3	1	0	12	8	2	141

Figure 14: Traffic per Maintenance Station

5. MAINTENANCE STATIONS

There are 23 maintenance stations under the Department of National Roads.

They serve as the frontline units for implementing maintenance programs and ensuring that the road network remains in serviceable condition year-round.

Road Maintenance Stations form the operational backbone of Uganda's road maintenance strategy.

They ensure:

- Improved road availability and safety.
- Reduced maintenance backlog through early intervention.
- Efficient use of public resources and better asset preservation.
- Strengthened data flow between field operations and central asset management databases.

5.1 Central Region

The Central region has a total of 4,787 km of roads under maintenance, comprising 1,790 km of bituminous highways and 2,995 km of unsealed roads. Unsealed roads account for a larger share of the network across all stations, highlighting a continued reliance on gravel and earth surfaces.

Kampala Maintenance Station manages the largest total network length (1,221 km), with a relatively high proportion of bituminous roads (694 km), reflecting its urban and high-traffic characteristics. In contrast, Luwero has the longest unsealed road network (971 km), indicating a predominantly rural network with greater maintenance demands; Masaka, Mpigi, and Mubende exhibit mixed surface compositions, with unsealed roads consistently exceeding paved sections.

Sub region	Maintenance Station	Bituminous	Unsealed	Total
Central	Kampala	694	527	1221
	Mpigi	268	399	667
	Luwero	243	971	1215
	Masaka	328	690	1019
	Mubende	257	408	665

Table 7: Maintenance Stations Central Region

Region	Maintenance Station	Length per Functional Class (Km)				
		A	B	C	M	Total
Central	Kampala	267.72	147.51	661.45	144.56	1221.24
	Luwero	151.61		1063.09		1214.70
	Masaka	190.68	105.41	721.70		1017.80
	Mpigi	146.89		519.72		666.60
	Mubende	109.99	143.59	411.87		665.45
	Grand Total	866.90	396.51	3377.82	144.56	4785.79

Table 8 : Length per Functional Class

5.1.1 Kampala station

Link_Id	Road_Class	Link_Name	Length(Km)	Surface_Type
A001_Link01	A	Kampala - Mukono	17.7	Bituminous
A001_Link02	A	Mukono - Lugazi	24.1	Bituminous
A001_Link03	A	Lugazi - Njeru	30.1	Bituminous
A001_Link04	A	Njeru - Jinja	2.3	Bituminous
A001N1_Link01	A	Njeru - Jinja (Dual Section)	2.9	Bituminous
A002_Link01	A	Kibuye - Natete - Busega	6.5	Bituminous
A003_Link01	A	Kibuye - Zana	4.9	Bituminous
A003_Link02	A	Zana - Entebbe Airport	32.0	Bituminous
A003N1_Link01	A	Kibuye - Zana (Dual Section)	5.0	Bituminous
A003N2_Link01	A	Entebbe Airport (Dual)	13.0	Bituminous
A003N3_Link01	A	Kajjansi (Dual)	0.4	Bituminous
A006_Link01	A	Kampala - Kawempe	7.7	Bituminous
A006_Link02	A	Kawempe - Matuga	8.6	Bituminous
A006N1_Link01	A	Bwaise (Dual)	0.7	Bituminous
A009_Link01	A	Kampala - Nansana	5.3	Bituminous
A009_Link02	A	Nansana - Busunju	45.6	Bituminous
A009_Link03	A	Busunju - Kiboga - Lwamata	50.0	Bituminous
A009N1_Link01	A	Kasubi (Dual)	1.4	Bituminous
A009N2_Link01	A	Namungoona (Dual)	0.5	Bituminous
A010_Link01	A	Nsambya-Kabalagala-Gaba	9.1	Bituminous
B100_Link01	B	Kubiri roundabout - Gayaza	13.3	Bituminous
B100_Link02	B	Gayaza - Kalagi	20.2	Bituminous
B100N1_Link01	B	Kalerwe (Dual)	1.7	Bituminous
B101_Link01	B	Mukono - Kalagi	17.9	Bituminous
B101_Link02	B	Kalagi - Bukoloto - Kayunga	31.7	Bituminous
B101_Link03	B	Kayunga - Busana - Isimba	20.2	Bituminous
B102_Link01	B	Njeru - Bukoloto	42.6	Bituminous
C001_Link01	C	Nsambya- Cape Town Villa	2.8	Bituminous
C002_Link01	C	Seeta-Namilyango	3.8	Bituminous

Link_Id	Road_Class	Link_Name	Length(Km)	Surface_Type
C003_Link01	C	Nazigo-Kireku-Nkokonjeru-Kitimbwa	41.6	Unsealed
C005_Link01	C	Salaama Road	12.2	Bituminous
C006_Link01	C	Kirongo-Kulwe	20.3	Unsealed
C007_Link01	C	Kyerima-Bulawula	10.2	Unsealed
C011_Link01	C	Walwanda-Kirongo	19.5	Unsealed
C022_Link01	C	Mbuya/SilverSprings-Kireka	4.6	Bituminous
C023_Link01	C	Old Njeru - Jinja	1.8	Bituminous
C024_Link01	C	Mukono-Kyetume-Kisoga-Katosi	26.6	Bituminous
C025_Link01	C	Kisoga - Lugasa	27.9	Bituminous
C025_Link02	C	Lugasa - Najja	10.4	Bituminous
C026_Link01	C	Bulumagi - Nyenga	4.1	Unsealed
C027_Link01	C	Lugazi - Buikwe	10.8	Unsealed
C028_Link01	C	Najja - Nyenga	9.8	Bituminous
C029_Link01	C	Njeru-Nyenga-Buikwe	9.8	Bituminous
C029_Link02	C	Nyenga-Buikwe	14.7	Unsealed
C030_Link01	C	Buikwe - Najja	9.0	Unsealed
C030_Link02	C	Najja - Kiyindi	7.8	Unsealed
C034_Link01	C	Bugungu Prisons Access	3.5	Unsealed
C035_Link01	C	Buvuma Women's prison Access	0.9	Bituminous
C036_Link01	C	Nambole - Kampala Industrial Park - Mukono	13.7	Unsealed
C037_Link01	C	Mukono Railway access off Mukono - Kyetu	2.2	Unsealed
C038_Link01	C	Kisoga - Kibanga Port	10.6	Unsealed
C039_Link01	C	Nyenga - Railway station Access	1.7	Unsealed
C040_Link01	C	Lugasa - Buikwe	8.7	Unsealed
C041_Link01	C	Namataba - Kyampisi	40.8	Unsealed
C042_Link01	C	Kawolo Railway access	0.9	Unsealed
C043_Link01	C	Access to Kituuza Agriculture Research C	5.4	Unsealed
C044_Link01	C	Buikwe - Lugasa(Makindu)	6.9	Unsealed
C045_Link01	C	Kabimbiri - Misindye	38.5	Unsealed
C047_Link01	C	Kasana - Bugobero	7.6	Unsealed
C140_Link01	C	Kasana - Mbulamuti ferry access	1.3	Unsealed

Link_Id	Road_Class	Link_Name	Length(Km)	Surface_Type
C150_Link01	C	Najjanankumbi - Busabala	11.1	Unsealed
C151_Link01	C	Busabala-Kazi	0.6	Unsealed
C152_Link01	C	Kireka-Namugongo-Misindye-Seeta	14.9	Bituminous
C153_Link01	C	Lweza - Kigo Prison	8.7	Unsealed
C157_Link01	C	Entebbe-Nakiwogo	3.4	Bituminous
C158_Link01	C	Nakiwogo Statehouse road	1.5	Bituminous
C159_Link01	C	Access to Kajjansi Fisheries Research Ce	1.7	Unsealed
C168_Link01	C	Bweyogerere - Bukasa	2.0	Bituminous
C170_Link01	C	Namboole Access Road	2.1	Bituminous
C171_Link01	C	Access to Kajjansi Air Strip	2.6	Unsealed
C172_Link01	C	Kawuku - Bwerenga	6.6	Unsealed
C173_Link01	C	Access to Lunnyo	2.1	Unsealed
C174_Link01	C	Kitala - Gerenge	9.6	Unsealed
C175_Link01	C	Abayita Ababiri - Kasenyi	5.4	Unsealed
C176_Link01	C	Access to Katabi	4.0	Unsealed
C177_Link01	C	Access to Kigungu	10.0	Unsealed
C178_Link01	C	Natete - Nakawuka - Kisubi	28.1	Unsealed
C179_Link01	C	Old Masaka Road (Kyengera -Kabojja Secondary)	1.6	Unsealed
C181_Link01	C	Access to Kakiri Army Barracks	2.0	Unsealed
C182_Link01	C	Buloba - Wakiso	8.9	Unsealed
C187_Link01	C	Namayumba - Kitalya Prison - Kamuli	19.3	Unsealed
C193_Link01	C	Wakiso-Kassengejja- Matugga	9.9	Unsealed
C194_Link01	C	Matugga - Kasangati	9.5	Unsealed
C194_Link02	C	Kasangati - Kyaliwajala	8.4	Unsealed
C195_Link01	C	Nakawuka - Kasanje	9.5	Unsealed
C300_Link01	C	Kayunga-Bale-Galiraya-Lake Kyoga	87.4	Unsealed
M20	M	Kampala NorthernBypass	20.0	Bituminous
M20Int1_S1	M	Namboole Interchange Slip 1	0.4	Bituminous
M20Int1_S2	M	Namboole Interchange Slip 2	0.4	Bituminous
M20Int1_S3	M	Namboole Interchange Slip 3	0.4	Bituminous
M20Int1_S4	M	Namboole Interchange Slip 4	0.3	Bituminous

Link_Id	Road_Class	Link_Name	Length(Km)	Surface_Type
M20Int1_S5	M	Namboole Interchange Slip 5	0.3	Bituminous
M20Int2_S1	M	Naalya Interchange Slip 1	0.3	Bituminous
M20Int2_S10	M	Naalya Interchange Slip 10	0.4	Bituminous
M20Int2_S11	M	Naalya Interchange Slip 11	0.4	Bituminous
M20Int2_S2	M	Naalya Interchange Slip 2	0.4	Bituminous
M20Int2_S3	M	Naalya Interchange Slip 3	0.2	Bituminous
M20Int2_S4	M	Naalya Interchange Slip 4	0.2	Bituminous
M20Int2_S5	M	Naalya Interchange Slip 5	0.2	Bituminous
M20Int2_S6	M	Naalya Interchange Slip 6	0.6	Bituminous
M20Int2_S7	M	Naalya Interchange Slip 7	0.4	Bituminous
M20Int2_S8	M	Naalya Interchange Slip 8	0.2	Bituminous
M20Int2_S9	M	Naalya Interchange Slip 9	0.2	Bituminous
M20Int3_S1	M	Kisaasi Interchange Slip 1	0.4	Bituminous
M20Int3_S2	M	Kisaasi Interchange Slip 2	0.4	Bituminous
M20Int3_S3	M	Kisaasi Interchange Slip 3	0.4	Bituminous
M20Int3_S4	M	Kisaasi Interchange Slip 4	0.2	Bituminous
M20Int3_S5	M	Kisaasi Interchange Slip 5	0.2	Bituminous
M20Int3_S6	M	Kisaasi Interchange Slip 6	0.3	Bituminous
M20Int3_S7	M	Kisaasi Interchange Slip 7	0.3	Bituminous
M20Int3_S8	M	Kisaasi Interchange Slip 8	0.1	Bituminous
M20Int4_S1	M	Kyebando Interchange Slip 1	0.3	Bituminous
M20Int4_S10	M	Kyebando Interchange Slip 10	0.1	Bituminous
M20Int4_S2	M	Kyebando Interchange Slip 2	0.1	Bituminous
M20Int4_S3	M	Kyebando Interchange Slip 3	0.5	Bituminous
M20Int4_S4	M	Kyebando Interchange Slip 4	0.5	Bituminous
M20Int4_S5	M	Kyebando Interchange Slip 5	0.1	Bituminous
M20Int4_S6	M	Kyebando Interchange Slip 6	0.1	Bituminous
M20Int4_S7	M	Kyebando Interchange Slip 7	0.4	Bituminous
M20Int4_S8	M	Kyebando Interchange Slip 8	0.2	Bituminous
M20Int4_S9	M	Kyebando Interchange Slip 9	0.5	Bituminous
M20Int5_S1	M	Kalerwe Interchange Slip 1	0.4	Bituminous

Link_Id	Road_Class	Link_Name	Length(Km)	Surface_Type
M20Int5_S2	M	Kalerwe Interchange Slip 2	0.4	Bituminous
M20Int5_S3	M	Kalerwe Interchange Slip 3	1.1	Bituminous
M20Int6_S1	M	Bwaise Interchange Slip 1	1.1	Bituminous
M20Int6_S2	M	Bwaise Interchange Slip 2	0.4	Bituminous
M20Int6_S3	M	Bwaise Interchange Slip 3	0.5	Bituminous
M20Int7_S1	M	Namungoona Interchange Slip 1	0.5	Bituminous
M20Int7_S2	M	Namungoona Interchange Slip 2	0.5	Bituminous
M20Int7_S3	M	Namungoona Interchange Slip 3	0.5	Bituminous
M20Int7_S4	M	Namungoona Interchange Slip 4	0.5	Bituminous
M20Int8_S1	M	Masanafu Interchange Slip 1	0.4	Bituminous
M20Int8_S2	M	Masanafu Interchange Slip 2	0.1	Bituminous
M20Int8_S3	M	Masanafu Interchange Slip 3	0.5	Bituminous
M20Int8_S4	M	Masanafu Interchange Slip 4	0.4	Bituminous
M20Int8_S5	M	Masanafu Interchange Slip 5	0.1	Bituminous
M20Int8_S6	M	Masanafu Interchange Slip 6	0.1	Bituminous
M20Int8_S7	M	Masanafu Interchange Slip 7	0.4	Bituminous
M20Int8_S8	M	Masanafu Interchange Slip 8	0.4	Bituminous
M20Int8_S9	M	Masanafu Interchange Slip 9	0.1	Bituminous
M20Int9_S1	M	Busega Interchange Slip 1	0.8	Bituminous
M20Int9_S2	M	Busega Interchange Slip 2	0.7	Bituminous
M20Int9_S3	M	Busega Interchange Slip 3	0.8	Bituminous
M20N1	M	Kampala NorthernBypass (dual)	20.0	Bituminous
M3_Link01	M	Kampala - Entebbe Expressway	24.8	Bituminous
M3_Link02	M	Munyonyo Spur	12.3	Bituminous
M3Int1_S1	M	Busega Interchange Slip 4	0.7	Bituminous
M3Int1_S2	M	Busega Interchange Slip 5	0.6	Bituminous
M3Int1_S3	M	Busega Interchange Slip 6	0.6	Bituminous
M3Int2_S1	M	Kajjansi Interchange Slip 1	0.6	Bituminous
M3Int2_S2	M	Kajjansi Interchange Slip 2	1.0	Bituminous
M3Int2_S3	M	Kajjansi Interchange Slip 3	0.7	Bituminous
M3Int2_S4	M	Kajjansi Interchange Slip 4	0.8	Bituminous

Link_Id	Road_Class	Link_Name	Length(Km)	Surface_Type
M3Int3_S1	M	Kajjansi Interchange Slip 5	0.4	Bituminous
M3Int3_S2	M	Kajjansi Interchange Slip 6	0.5	Bituminous
M3Int3_S3	M	Kajjansi Interchange Slip 7	0.4	Bituminous
M3Int3_S4	M	Kajjansi Interchange Slip 8	0.4	Bituminous
M3Int4_S1	M	Mpala Interchange Slip 1	0.4	Bituminous
M3Int4_S2	M	Mpala Interchange Slip 2	0.7	Bituminous
M3Int4_S3	M	Mpala Interchange Slip 3	0.2	Bituminous
M3Int4_S4	M	Mpala Interchange Slip 4	0.4	Bituminous
M3Int4_S5	M	Mpala Interchange Slip 5	0.7	Bituminous
M3N1_Link01	M	Kampala - Entebbe Expressway (dual)	25.0	Bituminous
M3N2_Link01	M	Munyonyo Spur (dual)	12.3	Bituminous

Table 9: Kampala Station

5.1.2 Luwero station

Link_Id	Road_Class	Link_Name	Length(Km)	Surface_Type
A006_Link03	A	Matuga - Wobulenzi	28.92	Bituminous
A006_Link04	A	Wobulenzi - Kasana - Luweero	15.644	Bituminous
A006_Link05	A	Luweero - Nakasongola	54.829	Bituminous
A006_Link06	A	Nakasongola - Kafu	52.216	Bituminous
C046_Link01	C	Ziobwe - Lwajjali - Kasawo - Kabimbiri	22.974	Unsealed
C154_Link01	C	Matugga - Semuto - Kapeka	39.679	Bituminous
C154_Link02	C	Kapeka-Butalangwa	18.24	Unsealed
C184_Link01	C	Kakiri-Masulita-Danze-Mawale	23.168	Unsealed
C185_Link01	C	Gobero-Segenga-Kakonda	14.357	Unsealed
C186_Link01	C	Namyumba-Kakonda-Wabikokoma-Semuto	14.651	Unsealed
C275_Link01	C	Mate - Kabulamuliro-Kakinga	9.2	Unsealed
C301_Link01	C	Ziobwe -Kikyusa - Luweero	37.188	Unsealed
C302_Link01	C	Gayaza-Ziobwe	30.873	Bituminous
C302_Link02	C	Ziobwe-Bamunanika	11.501	Unsealed
C302_Link03	C	Bamunanika-Wobulenzi	11.606	Unsealed
C303_Link01	C	Kalule - Bamunanika	11.055	Unsealed
C304_Link01	C	Kisule - Nakaseke - Kapeeka	34.106	Unsealed
C305_Link01	C	Busunju - Kapeeka	15.493	Unsealed
C306_Link01	C	Luwero-Kiwoko-Butalangu	28.761	Unsealed
C307_Link01	C	Butalangwa - Ngoma - Bulyamusenyu	82.212	Unsealed
C308_Link01	C	Nakasongola loop	12.762	Bituminous
C309_Link01	C	Nakasongola - Airbase	6.699	Bituminous
C311_Link01	C	Bombo - Ndejje - Kalasa	18.41	Unsealed
C312_Link01	C	Kalule - Bowa - Nakaseke	20.579	Unsealed
C312_Link02	C	Nakaseke - Kiwoko	14.97	Unsealed
C313_Link01	C	Katikamu - Kikyusa	16.881	Unsealed
C315_Link01	C	Kyankwazi - Ngoma	14.867	Unsealed
C315_Link02	C	Ngoma - Kasozi - Kyamukonda	42	Unsealed
C316_Link01	C	Ngoma-Buwana-Kinyogogga	27.15	Unsealed

Link_Id	Road_Class	Link_Name	Length(Km)	Surface_Type
C317_Link01	C	Katuugo-Kinyogogga	31.905	Unsealed
C317_Link02	C	Kinyogogga-Kaweweeta Barracks	8.984	Unsealed
C318_Link01	C	Sasira-Namika	22.082	Unsealed
C320_Link01	C	Kapeeka - Singo Military Barracks - Kituuma	19.513	Unsealed
C325_Link01	C	Kikyusa- Bamugolode - Kazwama - Nakasongola	83.131	Unsealed
C326_Link01	C	Nakasongola - Lwampanga - Zengebe Access	31.981	Unsealed
C326_Link02	C	Lwampanga - Lwabyata - Kafu	46	Unsealed
C329_Link01	C	Kayindu-Kalagala-Kyabakadde	27.65	Unsealed
C330_Link01	C	Kakooge - Nansaka - Wabusana	29.735	Unsealed
C331_Link01	C	Migeera-Nabisweera	7.079	Unsealed
C332_Link01	C	Kasiso-Mazzi-Kalungi	57.024	Unsealed
C333_Link01	C	Kiwoko-Kalagala-Ngogolo	34.8	Unsealed
C334_Link01	C	Kakinga -Kalungu - Dwaniro	32	Unsealed
C335_Link01	C	Sungira Hill Access	1.6	Bituminous
C336_Link01	C	Nakitooma Access	2.4	Unsealed
C337_Link01	C	Kikondo-Kikandwa-Nvuye	7.4	Unsealed
C338_Link01	C	Zengebe-Ferry-Access	3.025	Unsealed
C339_Link01	C	Kikubampanga - Lutabayima - Seganga	5.801	Unsealed
C340_Link01	C	Kyamukonda - Lugogo River - Ngoma	31.59524581	Unsealed

Table 10: Luwero station

5.1.3 Masaka Station

Link_Id	Road_Class	Link_Name	Length(Km)	Surface_Type
A002_Link05	A	Lukaya - Masaka - bypass	34	Bituminous
A002_Link06	A	Masaka - Lyantonde	67.781	Bituminous
A004_Link01	A	Masaka roundabout - Kyotera	44.248	Bituminous
A004_Link02	A	Kyotera - Mutukula	44.654	Bituminous
B103_Link01	B	Nyendo - Villa Maria	10.113	Bituminous

Link_Id	Road_Class	Link_Name	Length(Km)	Surface_Type
B103_Link02	B	Villa Maria - Sembabule	36	Bituminous
	B	Sembabule - Lwemiyaga junction - Nkonge	59.3	Unsealed
C166_Link02	C	R. Katonga - Sembabule	21.994	Bituminous
C166_Link03	C	Sembabule - Matete	18.799	Unsealed
C166_Link04	C	Matete - Mbirizi	17.309	Unsealed
C210_Link01	C	Nyendo - Masaka	5.398	Bituminous
C211_Link01	C	Nyendo - Lambu port Junction	30.752	Bituminous
C211_Link02	C	Lambu port Junction - Bukakata	5.039	Bituminous
C212_Link01	C	Bukakata - Lambu Port	4.979	Bituminous
C213_Link01	C	Bukakata - Old Landing Site	1.874	Unsealed
C214_Link01	C	Lyantonde - Lumbugu	48.889	Unsealed
C214_Link02	C	Lumbugu - Kyotera	16.241	Bituminous
C215_Link01	C	Villa Maria - Kalungu	25.792	Unsealed
C215_Link02	C	Kalungu - Mityegonga	9.315	Unsealed
C215_Link03	C	Mityegonga - Kabulasoke	13.25	Unsealed
C216_Link01	C	Lukaya - Miwuula	25.918	Unsealed
C217_Link01	C	Miwula - Bweera-Kagologolo	35.583	Unsealed
C218_Link01	C	Masaka - Kidda - Buwunga - Nkuke - Kyana	31.956	Unsealed
C219_Link01	C	Masaka army barracks	1.018	Unsealed
C220_Link01	C	Degeya PTTC off Masaka Township	3.757	Unsealed
C221_Link01	C	Kalisizo - Lusakalwamese	8.033	Unsealed
C221_Link02	C	Lusakalwamese - Bikira	24.712	Unsealed
C222_Link01	C	Kyesiga-Malembo Landing site	13.114	Unsealed
C223_Link01	C	Taba -Kyeesiga-Ddimo Landing site	17.097	Unsealed
C224_Link01	C	Kyapa - Kasensero	41.903	Unsealed
C225_Link01	C	Kyabakuza - Kiwangala - Ndagwe - Namabal	60.928	Unsealed
C226_Link01	C	Kyabakuza - Kyogya - Matete	30.297	Unsealed
C226_Link02	C	Matete - Kakinga - Kaliro	50.493	Unsealed
C227_Link01	C	Lyantonde - Kaliro - Nabitanga - Ntusi	44.311	Unsealed
C228_Link01	C	Ntusi - Nabitanga	12.339	Unsealed
C229_Link01	C	Luku Pier - Kalangala HQ	34.652	Unsealed

Link_Id	Road_Class	Link_Name	Length(Km)	Surface_Type
C230_Link01	C	Kalangala HQ - Mulabana	34.705	Unsealed
C231_Link01	C	Lumbugu - Rakai	4.5	Bituminous
C232_Link01	C	Lyantonde - High Street	1.33	Bituminous
C233_Link01	C	Bukulula-Kalungu	11.635	Unsealed
C234_Link01	C	Mukoko-Birinzi-Ssunga	12.763	Unsealed
C235_Link01	C	Villa Road Link	1.027040774	Bituminous

Table 11: Masaka Station

5.1.4 Mpigi Station

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
A002_Link02	A	Busega - Mpigi	25.342	Bituminous
A002_Link03	A	Mpigi - Buwama	32.081	Bituminous
A002_Link04	A	Buwama - Lukaya	30.5	Bituminous
A005_Link01	A	Busega - Bujuuko	32.22962948	Bituminous
A005_Link02	A	Bujuuko - Mityana	26.736	Bituminous
C160_Link01	C	Mpigi-Kasanje-Buwaya	19.789	Unsealed
C161_Link01	C	Mpigi Loop	3.434	Bituminous
C162_Link01	C	Mpigi - Kanoni	59.028	Bituminous
C162_Link02	C	Kanoni - Kabulasoke	11.347	Bituminous
C162_Link03	C	Kabulasoke - Madu	19.701	Bituminous
C162_Link04	C	Madu - Kasambya	36.155	Unsealed
C163_Link01	C	MitalaMaria-Bulo-Kanoni	29	Unsealed
C164_Link01	C	MatalaMaria Loop	4.303	Unsealed
C165_Link01	C	Buwama - Katebo Port	12.54	Unsealed
C166_Link01	C	Madu-Kisozi-R.Katonga	22.106	Bituminous
C167_Link01	C	Kyayi - Kasambya	7.668	Unsealed
C180_Link01	C	Nakawuka - Namutamala - Katende - Bujuko	35.426	Unsealed
C183_Link01	C	Buloba PTTC	0.785	Unsealed
C188_Link01	C	Kyabadaza - Kibibi	14.67	Unsealed
C189_Link01	C	Kayenje - Nkinga - Nakatoke	9.933	Unsealed
C190_Link01	C	Kayabwe - Nkozi - Kinyika - Ngando - Wab	38.574	Unsealed
C191_Link01	C	Katonga - Ggolo	11.119	Unsealed
C196_Link01	C	Bujuuko Railway Access	2.889	Unsealed
C197_Link01	C	Kawolongojjo Railway Access	2.56	Unsealed
C198_Link01	C	Budo-Nakasozi	3.718	Bituminous
C199_Link01	C	Nabbingo Access Road	1.484	Bituminous
C200_Link01	C	Lukolo-Bunjako	13.855	Unsealed
C201_Link01	C	Kabasanda-Kakindu-Zigoti	21.105	Unsealed
C260_Link01	C	Mityana - Busunju	28.372	Unsealed

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
C261_Link01	C	Matte - Sekanyonyi	16.595	Unsealed
C261_Link02	C	Sekanyonyi - Kikonge	13.567	Unsealed
C262_Link01	C	Mityana-Misigi-Kanoni	36.594	Unsealed
C265_Link02	C	Masozzi- Madu	20.742	Unsealed
C269_Link01	C	Kyengeza - Railway line	2.577	Unsealed
C272_Link01	C	Hoima Road/Kituuma-Kiryoka-Mutetema	20.08	Unsealed

Table 12: Mpigi Station

5.1.5 Mubende Station

Link_Id	Road_Class	Link_Name	Length(Km)	Surface_Type
A005_Link03	A	Mityana - Naama - Myanzi	15.842	Bituminous
A005_Link04	A	Myanzi - Kiganda	27.705	Bituminous
A005_Link05	A	Kiganda-Kitenga	20.351	Bituminous
A005_Link06	A	Kitenga-Mubende-Lusalira	29.794	Bituminous
A005_Link07	A	Lusalira - Nabingoola - Lubaale	16.3	Bituminous
B103_Link03	B	Nkonge - Kibula - Magege - Kasambya	18.8	Unsealed
B103_Link04	B	Kasambya - Lusalira	17.289	Unsealed
B203_Link01	B	Mubende - Kiboyo - Kakumiro	30.499	Bituminous
B203_Link02	B	Kakumiro - Nkondo - Kijaguza - Bulamagi- Kabaale swamp	77	Bituminous
C162_Link05	C	Kasambya - Nabakazi	29.857	Unsealed
C263_Link01	C	Myanzi loop	1.839	Unsealed
C264_Link01	C	Nabingoola - Kasambya	15.45	Unsealed
C265_Link01	C	Kitenga-Masozzi	17.769	Unsealed
C266_Link01	C	Kiganda Loop	1.07	Unsealed
C267_Link01	C	Mityana - Katakala - Naama	0.137	Unsealed
C268_Link01	C	Mityana-Katakala-Naama	7.471	Bituminous
C270_Link01	C	Mityana - District Offices - Nakaseeta	8.09	Unsealed
C271_Link01	C	Wakitundu - Bulera - Mutetema	18.662	Unsealed
C271_Link02	C	Mutetema-Kyamusisi - Bukuya	22.976	Unsealed
C271_Link03	C	Kyamusisi- Kikoloto - Kitumbi Bridge (Kayindiyindi)	26.499	Unsealed
C273_Link01	C	Myanzi - Kasanda	16.86	Unsealed
C273_Link02	C	Kasanda - Bukuya	14.88	Unsealed
C273_Link03	C	Bukuya - Kiboga	29.925	Unsealed
C274_Link01	C	Kasanda - Madudu	42.8	Unsealed
C274_Link02	C	Madudu - Kiyuya	16.9	Unsealed
C277_Link01	C	Kitenga -Ikula-Kanyogoga	43.59	Unsealed
C279_Link01	C	Kabamba/ Karama army barracks off Mubende	9	Unsealed
C280_Link01	C	Rwebituti-Gold Mines Spur	7.73	Unsealed
C281_Link01	C	Mubende-Biwanga	4.879	Unsealed

Link_Id	Road_Class	Link_Name	Length(Km)	Surface_Type
C283_Link01	C	Nkondo - Nalweyo	14.467	Unsealed
C284_Link01	C	Mityana Railway Access 1	1.922253527	Unsealed
C285_Link01	C	Mityana Railway Access 2	0.27549783	Unsealed
C550_Link01	C	Kakumiro-Kibale	32.205	Bituminous
C567_Link01	C	Kakumiro - Nkooko	26.618	Unsealed

Table 13: Mubende Station

5.2 Eastern Region

The Eastern Region manages a total of 2,763 km of roads, comprising 845 km of bituminous roads and 1,918 km of unsealed roads. Unsealed roads account for approximately 69% of the network, indicating a predominantly gravel and earth-surfaced system with relatively higher maintenance requirements.

The Jinja Maintenance Station (Busoga Sub-region) manages the largest network length (1,173 km), with unsealed roads (914 km) significantly exceeding bituminous sections (259 km), reflecting the extensive rural and feeder road connectivity in the sub-region. Mbale Maintenance Station (Bugisu Sub-region) shows a more balanced network, with 384 km of bituminous roads and 540 km of unsealed roads, consistent with its role as a regional urban and commercial hub. Tororo Maintenance Station (Bukedi Sub-region) manages the smallest network (666 km), which is also largely unsealed (464 km).

Region	Subregion	Maintenance station	Bituminous	Unsealed	Total
Eastern	Busoga	Jinja	259	914	1173

	Bugisu	Mbale	384	540	924
	Bukedi	Tororo	202	464	666

Table 14: Eastern Region Maintenance Stations

Region	Maintenance station	Length per Functional Class (Km)			
		A	B	C	Total
Eastern	Eastern	351.28	428.39	1982.15	2761.82
	Jinja	130.24	136.50	905.53	1172.28
	Mbale	118.67	250.75	554.09	923.50
	Tororo	102.38	41.14	522.53	666.05
	Grand Total	351.28	428.39	1982.15	2761.82

Table 15 : Length per Functional Class

5.2.1 Jinja Station

Link ID	Road Class	Link Name	Length(km)	Surface Type
A001_Link05	A	Jinja - Kakira Junction	11.852	Bituminous
A001_Link06	A	Kakira junction - Iganga	26.87	Bituminous
A001_Link07	A	Iganga - Nakalama	4.907	Bituminous
A001_Link08	A	Nakalama - Bugiri - Namutere	28.42495699	Bituminous
A001N2_Link01	A	Jinja - Kakira Junction (Dual section)	11.853	Bituminous
A012_Link01	A	Nakalama - Namutumba - Mpologoma bridge	46.333	Bituminous
B101_Link04	B	Isimba - Mbulamuti - Kamuli	13.531	Unsealed
B307_Link01	B	Jinja (kubiri round about)-Buwenge	23.16	Bituminous
B307_Link02	B	Buwenge - Kamuli	32.633	Bituminous
B307_Link03	B	Kamuli - Nawantale	15.86	Unsealed
B307_Link04	B	Nawantale - Bukungu	51.319	Unsealed
C310_Link01	C	Kamuli - Namasagali	20.8	Unsealed
C780_Link01	C	Iganga-Kitayungwa	50.041	Unsealed
C780_Link02	C	Kitayungwa-Kamuli	7.185	Unsealed
C781_Link01	C	Iganga - Mayuge	20.406	Unsealed
C781_Link02	C	Mayuge - Kaluuba	9.061	Unsealed
C781_Link03	C	Kaluuba - Bugadde - Bwondha	29.851	Unsealed
C782_Link01	C	Musita-Mayuge - Nankoma	35.6	Bituminous
C784_Link01	C	Iganga-Kaliro	32.032	Bituminous
C784_Link02	C	Kaliro-Nawaikoke-Irundu	52.2	Unsealed
C785_Link01	C	Buwenge-Nakabugu	23.051	Unsealed
C785_Link02	C	Nakabugu-Kaliro	24.376	Unsealed
C786_Link01	C	Kaliro - Kamuli	45.284	Unsealed
C787_Link01	C	Nawangasi-Busesa	11.37	Unsealed
C787_Link02	C	Busesa-Nakivumbi	8.39	Unsealed
C788_Link01	C	Iganga - Buniantole	15.286	Unsealed
C789_Link01	C	Kamuli Railway access 1	5.883	Unsealed
C790_Link01	C	Nawantale-Nakabila	6.532	Unsealed
C791_Link01	C	Gadaffi army barracks off Jinja - Iganga	0.911	Unsealed

Link ID	Road Class	Link Name	Length(km)	Surface Type
C792_Link01	C	Kaitabawaala - Buyala - Namagera	18.484	Unsealed
C792_Link02	C	Namagera - Lubanyi	37.199	Unsealed
C793_Link01	C	Mbulamuti railway access	2.157	Unsealed
C794_Link01	C	Kamuli railway access 2	2.403	Unsealed
C795_Link01	C	Namaganda railway access	8.719	Unsealed
C796_Link01	C	Magamaga - Bugolooza - Namasiga - Iziru - Bugobya	7.996	Unsealed
C797_Link01	C	Bugembe - Kakira	7.052	Unsealed
C797_Link02	C	Kakira - Namasiga	12.018	Unsealed
C797_Link03	C	Namasiga - Bulongo	19.1456	Unsealed
C798_Link01	C	Kakira railway access	3.519	Unsealed
C799_Link01	C	Kimaka army barracks	4.137	Unsealed
C800_Link01	C	Bugiri - Nankoma	16.699	Unsealed
C802_Link01	C	Iganga railway access	0.913	Unsealed
C803_Link01	C	Idudi - Busembatya	17.93	Unsealed
C803_Link02	C	Busembatya - Namakoko	32.09	Unsealed
C804_Link01	C	Bugiri - Kisetaka - Nabukalu - Naigaga	19.174	Unsealed
C805_Link01	C	Namalembe-Nawampandhu-Bulange	10.517	Unsealed
C805_Link02	C	Bulange - Kisiro	17.0048964	Unsealed
C806_Link01	C	Namatumba - Nawampandu	10.793	Unsealed
C807_Link01	C	Busoko - Busaba	0.773	Unsealed
C808_Link01	C	Kaliro railway access	3	Unsealed
C809_Link01	C	Kaliro - Namwiwa	22.26	Unsealed
C811_Link01	C	Kamuli - Nabirumba	10.427	Unsealed
C811_Link02	C	Nabirumba - Iyingo	36.418	Unsealed
C812_Link01	C	Nabirumbi- Buyende - Nkondo - Kidera	46.019	Unsealed
C815_Link01	C	Bugobya-Mugulula-Namagera	19.356	Unsealed
C816_Link01	C	Muguluka-Namagera	8.052	Unsealed
C817_Link01	C	Nankoma - Kaluba	23.866	Unsealed
C818_Link01	C	Namalembe-Nambale-Nawandala	12.051	Unsealed
C819_Link01	C	Nambale-Nawandala	14.874	Unsealed
C820_Link01	C	Namutumba-Nawansangwa	9.733	Unsealed

Link ID	Road Class	Link Name	Length(km)	Surface Type
C821_Link01	C	Kasejere-Budumba	10.56625417	Unsealed
C823_Link01	C	Access to Buyanga S/C, off Busesa Nawangisa road	4	Unsealed
C824_Link01	C	Access to Isimba Dam, off Namagera Lubanyi road	5	Bituminous
C825_Link01	C	Old -access-to-Isimba-dam	3.96	Unsealed
C826_Link01	C	Old Mbulamuti ferry access	3.296730241	Unsealed
C892_Link01	C	Bulumba - Namwiwa	19.822	Unsealed
C892_Link02	C	Namwiwa - Saaka	5.85	Unsealed

Table 16: Jinja Station

5.2.2 Mbale station

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
A007_Link03	A	Nabumali - Mbale	10.228	Bituminous
A007_Link04	A	Mbale - Namunsi - Kumi	54.686	Bituminous
A007N1_Link01	A	Mbale(Dual Section)	0.75	Bituminous
A012_Link02	A	Mpologoma bridge - Tirinyi	4.748	Bituminous
A012_Link03	A	Tirinyi - Budaka - Kamonkoli	38.859	Bituminous
A012_Link04	A	Kamonkoli - Mbale	9.395	Bituminous
B300_Link01	B	Namunsi - Sironko	21.805	Bituminous
B300_Link02	B	Sironko - Muyembe	10.46	Bituminous
B300_Link03	B	Muyembe - Namalu	71.65513592	Unsealed
B304_Link01	B	Muyembe - Kaserem - Kapchorwa	24.68	Bituminous
B304_Link02	B	Kapchorwa-Suam	80.7	Bituminous
B305_Link01	B	Tirinyi - Pallisa	19.765	Bituminous
B305_Link02	B	Pallisa - Kanyago Bridge	21.681	Bituminous
C810_Link01	C	Pallisa - Kasodo - Saaka	10.418	Unsealed
C848_Link01	C	Magale - Bumbo - Lwakhaka	13.149	Unsealed
C860_Link01	C	Kamonkoli-Pallisa	44.442	Bituminous
C861_Link01	C	Nalugugu-Mutufu-Budadiri	16.245	Unsealed
C862_Link01	C	Namagumba - Budadiri	18.427	Unsealed
C863_Link01	C	Mbale - Nkokonjeru	21.067	Unsealed
C864_Link01	C	Bugema-Busano	11.389	Unsealed
C867_Link01	C	Bumbobi-Bubulo	15.402	Bituminous
C867_Link02	C	Bubulo-Bududa Circle Road	28.482	Unsealed
C870_Link01	C	Bubulo-Busumbu	15.69	Bituminous
C871_Link01	C	Simu corner - Kaserem	9.801	Unsealed
C872_Link01	C	Budaka - Kaderuna	12.488	Unsealed
C872_Link02	C	Kaderuna - Butebo	9.212	Unsealed
C873_Link01	C	Nabiganda - Kaiti	3.436	Unsealed
C873_Link02	C	Kaiti - Naboa	5.864	Unsealed
C874_Link01	C	Mbale railway crossing Access	0.106	Unsealed

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
C875_Link01	C	Bugema army barracks Access	0.176	Unsealed
C876_Link01	C	Nabiganda -Nambale - Kamoto - Malukhu	16.266	Unsealed
C877_Link01	C	Kamonkoli - Kabwangasi - Nakaloke	7.792	Unsealed
C878_Link01	C	Nakaloke-Kabwangasi-Butebo	28.988	Unsealed
C878_Link02	C	Butebo-Kadoto	19.56	Unsealed
C880_Link01	C	Mbale-Bufumbo	16.458	Unsealed
C881_Link01	C	Bugusege - Buteza	8.765	Unsealed
C882_Link01	C	Korir - Sironko	13.552	Unsealed
C883_Link01	C	Nalugugu - Elgon	20.083	Unsealed
C884_Link01	C	Buyaga - Buluganya	12.431	Unsealed
C885_Link01	C	Buginyanya Agriculture Research Station	5.121	Unsealed
C887_Link01	C	Bulugeni - Siyiyi - Bumwambu	7.868	Unsealed
C887_Link02	C	Bumwambu - Bulaago - Gimadu	6.641	Unsealed
C888_Link01	C	Kapenguria - Kwot	10.629	Bituminous
C889_Link01	C	Chepsikunya -Girik	26.246	Unsealed
C889_Link02	C	Girik - Bukwa	29.559	Unsealed
C891_Link01	C	Buseta - Bugiri	7.55	Unsealed
C893_Link01	C	Kapnandi-Suam	15.818	Unsealed
C926_Link01	C	Kachumbala - Kidongole	15.431	Unsealed
C927_Link01	C	Kachumbala - Korir	12.293	Unsealed
C927_Link02	C	Korir - Malera - Kumi	37.241	Unsealed

Table 17: Mbale Station

5.2.3 Tororo station

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
A001_Link09	A	Namutere - Busitema Junction	24.98641832	Bituminous
A001_Link10	A	Busitema Junction - Tororo Junction	28.29	Bituminous
A001_Link11	A	Tororo junction - Malaba (Uganda/Kenya border)	11.649	Bituminous
A007_Link01	A	Malaba junction - Tororo	3.751	Bituminous
A007_Link02	A	Tororo - Magodes - Nabumali	33.7	Bituminous
B306_Link01	B	Tororo (Malaba junction) - Busia	24.235	Unsealed
B308_Link01	B	Namutere - Busia	16.905	Bituminous
C782_Link02	C	Nankoma-Namayingo-Lumino	41.8	Bituminous
C783_Link01	C	Namayingo - Lugala	16.928	Unsealed
C801_Link01	C	Lwangosha - Lufudu	12.645	Unsealed
C813_Link01	C	Namayingo - Bumeru (Namayingo - Lugala)	30.368	Unsealed
C830_Link01	C	Busia - Majanji	26.982	Bituminous
C831_Link01	C	Tororo - Morukatipe prison	6.5233	Unsealed
C832_Link01	C	Tororo-Nagongera	33.725	Unsealed
C832_Link02	C	Nagongera-Busolwe	10.101	Unsealed
C833_Link01	C	Nabumali junction-Busolwe	34.588	Unsealed
C833_Link02	C	Busolwe-Budumba	16.046	Unsealed
C835_Link01	C	Magodes-Railway Station	2.278	Unsealed
C836_Link01	C	Nyambogo - Iyolwa - Mulanda	18.9	Unsealed
C836_Link02	C	Mulanda - Nagongera	8.675	Unsealed
C837_Link01	C	Nagongera - Merikit - Kidoko	18.218	Unsealed
C837_Link02	C	Kidoko - Busiu - Isikhoye	15.862	Unsealed
C838_Link01	C	Butiru - Molo - Kidoko	8.213	Unsealed
C838_Link02	C	Kidoko - Kachonga	12.273	Unsealed
C839_Link01	C	Doho - Namulo - Amuro	13.594	Unsealed
C840_Link01	C	Malaba - Mella - Apokor	10.655	Unsealed
C840_Link02	C	Apokor - Kwapa - Tuba	15.083	Unsealed
C841_Link01	C	Nabaloba - Bukobe	10.9	Unsealed

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
C842_Link01	C	Tororo Prisons Access	1.036	Unsealed
C844_Link01	C	Rubongi - Mulanda	17.079	Unsealed
C844_Link02	C	Mulanda - Nabuyoga - Bubada	14.127	Unsealed
C844_Link03	C	Bubada - Busaba - Budhumba - Namutumba	5.193	Unsealed
C845_Link01	C	Bubada - Budhumba Station	15.344	Unsealed
C846_Link01	C	Budhumba - Busaba	11.983	Unsealed
C847_Link01	C	Nagongera - Paya - Leresi	18.578	Unsealed
C849_Link01	C	Leresi-Bunghaji-Budaka	13.5	Unsealed
C850_Link01	C	Busoko - Busaba - Nawanjofu - Hisiro	10.244	Unsealed
C865_Link01	C	Magodes-Busumbu	12.726	Unsealed
C866_Link01	C	Munamba - Lwakhakha	4.518	Bituminous
C870_Link02	C	Busumbu - Munamba	9.898	Bituminous
C870_Link03	C	Munamba-Magale - Nangya	23.947	Unsealed

Table 18: Tororo Station

5.3 Northern Region

The Northern Region manages a total of 4,645 km of roads, of which 882 km are bituminous and 3,763 km are unsealed. Unsealed roads, therefore, account for approximately 81% of the regional network, indicating a predominantly gravel and earth-surfaced system with high routine and periodic maintenance demands.

Within the Lango Sub-region, the Lira Maintenance Station manages 1,036 km of roads, with unsealed sections (893 km) significantly exceeding bituminous roads (143 km). In the Acholi Sub-region, Gulu manages a relatively higher proportion of paved roads (394 km) compared to other stations, while Kitgum has one of the largest unsealed networks (912 km), resulting in a total of 1,043 km.

The West Nile Sub-region is characterised by a largely unsealed network. Moyo Maintenance Station manages 714 km, all of which are unsealed, while Arua manages 907 km, with only 214 km paved. This reflects the rural and cross-border nature of the network, where upgrading priorities must be balanced against high maintenance needs.

Region	Subregion	Maintenance station	Bituminous	Unsealed	Total
Northern	Lango	Lira	143	893	1036
	Acholi	Gulu	394	551	945
		Kitgum	131	912	1043
	West Nile	Moyo	-	714	714
		Arua	214	693	907

Table 19: Northern Region Maintenance Stations

Region		Length per Functional Class (Km)			
	Maintenance station	A	B	C	Total
Northern	Arua	204.85	77.12	625.28	907.25
	Gulu	285.37	61.81	598.01	945.19
	Kitgum		230.51	812.23	1042.74
	Lira	125.68	181.34	728.95	1035.97
	Moyo		157.53	556.93	714.47
	Grand Total	615.90	708.32	3321.40	4645.62

Table 20 : Length per Functional Class

5.3.1 Arua Station

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
A008_Link03	A	Packwach - Nebbi	53.5	Bituminous
A008_Link04	A	Nebbi - Eruba	63.8	Bituminous
A008_Link05	A	Eruba - Arua - Manibe	18.8	Bituminous
A008_Link06	A	Manibe - Maracha - Koboko	49.9	Bituminous
A008_Link07	A	Koboko - Oraba(Uganda/Sudan border)	18.8	Bituminous
B250_Link03	B	Yumbe - Manibe	77.1	Unsealed
C687_Link01	C	Packwach Railway Access	0.2	Unsealed
C740_Link01	C	Koboko - Yumbe	36.2	Unsealed
C741_Link01	C	Wandi - Rhino camp	51.5	Unsealed
C742_Link01	C	Rhino camp-Ogoko-Inde	22.6	Unsealed
C743_Link01	C	Pakwach-Inde	59.8	Unsealed
C743_Link02	C	Inde-Ocoko	33.0	Unsealed
C744_Link01	C	Eruba - Vurra	9.4	Bituminous
C745_Link01	C	Nebbi - Goli	15.1	Unsealed
C746_Link01	C	Packwach - Panyimur	34.0	Unsealed
C747_Link01	C	Panyimur - Paidha Via Erusi-Goli	52.0	Unsealed
C748_Link01	C	Okullo - Inde	28.2	Unsealed
C749_Link01	C	Eruba - Logiri	23.3	Unsealed
C750_Link01	C	Arua - Muni PTTC - Eruba	6.0	Unsealed
C751_Link01	C	Arua - Girigiri - Ovisoni	14.6	Unsealed
C752_Link01	C	Arua - Lia	15.2	Unsealed
C753_Link01	C	Ragem Prisons Access	3.7	Unsealed
C755_Link01	C	Owaffa - Kubala	14.6	Unsealed
C759_Link01	C	Vurra Customs - Odramacaku	34.2	Unsealed
C760_Link01	C	Logiri - Bondo	16.8	Unsealed
C762_Link01	C	Arua - Biliafe	23.0	Unsealed
C762_Link02	C	Biliafe - Otrevu	13.8	Unsealed
C763_Link01	C	Paidha-Zombo	22.0	Unsealed
C763_Link02	C	Zombo-Vurra	61.2	Unsealed
C764_Link01	C	Katrini - Nyadri	22.1	Unsealed
C765_Link01	C	Packwach-Railway Access	0.3	Unsealed

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
C767_Link01	C	Omugo-Kubala	6.7	Unsealed
C769_Link01	C	Rhino Camp Ferry Access	5.9	Unsealed

Table 21: Arua Station

5.3.2 Gulu Station

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
A006_Link09	A	Karuma - Kamdini	12.157	Bituminous
A006_Link10	A	Kamdini - Minakulu	24.24	Bituminous
A006_Link11	A	Minakulu - Bobi - Gulu	37.495	Bituminous
A006_Link12	A	Gulu - Atiak	68.164	Bituminous
A006_Link13	A	Atiak - Nimule(Uganda/Sudan border)	37.275	Bituminous
A008_Link01	A	Karuma - Olwiyo	51.633	Bituminous
A008_Link02	A	Olwiyo - Packwach	54.406	Bituminous
B251_Link01	B	Gulu - Olwiyo	61.808	Bituminous
C654_Link01	C	Kamdini-Zambia	28.852	Unsealed
C654_Link02	C	Zambia-Minakulu	17.756	Unsealed
C655_Link01	C	Bobi-Aboke-Ayer	54.222	Unsealed
C665_Link01	C	Loro - Anyeke	11.857	Unsealed
C665_Link02	C	Anyeke-Minakulu	20.679	Unsealed
C666_Link01	C	Aber-Anyeke-Ngai	36.755	Unsealed
C666_Link02	C	Ngai-Abok-Otwal-Aromo	50.098	Unsealed
C667_Link02	C	Arom-Awere	11.04	Unsealed
C680_Link01	C	Gulu-Opit	64.108	Unsealed
C680_Link02	C	Opit-Rwackoko	26.995	Unsealed
C681_Link02	C	Aswa - Gulu	38.622	Bituminous
C682_Link01	C	Gulu - Logere - Adee	57.529	Unsealed
C683_Link01	C	Layibi - Custom corner	3.911	Bituminous
C684_Link01	C	Gulu Airport road	4.101	Bituminous
C685_Link01	C	Katikati - Tenumu - Nwoya	34.538	Unsealed
C686_Link01	C	Lamogi - Amuru Junction	31.103	Unsealed
C686_Link02	C	Amuru Junction - Awee	43.976	Unsealed
C686_Link03	C	Awee - Omee Rhino Camp	23.043	Unsealed
C690_Link01	C	Pabbo - Ajulu - Uyama	20.022	Unsealed
C691_Link01	C	Gulu Army Barracks Access	3.961	Unsealed
C692_Link01	C	Gulu Railway Access	1.633	Unsealed
C694_Link01	C	Teokur - Aboo	13.21	Unsealed

Table 22: Gulu Station

5.3.3 Kitgum Station

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
B252_Link02	B	Puranga Bridge - Corner Kilak - Pejule - Acholibur	61.6	Unsealed
B252_Link03	B	Acholibur - Kitgum	19.755	Bituminous
B252_Link04	B	Kitgum - Madi Opei	45.456	Bituminous
B252_Link05	B	Madi Opei - Uganda/Sudan border	20.512	Bituminous
B302_Link02	B	Abim - Kilak	83.189	Unsealed
C674_Link01	C	Patongo-Okee Bridge	22.085	Unsealed
C675_Link01	C	Pajule - Pader	18.1	Unsealed
C675_Link02	C	Pader - Kwonkwic (Palwo)	9.2	Unsealed
C676_Link01	C	Pader - Kalongo	37.1	Unsealed
C677_Link01	C	Patongo - Kalongo	31.986	Unsealed
C677_Link02	C	Kalongo - Kitgum Matidi	45.614	Unsealed
C678_Link01	C	Naamokora - Lokapel	37.201	Unsealed
C678_Link02	C	Lokapel - Adilang	37.26	Unsealed
C681_Link01	C	Acholibur - Aswa	45.119	Bituminous
C700_Link01	C	Atiak-Palabek	65	Unsealed
C700_Link02	C	Palabek-Kitgum	43	Unsealed
C701_Link01	C	Kitgum-Lukung-Ngomoromo	67.331	Unsealed
C702_Link01	C	Madi Opei-Agoro Hills	49.063	Unsealed
C703_Link01	C	Kitgum - Orom	79.113	Unsealed
C704_Link01	C	Palabek - Padibe	24.86	Unsealed
C705_Link01	C	Padibe - Paloga	16.832	Unsealed
C705_Link02	C	Paloga - Madiopei	18.978	Unsealed
C706_Link01	C	Paloga-Potika	17.307	Unsealed
C706_Link02	C	Potika - Lututur	12.038	Unsealed
C707_Link01	C	Acholi Pii Army Baracks Access	1.342	Unsealed
C708_Link01	C	Ngomoromo - Nyimur - Bibia	45.085	Unsealed
C709_Link01	C	Potika - Aweno Olwiyo - Ngomoromo	37.125	Unsealed
C710_Link01	C	Orom - Locomo - Karenga	41.4	Unsealed
C711_Link01	C	Pajimo-Army Barracks	1.264	Unsealed
C996_Link01	C	Kalongo - Paimol	8.828	Unsealed

Table 23: Kitgum Station

5.3.4 Lira Station

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
A007_Link07	A	Dokolo - Agwata	23.493	Bituminous
A007_Link08	A	Agwata - Lira	31.149	Bituminous
A007_Link09	A	Lira - Ayer	27.084	Bituminous
A007_Link10	A	Ayer - Kamdini	43.956	Bituminous
B252_Link01	B	Lira - Puranga Bridge	42.9	Unsealed
B253_Link02	B	Masindi Port-Akokoro-Apac-Aduku	103.421	Unsealed
B253_Link03	B	Aduku - Lira	35.018	Unsealed
C649_Link01	C	Lira Army Barracks Access	1.4	Bituminous
C649_Link02	C	Alir Police Access	12	Unsealed
C650_Link01	C	Lira - Akia	8.2	Bituminous
	C	Akia - Olilim	75.6	Unsealed
C651_Link01	C	Agwata - Aduku	30.306	Unsealed
C652_Link01	C	Agwata - Kachung	9.141	Unsealed
C653_Link01	C	Dokolo-Ochero	45.661	Unsealed
C653_Link02	C	Ochero-Namasale	42.292	Unsealed
C656_Link01	C	Namasale - Alemere	40.907	Unsealed
C656_Link02	C	Alemere - Muntu	11.26	Unsealed
C657_Link01	C	Odyek - Muntu	9.255	Unsealed
C658_Link01	C	Aduku-Nambieso	18.065	Unsealed
C659_Link01	C	Ami-Kidilani	16.38	Unsealed
C660_Link01	C	Cegere-Kidilani	14.83	Unsealed
C661_Link01	C	Apac-Cegere	12.278	Unsealed
C661_Link02	C	Cegere-Teboke	14.621	Unsealed
C662_Link01	C	Aduku-Teboke-Loro	34.272	Unsealed
C663_Link01	C	Loro Prisons Access	1.935	Unsealed
C664_Link01	C	Atopi Prisons Access	0.648	Unsealed
C667_Link01	C	Agweng-Arom	18.392	Unsealed
C668_Link01	C	Agwata Bypass	1.6	Bituminous
C669_Link01	C	Lira Railway Access	2.277	Bituminous
C670_Link01	C	Lira - Boroboro - Abako - Okude	59.43	Unsealed

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
C671_Link01	C	Aloi - Aboko - Bata - Dokolo	42.37	Unsealed
C672_Link01	C	Ogur - Apala	12.72	Unsealed
C672_Link02	C	Apala-Aloi	20.683	Unsealed
C673_Link01	C	Ngetta-Apala	19.803	Unsealed
C673_Link02	C	Apala-Adwari	27.187	Unsealed
C674_Link02	C	Okee Bridge-Adwari	15.95	Unsealed
C679_Link01	C	Lira bypas	3.8	Bituminous
C693_Link01	C	Atapara-Aber-Atura-Kidilani	23.087	Unsealed
C941_Link02	C	Obalang - Alito	17.094	Unsealed
C994_Link01	C	Okwang-Okwang Subcounty spur	3.21	Unsealed
C997_Link01	C	Aloi-Aleptong	10.415	Unsealed
C998_Link01	C	Adwari-Okwang	24.864	Unsealed
C998_Link02	C	Okwang-Okee River - Omwonylee	12.46	Unsealed
C999_Link01	C	Corner Chwagera-Ekwera	14.56	Unsealed

Table 24: Lira Station

5.3.5 Moyo Station

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
B250_Link01	B	Atiak - Moyo	91.58	Unsealed
B250_Link02	B	Moyo - Yumbe	65.954	Unsealed
C688_Link01	C	Amuru Junction - Mungula	25.652	Unsealed
C688_Link02	C	Mungula - Adjumani	59.454	Unsealed
C689_Link01	C	Pakele - Pabbo	59.895	Unsealed
C720_Link01	C	Moyo - Sudan border	10.662	Unsealed
C721_Link01	C	Obongi - Kulikulinga	45.546	Unsealed
C722_Link01	C	Moyo - Obongi	53.037	Unsealed
C723_Link01	C	Access to Adjumani Prison	3.441	Unsealed
C725_Link01	C	Dzaipi - Tete	12.2	Unsealed
C725_Link02	C	Tete - Bibia (Nimule border)	6.6	Unsealed
C726_Link01	C	Adjumani - Sinyanya Ferry landing	34.352	Unsealed
C727_Link01	C	Tete - Nimule Border	14.329	Unsealed
C728_Link01	C	Aliodranusi-Gobolo-Matu-Kerwa-kei	76	Unsealed
C756_Link01	C	Lomunga - Bidibidi - Kochi	44.148	Unsealed
C757_Link01	C	Keri - Lima - Midigo - Kerila	38.536	Unsealed
C758_Link01	C	Keriri - Midigo	14.013	Unsealed
C758_Link02	C	Midigo - Kerwa	21.733	Unsealed
C761_Link01	C	Lodonga - Iti - Otumbari	17.651	Unsealed
C766_Link01	C	Elefe - Odokibo (Iti)	9.455	Unsealed
C768_Link01	C	Yuku - Lobe spur	10.228	Unsealed

Table 25: Moyo Station

5.4 Western Region

The Western Region manages a total of 2,828 km of roads, comprising 1,257 km of bituminous roads and 1,571 km of unsealed roads. Unsealed roads account for approximately 56% of the network, indicating a relatively more balanced surface composition compared to other regions.

In the Rwenzori Sub-region, the Fort Portal Maintenance Station manages 998 km of roads, with unsealed roads (633 km) exceeding bituminous sections (365 km), reflecting a mixed urban–rural network. The Bunyoro Sub-region manages the largest share of the regional network. Hoima Maintenance Station oversees 1,144 km, with a significant proportion of bituminous roads (472 km), consistent with its strategic role in supporting oil and gas activities. Masindi Maintenance Station manages 686 km, with a higher proportion of paved roads (420 km) than unsealed roads (266 km), indicating comparatively better surface conditions.

Region	Subregion	Maintenance station	Bituminous	Unsealed	Total
Western	Rwenzori	Fort Portal	365	633	998
	Bunyoro	Hoima	472	672	1144
		Masindi	420	266	686

Table 26: Western Region Maintenance Stations

Region	Maintenance station	Length per Functional Class (Km)			
		A	B	C	Total
Western	Fort Portal	158.75	102.68	736.49	997.93
	Hoima	96.50	143.08	904.45	1144.03
	Masindi	86.41	121.13	478.58	686.13
	Grand Total	341.66	366.89	2119.53	2828.08

Table 27 : Length per Functional Class

5.4.1 Fort Portal Station

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
A005_Link08	A	Lubaale - Kyegegwa	12	Bituminous
A005_Link09	A	Kyegegwa - Kakabala - Kyenjojo	52.261	Bituminous
A005_Link10	A	Kyenjojo - Rugombe - Fortportal	49.811	Bituminous
A005_Link11	A	FortPortal - Rwimi(bridge)	44.681	Bituminous
B150_Link04	B	Kamwenge - Fortportal	64.78	Bituminous
B202_Link01	B	Kyenjojo - Katoke - R. Muzizi	37.9	Bituminous
C378_Link01	C	Bijutsyo - Bihanga	27.424	Unsealed
C539_Link01	C	Itojo - Sempaya	15	Unsealed
C540_Link01	C	Fortportal-Kichwamba-Karugutu	27.414	Bituminous
C540_Link02	C	Karugutu-Bundibugyo - Lamia	76.2	Bituminous
C541_Link01	C	Karugutu - Ntoroko	50.281	Unsealed
C542_Link01	C	Fortportal - Kijura - Kabende Bridge-Sogahe-Kyarusozi	59.78	Unsealed
C543_Link01	C	Bubandi - Bundibugyo Army Barracks - Butama Health Centre	4.75	Unsealed
C544_Link01	C	Bubandi - Kahuka -Malindi	11	Unsealed
C545_Link01	C	Nyahuka - Busalu - Butoogo	12.565	Unsealed
C546_Link01	C	Kigarama-Gweri-Harubaho	6.415	Unsealed
C547_Link01	C	Rwimi-Dura-Kamwenge	58.624	Unsealed
C548_Link01	C	Rugombe-Kyarusozi-Katooke	15	Unsealed
	C		21.8	Unsealed
C549_Link01	C	Kakabara-Bujuzo-Katooke	45.144	Unsealed
C551_Link01	C	Kyegegwa-Hapuyo-kibale	36.551	Unsealed
C554_Link01	C	Ntandi - Kicyo - Bundibugyo	19.926	Unsealed
C555_Link01	C	Nyakigumba-Katebwa	6.477	Unsealed
C556_Link01	C	Bukuku - Rubona	16.879	Unsealed
C557_Link01	C	Kasisi - Rutete -Kabata-Rwenkenzi-Kyanga	27.85	Unsealed
C558_Link01	C	Kakara - Rwebisengo	26.152	Unsealed
C560_Link01	C	Butiti PTTC Access	1.855	Unsealed
C561_Link01	C	Access to Canon Apollo PTTC	5.047	Unsealed
C562_Link01	C	Access to Muhooti Army Barracks	6	Unsealed

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
C564_Link01	C	Kitumba-Harubako	2.948	Unsealed
C564_Link02	C	Harubako-Kasusu	2.876	Unsealed
C568_Link01	C	Kihura - Bwizi	27.714	Unsealed
C568_Link02	C	Bwizi - Bisozi	19.735	Unsealed
C568_Link03	C	Bisozi - Kahunge	19.567	Unsealed
C569_Link01	C	Mpara - Kazinga - Bwizi	37.837	Unsealed
C571_Link01	C	Kamwenge - Kabambiro - Bigusyo - Bihanga	22.682	Unsealed
C573_Link01	C	Kamwenge Railway Access	2	Unsealed
C575_Link01	C	Kibuku - Nyabushozi	15	Unsealed
C579_Link01	C	Harugale - Bupompoli	8	Unsealed

Table 28: Fort Portal Station

5.4.2 Masindi Station

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
A006_Link07	A	Kafu - Kigumba	29.676	Bituminous
A006_Link08	A	Kigumba - Karuma	56.735	Bituminous
B200_Link01	B	Kafu - Masindi	43.263	Bituminous
B201_Link01	B	Kigumba - Masindi	39.058	Bituminous
B204_Link01	B	Masindi - Kisalizi	31.469	Bituminous
B253_Link01	B	Rwekunya - Masindi Port	7.343	Unsealed
C590_Link02	C	Biso-Bukumi	17.596	Bituminous
C603_Link01	C	Waki 2 - Katanga - Karongo	18.116	Unsealed
C621_Link01	C	Rwekunya - Masindi	35.426	Unsealed
C622_Link01	C	Masindi - Biiso	49.704	Unsealed
C623_Link01	C	Bukumi-Bulisa	41.349	Bituminous
C623_Link02	C	Bulisa-Wanseko	8.52	Bituminous
C624_Link01	C	Bukumi - Butiaba	8.191	Bituminous
C625_Link01	C	Kisanja-Park junction	71.121	Bituminous
C625_Link02	C	Park junction - Buliisa	21.433	Bituminous
C626_Link01	C	Park junction - Paraa	7.701	Bituminous
C626_Link02	C	Paraa - Packwach	21.83161513	Bituminous
C630_Link01	C	Ikooba - Ntoma	12.973	Unsealed
C630_Link02	C	Ntoma - Bwijanga	34.777	Unsealed
C631_Link01	C	Bwijanga - Isimba Prisons	3.187	Unsealed
C632_Link01	C	Isimba-Ntoma	14	Unsealed
C633_Link01	C	Butiaba Army Barracks Access	1.197	Bituminous
C634_Link01	C	Nguedo - Bugana - Waiga	22.103	Unsealed
C635_Link01	C	Katulikile - Mutunda - Atura / Nanda	23.301	Unsealed
C636_Link01	C	Kirasa-Kamurasi-Kiwanana (Kisengya)	2.552	Unsealed
C637_Link01	C	(Kisengya)	1.543	Unsealed
C638_Link01	C	Ihungu - Kijunjubwa	3.449	Unsealed
C638_Link02	C	Kijunjubwa - Bulyamusenyu (Kafu)	37.29	Unsealed
C640_Link01	C	Bugungu - Wanseko	21.22237984	Bituminous

Table 29: Masindi Station

5.4.3 Hoima station

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
A009_Link04	A	Lwamata - Hoima	96.5	Bituminous
B202_Link02	B	R. Muzizi - Muhooro - Kagadi	15	Bituminous
B202_Link03	B	Kagadi - Mabale - Kabwoya	49.704	Bituminous
B202_Link04	B	Kabwoya - Kiziranfumbi - Buhimba	31.503	Bituminous
B202_Link05	B	Buhimba - Hoima	10.573	Bituminous
B203_Link03	B	Kabaale Swamp - Buhimba	16	Bituminous
B204_Link02	B	Kisalizi - Hoima	20.3	Bituminous
C271_Link04	C	Kitumbi Bridge - Bukwiri	39.386	Unsealed
	C		15.743	Unsealed
C550_Link02	C	Kibale-Kagadi	42.543	Bituminous
C553_Link01	C	Kibaale-Kyebando - Pacwa	46.268	Unsealed
C563_Link01	C	Muhooro-Ndaiga-L. Albert	30.252	Unsealed
C565_Link01	C	Kyenzige-Rugashali-Mabaale	30.085	Unsealed
C566_Link01	C	Isunga-Bugwara	27.591	Unsealed
C566_Link02	C	Bugwara-Kikwaya	8.653	Unsealed
C590_Link01	C	Hoima (Parajwoki) -Biso	35.703	Bituminous
C591_Link01	C	Kabwoya - Kituti	41.302	Unsealed
C592_Link01	C	Parajwoki-Buseruka	21.728	Bituminous
C592_Link02	C	Buseruka-Kabaale	21.341	Bituminous
C593_Link01	C	Bugambe-Buseruka	19.172	Unsealed
C594_Link01	C	Bugambe-Kidoma	27.202	Unsealed
C595_Link01	C	Mairirwe-Wambabya	7.361	Unsealed
C596_Link01	C	Kiziranfumbi - Kabaale	25.08130775	Bituminous
C596_Link02	C	Kabaale -Kaiso	33.7	Bituminous
C597_Link01	C	Kyehooro Link 1	7.5	Bituminous
C597_Link02	C	Kyehooro Link 2		Unsealed
C598_Link01	C	Hohwa - Nyairongo - Kyarushesha	24.95844521	Bituminous
C599_Link01	C	Kaiso-Tonya	23.123	Unsealed
C600_Link01	C	Katasiiha-Waki	32.735	Unsealed
C601_Link01	C	Buseruka-Kigorobya	17.582	Unsealed
C602_Link01	C	Bulera PTC Access	0.583	Unsealed

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
C604_Link01	C	Buseruka-Tonya	9.325	Unsealed
C605_Link01	C	Kiryamboga Link	2.785	Unsealed
C606_Link01	C	Rwera-Kaseeta	15.448	Unsealed
C607_Link01	C	Bukwiri-Byerima-Kikuya	18.154	Unsealed
C608_Link01	C	Kyenda-Banda-River Mayanja	37	Unsealed
C609_Link01	C	Sebagoro Link	8.063	Unsealed
C610_Link01	C	Kyehooro Link 3	6.7	Unsealed
C611_Link01	C	Kituti-Buhuka	10.1	Bituminous
C613_Link01	C	Kaiso Airstrip link 1	9.309327499	Bituminous
C613_Link02	C	Kaiso Airstrip link 2	6.690445732	Unsealed
C620_Link01	C	Bukwiri - Kyankwanzi	28.829	Unsealed
C627_Link01	C	Masoode-Nkooko	35.684	Unsealed
C627_Link02	C	Nkooko-Nalweyo	34.868	Unsealed
C629_Link01	C	Kyenda - Mpongo Swamp - Kisita	33.373	Unsealed
C639_Link01	C	Bukommero-Dwaniro-Kyankwanzi	68.528	Unsealed

Table 30: Hoima Station

5.5 Southern Region

The combined network under the Southern Region totals 3,172 km, comprising 991 km of bituminous roads and 2,181 km of unsealed roads. Unsealed roads account for approximately 69% of the network, reflecting the predominantly rural and mountainous terrain of the area, which presents higher maintenance and accessibility challenges.

Within the Ankole Sub-region, Ibanda Maintenance Station manages 883 km of roads, of which 679 km are unsealed, while Mbarara manages 1,053 km, with a comparatively higher proportion of bituminous roads (370 km). This reflects Mbarara's role as a regional urban and commercial hub, where paved infrastructure is more developed.

In the Kigezi Sub-region, Kabale Maintenance Station manages the largest network (1,210 km), dominated by unsealed roads (800 km), consistent with the region's rugged topography and dispersed settlements. Kasese Maintenance Station manages a relatively small network (26 km), with limited paved and unsealed sections, indicating a localised maintenance responsibility within this dataset.

Region	Subregion	Maintenance station	Bituminous	Unsealed	Total
Southern	Ankole	Ibanda	204	679	883
		Mbarara	370	683	1053
	Kigezi	Kabale	410	800	1210
		Kasese	7	19	26

Table 31: Southern Region Maintenance Station

Region	Maintenance station	Length per Functional Class (Km)			
		A	B	C	Total
Southern	Ibanda		90.27	793.11	883.38
	Kabale	96.06	139.01	974.87	1209.93
	Kasese	89.63	33.10	303.85	426.57
	Mbarara	129.04	117.43	806.21	1052.68
	Grand Total	314.72	379.80	2878.04	3572.56

Table 32 : Length per Functional Class

5.5.1 Ibanda Station

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
B150_Link02	B	Bwizibwera - Ibanda	45.806	Bituminous
B150_Link03	B	Ibanda - Muziza - Kamwenge	44.461	Bituminous
C228_Link02	C	Nabitanga - Rushere	29.727	Unsealed
C355_Link01	C	Nyakahita-Rushere	33.232	Bituminous
C355_Link02	C	Rushere-Kazo	34.758	Bituminous
C356_Link01	C	Ibanda-Kanoni-Kazo	32.433	Bituminous
C356_Link02	C	Kazo-Buremba	29.938	Unsealed
C357_Link01	C	Muzizi-Buremba	53.483	Unsealed
C357_Link02	C	Buremba-Remiyaga	32.53	Unsealed
C358_Link01	C	Rwemikoma-Kijuma	4.212	Unsealed
C358_Link02	C	Kijuma-Rwakitura	31.257	Unsealed
C367_Link01	C	Biharwe - Rushozi - Ruhengere - Kikatsi	49.51	Unsealed
C370_Link01	C	Ruhumba - Byanamira	6.301	Unsealed
C370_Link02	C	Byanamira - Kashwa	25.047	Unsealed
C371_Link01	C	Kashongi - Kantaganya	24.475	Unsealed
C372_Link01	C	Kyankanda-Bitsya	17.099	Unsealed
C372_Link02	C	Bitsya-Ruhoko	25.89	Unsealed
C373_Link01	C	Ruhoko - Kabujogera	14.531	Unsealed
C373_Link02	C	Kabujogera - Mahyoro Junction	21.03	Unsealed
C374_Link01	C	Mahyoro Junction- Mahyoro landing site	4.605	Bituminous
C375_Link01	C	Ishongororo - Bisheshe	24.126	Unsealed
C376_Link01	C	Kanyarigiri-Nyamarebe-Ishongororo	23.427	Unsealed
C377_Link01	C	Kiburara T/c - Kiburara Prison Fram	1.487	Unsealed
C380_Link01	C	Engarusya - Buremba	24.312	Unsealed
C383_Link01	C	Rushere-Rwakitura	8.605	Bituminous
C385_Link01	C	Bihanga Army Barracks Access	1.71	Unsealed
C391_Link01	C	Access to Tumu hospital	10.195	Unsealed
C415_Link01	C	Kabwohe - Nyakambu - Bihanga	21.129	Unsealed
C415_Link02	C	Bihanga - Bwizibwera	14.057	Unsealed
C416_Link01	C	Bihanga - Nsiika	13.222	Unsealed
C416_Link02	C	Nsiika - Bihanga -Katerera(Ishaka T/C)	44.31	Unsealed

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
C449_Link01	C	Nyakabirizi-Burere-Nsiika	43.812	Unsealed
C450_Link03	C	Buhindagye - Mahyoro	8.269	Unsealed
C552_Link01	C	Nyakaliiro-Kabagole	10.156	Unsealed
C552_Link02	C	Kabagole-Kyegegwa	40.784	Unsealed
C572_Link01	C	Rwenjaza - Kabujogera	33.454	Unsealed

Table 33: Ibanda Station

5.5.2 Kabale Station

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
A002_Link09	A	Ntungamo - Rubaale	14.951	Bituminous
A002_Link10	A	Rubaale - Muhanga - Kabale	59.407	Bituminous
A002_Link11	A	Kabale - Katuna	21.697	Bituminous
B152_Link01	B	Ntungamo - Kagamba	15.229	Bituminous
B152_Link02	B	Kagamba - Ishaka	35.906	Bituminous
B153_Link01	B	Kabale - Ikumba - Muko	41.999	Bituminous
B153_Link02	B	Muko - Nyakabande - Kisoro	33.845	Bituminous
B153_Link03	B	Kisoro - Bunagana	12.026	Bituminous
C410_Link01	C	Kagamba-Kebisoni	20.602	Bituminous
C410_Link02	C	Kebisoni-Rukungiri	13.941	Bituminous
C411_Link01	C	Muhanga-Kisiizi-Kebisoni	59.882	Unsealed
C412_Link01	C	Kisoro - Kyanika	9.89	Bituminous
C413_Link01	C	Kalengyere bypass-Katojo-Rubuguri	28.218	Unsealed
C417_Link01	C	Ntungamo-Kakukuru	13.539	Bituminous
C417_Link02	C	Kakukuru-Kafunzo	16.132	Bituminous
C417_Link03	C	Kafunzo-Kakitumba	6.04	Bituminous
C418_Link01	C	Kakukuru - Rubale	11.343	Unsealed
C420_Link01	C	Kabale access roads	2.897	Bituminous
C422_Link01	C	Rwentobo - Ngoma - Kizinga	18.188	Unsealed
C423_Link01	C	Rutobo - Kamwezi	17.685	Unsealed
C424_Link01	C	Old Kabale Road (Kigata - Kabunyonyi - N	20.068	Unsealed
C425_Link01	C	Katuna - Rubaya - Muko	66.59	Unsealed
C426_Link01	C	Kabale - Lake Bunyonyi	7.874	Unsealed
C427_Link01	C	Access to Kacwekano Agriculture Research	0.404	Unsealed
C428_Link01	C	Nyamirama - Ishasha	14.89018659	Bituminous
C429_Link01	C	Butobere - Muyumbu - Rwamucucu	18.254	Unsealed
C430_Link01	C	Rwashamaire - Rwahi	37.745	Unsealed
C431_Link01	C	Rubaare - Kyempene	7.88	Unsealed
C431_Link02	C	Kyempene - Rubirizi	15.755	Unsealed
C432_Link01	C	Kanungu - Rugyeyo - Kabaranga	30.663	Unsealed
C432_Link02	C	Kabaranga - Kisiizi	6.429	Unsealed

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
C433_Link01	C	Ikumba - Kanungu	46.813	Unsealed
C433_Link02	C	Kanungu - Kihhi	22.22559206	Bituminous
C433_Link03	C	Kihhi - Kazinga	4.142	Bituminous
C433_Link04	C	Kazinga - Isaka	5.477	Unsealed
C434_Link01	C	Ikumba - Nfasha - Ruhija - Mpungu - Hama	63.56	Unsealed
C435_Link01	C	Rukungiri - Campbell	13.958987	Bituminous
C436_Link01	C	Kisoro - Nyabwishenya	1.964	Unsealed
C436_Link02	C	Nyabwishenya - Nteko	42.736	Unsealed
C437_Link01	C	Nyakabande - Mutorere	4.932	Unsealed
C438_Link01	C	Kisoro - Nyarusiza	3.986	Unsealed
C438_Link02	C	Nyarusiza - Muhabura	4.886	Unsealed
C439_Link01	C	Natete - Busanza - Mpaka	18.389	Unsealed
C440_Link01	C	Kanyantorogo - Butogota	17.31	Unsealed
C440_Link02	C	Butogota - Kyeshero-Buhom	14.115	Unsealed
C441_Link01	C	Katojo - Kihhi	16.961	Unsealed
C442_Link01	C	Rukungiri - Ruerere	11.144	Unsealed
C442_Link02	C	Ruerere - Mitaano	21.211	Unsealed
C442_Link03	C	Mitaano - Kanungu	11.933	Unsealed
C443_Link01	C	Bugangari - Rwerere	10.63	Unsealed
C444_Link01	C	Access to Rukungiri PTTC	1.402	Unsealed
C445_Link01	C	Katobo - Bugangari	9.909	Unsealed
C445_Link02	C	Bugangari - Campbell	4.375	Unsealed
C445_Link03	C	Campbell - Bukurungu	6.442	Bituminous
C445_Link04	C	Bukurungu - Bwambara	22.656	Unsealed
C446_Link01	C	Bukurungu - Nyamirama	7.644	Bituminous
C446_Link02	C	Nyamirama - Kikongi - Burama	15.75437	Bituminous
C447_Link02	C	Kabira - Rukungiri	15	Unsealed
C448_Link01	C	Mgahinga - Ntebeko	9.365	Unsealed
C451_Link01	C	Kisoro army barracks off Kabale - Kisoro	0.093	Unsealed
C452_Link01	C	Rukungiri - Station Boundary	19.6	Unsealed
C453_Link01	C	Nyakabande-Muganzi	2.105	Bituminous
C454_Link01	C	Rwashameire-Kyafora-Kiyenje	18.84	Unsealed

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
C455_Link01	C	Muhanga-Kyogo-Kamwezi	20.134	Unsealed
C456_Link01	C	Rwabuteera-Kanyansande spur	6.74	Unsealed
C457_Link01	C	Kisoro - Muganzi - Chahi	5.1	Bituminous
C458_Link01	C	Kalengyere - Katojo	3.725	Unsealed
C459_Link01	C	Ruwerere - Biraara - Kanungu	24.7	Unsealed

Table 34: Kabale Station

5.5.3 Kasese station

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
A005_Link12	A	Rwimi(bridge)-Hima-Mubuku	17.802	Bituminous
A005_Link13	A	Mubuku - Kasese	11.617	Bituminous
A005_Link14	A	Kasese - Kikorongo	21.956	Bituminous
A005_Link15	A	Kikorongo - Bwera - Mpondwe	38.25	Bituminous
B152_Link04	B	Rugazi - Katunguru - Kikorongo	33.1	Bituminous
C414_Link01	C	Katunguru - Ishasha	87.025	Unsealed
C510_Link01	C	Mubuku-Maliba-Nyakalingijo	15.32	Unsealed
C511_Link01	C	Kasese - Kilembe mines	11.734	Bituminous
C512_Link01	C	Rugendabara - Kaswangali	24.661	Unsealed
C513_Link01	C	Kinyamaseke-Kisinga	12.747	Unsealed
C513_Link02	C	Kisinga-Kyarumba-Kibirizi	26.445	Unsealed
C514_Link01	C	Kiburara -Kisinga	8.012	Unsealed
C514_Link02	C	Kisinga-Nsenyi	2.142	Unsealed
C515_Link01	C	Katojo-Mundongo-Bwera	7.656	Unsealed
C516_Link01	C	Katojo-Katwe-Rwentale	38.816	Unsealed
C516_Link02	C	Rwentale-Lake George	16.422	Unsealed
C517_Link01	C	Kasese Railway station Road	0.764	Bituminous
C518_Link01	C	Hima army barracks off Kasese FP- Redone	3.722	Unsealed
C519_Link01	C	Nkenda - Bugoye	10.267	Unsealed
C520_Link01	C	Bwera - Kithoma	5.477	Unsealed
C520_Link02	C	Kithoma - Kiraro	8.016	Unsealed
C521_Link01	C	Muruseghe - Ihandiro	6.827	Unsealed
C522_Link01	C	Nchwera-Rwenshama	6.709	Unsealed
C523_Link01	C	Chanya-Nyuyo Institute	2.869	Unsealed
C574_Link01	C	Accesses to Rwimi Prisons	1.047	Unsealed
C578_Link01	C	Accesses to Ibuga	7.169	Unsealed

Table 35: Kasese Station

5.5.4 Mbarara Station

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
A002_Link07	A	Lyantonde - Mbarara(Bushenyi junction)	67.306	Bituminous
A002_Link08	A	Mbarara(Bushenyi Junction) - Ntungamo	61.729	Bituminous
B150_Link01	B	Ishanyu - Bwizibwera	18.949	Bituminous
B151_Link01	B	Mbarara - Ishanyu	4.934	Bituminous
B151_Link02	B	Ishanyu - Kabwohe	26.171	Bituminous
B151_Link03	B	Kabwohe - Ishaka	28.078	Bituminous
B152_Link03	B	Ishaka - Buhinda - Rugazi	39.3	Bituminous
C350_Link01	C	Katete-Isingiro	30.649	Bituminous
C350_Link02	C	Isingiro-Nsongezi	23.654	Bituminous
C351_Link01	C	Isingiro-Kityanza	22.203	Unsealed
C351_Link02	C	Kityanza-Nakabanga	41.311	Unsealed
C351_Link03	C	Nakabanga-Rakai	40.058	Unsealed
C352_Link01	C	Kityaza-Burema-Bugango(Uganda/Tanzania border)	25.217	Unsealed
C353_Link01	C	Nsongezi-Kyaka	13.783	Unsealed
C354_Link01	C	Kikagati - Murungo bridge	2.719	Bituminous
C359_Link01	C	Rugaaga-Rushasha-Rwentaha	49.707	Unsealed
C359_Link02	C	Rwentaha-Endizi	5.209	Unsealed
C360_Link01	C	Ekitindo - Ngarama - Kasheshe	41.2	Unsealed
C360_Link02	C	Isingiro-Ngarama	6.1	Bituminous
C360_Link03	C	Isingiro - Mabona Loop	7.1	Bituminous
C361_Link01	C	Ntantamukyi - Kamwema	16.544	Unsealed
C363_Link01	C	Kabingo - Nyakitunda - Kabuyanda - Kyezi	39.36	Unsealed
C364_Link01	C	Ruti - Mwizi - Kabuyanda - Kikagati	63.63	Unsealed
C365_Link01	C	Nyakiragaju - Ruzinga (Bugamba) Chitwe	32.825	Unsealed
C365_Link02	C	Ruzinga (Bugamba) Chitwe	19.497	Unsealed
C366_Link01	C	Nyamukana-Kahambo-Kashuro	23.33	Unsealed
C368_Link01	C	Biharwe - Bwizibwera	22.944	Unsealed
C369_Link01	C	Lubingo-Kacwangobe-Kashenshama	20.465	Unsealed
C379_Link01	C	Saano - Endizi Junction	10.941	Unsealed
C382_Link01	C	Ntare-Mutonto-Kacwangobe	17.736	Unsealed
C384_Link01	C	Nyakayojo TC-Kibingo PTC	2.839	Unsealed

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
C386_Link01	C	Kiyoora PTC Access	0.229	Unsealed
C387_Link01	C	Kyambura-Kashaka	19.055	Unsealed
C388_Link01	C	Nyanga Swamp	0.7	Unsealed
C389_Link01	C	Kityaza Bugango access	1	Unsealed
C390_Link01	C	Mbarara Bypass	14	Bituminous
C390N1_Link01	C	Mbarara Bypass (dual)	14	Bituminous
C419_Link01	C	Kafunzo-Kikagati	30.111	Unsealed
C419_Link02	C	Kikagati-Nsongezi	13.765	Bituminous
C421_Link01	C	Kahunga - Nyakyera-Rukoni	31	Unsealed
C447_Link01	C	Kabwohe - Kitagata – Kabira (Mitooma)	50.5	Unsealed
C450_Link01	C	Kyambura - Katerera	18.566	Unsealed
C450_Link02	C	Katerera - Buhindagye	8.864	Unsealed
C452_Link02	C	Station Boundary - Mitooma HQ	13.9	Unsealed
C452_Link03	C	Mitooma HQ - Ruhinda/Kashenyi	11.5	Bituminous

Table 36: Mbarara Station

5.6 North Eastern Region

The combined network under the North Eastern Region totals 2,697 km, comprising 418 km of bituminous roads and 2,279 km of unsealed roads. Unsealed roads therefore account for approximately 85% of the network, highlighting a predominantly gravel and earth-surfaced system with substantial maintenance requirements.

In the Teso Sub-region, Soroti Maintenance Station manages 1,048 km of roads, with unsealed sections (814 km) significantly exceeding bituminous roads (234 km), reflecting the largely rural nature of the network. Within the Karamoja Sub-region, Moroto Maintenance Station oversees 813 km, with a limited proportion of paved roads (184 km), while Kotido Maintenance Station manages 836 km, all of which are unsealed. This distribution reflects the remoteness, low traffic volumes, and challenging climatic and terrain conditions characteristic of Karamoja.

Region	Subregion	Maintenance station	Bituminous	Unsealed	Total
North Eastern	Teso	Soroti	234	814	1048
	Karamoja	Moroto	184	629	813
		Kotido	-	836	836

Table 37: North Eastern Region Maintenance Stations

Region	Maintenance Station	Length per Functional Class (Km)			
		A	B	C	Total
North Eastern Region	Kotido		265.21	571.01	836.22
	Moroto		184.40	629.29	813.70
	Soroti	114.19	115.74	817.82	1047.75
	Grand Total	114.19	565.36	2018.12	2697.67

Table 38 : Length per Functional Class

5.6.1 Kotido Station

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
B301_Link01	B	Ariamoi - Kaladonapal - Kaperimoru	83.373	Unsealed
B301_Link02	B	Kapelimoru - Kotido	19.038	Unsealed
B301_Link03	B	Kotido - Apaam - Kabong	98.98	Unsealed
B302_Link01	B	Kotido - Abim	63.821	Unsealed
C650_Link02	C	Olilim - Abim	24.9	Unsealed
C940_Link02	C	Kapelebyong-Oreta	18.98	Unsealed
C969_Link01	C	Lokicher - Turtuko	23.396	Unsealed
C969_Link03	C	Turtuko - Opekit	1.77	Unsealed
C969_Link04	C	Opekit - Nyakwae	19.135	Unsealed
C979_Link01	C	Achan Pii-Alito	17.7995	Unsealed
C980_Link01	C	Akwanamoru - Opua - Orogom - Oreta	57.258	Unsealed
C981_Link01	C	Koputh - Koputh Junction	6.354	Unsealed
C981_Link02	C	Koputh Junction-Orom	60	Unsealed
C982_Link01	C	Kotido - Loslang - Layoro	38.709	Unsealed
C983_Link01	C	Kapelimoru - Kotein	0.057	Unsealed
C983_Link02	C	Kotein - Kenya Border	37.434	Unsealed
C984_Link01	C	Kapelimoru Barracks Access	0.619	Unsealed
C985_Link01	C	Kaabong - Kalapata - Piire	33.621	Unsealed
C986_Link01	C	Karenga - Birra	30.23	Unsealed
C987_Link01	C	Old Depoth Bridge Access	5.23	Unsealed
C988_Link01	C	Koputh Junction - Lolelia	22	Unsealed
C989_Link01	C	Lokatelebu - Kacheri - Lolelia	40.124	Unsealed
C990_Link01	C	Kapedo-Lomej	32	Unsealed
C991_Link01	C	Nyakwae(Aremo)-Kiru	13.39	Unsealed
C992_Link01	C	Kapelimoru-Loyoro - Apaam	50	Unsealed
C993_Link01	C	Kapedo-Karenga	38	Unsealed

Table 39: Kotido Station

5.6.2 Moroto Station

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
B300_Link04	B	Namalu - Chosan - Lokapel	58.79062469	Bituminous
B300_Link05	B	Lokapel - Ariamoi	45.803	Bituminous
B300_Link06	B	Ariamoi - Moroto	10.997	Bituminous
B303_Link03	B	Irir - Akisim (Lorengchora) - Ariamoi - Nadunget	68.814	Bituminous
C960_Link01	C	Angatun-Nabilatuk-Lokapel	46.817	Unsealed
C961_Link01	C	Chosan to Amudat	30.731	Unsealed
C962_Link01	C	Girik River - Kalita	32.741	Unsealed
C963_Link01	C	Moroto-Lokitanyara	28.078	Unsealed
C963_Link02	C	Lokitanyara-Loro-Amudat	62.855	Unsealed
C963_Link03	C	Amudat-Alakasi-Kalita	56.73	Unsealed
C964_Link03	C	Magoro-Lorachat	19.944	Unsealed
C965_Link01	C	Apeitolim - Iriri	46.325	Unsealed
C966_Link01	C	Turtuko - Apeitolim	37.196	Unsealed
C967_Link01	C	Kokeris - Lopei	17.517	Unsealed
C968_Link01	C	Matany - Lokopo - Turtuko	29.827	Unsealed
C969_Link02	C	Turtuko - Nyakwae	24.801	Unsealed
C970_Link01	C	Moroto army barracks access	0.952	Unsealed
C971_Link01	C	Moroto - Rupa - Nakiloro - Nakabat	31.744	Unsealed
C972_Link01	C	Nakiloro-Lomukura	85	Unsealed
C973_Link01	C	Lokopo Link	5.652	Unsealed
C974_Link01	C	Lokopo Link 2	1.232	Unsealed
C975_Link01	C	Tapach - Katikekile	10.567	Unsealed
C976_Link01	C	Kitale Road	1.584	Unsealed
C978_Link01	C	Lorachat - Magoro	59	Unsealed

Table 40: Moroto Station

5.6.3 Soroti Station

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
A007_Link05	A	Kumi - Soroti	46.745	Bituminous
A007_Link06	A	Soroti - Dokolo	67.444	Bituminous
B303_Link01	B	Soroti - Arapai	7.999	Bituminous
B303_Link02	B	Arapai - Katakwi - Irii	81.862	Bituminous
B305_Link03	B	Kanyago Bridge - Kumi	25.882	Bituminous
C670_Link02	C	Okude - Amuria	34.046	Unsealed
C879_Link01	C	Morita -Kanyum	12.538	Unsealed
C879_Link02	C	Kanyum - Kidongole	16.819	Unsealed
C920_Link01	C	Kumi-Brooks corner	45.953	Unsealed
C920_Link02	C	Brooks corner-Serere-Bugondo	33.643	Unsealed
C921_Link01	C	Soroti to Brooks Corner	26.076	Unsealed
C922_Link01	C	Lira junction-Arapai	8.502	Unsealed
C923_Link01	C	Arapai - Railway Station	1.93	Bituminous
C924_Link01	C	Katine to Ocheri	69.936	Unsealed
C925_Link01	C	Soroti - Serere	27.443	Unsealed
C926_Link02	C	Kidongole - Mukongoro	13.244	Unsealed
C928_Link01	C	Kumi railway access	0.46	Unsealed
C929_Link01	C	Kumi - Ongino	0.115	Unsealed
C929_Link02	C	Ongino - Akide	20.15	Unsealed
C930_Link01	C	Kapir - Ngora	19.678	Unsealed
C930_Link02	C	Ngora - Mukongoro	23.068	Unsealed
C931_Link01	C	Serere - Kateta - Kyere	26.463	Unsealed
C932_Link01	C	Serere-Pingire	30.436	Unsealed
C932_Link02	C	Pingire-Mugarama	5.031	Unsealed
C934_Link01	C	Serere - Kasilo - Kadungulu	22.807	Unsealed
C934_Link02	C	Kadungulu - Kagwara	14.378	Unsealed
C935_Link01	C	Bugondo - Butiku - Kadungulu	13.821	Unsealed
C937_Link01	C	Ngariam-Magoro	27.376	Unsealed
C938_Link01	C	Usuk - Katakwi	10.522	Unsealed
C938_Link02	C	Katakwi - Toroma	18.849	Unsealed

Link_ID	Road_Class	Link_Name	Length(km)	Surface_Type
C939_Link01	C	Arapai-Amuria	27.813	Unsealed
C939_Link02	C	Amuria-Acowa-Usuk	39.05	Unsealed
C940_Link01	C	Amuria-Amucu-Kapelebyong	35.817	Unsealed
C941_Link01	C	Amuria (Kuju) - Obalang	33.058	Unsealed
C942_Link01	C	Kalaki - Lwala	9.63	Unsealed
C943_Link01	C	Lwala - Kaberamaido	18.353	Unsealed
C944_Link01	C	Kaberamaido - Dokolo	16.332	Unsealed
C945_Link01	C	Orungo Corner - Adachal - Usuku	22.155	Unsealed

Table 41: Soroti Station

6. PAVED ROADS NETWORK CONDITION

- The average paved road VCI is 77%.
- Moderate to severe 'All Cracking' exists on 24% (1,424 km) of the paved roads.
- Moderate to severe 'Wide Cracking' exists on 19% (1,160 km) of the paved roads.
- 23% (1,366 km) of roads have severe to moderate ravelling (surface disintegration) and immediate maintenance is required on these roads.
- There is severe to warning roughness on 14% (745 km) of the paved roads.
- 3% (193 km) of paved roads are in a moderate to severe condition due to the occurrence of potholes. Isolated potholes occur on a further 15% (928 km) of the network.
- 41% (2,186km) of the road network exhibits rutting in a moderate to severe state.
- Overall, the paved road network is in good to fair condition, with less than 3% in poor and very poor condition.

6.1 Background to paved VCI

The Visual Condition Index (VCI) is a percentage index ranging from 0 to 100, calculated for each paved road segment (typically 1 km) surveyed. It is used to represent the condition of the paved road network or any sub-network (e.g., regional network) into one of five condition categories. The categories adopted are shown in the table below:

Visual Condition Index (VCI)	Severe / Very Poor	Warning / Poor	Moderate / Fair	Isolated / Good	None / Very Good
	0-29%	30-49%	50-69%	70-84%	85%+

Table 42: VCI ratings on paved roads.

6.2 Visual Assessment and Distress Graphs for Paved Road Network

The paved roads were evaluated using visual inspection and pavement surveillance equipment. MoWT staff performed visual assessments and roughness measurements of the paved roads in FY 2024/25. The data was validated and updated in the National Roads Pavement Management System (PMS).

These levels indicate how many paved roads have no, isolated, moderate, warning, or severe problems.

Global asset management standards suggest that a road network is "healthy" if fewer than 10% of roads are poor or very poor. Therefore, the roads with warning and severe defects should be prioritised for maintenance. The visual and automated evaluations reveal the following findings about the paved roads:

- Cracking
- Moderate to severe 'All Cracking' is noted on 24% (1,424 km) of the paved roads, with 26% (1,540 km) exhibiting isolated cracking and 51% (3,056 km) exhibiting no cracking.
 - 19% (1,160 km) of the paved network presents moderate to severe wide cracking, another 16% (962 km) presents isolated wide cracking, and 65% (3,899 km) presents no wide cracking. Wide cracking is a particular concern because these cracks indicate the disintegration of the structural layers in the wheel paths. Wide cracks also initiate the formation of rutting. Preventive measures should be considered as soon as possible to delay further deterioration and the development of secondary distress.

Ravelling	■ Ravelling is the loss of aggregate material from the road surfacing. In seals, this manifests as stone loss; in asphalts, as surfacing disintegration. ■ 6% (364 km) of roads have severe to warning ravelling and immediate maintenance is required on these roads. ■ 17% (1,002 km) display moderate ravelling. Future maintenance of roads with moderate ravelling is crucial since it accounts for the percentage of roads which could easily deteriorate to a warning condition.
Roughness (measured)	■ ROMDAS surveys for roughness (IRI) and rutting were done on 5,189 km of the paved road network, which accounts for 82% of the paved road network. ■ From the IRI surveys, 14% (745 km) of the road network has severe to warning roughness. These roads typically require medium or heavy rehabilitation. 25% (1,272 km) have moderate roughness, and 61% (3,172 km) have very good and good roughness. Although some of these roads might not require immediate attention, it is crucial to monitor the condition continuously and apply the right treatment at the right time to delay further deterioration.
Rutting	■ 41% (2,186 km) of the road network exhibits rutting in a moderate to severe state, 52% (2,779 km) with isolated rutting and 7% (385 km) with no rutting.
Bleeding	■ 2% (122 km) of the paved network exhibits bleeding in severe to warning states, with 28% (1,656 km) having isolated bleeding and 56% (3,391 km) having no bleeding.
Width Loss	■ There is very minimal width loss (due to edge break) of the pavement on the network. 98% (5,925 km) of the network exhibits no width loss.
Edge Drops	■ There is also very little edge drop on the network, with 98% (5,906 km) of it having none.
Shoulder condition	■ The 2m-wide area is available to road users as an emergency stopping area. 52% (3,147 km) have no defects, 35% (2,078 km) have isolated problems, and 13% (798 km) are in moderate to severe condition.
Drainage on the road	■ This refers to surface drainage and the road's ability to drain water from the surfacing. Generally, not a problem with 84% (5,080 km) in good condition, only 13% (795 km) in moderate condition and 2% (143 km) in severe condition.
Drainage off road	■ Referring to the condition of side drainage, mitre drains and cross drainage underneath the road. 10% (569 km) of the paved road network is in a state of severe condition, 55% (3,282 km) is in a moderate state, 32% (1,935 km) has isolated drainage problems, and 4% (229 km) is in good condition.

- Roadside friction
- Roadside friction refers to activities that take place on and alongside the road, which affect the travel performance and level of service of a road.
 - 59% (3,527 km) of the paved road network has no roadside friction, 33% (1,978 km) has moderate roadside friction, and 9% (515 km) has severe roadside friction.
- Potholes
- 3% (193 km) of roads are in a moderate to severe condition due to the occurrence of potholes. Isolated potholes occur on a further 15% (928 km) of the network, and 81% (4,905 km) have no potholes. 167 km of the paved network are in moderate condition, whereas 26 km are in warning condition. A detailed list of the roads affected by potholes and the total lengths of the affected sections is shown in Appendix 4.

Performance of Paved roads 2025










Figure 15: Distress ratings of defects on paved roads, 2025







Generally, the paved road network is in good condition. However, from a pavement management perspective, the roads appear structurally sound; however, increased cracking, ravelling, rutting, and roughness indicate significant pavement deterioration. A preventive maintenance regime of timely patching, crack sealing, diluted emulsions, and resurfacing will significantly delay structural deterioration by preventing water ingress into pavement structures.

6.3 Comparison of the condition of Paved roads

Distress Cracking	2024	2025																				
	All Cracking <table><tr><td>None</td><td>48%</td></tr><tr><td>Isolated</td><td>28%</td></tr><tr><td>Moderate</td><td>15%</td></tr><tr><td>Warning</td><td>7%</td></tr><tr><td>Severe</td><td>2%</td></tr></table>	None	48%	Isolated	28%	Moderate	15%	Warning	7%	Severe	2%	All Cracking <table><tr><td>None</td><td>51%</td></tr><tr><td>Isolated</td><td>26%</td></tr><tr><td>Moderate</td><td>18%</td></tr><tr><td>Warning</td><td>4%</td></tr><tr><td>Severe</td><td>1%</td></tr></table>	None	51%	Isolated	26%	Moderate	18%	Warning	4%	Severe	1%
	None	48%																				
	Isolated	28%																				
	Moderate	15%																				
Warning	7%																					
Severe	2%																					
None	51%																					
Isolated	26%																					
Moderate	18%																					
Warning	4%																					
Severe	1%																					
Wide Cracking <table><tr><td>None</td><td>56%</td></tr><tr><td>Isolated</td><td>23%</td></tr><tr><td>Moderate</td><td>13%</td></tr><tr><td>Warning</td><td>5%</td></tr><tr><td>Severe</td><td>3%</td></tr></table>	None	56%	Isolated	23%	Moderate	13%	Warning	5%	Severe	3%	Wide Cracking <table><tr><td>None</td><td>65%</td></tr><tr><td>Isolated</td><td>16%</td></tr><tr><td>Moderate</td><td>15%</td></tr><tr><td>Warning</td><td>3%</td></tr><tr><td>Severe</td><td>1%</td></tr></table>	None	65%	Isolated	16%	Moderate	15%	Warning	3%	Severe	1%	
None	56%																					
Isolated	23%																					
Moderate	13%																					
Warning	5%																					
Severe	3%																					
None	65%																					
Isolated	16%																					
Moderate	15%																					
Warning	3%																					
Severe	1%																					
There has been a general improvement in the condition of the road from 2024 to 2025, with no all cracking increasing from 48% in 2024 to 51% in 2025, and no wide cracking from 56% in 2024 to 65% in 2025. This indicates an improvement in the condition, and immediate crack sealing is required to extend the longevity of the road asset and reduce the long-term maintenance costs.																						
Ravelling	Ravelling <table><tr><td>None</td><td>55%</td></tr><tr><td>Isolated</td><td>29%</td></tr><tr><td>Moderate</td><td>10%</td></tr><tr><td>Warning</td><td>4%</td></tr><tr><td>Severe</td><td>2%</td></tr></table>	None	55%	Isolated	29%	Moderate	10%	Warning	4%	Severe	2%	Ravelling <table><tr><td>None</td><td>51%</td></tr><tr><td>Isolated</td><td>26%</td></tr><tr><td>Moderate</td><td>17%</td></tr><tr><td>Warning</td><td>5%</td></tr><tr><td>Severe</td><td>1%</td></tr></table>	None	51%	Isolated	26%	Moderate	17%	Warning	5%	Severe	1%
None	55%																					
Isolated	29%																					
Moderate	10%																					
Warning	4%																					
Severe	2%																					
None	51%																					
Isolated	26%																					
Moderate	17%																					
Warning	5%																					
Severe	1%																					

Distress	2024	2025
	There is a slight decline in the condition of the road regarding ravelling, as the length of paved roads with no ravelling dropped from 55% in 2024 to 51% in 2025. The percentage length with isolated ravelling has decreased from 29% in 2024 to 26% in 2025. Depending on the extent, an overlay or patching is required since ravelling reduces the skid resistance of a pavement and exposes the underlying layers to deterioration.	
Potholes	 Potholes - None - Isolated - Moderate - Warning - Severe	 Potholes - None - Isolated - Moderate - Warning - Severe
	Based on potholes, the condition of paved roads has improved from 77% of the length having no potholes in 2024 to 81% in 2025.	
Roughness (measured)	 IRI - None / Very Good - Isolated / Good - Moderate / Fair - Warning / Poor - Severe / Very Poor	 IRI - None - Isolated - Moderate - Warning - Severe
	IRI surveys indicate a slight decline in the paved road network from 65% in 2024 to 51% in 2025 in very good and good condition. The percentage in fair condition has also decreased from 28% in 2024 to 24% in 2025.	
Rutting (measured)	 Rutting - None - Isolated - Moderate - Warning - Severe	 Rutting - None - Isolated - Moderate - Warning - Severe
	There is a decline in the performance, with 75% in 2024 having none or isolated problems, to 59% in 2025.	

Distress	2024	2025																				
Width Loss	Width Loss <table><tr><td>None</td><td>99.4%</td></tr><tr><td>Isolated</td><td>0.6%</td></tr><tr><td>Moderate</td><td>0%</td></tr><tr><td>Warning</td><td>0%</td></tr><tr><td>Severe</td><td>0%</td></tr></table>	None	99.4%	Isolated	0.6%	Moderate	0%	Warning	0%	Severe	0%	Width Loss <table><tr><td>None</td><td>98%</td></tr><tr><td>Isolated</td><td>2%</td></tr><tr><td>Moderate</td><td>0%</td></tr><tr><td>Warning</td><td>0%</td></tr><tr><td>Severe</td><td>0%</td></tr></table>	None	98%	Isolated	2%	Moderate	0%	Warning	0%	Severe	0%
None	99.4%																					
Isolated	0.6%																					
Moderate	0%																					
Warning	0%																					
Severe	0%																					
None	98%																					
Isolated	2%																					
Moderate	0%																					
Warning	0%																					
Severe	0%																					
No significant change in the extent of width loss on the paved network																						
Edge Drops	Edge Drop <table><tr><td>None</td><td>99.2%</td></tr><tr><td>Isolated</td><td>0.8%</td></tr><tr><td>Moderate</td><td>0%</td></tr><tr><td>Warning</td><td>0%</td></tr><tr><td>Severe</td><td>0%</td></tr></table>	None	99.2%	Isolated	0.8%	Moderate	0%	Warning	0%	Severe	0%	Edge Drop <table><tr><td>None</td><td>98%</td></tr><tr><td>Isolated</td><td>2%</td></tr><tr><td>Moderate</td><td>0%</td></tr><tr><td>Warning</td><td>0%</td></tr><tr><td>Severe</td><td>0%</td></tr></table>	None	98%	Isolated	2%	Moderate	0%	Warning	0%	Severe	0%
None	99.2%																					
Isolated	0.8%																					
Moderate	0%																					
Warning	0%																					
Severe	0%																					
None	98%																					
Isolated	2%																					
Moderate	0%																					
Warning	0%																					
Severe	0%																					
No significant change in the extent of edge drop on the paved network																						
Bleeding	Bleeding <table><tr><td>None</td><td>72%</td></tr><tr><td>Isolated</td><td>24%</td></tr><tr><td>Moderate</td><td>4%</td></tr><tr><td>Warning</td><td>0%</td></tr><tr><td>Severe</td><td>0%</td></tr></table>	None	72%	Isolated	24%	Moderate	4%	Warning	0%	Severe	0%	Bleeding <table><tr><td>None</td><td>56%</td></tr><tr><td>Isolated</td><td>28%</td></tr><tr><td>Moderate</td><td>14%</td></tr><tr><td>Warning</td><td>2%</td></tr><tr><td>Severe</td><td>0%</td></tr></table>	None	56%	Isolated	28%	Moderate	14%	Warning	2%	Severe	0%
None	72%																					
Isolated	24%																					
Moderate	4%																					
Warning	0%																					
Severe	0%																					
None	56%																					
Isolated	28%																					
Moderate	14%																					
Warning	2%																					
Severe	0%																					
There has been a decline in the condition of roads as the length of paved roads with no bleeding has dropped from 72% in 2024 to 56% in 2025. The percentage length with isolated bleeding has also increased from 24% in 2024 to 28% in 2025. This also indicates a deterioration in the condition of the paved roads.																						

Distress Shoulder condition	2024	2025																				
	2m width Shoulder Condition  <table><tr><td>None</td><td>66%</td></tr><tr><td>Isolated</td><td>17%</td></tr><tr><td>Moderate</td><td>11%</td></tr><tr><td>Warning</td><td>3%</td></tr><tr><td>Severe</td><td>3%</td></tr></table>	None	66%	Isolated	17%	Moderate	11%	Warning	3%	Severe	3%	2m width Shoulder Condition  <table><tr><td>None</td><td>52%</td></tr><tr><td>Isolated</td><td>35%</td></tr><tr><td>Moderate</td><td>10%</td></tr><tr><td>Warning</td><td>1%</td></tr><tr><td>Severe</td><td>2%</td></tr></table>	None	52%	Isolated	35%	Moderate	10%	Warning	1%	Severe	2%
None	66%																					
Isolated	17%																					
Moderate	11%																					
Warning	3%																					
Severe	3%																					
None	52%																					
Isolated	35%																					
Moderate	10%																					
Warning	1%																					
Severe	2%																					
There has been a decline in the shoulder condition of paved roads from 66% having no defect in 2024 to 52% in 2025. The percentage length with isolated problems has increased from 17% in 2024 to 35% in 2025.																						
Drainage on the road	Drainage on Road  <table><tr><td>None</td><td>84%</td></tr><tr><td>Moderate</td><td>13%</td></tr><tr><td>Severe</td><td>3%</td></tr></table>	None	84%	Moderate	13%	Severe	3%	Drainage on Road  <table><tr><td>None</td><td>85%</td></tr><tr><td>Moderate</td><td>13%</td></tr><tr><td>Severe</td><td>2%</td></tr><tr><td>Warning</td><td>0%</td></tr></table>	None	85%	Moderate	13%	Severe	2%	Warning	0%						
	None	84%																				
Moderate	13%																					
Severe	3%																					
None	85%																					
Moderate	13%																					
Severe	2%																					
Warning	0%																					
No significant change in the drainage on the road for the paved network, though it can be noted that the condition has improved as the percentage of length on the road network with no defects has increased to 85% in 2025 from 84% in 2024.																						
Drainage off road	Drainage off Road  <table><tr><td>None</td><td>4%</td></tr><tr><td>Isolated</td><td>30%</td></tr><tr><td>Moderate</td><td>50%</td></tr><tr><td>Warning</td><td>11%</td></tr><tr><td>Severe</td><td>5%</td></tr></table>	None	4%	Isolated	30%	Moderate	50%	Warning	11%	Severe	5%	Drainage off Road  <table><tr><td>None</td><td>4%</td></tr><tr><td>Isolated</td><td>32%</td></tr><tr><td>Moderate</td><td>54%</td></tr><tr><td>Warning</td><td>8%</td></tr><tr><td>Severe</td><td>2%</td></tr></table>	None	4%	Isolated	32%	Moderate	54%	Warning	8%	Severe	2%
	None	4%																				
Isolated	30%																					
Moderate	50%																					
Warning	11%																					
Severe	5%																					
None	4%																					
Isolated	32%																					
Moderate	54%																					
Warning	8%																					
Severe	2%																					
Generally, there has been an improvement in the condition of drainage off the road, with the percentage length of paved roads with none to isolated problems remaining constant at 34% in both years.																						

Distress	2024	2025
Roadside friction	Roadside Friction 7% 31% 62% ■ None ■ Moderate ■ Severe	Roadside Friction 8% 33% 59% ■ None ■ Moderate ■ Severe
Roadside friction has reduced on the network, with 59% having no friction in 2025 from 31% in 2024.		

Table 43: Comparison of the condition of Paved roads

6.4 Average VCI for Paved roads

The average VCI for paved roads, based on 2025 data, is 77%, which places the road network in the “good” condition category. In 2024, the average VCI for paved roads was 74%, an increase of 3%. The graph below compares VCI over the years.




Figure 16: Average Paved VCI comparison

6.5 Condition distribution graphs for VCI of Paved Roads




Figure 17: Paved VCI for 2025

6.6 Condition trends for Paved roads




Figure 18: Condition trend for the paved roads from 2009/10 to 2024/25

YEAR	Paved Roads Condition (km)				Paved Roads Condition (%)		
	Good (km)	Fair (km)	Poor (km)	Total (km)	Good (%)	Fair (%)	Poor (%)
2009/10	1,230	1,180	709	3,119	39%	38%	23%
2010/11	1,742	680	843	3,264	53%	21%	26%
2011/12	1,717	856	744	3,317	52%	26%	22%
2012/13	1,794	893	803	3,490	51%	26%	23%
2013/14	2,505	531	759	3,795	66%	14%	20%
2014/15	2707	478	796	3981	68%	12%	20%
2015/16	2040	913	1204	4157	49%	22%	29%
2016/17	2924	979	354	4257	69%	23%	8%
2017/18	3413	1001	136	4551	75%	22%	3%
2018/19	3862	802	351	5015	77%	16%	7%
2019/20	2753	1727	864	5398	51%	32%	16%
2020/21	4220	861	177	5258	80%	16%	3%
2021/22	4272	902	159	5333	80%	17%	3%
2022/23	2987	1724	274	4985	60%	35%	5%
2023/24	3492	271	4931	8694	40%	3%	57%
2024/25	4483	1377	174	6034	74%	23%	3%

Table 44: Condition of paved roads from 2009/10 to 2024/25

6.7 Performance of the paved road network per station

Station	Length surveyed (km)	VCI rating (km)					VCI rating (%)				
		Very Good	Good	Fair	Poor	Very Poor	Very Good	Good	Fair	Poor	Very Poor
Arua	214.220	0.00	53.46	112.76	38.70	9.30	0%	25%	53%	18%	4%
Fort Portal	365.047	48.71	240.85	66.44	9.04	0.00	13%	66%	18%	2%	0%
Gulu	393.812	0.82	102.80	238.53	51.66	0.00	0%	26%	61%	13%	0%
Hoima	365.478	93.28	213.89	58.31	0.00	0.00	26%	59%	16%	0%	0%
Ibanda	202.467	16.00	122.87	61.99	0.61	1.00	8%	61%	31%	0%	0%
Jinja	258.604	92.17	143.97	22.46	0.00	0.00	36%	56%	9%	0%	0%
Kabale	404.463	95.84	254.45	53.18	1.00	0.00	24%	63%	13%	0%	0%
Kampala	684.458	149.51	345.68	176.92	12.35	0.00	22%	51%	26%	2%	0%
Kasese	96.973	68.01	17.93	10.03	1.00	0.00	70%	18%	10%	1%	0%
Kitgum	130.842	1.00	89.39	39.46	1.00	0.00	1%	68%	30%	1%	0%
Kotido	0.000										
Lira	142.959	5.00	122.39	14.37	1.20	0.00	3%	86%	10%	1%	0%
Luwero	274.095	4.08	176.10	71.24	22.68	0.00	1%	64%	26%	8%	0%
Masaka	239.154	107.76	106.68	20.11	4.61	0.00	45%	45%	8%	2%	0%
Masindi	420.363	212.03	149.61	53.73	5.00	0.00	50%	36%	13%	1%	0%
Mbale	383.917	165.65	193.66	24.61	0.00	0.00	43%	50%	6%	0%	0%
Mbarara	369.812	168.62	152.83	48.36	0.00	0.00	46%	41%	13%	0%	0%
Moroto	162.400	0.00	37.21	115.78	9.41	0.00	0%	23%	71%	6%	0%
Moyo	0.000										
Mpigi	267.707	77.94	173.33	16.43	0.00	0.00	29%	65%	6%	0%	0%
Mubende	193.509	74.00	114.67	4.84	0.00	0.00	38%	59%	3%	0%	0%
Soroti	259.744	51.76	56.00	142.05	8.93	1.00	20%	22%	55%	3%	0%
Tororo	203.927	13.59	137.13	51.55	1.66	0.00	7%	67%	25%	1%	0%

Table 45 : Station VCI




Figure 19: VCI rating of the paved road network per station

The Figure above indicates the performance of the paved road network by station. Most stations maintain the road network in good and fair condition. Masindi (50%, 212 km), Mbarara (46%, 168 km), and Masaka (45% 107 km) stations have the highest percentage of roads in very good condition, while Arua (4% 9 km) station has the highest percentage of roads in very poor conditions.

7. UNPAVED ROAD NETWORK CONDITION

7.1 Background to Unpaved VCI

The assessment ratings are utilised to calculate a Visual Condition Index (VCI) similar to the VCI of paved roads. The unpaved VCI is calculated for each unpaved road segment that was surveyed. VCI is a percentage index ranging between 0 and 100; 0 represents a road segment in very poor condition, and 100 represents a road segment in very good condition. During this analysis, the VCI is used as follows:

- An average unpaved network VCI is calculated, representing the average condition of the unpaved road network or any sub-network.
- The VCI is further used to categorise the condition of an unpaved road segment, the unpaved road network or sub-network into one of five condition categories. The condition categories adopted are:

Visual Condition Index (VCI)	Severe / Very Poor	Warning / Poor	Moderate / Fair	Isolated / Good	None / Very Good
	0-29%	30-49%	50-69%	70-84%	85%+

Table 46: VCI ratings on unpaved roads

7.2 Visual assessment of the Unpaved Road network

Unpaved visual assessment data was collected in 2025, and the PMS was updated with this data. The assessment data expresses the condition and characteristics of the wearing course material and the functional condition of the gravel roads as a set of rating scores. The following conclusions can be made regarding the visual condition assessment of unpaved roads on the national road network.

- | | |
|------------------|--|
| Gravel thickness | ■ 11% (1,511km) of the unpaved road network requires re-gravelling due to low gravel thickness of less than 50mm. 67% (9,272km) is in the moderate condition state, with subgrade exposed in local areas (average of 50 to 100mm gravel thickness). |
| Material quality | ■ 11% (1,511km) of unpaved roads have severe material quality exhibiting a poorly distributed range of particle sizes and/or zero or excessive plasticity. 67% (9,272km) have moderate material quality with cracking, loose material, or stones visible. 22% (3,089km) has good material quality. |
| Roughness | ■ 5% (741km) of the unpaved road network has a very poor and uncomfortable ride quality, which results in very high road user costs. 23% (3,167km) has moderate roughness. 69% (9,639km) have isolated problems with the ride being smooth/fair, and comfortable |
| Potholes | ■ The high occurrence of potholes, especially in severe to moderate states on 48% (6,617km) and 50% (6,952km) in the isolated state, is indicative of inadequate maintenance. |
| Rutting | ■ Roads with moderate to severe rutting account for 72% (9,959km) of the network. These roads require blading and re-gravelling. |
| Corrugations | ■ 48% (6,642km) of all roads have severe to moderate corrugations. A further 50% (6,953km) has isolated corrugations. Although these roads require blading, there seems to be a need to investigate whether material properties contribute to the formation of corrugations. |

Erosion	■ Erosion was rated moderate to severe on 44% (6,046km) of the road network. There is a need to repair erosion gullies more regularly.
Drain condition and formation level	■ Drainage condition and formation level indicate the ability of roads to drain water away. Roads with severe or warning formation levels would act as water channels; this is the case for 8% (1,175) of the unpaved road network. 49% (6,846km) of the unpaved roads have moderate formation levels, indicating that the drainage is level with ground level. ■ Furthermore, the drainage condition is considered severe for 9% (1,279km) of the network, with moderate drainage conditions existing on 47% (6,589km) of the network.
Roadside friction	■ 17% (2,320km) of the unpaved road network has no roadside friction, 81% (11,176km) has moderate roadside friction, and 3% (377km) has severe roadside friction.

Distress, characteristic and condition ratings of unpaved roads





Figure 20: Distress, characteristic and condition ratings of unpaved roads, 2025

In summary, the unpaved network is in fair condition. From a road user's perspective, material quality and possibly insufficient maintenance regimes contribute to the development of rough roads with potholes, rutting and corrugations. From an unpaved road management perspective, low gravel thickness, low formation levels and poor drainage conditions result in erosion, which wets the gravel layers and subgrade, which ultimately results in potholes and rutting. A well-planned re-gravelling programme should be supported by an effective maintenance regime of blading (to maintain cambers and limit roughness), cleaning of side drains, mitre drains and cross drainage.

7.3 Condition of Unpaved Roads






Table 47: Condition of Unpaved Roads

7.4 Condition distribution graph for the VCI of Unpaved roads




Figure 21: VCI distribution for the unpaved road network

The general condition of the unpaved road network is generally Fair, standing at 61%

7.5 Condition trends for Unpaved roads




Figure 22: Condition trend for the unpaved roads over the Years

YEAR	Unpaved Roads Condition (km)				Unpaved Roads Condition (%)		
	Good	Fair	Poor	Total	Good	Fair	Poor
2009/10	1,535	2,340	3,436	7,311	21%	32%	47%
2010/11	3,719	7,215	6186	17,120	22%	42%	36%
2011/12	3,926	7,853	5,904	17,683	22%	44%	33%
2012/13	3,852	7,705	5,954	17,510	22%	44%	34%
2013/14	5,678	5,850	5,677	17,205	33%	34%	33%
2014/15	6297	5616	5106	17019	37%	33%	30%
2015/16	1737	5707	2033	9477	18%	60%	21%
2016/17	5212	7003	4072	16287	32%	43%	25%
2017/18	3678	9755	2558	15993	23%	61%	16%
2018/19	3802	8079	3960	15841	24%	51%	25%
2019/20	3591	6245	5776	15612	37%	40%	23%
2020/21	4695	6111	2669	13745	36%	44%	20%
2021/22	2223	8961	1445	12629	18%	71%	11%
2022/23	2298	8527	3169	13971	16%	61%	25%

Table 48 : Trend of the condition of unpaved roads over the years

7.6 Performance of the unpaved road network per station, 2025

Station	Length surveyed (km)	VCI rating (km)					VCI rating (%)				
		Very Good	Good	Fair	Poor	Very Poor	Very Good	Good	Fair	Poor	Very Poor
Arua	692.387	9.00	27.97	595.60	59.17	0.65	1.30%	4.04%	86.02%	8.55%	0.09%
Fort Portal	599.381	0.00	0.00	284.14	298.24	17.00	0.00%	0.00%	47.41%	49.76%	2.84%
Gulu	550.618	5.96	62.64	448.85	33.16	0.00	1.08%	11.38%	81.52%	6.02%	0.00%
Hoima	634.511	0.00	2.00	271.09	322.91	38.52	0.00%	0.32%	42.72%	50.89%	6.07%
Ibanda	675.212	6.42	42.76	484.50	140.53	1.00	0.95%	6.33%	71.76%	20.81%	0.15%
Jinja	909.450	7.98	1.00	201.68	622.04	76.74	0.88%	0.11%	22.18%	68.40%	8.44%
Kabale	845.557	25.04	142.84	526.46	145.22	6.00	2.96%	16.89%	62.26%	17.17%	0.71%
Kampala	466.620	11.56	163.39	280.67	11.00	0.00	2.48%	35.02%	60.15%	2.36%	0.00%
Kasese	291.693	2.00	52.45	207.87	23.37	6.00	0.69%	17.98%	71.26%	8.01%	2.06%
Kitgum	894.654	0.55	117.33	761.31	10.13	5.35	0.06%	13.11%	85.10%	1.13%	0.60%
Kotido	480.099	0.00	3.62	330.52	140.96	5.00	0.00%	0.75%	68.84%	29.36%	1.04%
Lira	762.049	9.00	61.23	630.84	59.97	1.00	1.18%	8.04%	82.78%	7.87%	0.13%
Luwero	936.555	5.38	240.15	644.54	46.49	0.00	0.57%	25.64%	68.82%	4.96%	0.00%
Masaka	649.599	1.00	275.87	365.63	7.10	0.00	0.15%	42.47%	56.29%	1.09%	0.00%
Masindi	208.564	0.00	14.00	184.56	10.00	0.00	0.00%	6.71%	88.49%	4.79%	0.00%
Mbale	622.716	83.82	25.11	263.74	219.37	30.68	13.46%	4.03%	42.35%	35.23%	4.93%
Mbarara	680.358	28.73	93.43	496.88	61.32	0.00	4.22%	13.73%	73.03%	9.01%	0.00%
Moroto	352.872	36.95	3.00	110.95	156.73	45.24	10.47%	0.85%	31.44%	44.42%	12.82%
Moyo	605.667	5.00	128.80	455.64	16.23	0.00	0.83%	21.27%	75.23%	2.68%	0.00%
Mpigi	398.155	11.26	142.56	240.34	4.00	0.00	2.83%	35.80%	60.36%	1.00%	0.00%
Mubende	437.493	3.00	185.06	244.34	5.09	0.00	0.69%	42.30%	55.85%	1.16%	0.00%
Soroti	812.890	10.44	5.00	411.28	351.98	34.20	1.28%	0.62%	50.59%	43.30%	4.21%
Tororo	463.567	7.00	1.00	136.32	245.79	73.45	1.51%	0.22%	29.41%	53.02%	15.84%




Figure 23: Condition rating of the unpaved road network per station

The Figure above indicates the performance of the unpaved road network by station. All stations maintain the road network in fair to poor condition, which indicates a need for improved maintenance and further investigation into the causes of defects. Mbale (13%), Moroto (10%), and Kabale (3%) stations have the highest percentage of roads in very good condition, while Tororo (16%), Moroto (13%) and Jinja (8%) stations have the highest percentage of roads in very poor conditions.

8. CONCLUSION

The FY 2024/25 situational analysis demonstrates that Uganda's national road network is largely in fair to good condition, reflecting the benefits of sustained investment in construction, maintenance, and asset management. The systematic collection of inventory, traffic, and condition data has strengthened the Ministry's capacity to understand network performance and identify priority needs across regions and asset types.

However, the analysis also highlights key challenges, including the dominance of unpaved roads, uneven regional asset distribution, rising traffic volumes, and data gaps resulting from transitional institutional changes. Without timely maintenance and targeted rehabilitation, sections of the network, particularly heavily trafficked paved roads and vulnerable unpaved links, risk accelerated deterioration and higher lifecycle costs.

The report therefore underscores the importance of maintaining consistent data collection, strengthening asset management systems, and translating analytical outputs into timely maintenance and investment actions to preserve the value and functionality of the national road network.

9. RECOMMENDATIONS

Based on the findings of this report, the following recommendations are proposed:

- **Strengthen Preventive Maintenance**
Prioritise timely routine and periodic maintenance interventions, particularly on paved roads carrying high traffic volumes, to slow deterioration and reduce long-term rehabilitation costs.
- **Enhance Data Coverage and Quality**
Expand inventory, traffic, and condition surveys to achieve full network coverage, and institutionalise standardised data verification and quality assurance procedures across all regions.
- **Improve Asset Management Integration**
Strengthen the integration of road, traffic, and structure data within national asset management and GIS platforms to support comprehensive network analysis and investment planning.
- **Address Regional Disparities**
Allocate maintenance and rehabilitation resources based on asset condition, traffic demand, and regional infrastructure needs, with particular attention to regions with high concentrations of bridges and unpaved roads.
- **Support Maintenance Stations**
Enhance the capacity of road maintenance stations through adequate staffing, equipment, and funding to enable early intervention and effective network stewardship.
- **Inform the National Roads Investment Plan**
Use the outputs of this situational analysis as a core input into the National Roads Investment Plan to guide prioritisation of maintenance, rehabilitation, and upgrading projects.
- **Ensure Continuity of Monitoring**
Institutionalise annual or periodic situation analyses to track condition trends, evaluate the impact of interventions, and support transparent, data-driven decision-making

