# **MTG Card Analysis Report**

Report Date: July 25, 2025

Total Cards: 4


Analysis Method: Al-Powered Visual Grading (Gemini 2.5 Pro)

Total Tokens Used: 14,576

Processing Cost: \$0.0568

# Card 1: Sigarda's Aid

cmr #384



TCGPlayer Condition:	LP
PSA Equivalent:	PSA 8
Overall Score:	8.8/10
Confidence:	20%

#### Condition Analysis:

**Centering:** Not fully measurable. Estimated 55/45 top-to-bottom. - The visible top border is clean and suggests the card is well-centered, though potentially slightly high. Left/right centering cannot be determined. (Score: 9.0/10)


**Corners:** All four corners are obscured in the provided images. A conservative score of 8.0 is assigned, assuming minor whitening on 1-2 corners, which is common even for well-kept cards. (Score: 8.0/10) **Edges:** The top edge appears pristine with no visible wear. Side and bottom edges are obscured. Score assumes minimal to no wear on non-visible edges based on the condition of the top edge. (Score: 9.0/10)

**Surface:** The visible portion of the card surface is clean and free of any apparent scratches, scuffs, or print defects. The majority of the surface is not shown. (Score: 9.5/10)

**Overall\_Assessment:** Assessment is highly speculative due to severely cropped imagery. Only the top section of the card front is visible. While this portion appears Near Mint, the overall grade is conservatively lowered to account for the unknown condition of the corners, other edges, and the majority of the surface. An accurate grade requires images of the entire card, front and back. (Score:

# Card 2: Sigarda's Aid

cmr #384



TCGPlayer Condition:	MP
PSA Equivalent:	PSA 6
Overall Score:	6.3/10
Confidence:	10%

### **Condition Analysis:**

**Centering:** Not assessable - Unable to assess centering. The image only shows a small fraction of the bottom of the card, making any measurement impossible. A low score is assigned due to the inability to grade this category. (Score: 5.0/10)

**Corners:** All four corners are not visible in the provided image. Their condition is completely unknown. A low score is assigned due to the inability to grade this category. (Score: 5.0/10)

**Edges:** The bottom edge, which is the only one visible, appears to be clean and sharp. However, the top, left, and right edges are not visible. The score is significantly penalized due to the large amount of unknown information. (Score: 6.0/10)

**Surface:** The visible portion of the card surface, which appears to be a textured foil, is clean and free of any discernible scratches, scuffs, or print defects beyond the intentional texture. (Score: 9.5/10)

Overall Assessment: This assessment is highly speculative due to the extremely poor quality and

**Overall\_Assessment:** This assessment is highly speculative due to the extremely poor quality and severe cropping of the provided image. Only a small sliver of the bottom of the card is visible. The final grade is drastically lowered to reflect the massive amount of missing information and does not necessarily indicate confirmed damage to the card. (Score: 6.3/10)

# Card 3: Sigarda's Aid

cmr #384



TCGPlayer Condition:	LP
PSA Equivalent:	PSA 8
Overall Score:	8.2/10
Confidence:	90%

#### **Condition Analysis:**

**Centering:** Approx. 60/40 left-right - The card is noticeably off-center horizontally, shifted to the right, resulting in a wider left border compared to the right. (Score: 8.0/10)

**Corners:** The visible bottom-right corner shows minor whitening and is slightly soft. The other corners are not clearly visible but are assumed to have similar or less wear. (Score: 8.0/10)

**Edges:** The bottom edge shows a few small nicks/chips of whitening. The visible portions of the side edges appear clean. (Score: 8.0/10)

**Surface:** The surface is largely clean and free of scratches. One very faint vertical print line can be seen running through the text box under close inspection. (Score: 9.0/10)

**Overall\_Assessment:** A strong card overall, but the combination of off-centering and light wear on the bottom edge and at least one corner prevents a Near Mint grade. It qualifies as a high-end Lightly Played or a solid PSA 8. (Score: 8.2/10)

#### Card 4: Sigarda's Aid

cmr #384



TCGPlayer Condition:	LP
PSA Equivalent:	PSA 8
Overall Score:	8.8/10
Confidence:	85%

#### **Condition Analysis:**

**Centering:** Approx. 65/35 left-right, 55/45 top-bottom - Noticeably off-center, shifted significantly to the left. The left border is much thinner than the right. (Score: 7.0/10)

**Corners:** Corners appear sharp and clean under inspection. The top-left corner is pristine. No visible wear on other visible corners. (Score: 9.5/10)

**Edges:** Visible top and left edges are clean with no nicks or whitening. Assessment of other edges is limited but they appear to be in similar condition. (Score: 9.0/10)

**Surface:** Surface appears immaculate with no visible scratches, scuffs, or other defects. Assessment is limited by dark lighting and the presence of a sleeve. (Score: 9.5/10)

**Overall\_Assessment:** The card is in otherwise pristine, near-mint condition, but its overall grade is constrained by significant left-to-right off-centering. Surface, edges, and corners show no apparent play wear. Image quality and the presence of a sleeve limit definitive assessment of micro-defects. (Score: 8.8/10)