


Bathroom 1.20 — section on the fall  
vertical ×10, horizontal true  
RD Šíma 1.NP

1.500% along the diagonal, fall -43.489 mm

NE corner +0.026 mm

elevation 0, unsloped floor

0 east jamb 0.000 mm



drain -43.489 mm

1:9 · 1000 mm