


Bathroom 1.20 — section along the door wall
vertical ×10, horizontal true
RD Šíma 1.NP

1.0735% east-west, door leaf fall 9.662 mm / 900 mm

west -23.847 mm

elevation 0, unsloped floor

east -0.498 mm



tile 8.5 mm; screed thickness not measured

1:7 · 1000 mm

