


Bathroom 1.20 — section along the door wall
vertical ×10, horizontal true
RD Šíma 1.NP

1.0735% east-west
door leaf fall 9.662 mm / 900 mm

west -23.847 mm

elevation 0, unsloped floor

east -0.498 mm



10× vertical exaggeration

tile 8.5 mm; screed thickness not measured

1:1 true scale



1:9 · 1000 mm

