M1-R(c) Top: largest measured local support frame; bottom: reset / full refresh
Image support is not a foreground mask or Transformer reuse certificate

CAM_FRONT | stable 9.7% | invalid 90.3%



CAM_FRONT_RIGHT | stable 3.9% | invalid 96.1%




CAM_FRONT_LEFT | stable 15.8% | invalid 84.2%




CAM_BACK | stable 16.8% | invalid 83.2%



CAM_BACK_LEFT | stable 17.2% | invalid 82.8%



CAM_BACK_RIGHT | stable 21.3% | invalid 78.7%



CAM_FRONT | stable 0.0% | invalid 100.0%




CAM_FRONT_RIGHT | stable 0.0% | invalid 100.0%



CAM_FRONT_LEFT | stable 0.0% | invalid 100.0%



CAM_BACK | stable 0.0% | invalid 100.0%



CAM_BACK_LEFT | stable 0.0% | invalid 100.0%



CAM_BACK_RIGHT | stable 0.0% | invalid 100.0%



Verified image support Observed residual change Unknown