



Nebula Vision Inspection

Place one 150 mm end-to-end ruler flat beside one mechanical component. Photograph from directly above.

[Capture photo](#)[Upload photo](#)[Download PDF report](#)

► Optional dimensional tolerance

[Capture photo](#)[Upload photo](#)[Download PDF report](#)

► Optional dimensional tolerance

Status: accepted

Component: mounting bracket (AI confidence 0.9%)

Calibration: Ruler: 150.0 mm end-to-end; confidence 91%


Measured length x width: 32.27 x 14.99 mm

Hole-to-hole: 11.79 mm

Defects: none flagged


Verdict: REVIEW

No complete dimensional tolerance was supplied; automatic PASS is disabled.




Nebula Vision Inspection

Place one 150 mm end-to-end ruler flat beside one mechanical component. Photograph from directly above.

[Capture photo](#)[Upload photo](#)[Download PDF report](#)

► Optional dimensional tolerance

[Capture photo](#)[Upload photo](#)[Download PDF report](#)

► Optional dimensional tolerance

Status: accepted

Component: screw (AI confidence 0.95%)


Calibration: Ruler: 150.0 mm end-to-end;
confidence 88%

Measured length x width: 17.98 x 8.78 mm

Defects: none flagged


Verdict: REVIEW

No complete dimensional tolerance was
supplied; automatic PASS is disabled.



Nebula Vision Inspection

Place one 150 mm end-to-end ruler flat beside one mechanical component. Photograph from directly above.

[Capture photo](#)[Upload photo](#)[Download PDF report](#)

► Optional dimensional tolerance

[Capture photo](#)[Upload photo](#)[Download PDF report](#)

► Optional dimensional tolerance

Status: accepted

Component: latch bracket (AI confidence 0.85%)

Calibration: Ruler: 150.0 mm end-to-end; confidence 95%

Measured length x width: 68.67 x 22.86 mm

Hole-to-hole: 1.8 mm

Defects: none flagged

Verdict: REVIEW

No complete dimensional tolerance was supplied; automatic PASS is disabled.