

Occurrence Details

Occurrence Number

105H 088 MINFILE 13373

Occurrence Name

Billings

Occurrence Type

Hard-rock

Status

Showing

General Information

Location Map

Work History ⁽⁰⁾

Assessment Reports ⁽²⁾

Related References ⁽⁰⁾

Drill Cores ⁽⁰⁾

Submit Info

Primary Commodities: molybdenum, tungsten

Deposit Type(s): Skarn W

Location(s): 61.84778N, 129.24583W

NTS Mapsheet(s): 105H14

Location Comments: .5 Kilometres

Hand Samples Available at YGS: No

Capsule

Work History

Discovered by prospecting in 1977 and 1978 by Welcome North ML's Basin Project.

Capsule Geology

Scheelite and molybdenite occur in skarn pendants within the Cretaceous Mt Billings Batholith.

References

WELCOME NORTH MINES LTD, Jun/78. Assessment Report #090357 by J.S. Brock.

Assessment reports are quite negative – DWA

<https://yma.gov.yk.ca/019136.pdf>

Occurrence Details

Occurrence Number

105H 043 MINFILE 13335

Occurrence Name

Guy

Occurrence Type

Hard-rock

Status

Showing

General Information

Location Map

Work History ⁽¹⁾

Assessment Reports ⁽²⁾

Related References ⁽⁰⁾

Drill Cores ⁽⁰⁾

Submit Info

Primary Commodities: copper, tungsten

Deposit Type(s): Skarn W

Location(s): 61.79778N, 128.93861W

NTS Mapsheet(s): 105H15

Location Comments: .5 Kilometres

Hand Samples Available at YGS: No

Capsule

Work History

Staked as Guy cl (89357) in Sep/65 by Mt Billings Venture (Asarco, Serro and Duval). Only preliminary sampling was done.
Restaked as Hal cl (Y28684) in Oct/68 by M. Martin.

Capsule Geology

Scheelite and chalcopyrite occur in skarn, either in roof pendants in the Cretaceous Mt Billings Batholith, or in Proterozoic or Cambrian limy phyllite and limestone to the north. Samples collected by Mt Billings Venture assayed as high as 0.85% WO3, but the skarn patches are quite small.

References

CATHRO, R.J., Apr/69. Tungsten in Yukon. Western Miner, p. 29.

GEOLOGICAL SURVEY OF CANADA Paper 67-36, Figure 1.



Numbered showings are described in the assessment report



Woah APPEARS TO BE OPEN

Tai are leased third party and host the main showings, following table lists the occurrences

48 and 49 look the best (not shown as occurrence on Yukon Minfile)

Also 35, 36 38 – hard to locate probably at B?

Zeut is open – see 22 and 26 large scheelite boulders toe of glacier (likely receded now)



<u>Showing No.</u>	<u>Description</u>
1	Sphalerite and galena mineralizing meta-sediments, found at head of small cirque; float.
2	Shale-hosted zinc float.
3	Lead-zinc float in skarn; later followed up and found to be minor local patches of mineralization.
4	Chalcopyrite in quartzitic host-rock; several very large pieces of float.
5	Fine grained sphalerite and galena in skarn. Follow-up work, checking for scheelite in same skarn, established the WOA# tungsten occurrence.
6	One-inch bands or lenses of galena and black sphalerite in diopside skarn. Abundant float at several localities in scree slope.
7	Disseminated galena and brown sphalerite in fine grained massive, green diopside skarn. Abundant float from several separate areas of scree slope.
8	Skarn bands containing sphalerite and galena outcropping in creek.
9	Hydrozincite coating skarny marble float fragments.
10	Coarse grained galena in rusty weathering diopside skarn, mineralized bands to 3 inches thick in fragments of float; lesser fine grained galena and sphalerite found in place.
11	Bands, in place, of coarse grained white granitic rock up to 20 feet in width contain disseminated galena and molybdenum. Also an associated band of dark green diopside skarn contains abundant brown sphalerite veinlets up to 3 inches in thickness.
12	Copper stain on pale green, white altered skarn. Rock mainly quartz plus an unidentified soft pink mineral.
13	Bands to 2 feet thick, fracture controlled gypsum, conformable to bedding in shale; in place.

- 14 Scheelite and molybdenite in skarn; in place.
- 16 Lead and zinc in skarn; in place.
- 17 Semi-massive galena in quartz; float.
- 18 Scheelite and sphalerite in skarn, scattered outcrops to be followed up. Staked as TAI group.
- 19 Scheelite and sphalerite in skarn; float.
- 20 Scheelite and sphalerite in skarn; float.
- 21 Scheelite in garnetiferous skarn; in place. Included in TAI group.
- 22 Scheelite and pyrrhotite in massive garnet skarn; found in large boulders at toe of glacier. Staked as ZEUT, requires follow up.
- 23 Sphalerite in actinolite, diopside skarn; float boulders in shallow scree slope. P. Risby knows location of mineralization in place. Included in TAI group.
- 24 Sphalerite-scheelite bands in actinolite diopside skarn, found in place low in valley floor. Not examined to date.
- 25 Sphalerite in migmatite boulders found in creek bed.
- 26 Large boulders of scheelite-bearing skarn found at the toe of a glacier, part of ZEUT showing.
- 31 Scheelite, sphalerite and galena in skarny migmatite; float, possible extension of WOA.
- 33 Scheelite and pyrrhotite in skarn; float.
- 34 Scheelite and pyrrhotite in skarn; float.
- 35 Garnet-actinolite-bearing scheelite in two separate bands up to 30 feet thick; in place.
- 36 Scheelite with minor sphalerite and galena in garnet-diopside skarn bands 10 to 20 feet thick and traceable for approximately 1000 feet. Locally high-grade tungsten ranging in estimated grade from 1 to 5%; in place.
- 37 Sphalerite and scheelite in blackish-brown weathering locally epidotic skarn. Similar float found above out-cropping.
- 38 Scheelite with minor sphalerite and galena in garnet-diopside skarn band approximately 3000 feet long. Locally well mineralized; in place.

39	Scheelite and pyrrhotite in skarn; float.
40	Fine grained scheelite in garnet skarn boulders at base of a large talus slope.
44	Minor narrow bands scheelite and pyrite in granitic rock; in place.
45	High grade scheelite in skarn, float appears to be from narrow bands.
46	As showing 45.
47	Minor scheelite in skarn.
48	Scheelite and pyrrhotite in skarn bands up to 12 feet thick.
49	Scheelite and pyrrhotite in skarn bands, similar to showing 48.

The following mineral occurrence descriptions are summarized from the Archer, Cathro Northern Cordillera Mineral Inventory. The showing or claim block locations within the Basin Project Area are shown on Fig. 3.

<u>Mineral Occurrence Map Ref. No.</u>	<u>Description</u>
50	Rea - massive sulphide (lead/zinc/silver) lens measuring 10 x 25 feet in skarn near granitic contact.
51	Nort - staked in a drift-filled valley, type of mineralization unknown.
52	Cree - molybdenite in narrow quartz veins.
53	BR - copper, tungsten in a skarn near granitic contact.
54	Tanya - chalopyrite, scheelite, galena and sphalerite occur in pyrrhotite lenses and veinlets in skarn zones at edge and as roof pendants in granitic stock. Trenching and diamond drilling carried out in the early 70's indicated erratic nature of mineralization.
55	Guy - similar to Tanya, skarn patches found to be small.
56	Thor - molybdenite and scheelite within a hydrothermally altered quartz stockwork related to a fracture zone and pyritic gossans near the contact between quartz monzonite and earlier granodiorite batholith.

WOAH 13359

Primary Commodities: tungsten

Deposit Type(s): Skarn W

Location(s): 61.84306N, 129.19778W

NTS Mapsheet(s): 105H14

Location Comments: .5 Kilometres

Hand Samples Available at YGS: No

Capsule

Work History

Staked as WOA H cl (YA25740) in Sep/77 by Welcome North ML, which explored with mapping and sampling in 1977 and 1978. Riocanex explored in 1979 with rock geochem sampling and 4 holes (191 m) under a brief option. In 1981, the property was optioned briefly to Union Carbide EL.

Capsule Geology

Four scheelite showings occur in garnet-diopside-quartz skarn developed in screens and xenoliths of Proterozoic limestone and limy phyllite along the margin of the Mt Billings Batholith. The mineralization tends to be deficient in sulphides although pyrrhotite, pyrite, chalcopyrite and sphalerite are locally present in minor amounts. Quartz veins cutting the skarn contain scheelite, molybdenite, chalcopyrite and anomalous amounts of radioactive minerals. Chip sampling of the best scheelite occurrence (A showing) in 1977 indicated an average grade of 0.4% WO3, but the 1979 surface sampling returned an average grade of 0.09% WO3. Drilling failed to intersect the Woah A mineralization. The best intersection from the Woah B assayed 0.02% WO3 over 29.7 m.

References

DICK, L.A., 1980. A comparative study of the geology, mineralogy, and conditions of formation of contact metasomatic mineral deposits in the northeastern Canadian Cordillera. Unpublished Ph.D. Thesis, Queen's University, p. 8, 118, 123-126, 163, 179-180.

GEOLOGICAL SURVEY OF CANADA Paper 78-1A, p. 289-290.

MINERAL INDUSTRY REPORT 1978, p. 68.

RIOCANEX, Dec/79. Assessment Report #090516 by D.C. Durin.

YUKON GEOLOGY AND EXPLORATION 1979-80, p. 187-188.

1977

6. Drilling

Between August 5th and August 20th Longyear Canada Ltd. drilled a total of 351.1 metres of BQ core in six holes, using a Hydrowink drill. All holes, except DDH-1, were inclined. Drill logs and sections through the drill holes are included in the appendix (Appendix III and Drawing G-7535). All skarn intercepts were sampled (except hole 6), in three metre sections in holes 1 and 2, and in one metre sections in holes 3, 4 and 5.

<u>Zone</u>	<u>Hole</u>	<u>Depth</u>	<u>Comments</u>
WOAH A	DDH-3	39.7 m	base of talus below main zone, main skarn not intersected.
WOAH B	DDH-1	45.1 m	29.7 m true skarn thickness average 0.017% WO ₃ .
	DDH-2	93.9 m	85 m north of DDH-1, 31.25 m true skarn thickness, average 0.012% WO ₃ .
WOAH C	DDH-4	11.8 m	9.5 m true skarn thickness, average 0.015% WO ₃ .
TAI East	DDH-5	92.3 m	Canuck showing, N. end, 15 metres skarn thickness, average 0.016% WO ₃ .
TAI East	DDH-6	68.3 m	Canuck showing, S. end, 27.4 m of skarn, not assayed, very low WO ₃ .