
Wordpress plugin Live Chat v8.0.15 XSS vulnerability



The location of the vulnerability exists in wp-live-chat-support\modules\gdpr.php Line 159:

```
| Authorized | Aut
```

The "term" parameters submitted by the user are not processed and output to the page. Use XSS code:



