




Figure 7.
Estimated cumulative damage for impeller blades.




Figure 8.
Estimated residual life of impeller blades by the criterion of cracking.




Figure 9.
Estimated residual life of impeller blades at the stage of crack development.