

MARUTI SUZUKI Swift


VXI AMT [2018 - 2021] - 2021

Year Of Manufacturing	:	**2021**
No. Of Owner(S)	:	**1**
Duplicate Key	:	**Yes**
KM	:	**101441**
Fuel Type	:	**Petrol**
Reg. State	:	**Delhi**
Reg. City	:	**Delhi NCR**
Insurance Type	:	**Zero Depreciation**
Insurance Expiry	:	**02-Feb-2027**
RC Availability	:	**Original**
Road Tax Paid	:	**OTT/LTT**
Road Tax Date (Validity)	:	**02-Feb-2036**
CNG/LPG Fitment In RC	:	**No**

Car Details

Registration Number	**DL3CXXXXXX**	RTO	**DL-03 SHEKH SARAI**
City	**Gurgaon**	RTO NOC Issued	**No**
Inspection At	**Doorstep**	Under Hypothecation	**Yes**
Branch	**HI-Gurgaon New**	CNG/LPG Fitment In RC	**No**
To Be Scrapped	**No**	Chassis Number Embossing	**Ok**
Manufacturing Month	**January**		
Registration Year	**2021**		
Registration Month	**February**		
Fitness Upto	**02-Feb-2036**		
RC Condition	**Ok**		
Mismatch In RC	**No Mismatch**		

Summary



Exterior + Tyres

Part	Subpart	Status	Work Done / Current Condition
Bumper	Front	✗	Faded, Grill Damaged, Scratched, Damaged
	Rear	✗	Faded, Scratched
Bonnet/Hood	-	✗	Replaced, Repainted
Roof	-	✗	Dented, Scratched
Fender	LHS	✗	Faded / Repainted
	RHS	✗	Replaced
Door	LHS Front	✗	Faded, Scratched / Repaired, Repainted
	LHS Rear	✓	-
	RHS Front	✓	-

Exterior + Tyres

Part	Subpart	Status	Work Done / Current Condition
	RHS Rear	✓	-
Pillar	LHS A	✗	Scratched
	LHS B	✗	Scratched
	LHS C	✗	Scratched
	RHS A	✓	-
	RHS B	✓	-
	RHS C	✗	Scratched
Running Border	-	✓	-
Quarter Panel	-	✓	-
Dicky Door / Boot Door	-	✗	Replaced, Repainted
Boot Floor	-	✗	Rusted
Apron	LHS	✓	-
	RHS	✓	-
	LHS LEG	✓	-
	RHS LEG	✗	Rusted
Firewall	-	✓	-
Cowl Top	-	✓	-
Lower Cross Member	-	✓	-
Upper Cross Member (Bonnet Patti)	-	✓	-
Head Light Support	-	✓	-
Radiator Support	-	✗	Damaged, Rusted / Repaired
Windshield	Front	✗	Scratched / Replaced
	Rear	✓	-
ORVM - Manual / Electrical	LHS	✗	Scratched, Damaged
	RHS	✗	Scratched
Light	LHS Headlight	✗	Moisture in light
	RHS Headlight	✗	Damaged
	LHS Taillight	✗	Scratched, Damaged
	RHS Taillight	✗	Damaged
	LHS Fog Light	✗	Scratched
	RHS Fog Light	✗	Scratched

Exterior + Tyres

Part	Subpart	Status	Work Done / Current Condition
Alloy Wheel	-	✗	-
LHS Front Tyre	-	4 - 5 mm	-
RHS Front Tyre	-	1.6 - 2 mm	-
LHS Rear Tyre	-	1.6 - 2 mm	Damaged
RHS Rear Tyre	-	3 - 4 mm	-
Spare Tyre	-	6 - 7 mm	-

Electricals + Interior

Part	Subpart	Status	Work Done / Current Condition
No. Of Power Windows	-	4	-
No. Of Airbags	-	2	-
Power Windows	-	✓	-
Electrical	-	✓	-
Interior	-	✗	Dashboard scratched & broken
Airbag Feature	-	✓	-
Music System	-	✗	Buttons not working
Leather Seat	-	✗	Worn Out
Fabric Seat	-	✗	-
Sunroof	-	✗	-
Steering Mounted Audio Control	-	✓	-
ABS	-	✓	-
Rear Defogger	-	✗	-
Reverse Camera	-	✗	-
Parking Sensor	-	✓	-
Navigation chip	-	✗	-

Engine + Transmission

Part	Subpart	Status	Work Done / Current Condition
Engine	-	✓	-
Battery	-	✗	Acid leakage

Engine + Transmission

Part	Subpart	Status	Work Done / Current Condition
Engine Oil Level Dipstik	-	✓	-
Engine Oil	-	✓	-
Coolant	-	✓	-
Engine Mounting	-	✗	Excess Vibration
Engine Sound	-	✗	No Blow-by, Minor Sound
Exhaust Smoke	-	✓	-
Clutch	-	✗	-
Gear Shifting	-	✓	-
Turbo Charger	-	✓	-
Fuel Injector	-	✓	-

Steering/Suspension + Brakes

Part	Subpart	Status	Work Done / Current Condition
Steering	-	✗	Abnormal Noise
Suspension	-	✗	Abnormal Noise
Brake	-	✓	-

Air Conditioning

Part	Subpart	Status	Work Done / Current Condition
AC Cooling	-	✓	-
Heater	-	✓	-
Climate Control AC	-	✗	-

Comments

Air Conditioning

- AC Vent damaged

Electricals + Interior

- Door Trim torn
- Navigation chip not available

Exterior + Tyres



Front Main



Front Right Side



Front Left Side



Left Main



Rear Left Side



Rear Main

Exterior + Tyres



Rear Right Side



Rear Boot Opened



Right Main



Bumper - Front (Faded, Grill Damaged, Scratched, Damaged)



Bumper - Rear (Faded, Scratched)



Bonnet/Hood (Replaced, Repainted)

Exterior + Tyres



Roof (Dented, Scratched)



Fender - LHS (Faded)



Fender - LHS (Repainted)



Fender - RHS (Replaced)



Door - LHS Front (Faded, Scratched)



Door - LHS Front (Repaired, Repainted)

Exterior + Tyres



Door - LHS Rear



Door - RHS Front



Door - RHS Rear



Pillar - LHS A (Scratched)



Pillar - LHS B (Scratched)



Pillar - LHS C (Scratched)

Exterior + Tyres



Pillar - RHS A



Pillar - RHS B



Pillar - RHS C (Scratched)



Dicky Door / Boot Door (Replaced, Repainted)



Boot Floor (Rusted)



Boot Floor (Rusted)

Exterior + Tyres



Apron - LHS



Apron - RHS



Apron - LHS LEG



Apron - RHS LEG (Rusted)



Apron - RHS LEG (Rusted)



Firewall

Exterior + Tyres



Cowl Top



Lower Cross Member



Upper Cross Member (Bonnet Patti)



Head Light Support



Radiator Support (Damaged, Rusted)



Radiator Support (Repaired)

Exterior + Tyres



Radiator Support (Repaired)



Windshield - Front (Scratched, Replaced)



Windshield - Rear



ORVM - Manual / Electrical - LHS (Scratched, Damaged)



ORVM - Manual / Electrical - LHS (Scratched, Damaged)



ORVM - Manual / Electrical - RHS (Scratched)

Exterior + Tyres



ORVM - Manual / Electrical - RHS (Scratched)



Light - LHS Headlight (Moisture in light)



Light - RHS Headlight (Damaged)



Light - LHS Taillight (Scratched, Damaged)



Light - RHS Taillight (Damaged)



Light - LHS Fog Light (Scratched)

Exterior + Tyres



Light - RHS Fog Light (Scratched)



LHS Front Tyre



RHS Front Tyre



LHS Rear Tyre (Damaged)



RHS Rear Tyre



Spare Tyre

Electricals + Interior



Lock system



Steering mounted audio controls



Odometer



Flooring



Driver Seat



Second Row Seat

Electricals + Interior



Dashboard



Electrical



Leather Seat (Worn Out)



Steering Mounted Audio Control

Engine + Transmission



Engine



Battery (Acid leakage)


Engine + Transmission



Engine Oil Level Dipstik



Engine Oil



Coolant