

a
HOT (AI-assisted)
n = 1,053 graded footprints
AOI2 Timure
AOI3 Bidur
Copernicus EMS
AOI1 Syaphrubesi
AOI5 Phosretar
no satellite building grading downstream
UNOSAT
flow extent mapped; 684 destroyed records (ticks)
local levels reported in the RDNA (15)
Official RDNA
0 25 50 75 100 125 150 175 200
Distance downstream of source (km)
b
HOT 937
CEMS (latest) 4,685
UNDP: CEMS 2,311
UNDP: SERTIT 48
UNDP: UNOSAT 684
Union (≥1 product) 5,781
Destroyed in ≥2 1,912
Official RDNA 7,570
Destroyed
Other damage grades
Affected (official)
0 2K 4K 6K 8K
Buildings
c
n = 867 buildings graded by both; Cohen's κ (destroyed) = 0.49
HOT label
No damage 49% (32) 40% (26) 9% (6) 2% (1)
Minor 63% (74) 19% (23) 16% (19) 2% (2)
Major 49% (36) 27% (20) 11% (8) 12% (9)
Destroyed 33% (201) 0% (2) 2% (10) 65% (398)
No record
Possibly damaged
Damaged
Destroyed
CEMS EMSR927 grade (same buildings)
d
Graded by satellite products
Not graded (plotted at axis floor)
Graded local levels: median ratio 1.16
Bidur
Gosaikunda
Galchhi
Kispang
Uttargaya
Tarakeshwor
Belkotgadhi
Gajuri
Kalika, Ichchhyakamana
Gandaki, Siddhalek
Benighat Rorang
1:1
Satellite-graded damaged buildings
RDNA affected private buildings
e
Syaphrubesi, 2025-10-11
Syaphrubesi, 2026-10-01
Trishuli Bazar, 2025-10-11
Trishuli Bazar, 2026-09-21
1 km
f
HOT (AUC 0.94)
111 153 104 652
CEMS/UNDP (AUC 0.95)
17,842 644 375 3,862
Sentinel-2 NDVI change (Oct 2026 minus Oct 2025)
None Minor Major Destr.
None Poss. Dam. Destr.