QA TESTING PORTFOLIO: TEST CASES & BUG REPORTS

Tester: Muhammad Rizali Hafizhi | Email: hafizhi46@gmail.com | Location: Indonesia
Tools Used: Jira, Trello, Chrome DevTools, Cross-Browser & Responsive Viewport Testing

PART 1: SAMPLE TEST CASE EXECUTION SUITE


Project Audit: Polymesh Web Portal / Dashboard UI (Mainnet)
Test Environment: Windows 11 | Google Chrome (Mobile Viewport Emulation & Responsive View)

Test Case ID	Module	Test Scenario	Expected Result	Status
TC-UI-01	Mobile Sidebar Drawer	Verify mobile sidebar navigation drawer stretches to 100% viewport height and displays all menu items cleanly	Sidebar extends to the bottom of the screen without clipping 'Authorizations' or lower menu items	**FAIL (BUG-101)**
TC-UI-02	Activity Card Component	Verify 'Activity' (Historical) card component wraps or scrolls table columns (ID, Date/Time, Module, Call, Status) with visible data values on mobile viewports	Activity card either scrolls horizontally or stacks label-value pairs cleanly within the card container	**FAIL (BUG-102)**
TC-FUNC-03	Sidebar External Links Menu	Verify secondary external links submenu (SubScan, Governance, Developer App, Asset Explorer, Newsletter) stays open when triggered from the mobile sidebar	Submenu drawer remains open until the user clicks a link or taps the 'X' close button	**FAIL (BUG-103)**
TC-UI-04	Key & DID Cards	Verify 'Selected key' and 'Your DID' cards align and truncate long strings cleanly on mobile view	Account keys and DID dropdowns remain contained within card padding without horizontal overflow	**PASS**
TC-FUNC-05	Balance Action Buttons	Verify 'Send', 'Receive', and 'Get POLYX' buttons remain clickable when sidebar is closed	Buttons trigger respective modals and stay aligned inside the balance card container	**PASS**

PART 2: DETAILED JIRA-STYLE BUG REPORTS (POLYMESH)


BUG-101: [Polymesh Mobile UI] Sidebar navigation drawer cuts off mid-screen and clips the 'Authorizations' menu item

Bug ID	BUG-101
Severity / Priority	Severity: Minor (UI / Visual Layout Defect)	Priority: Medium
Environment	Polymesh Dashboard (Mainnet)	Mobile Viewport	Google Chrome
Preconditions	User is logged into the Polymesh Portal on a mobile viewport and views the Overview dashboard.
Steps to Reproduce	1. Open the Polymesh dashboard in a mobile viewport. 2. Tap the menu icon to open the left-hand navigation sidebar. 3. Observe the bottom boundary of the sidebar drawer near the 'MultiSig' and 'Authorizations' links.
Expected Result	The mobile sidebar drawer should extend to full viewport height (100vh / 100dvh) with internal vertical scrolling enabled, displaying 'Authorizations' and any lower navigation items completely.
Actual Result	The sidebar drawer container terminates abruptly about halfway down the screen right above the 'Locked' balance section, vertically clipping the 'Authorizations' icon and label.
Technical / DevTools Note	The sidebar overlay container lacks full-screen height styling (e.g., height: 100vh or fixed bottom: 0) and overflow-y: auto, causing the drawer background to cut off mid-page and clip child navigation

	links.
Visual Evidence (Actual Result)	

BUG-102: [Polymesh Mobile UI] 'Activity' card component fails to render row values and clips right border on mobile viewport

Bug ID	BUG-102
Severity / Priority	Severity: Minor (Responsive Layout / Data Visibility Defect) | Priority: Medium
Environment	Polymesh Dashboard (Mainnet - Overview Activity Section) | Mobile Viewport | Google Chrome
Preconditions	User is on the Polymesh Overview page on a mobile viewport and scrolls down to the 'Activity' card component.
Steps to Reproduce	1. Open the Polymesh Overview dashboard on a mobile viewport. 2. Scroll down to the 'Activity' card at the bottom of the page.

	3. Inspect the 'Historical' dropdown filter and the stacked row blocks (ID, Date / Time, Module, Call, Status).
Expected Result	The 'Activity' card component should adapt responsively to mobile viewports—keeping the 'Historical' select box inside the card padding and displaying each row's corresponding values (or an 'Empty / No recent activity' state) without clipping the right edge.
Actual Result	The 'Activity' card and 'Historical' dropdown overflow past the right edge of the mobile container (cutting off the dropdown arrow), and the table rows stack field labels vertically (ID, Date / Time, Module, Call, Status) in repetitive empty blocks with corresponding data columns pushed off-screen or hidden.
Technical / DevTools Note	The Activity table/card container uses a desktop grid/flex layout without a mobile breakpoint override or overflow-x: auto wrapper, causing the right side of the card and data columns to be pushed outside the mobile viewport width.
Visual Evidence (Actual Result)	

BUG-103: [Polymesh Mobile UI] Secondary sidebar menu drawer (SubScan, Governance, etc.) auto-dismisses in under 1 second after clicking

Bug ID	BUG-103
Severity / Priority	Severity: Major (Functional UI / State Management Defect) | Priority: High
Environment	Polymesh Dashboard (Mainnet - Mobile Sidebar Menu) | Mobile Viewport | Google Chrome
Preconditions	User is on the Polymesh Portal on a mobile viewport with the main navigation sidebar open.
Steps to Reproduce	1. Open the main left-hand navigation sidebar on a mobile viewport. 2. Tap the menu trigger inside the sidebar to open the secondary ecosystem links drawer (displaying SubScan, Governance, Developer App, Asset Explorer, Newsletter). 3. Observe the secondary menu drawer immediately after clicking.
Expected Result	The secondary ecosystem links drawer should remain open and interactive until the user selects a link or explicitly taps the 'X' close button.
Actual Result	Immediately after clicking inside the main sidebar to open the secondary dropdown/drawer, the submenu flashes on screen and automatically closes/disappears in less than 1 second, preventing the user from clicking any of the links.
Technical / DevTools Note	Click event propagation (event bubbling) or an 'onClickOutside' / sidebar close listener on the parent mobile drawer is firing after the submenu trigger click, immediately unmounting or resetting the open state of the secondary drawer.
Visual Evidence (Actual Result)	