





Expansion Rotor: Bank Angle & Pitch Depower Risk

Normal Operation: Rotor Spreading



Pitch Depower: Back-Wind Risk



Static optimiser cannot detect transient back-wind collapse — dynamic ODE validation required.

Mitigation: lower bank angle (20–30°), symmetric airfoils, conservative prototyping