



Inspection report, Final: PO003459

KS106366-NAVY BLAZER: ALL I WISH FOR - JEWELRY



[Online report](#)

2nd inspection

Inspector	Nya Ni	Inspection Date	Jun 18, 2026
Sample Qty	80	Order Qty	804
Location	29° 21' 13" N x 120° 3' 47" E	Checklist Name	Final
Planned Date	Jun 17, 2026	Sampling Method	AQL 2.5/4 Level II
Supplier Name	10 FASHION		

Inspector Conclusion	Pending	Issues raised during the first final inspection of the bulk order that have been improved include: 1. The edges of the mirrored surface inside the jewelry box lid are now flush and properly recessed (corrected); 2. Glue stains inside the jewelry box have been thoroughly cleaned (corrected); Issues raised during the first final inspection of the bulk order that have not been improved include: 1. Whether the film on the mirrored surface of the jewelry box requires a warning label; please confirm with the customer (not improved); 2. The film on the mirrored surface of the jewelry box is not applied evenly (not improved), approximately 50% of cases. (Automatic translation)
----------------------	---------	---

Constanza Frías	Approved	The warning it was concluded that is not necessary. The protection film for the mirror inconsistency will be approved this time. Next time it is necessary to be applied properly
-----------------	----------	---

Status: **Approved**

SUMMARY

	PO003459:KS106366-NAVY BLAZER
1 Factory details	
2 Quantity Check	
3 Product	
3.5 Workmanship	1
4 On-site Test	
5 Pack and Packaging	


- 1
- 1. The edges of the mirrored surface inside the jewelry box lid have been smoothly embedded (repaired);
 - 2. Glue stains inside the jewelry box lid have been cleaned;
 - 3. Please confirm with the customer whether the film on the mirror needs a warning label (no improvement);
 - 4. The film on the mirror is not applied evenly (no improvement), approximately 50% of the film is not applied evenly.

- The mirror on the jewelry box is flush with the surface, but the plastic film is uneven.
- One piece of protective film for the mirror surface of a jewelry box.
- The inner mirror film on the jewelry box lid is uneven in about 50% of cases.

	CRITICAL	MAJOR	MINOR
WX Other.	-	1	-
WX Other.	-	-	1
WX Other.	-	-	1
WX Other.	-	-	1
WX Other.	-	-	1
W1 Threads, untrimmed.	-	-	1
W1 Threads, untrimmed.	-	-	1
WX Other.	-	-	1
TOTAL	0	1	7
AQL MAX	0	5	7

DEFECTS: 8

1	WX Other. Cardboard box broken (Automatic translation)	MAJOR Items affected: 1
---	---	----------------------------



2	WX Other. Embroidered colored stripes (Automatic translation)	MINOR Items affected: 1
---	--	----------------------------



3	WX Other. The plastic film was not applied to the edges. (Automatic translation)	MINOR Items affected: 1
---	---	----------------------------



4	WX Other. There are lint scraps (Automatic translation)	MINOR Items affected: 1
---	--	---



5	WX Other. The mirror film was not applied to the edges. (Automatic translation)	MINOR Items affected: 1
---	--	---



6	W1 Threads, untrimmed. -	MINOR Items affected: 1
---	--------------------------	---



7	W1 Threads, untrimmed. -	MINOR Items affected: 1
---	--------------------------	---



8	WX Other. Missing film (Automatic translation)	MINOR Items affected: 1
---	---	----------------------------



CHECKPOINTS: 27

1	Factory details	
1.1	Factory name at the location for QC (not supplier name)	OK

Factory Name:

Factory Address:

义乌市萌萱贸易有限公司
浙江省义乌市柳青路1565号



workshop



Package

2	Quantity Check	
2.1	Warehouse / carton piled view	OK
	Factory achieves 100% box fulfillment rate. (Automatic translation)	




Stacked container photos




Box Photo

2.2	Production quantity match PO	OK
	The quantity of bulk goods matches the number of orders. (Automatic translation)	



Order



Packing list

3	Product	
---	---------	-------------

3.1	Product compare against approved sample / color swatch/TECH file	OK
	The bulk order is OK after comparing it with the confirmed sample provided by the factory. (Automatic translation)	



3.2	Labelling (hangtag, main label, size label, care label, tracking label)	OK
	The barcode on the color box has been scanned and verified as OK; the instruction manual, the markings and barcodes on the color box, the main label on the outside of the jewelry box, and the KS mark inside the jewelry box are shown in the following images: (Automatic translation)	

OS: (804)

Barcode can be scanned	OK
Scanned barcode	5715681362075
Barcode from order data	5715681362075


Scanned format	EAN_13
----------------	--------

彩盒条形码

Barcode can be scanned	OK
Scanned barcode	5715681362082
Barcode from order data	
Scanned format	EAN_13



front



back



front of the jewelry box



The main label on the back of the jewelry box is located slightly below the center.



KS Logo inside the jewelry box lid: 1cm directly below the mirror.



Front



rear



right side




Left side




Front side of the middle box



Bottom of middle box



Instruction Manual 1



Instruction Manual 2

3.3	Embroidery / Printing check	OK
	The printed product is OK compared to the confirmed sample provided by the factory. (Automatic translation)	



3.4	Lace / Trimming / Accessories check
-----	-------------------------------------

3.5	Workmanship	Pending
	1. The edges of the mirrored surface inside the jewelry box lid have been smoothly embedded (repaired); 2. Glue stains inside the jewelry box lid have been cleaned; 3. Please confirm with the customer whether the film on the mirror needs a warning label (no improvement); 4. The film on the mirror is not applied evenly (no improvement), approximately 50% of the film is not applied evenly. (Automatic translation)	



The mirror on the jewelry box is flush with the surface, but the plastic film is uneven.



One piece of protective film for the mirror surface of a jewelry box.



The inner mirror film on the jewelry box lid







3.6	Measurement	OK
	Necklace: 39CM Bracelet: 14CM Ring inner diameter: 1.5CM (Automatic translation)	

	Specification	Tolerance	Actual
	-	-	

4	On-site Test	
---	--------------	---

4.1	Metal detection
-----	-----------------

4.2	Pull test	OK
	Large cargo manual tensile test OK (Automatic translation)	




4.3	Smell check	OK
	The artificial olfactory odor test was OK; there was no pungent odor, which is acceptable. (Automatic translation)	



4.4	Humidity check
-----	----------------

4.5	Garment weight (sweater only)
-----	-------------------------------

4.6	Prove of color fastness test from supplier	OK
	After wiping with wet wipes, there was no obvious color fading in the bulk product, which is acceptable. (Automatic translation)	



4.7	Shrinkage test - prove from supplier	OK
	After wiping with wet wipes and drying, there was no obvious color fading. (Automatic translation)	



4.8	The product is packed in poly bag or carton. Supplier can't send products without packaging.	OK
	The cardboard box packaging is correct. (Automatic translation)	



Outer box shape



medium box



4.9	摔箱测试	OK
	After the drop test, the goods inside the box were not damaged. (Automatic translation)	



5	Pack and Packaging	
---	--------------------	------------------------

5.1	Approved sample/QA file available during inspection	OK
	There are confirmation samples, orders, packing lists, and barcode information provided by the factory. (Automatic translation)	




Factory confirmed sample




Factory confirmed sample




Factory confirmed sample



Order



Packing list




Barcode data

5.2	Export carton (shipping mark, barcode)	OK
-----	--	----

Barcode can be scanned	
Scanned barcode	
Barcode from order data	
Scanned format	



Outer box shape



Front box label



Side box markings

5.3	Export carton (dimension, weight)	OK
-----	-----------------------------------	----

	Specification	Tolerance	Actual
L	-	-	44
W	-	-	40
H	-	-	40
Gross Weight	-	-	12.7



The cardboard box is 44 cm long.



Cardboard box width 40CM




The cardboard box is 40cm high.



Actual gross weight: 12.7KG

5.4	Carton Packing (quantity, ratio etc), 3 ply carton	OK
-----	--	----

	The quantity per carton is based on the packing list provided by the factory; 36 pieces per carton (6 inner boxes per carton, 6 pieces per inner box). (Automatic translation)
--	---



Packing list



Outer box shape





medium box



The middle box contains 6 pieces.

5.5	Inner package (polybag, sticker, tissue paper, silica gel etc)	OK
	The inner packaging of the box contained no plastic bags, no tissue paper, and no desiccant. The inside of the jewelry box lid had a plastic film covering the mirrored surface. The white inner box had a barcode sticker on the front. The color box had a barcode sticker on the back. (Automatic translation)	



Each box contains 6 medium-sized boxes.



The white box has a barcode sticker on the front.




The middle box contains 6 pieces.



Color box



front



back



Front



There is a barcode sticker on the back of the color box.



Right side of the color box



Left side of the color box



The jewelry box contains: an instruction manual, a necklace, a bracelet, and a ring (one set in blue and one set in red).



The jewelry box has dividers inside.



Front view (jewelry secured with foam blocks)



On the other hand



The inner mirror surface of the color box lid is covered with a plastic film.

5.6	Hanger (quality, size etc)	
5.7	Header card	
5.8	FSC marking on the transportation boxes	OK
	The outer packaging does not require the FSC mark. (Automatic translation)	



Outer box shape

5.9	Products are in polybags	OK
	The box was not packaged in a plastic bag. (Automatic translation)	



Outer box shape



COMMENTS

Constanza Frías Conclusion set to approved Jun 19, 2026 07:57

The warning it was concluded that is not necessary. The protection film for the mirror inconsistency will be approved this time. Next time it is necessary to be applied properly

Nya Ni Inspector's conclusion Jun 18, 2026 14:16

Issues raised during the first final inspection of the bulk order that have been improved include:

1. The edges of the mirrored surface inside the jewelry box lid are now flush and properly recessed (corrected);
2. Glue stains inside the jewelry box have been thoroughly cleaned (corrected);

Issues raised during the first final inspection of the bulk order that have not been improved include:

1. Whether the film on the mirrored surface of the jewelry box requires a warning label; please confirm with the customer (not improved);
 2. The film on the mirrored surface of the jewelry box is not applied evenly (not improved), approximately 50% of cases.
-