



Inspection report, Final: PO003632

KS102397-PEONY: PERLA BAG



[Online report](#)

Inspector	Nya Ni	Inspection Date	Sep 29, 2026
Sample Qty	125	Order Qty	2796
Location	29° 21' 10" N x 120° 3' 48" E	Checklist Name	Final
Planned Date	Sep 28, 2026	Sampling Method	AQL 2.5/4 Level II
Supplier Name	10 FASHION		

Inspector Conclusion	Approved
----------------------	----------

SUMMARY

	PO003632:KS102397-PEONY
1 Factory details	
2 Quantity Check	
3 Product	
4 On-site Test	
5 Pack and Packaging	

	CRITICAL	MAJOR	MINOR
WX Other.	-	-	1
WX Other.	-	-	1
TOTAL	0	0	2
AQL MAX	0	7	10

DEFECTS: 2

1	WX Other. A single plastic bag with a hole (Automatic translation)	MINOR Items affected: 1
---	---	----------------------------



2	WX Other. The plastic bag has a hole and needs to be replaced. (Automatic translation)	MINOR Items affected: 1
---	---	----------------------------



CHECKPOINTS: 26

1	Factory details	
1.1	Factory name at the location for QC (not supplier name)	OK

Factory Name:

Factory Address:

义乌市萌萱贸易有限公司
浙江省义乌市柳青路1565号



Package

2	Quantity Check	
2.1	Warehouse / carton piled view	OK
	80% of bulk cargo was successfully containerized. (Automatic translation)	




Stacked container photos




Box Photo

2.2	Production quantity match PO	OK
	Number of orders: 2796 pieces. Packing list: 2796 pieces. Quantities match. (Automatic translation)	



Order



Packing list (this column is unmarked)

3	Product	
---	---------	---

3.1	Product compare against approved sample / color swatch/TECH file	OK
	The bulk order is OK after comparing it with the confirmed sample provided by the factory. (Automatic translation)	



front



back

3.2	Labelling (hangtag, main label, size label, care label, tracking label)	OK
	Barcode scan and verification OK. (Automatic translation)	

OS: (2796)

Barcode can be scanned	OK
Scanned barcode	5715681012154
Barcode from order data	5715681012154
Scanned format	EAN_13

单件胶袋条形码

Barcode can be scanned	OK
Scanned barcode	5715681012161
Barcode from order data	
Scanned format	EAN_13

吊牌条形码

Barcode can be scanned	OK
Scanned barcode	5715681012161
Barcode from order data	
Scanned format	EAN_13




Hang tag 1



Hang tag 2 (with barcode sticker)




Hang tag 3



Hang tag 4




Tag 5



Hang tag 6



Tag 7



Tag 8



Hang tag 9




Main title



KS main label location: 2CM below the bag opening

3.3	Embroidery / Printing check
-----	-----------------------------

3.4	Lace / Trimming / Accessories check	OK
	The white fishing line securing the cherry ornament is secure. (Automatic translation)	



3.5	Workmanship
-----	-------------


3.6	Measurement	OK
	Bulk dimensions are acceptable. (Automatic translation)	

Measurement-OS	Specification	Tolerance	Actual
CHERRY PLACEMENT FROM TOP EDGE (cm)	2.50	-	2.5
CHERRY SIZE (cm)	0.00	-	0
2 x STRAP LENGTH (cm)	38.00	-	38.8
HEIGHT (cm)	14.00	-	14
STRAP WIDTH (cm)	2.00	-	2
WIDTH (cm)	14.00	-	14.5
DEPTH (cm)	6.00	-	6

4	On-site Test	
---	--------------	------------------------

4.1	Metal detection
-----	-----------------

4.2	Pull test	OK
	The manual tensile test is OK. (Automatic translation)	



4.3	Smell check	OK
	The artificial olfactory odor test was OK; there was no pungent odor, which is acceptable. (Automatic translation)	



4.4	Humidity check
-----	----------------

4.5	Garment weight (sweater only)	
4.6	Prove of color fastness test from supplier	OK
	The color fastness test on the bulk shipment showed no significant color fading after rubbing and wiping with a damp cloth, which is acceptable. (Automatic translation)	



4.7	The product is packed in poly bag or carton. Supplier can't send products without packaging.	OK
	The bulk goods were packaged correctly using cardboard boxes and plastic bags. (Automatic translation)	



Outer box shape



The box was opened.



Inner packaging of the box




Each box contains 8 Colli (8 Colli * 6 = 48 pieces)



Each Colli contains 6 items.


4.8	Sharp edges check	OK
	The workmanship and auxiliary materials of the bulk goods have no sharp corners or unevenness, which is acceptable. (Automatic translation)	



4.9	摔箱测试	OK
After the large shipment was dropped, the cartons and the goods inside were undamaged, which is acceptable. (Automatic translation)		



5	Pack and Packaging	
5.1	Approved sample/QA file available during inspection	OK
There are confirmation samples, orders, and packing lists provided by the factory. (Automatic translation)		



front

back

Order

Packing list (this column is unmarked)

5.2	Export carton (shipping mark, barcode)	OK
Barcode stickers are not required on the outer cartons. For cartons with a gross weight exceeding 15KG, the HEAVY logo must be affixed to the front (already affixed at the factory). (Automatic translation)		

Barcode can be scanned	
------------------------	--


Scanned barcode	
Barcode from order data	
Scanned format	



Outer box shape



Front box label



Side box markings

5.3	Export carton (dimension, weight)	OK
	Actual gross weight: 16.2KG (Automatic translation)	

	Specification	Tolerance	Actual
L	-	-	45
W	-	-	35
H	-	-	34.5
Gross Weight	-	-	16.2



45



Width 35




Height 34.5



Gross weight: 16.20KG (For orders exceeding 15KG, the HEAVY logo must be affixed to the front of the carton; the factory has already affixed it to all of them.)

5.4	Carton Packing (quantity, ratio etc), 3 ply carton	OK
	The quantity per carton is based on the packing list provided by the factory; each carton contains 8 Colli, and each Colli contains 6 pieces (8 Colli * 6 = 48 pieces). (Automatic translation)	



Packing list (this column is unmarked)



Outer box shape



The box was opened.



Inner packaging of the box



Each box contains 8 Colli (8 Colli * 6 = 48 pieces)



Each Colli contains 6 items.

5.5	Inner package (polybag, sticker, tissue paper, silica gel etc)	OK
	There is no copy paper or desiccant inside the plastic bag; each box contains 8 Colli, and each Colli contains 6 pieces (8 Colli * 6 = 48 pieces); the back of the plastic bag has a warning and an environmental protection symbol. (Automatic translation)	



The box was opened.



Inner packaging of the box



Each box contains 8 Colli (8 Colli * 6 = 48 pieces)



Colli plastic bag front



Back of Colli plastic bag



Each Colli contains 6 items.



front of individual plastic bag



Back of individual plastic bag



Colli plastic bags barcode stickers



The barcode sticker on each plastic bag matches the hangtag sticker.



Colli plastic bags have warnings and environmental protection logos on the back.



Each plastic bag has a warning and an environmental protection symbol on the back.

5.6	Hanger (quality, size etc)	
5.7	Header card	
5.8	Products are in polybags	OK
	The plastic bag packaging is correct. (Automatic translation)	



The box was opened.



Inner packaging of the box



Each box contains 8 Colli (8 Colli * 6 = 48 pieces)



Colli plastic bag front



Back of Colli plastic bag



Each Colli contains 6 items.



front of individual plastic bag



Back of individual plastic bag