Test Report

Report No.: CTT2507010794EN

Applicant: KONGES SLØJD A/S
Address: KUGLEGÅRDSVEJ 13-17, BUILDING 13, 1434 COPENHAGEN, DENMARK

Sample Received Date: Jul. 04, 2025
Testing Period: Jul. 04, 2025 - Jul. 05, 2025
Report Date: Jul. 05, 2025

The following merchandise was (were) submitted and identified on behalf of the applicant as:

Sample Name: TUT KITTY SHOULDER BAG – FRAPPE – 10 FASHION
Model No.: KS105193
P/O No.: WINTER25
Sample Color: FRAPPE
Supplier: 10 FASHION LEVEL TEN FASHION LIMITED
Exported to: US.
Country of Origin: China
Test Age Group: +3y
Age Group for testing: Children

Test Result(s): Please refer to next page(s).

Test Requested and Conclusion(s):

No.	Standard and Requirement	Conclusion(s)
1	Refer to US Public Law 110-314 [Consumer Product Safety Improvement Act of 2008(CPSIA) Sec. 101] and 15 U.S.C. § 1278a - Total Lead (Pb) in accessible substrate materials	PASS
2	Refer to California Proposition 65, Alameda Superior Court, Case No. RG-07-356892 - Lead	PASS

Signed for and on Behalf of CTT:

Tony Ye
Technical Manager

Verification Report

Test Result(s):

Total Lead (Pb) in accessible substrate materials - Refer to US Public Law 110-314 [Consumer Product Safety Improvement Act of 2008(CPSIA) Sec. 101] and 15 U.S.C. § 1278a

Method: CPSC-CH-E1002-08.3

Substances	Lead (Pb)	**Conclusion**
CAS No.	7439-92-1	
LOQ (mg/kg)	10	
Limit (mg/kg)	100	
Material No.	**Result (mg/kg)**	
1	N.D.	PASS
2	N.D.	PASS

NOTE: 1. mg/kg = milligram per kilogram (ppm).
2. N.D. = Not Detected (Less than LOQ, LOQ = Limit of Quantitation).

Test Result(s):

Lead - Refer to California Proposition 65, Alameda Superior Court, Case No. RG-07-356892

Substances	Lead (Pb)	**Conclusion**
CAS No.	7439-92-1	
LOQ (mg/kg)	10	
Limit (mg/kg)	100	
Material No.	**Result (mg/kg)**	
1D	N.D.	PASS
2D	N.D.	PASS

NOTE: 1. mg/kg = milligram per kilogram (ppm).
2. N.D. = Not Detected (Less than LOQ, LOQ = Limit of Quantitation).
3. "D" = The sample(s) is(are) tested according to the method CPSC-CH-E1002-08.3.

Test Material List

Material No.	Sample Description	Location
1	White fabric with white coating with glitter powder	Bag body
2	White fabric with glitter powder	Bag cover

Note: All testing materials were taken from components/raw materials.

Photo of Sample:



*** End of Report ***

This test report is issued by the company subject to its General Conditions of Services and accessible at http://www.cttlab.com/order/202103190908290166.pdf. The sample and sample information are provided by the applicant, our company are not responsible for their integrity and authenticity. Unless otherwise stated the results shown in this report only apply to the sample as received. Any inquiry

about this report, please raise from the date of receipt of the report within 30 days, overdue will not be accept. Without prior written permission of the company, this test report cannot be reproduced, except in full. Items marked with “n” means they are not accredited by CNAS (if with CNAS logo), “s” means the item of subcontractor. This report is only used for scientific research, teaching, internal quality control, not for domestic social impartiality proof data.