DryTech Restoration Inc. 2225 Skyway Drive Suite B Santa Maria, CA 93455 (805) 349-2700 License Number 789995 Tax I.D. Number 20-1664658 Insured: GUZMAN, ROSA

Claim #: 010929772

Policy #: CHO023957023



Picture 036

Date Taken: 10/30/2012

Taken By: Jason Hylton

Front view of the home.



Picture 037

Date Taken: 10/30/2012

Taken By: Jason Hylton

The insured pointed out that she found shingles on the ground in the backyard.

DryTech Restoration Inc. 2225 Skyway Drive Suite B Santa Maria, CA 93455 (805) 349-2700 License Number 789995 Tax I.D. Number 20-1664658 Insured: GUZMAN, ROSA

Claim #: 010929772

Policy #: CHO023957023



Picture 038

Date Taken: 10/30/2012
Taken By: Jason Hylton
Overview of the roof.



Picture 039

Date Taken: 10/30/2012
Taken By: Jason Hylton

Overview of the roof.

DryTech Restoration Inc. 2225 Skyway Drive Suite B Santa Maria, CA 93455 (805) 349-2700 License Number 789995 Tax I.D. Number 20-1664658 Insured: GUZMAN, ROSA

Claim #: 010929772


Policy #: CHO023957023



Picture 040

Date Taken: 10/30/2012 Taken By: Jason Hylton

Overview of the roof.



Picture 041

Date Taken: 10/30/2012

Taken By: Jason Hylton

Overview of the roof.

DryTech Restoration Inc. 2225 Skyway Drive Suite B Santa Maria, CA 93455 (805) 349-2700 License Number 789995 Tax I.D. Number 20-1664658 Insured: GUZMAN, ROSA

Claim #: 010929772


Policy #: CHO023957023



Picture 042

Date Taken: 10/30/2012
Taken By: Jason Hylton

Overview of the roof.



Picture 043

Date Taken: 10/30/2012

Taken By: Jason Hylton

Overview of the roof.

Photo Sheet - 4 - 10/30/2012

DryTech Restoration Inc. 2225 Skyway Drive Suite B Santa Maria, CA 93455 (805) 349-2700 License Number 789995 Tax I.D. Number 20-1664658 Insured: GUZMAN, ROSA

Claim #: 010929772

Policy #: CHO023957023



Picture 044

Date Taken: 10/30/2012
Taken By: Jason Hylton

The neighboring houses have relatively

newer roofs.



Picture 045


Date Taken: 10/30/2012 Taken By: Jason Hylton

The ridge cap is deteriorated.

DryTech Restoration Inc. 2225 Skyway Drive Suite B Santa Maria, CA 93455 (805) 349-2700 License Number 789995 Tax I.D. Number 20-1664658 Insured: GUZMAN, ROSA

Claim #: 010929772

Policy #: CHO023957023



Picture 046

Date Taken: 10/30/2012
Taken By: Jason Hylton
The ridge cap is deteriorated.



Picture 047

Date Taken: 10/30/2012
Taken By: Jason Hylton
The ridge cap is deteriorated.

DryTech Restoration Inc. 2225 Skyway Drive Suite B Santa Maria, CA 93455 (805) 349-2700 License Number 789995 Tax I.D. Number 20-1664658 Insured: GUZMAN, ROSA

Claim #: 010929772

Policy #: CHO023957023



Picture 048

Date Taken: 10/30/2012
Taken By: Jason Hylton
The ridge cap is deteriorated.



Picture 049

Date Taken: 10/30/2012
Taken By: Jason Hylton
The ridge cap is deteriorated.

DryTech Restoration Inc. 2225 Skyway Drive Suite B Santa Maria, CA 93455 (805) 349-2700 License Number 789995 Tax I.D. Number 20-1664658 Insured: GUZMAN, ROSA

Claim #: 010929772

Policy #: CHO023957023



Picture 050

Date Taken: 10/30/2012
Taken By: Jason Hylton
The ridge cap is deteriorated.



Picture 051

Date Taken: 10/30/2012

Taken By: Jason Hylton

The shingles are in poor condition with

the aggregate falling off.

DryTech Restoration Inc. 2225 Skyway Drive Suite B Santa Maria, CA 93455 (805) 349-2700 License Number 789995 Tax I.D. Number 20-1664658 Insured: GUZMAN, ROSA

Claim #: 010929772

Policy #: CHO023957023



Picture 052

Date Taken: 10/30/2012 Taken By: Jason Hylton

The shingles are in poor condition with

the aggregate falling off.



Picture 053

Date Taken: 10/30/2012
Taken By: Jason Hylton

The shingles show a 5.5 inch exposure.

DryTech Restoration Inc. 2225 Skyway Drive Suite B Santa Maria, CA 93455 (805) 349-2700 License Number 789995 Tax I.D. Number 20-1664658 Insured: GUZMAN, ROSA

Claim #: 010929772

Policy #: CHO023957023



Picture 054

Date Taken: 10/30/2012 Taken By: Jason Hylton

The shingles are in poor condition with the aggregate falling off.



Picture 055

Date Taken: 10/30/2012 Taken By: Jason Hylton

The closed valleys are generally free of

debris.

DryTech Restoration Inc. 2225 Skyway Drive Suite B Santa Maria, CA 93455 (805) 349-2700 License Number 789995 Tax I.D. Number 20-1664658 Insured: GUZMAN, ROSA

Claim #: 010929772

Policy #: CHO023957023



Picture 057

Date Taken: 10/30/2012 Taken By: Jason Hylton

One shingle appears to have lifted due to recent winds.



Picture 056

Date Taken: 10/30/2012 Taken By: Jason Hylton

One shingle appears to have lifted due to

recent winds.

Photo Sheet - 11 -10/30/2012

DryTech Restoration Inc. 2225 Skyway Drive Suite B Santa Maria, CA 93455 (805) 349-2700 License Number 789995 Tax I.D. Number 20-1664658 Insured: GUZMAN, ROSA

Claim #: 010929772

Policy #: CHO023957023



Picture 058

Date Taken: 10/30/2012 Taken By: Jason Hylton

There is a missing shingle on the front

elevation.



Picture 059

Date Taken: 10/30/2012
Taken By: Jason Hylton

There is a missing shingle on the front

elevation.

DryTech Restoration Inc. 2225 Skyway Drive Suite B Santa Maria, CA 93455 (805) 349-2700 License Number 789995 Tax I.D. Number 20-1664658 Insured: GUZMAN, ROSA

Claim #: 010929772

Policy #: CHO023957023



Picture 081

Date Taken: 10/30/2012 Taken By: Jason Hylton

View of an additional damaged shingle.



Picture 060

Date Taken: 10/30/2012

Taken By: Jason Hylton

There is a missing shingle on the front

elevation.

DryTech Restoration Inc. 2225 Skyway Drive Suite B Santa Maria, CA 93455 (805) 349-2700 License Number 789995 Tax I.D. Number 20-1664658 Insured: GUZMAN, ROSA

Claim #: 010929772

Policy #: CHO023957023



Picture 064

Date Taken: 10/30/2012
Taken By: Jason Hylton

Blown off sections of the ridge cap are found all over the roof. They are not

damaged by the wind.



Picture 065

Date Taken: 10/30/2012

Taken By: Jason Hylton

Blown off sections of the ridge cap are found all over the roof. They are not

damaged by the wind.

DryTech Restoration Inc. 2225 Skyway Drive Suite B Santa Maria, CA 93455 (805) 349-2700 License Number 789995 Tax I.D. Number 20-1664658 Insured: GUZMAN, ROSA

Claim #: 010929772

Policy #: CHO023957023



Picture 066

Date Taken: 10/30/2012 Taken By: Jason Hylton

Blown off sections of the ridge cap are found all over the roof. They are not

damaged by the wind.



Picture 067

Date Taken: 10/30/2012

Taken By: Jason Hylton

View of the chimney

DryTech Restoration Inc. 2225 Skyway Drive Suite B Santa Maria, CA 93455 (805) 349-2700 License Number 789995 Tax I.D. Number 20-1664658 Insured: GUZMAN, ROSA

Claim #: 010929772

Policy #: CHO023957023



Picture 068

Date Taken: 10/30/2012
Taken By: Jason Hylton
There is a crack in the crown.



Picture 069

Date Taken: 10/30/2012

Taken By: Jason Hylton

There is a crack in the crown.

DryTech Restoration Inc. 2225 Skyway Drive Suite B Santa Maria, CA 93455 (805) 349-2700 License Number 789995 Tax I.D. Number 20-1664658 Insured: GUZMAN, ROSA

Claim #: 010929772

Policy #: CHO023957023



Picture 071

Date Taken: 10/30/2012
Taken By: Jason Hylton



Picture 070

Date Taken: 10/30/2012

Taken By: Jason Hylton

The flashing needs maintenance.

DryTech Restoration Inc. 2225 Skyway Drive Suite B Santa Maria, CA 93455 (805) 349-2700 License Number 789995 Tax I.D. Number 20-1664658 Insured: GUZMAN, ROSA

Claim #: 010929772

Policy #: CHO023957023



Picture 072

Date Taken: 10/30/2012

Taken By: Jason Hylton

The flashing needs maintenance.



Picture 073

Date Taken: 10/30/2012

Taken By: Jason Hylton

The flashing needs maintenance.

DryTech Restoration Inc. 2225 Skyway Drive Suite B Santa Maria, CA 93455 (805) 349-2700 License Number 789995 Tax I.D. Number 20-1664658 Insured: GUZMAN, ROSA

Claim #: 010929772

Policy #: CHO023957023



Picture 074

Date Taken: 10/30/2012

Taken By: Jason Hylton

The flashing needs maintenance.



Picture 075

Date Taken: 10/30/2012

Taken By: Jason Hylton

The flashing needs maintenance.

Photo Sheet - 19 - 10/30/2012

DryTech Restoration Inc. 2225 Skyway Drive Suite B Santa Maria, CA 93455 (805) 349-2700 License Number 789995 Tax I.D. Number 20-1664658 Insured: GUZMAN, ROSA

Claim #: 010929772

Policy #: CHO023957023



Picture 076

Date Taken: 10/30/2012

Taken By: Jason Hylton

The flashing needs maintenance.



Picture 077

Date Taken: 10/30/2012

Taken By: Jason Hylton

The flashing needs maintenance.

DryTech Restoration Inc. 2225 Skyway Drive Suite B Santa Maria, CA 93455 (805) 349-2700 License Number 789995 Tax I.D. Number 20-1664658 Insured: GUZMAN, ROSA

Claim #: 010929772

Policy #: CHO023957023



Picture 078

Date Taken: 10/30/2012

Taken By: Jason Hylton

The flashing needs maintenance.



Picture 079

Date Taken: 10/30/2012

Taken By: Jason Hylton

The flashing needs maintenance.

Photo Sheet - 21 - 10/30/2012

DryTech Restoration Inc. 2225 Skyway Drive Suite B Santa Maria, CA 93455 (805) 349-2700 License Number 789995 Tax I.D. Number 20-1664658 Insured: GUZMAN, ROSA

Claim #: 010929772

Policy #: CHO023957023



Picture 080

Date Taken: 10/30/2012

Taken By: Jason Hylton

The flashing needs maintenance.

Photo Sheet - 22 - 10/30/2012