
Variant-calling errors by long-read polishing



**Figure S3**: Variant-calling errors, before and after Medaka polishing, for each of the long-read assembly methods.