



Outlook

**[External] FW: 62T8602 (90393801 & 90393801) - CARTON INCIDENT// BUYER - CASUAL BOYS & TODDLER SS26**

**From** Ameek Hassan <ameek@ntg.com.bd>

**Date** Thu 11/13/2025 12:42 PM

**To** Inspectioneci Bgd Intertek <inspectioneci.bgd@intertek.com>

**Cc** 'Shayem' <shayem@ntg.com.bd>; 'MAHBUBUR RAHMAN' <mahbubur.ecidhaka@elcorteingles.es>; falgpq1@ntg.com.bd <falgpq1@ntg.com.bd>; 'falpco' <falpco@ntg.com.bd>; 'fal.packing' <fal.packing@ntg.com.bd>; 'Ariful Islam' <arifulislam@ntg.com.bd>; amit.sajib@ntg.com.bd <amit.sajib@ntg.com.bd>; 'Ikbal' <ikbal@ntg.com.bd>

📎 1 attachment (10 KB)

62T8602 - 90393801 & 90393801 - CARTON INCIDENT.XLSX;

Dear Mr. Minhaj,

Please find the attached carton incident and below approval mail for your reference.



Best Regards,  
**Ameek Hassan**  
 Executive, (M&M)  
 Fashion Asia Limited

Head Office: Gopalpur, Munnu Nagar, Tongi, Gazipur,  
 Factory: Tepirbari, Sreepur, Gazipur  
 Mobile: 01810157698, e-mail: [ameek@ntg.com.bd](mailto:ameek@ntg.com.bd),  
[www.ntg.com.bd](http://www.ntg.com.bd) [[ntg.com.bd](http://ntg.com.bd)]

**From:** FAZILATUNNES KAKON [mailto:[shipping.ecidhaka@elcorteingles.es](mailto:shipping.ecidhaka@elcorteingles.es)]

**Sent:** Thursday, November 13, 2025 12:20 PM

**To:** Ameek Hassan

**Cc:** 'Shayem'; MAHBUBUR RAHMAN; 'Ariful Islam'; amit.sajib@ntg.com.bd; MARK AMIT GOMES

**Subject:** Re: 62T8602 (90393801 & 90393801) - CARTON INCIDENT// BUYER - CASUAL BOYS & TODDLER SS26

Dear Mr. Ameek,

Reported carton/s incidence out of standard, is exceptionally ACCEPTED on this occasion. However, remember that it is mandatory to follow our policy and be very aware that the packing zero tolerance policy will be implement very shortly. We kindly ask you to find solution now for your future order out of the allowed range.

**Thanks & Best Regards**

**FAZILATUN NESA KAKON**

-Supply Chain & Commercial Manager-

In charge of Shipping, Trims & Commercial

**El Corte Inglés S.A. Liaison Office Bangladesh**

Gulshan Center Point,

9th Floor, House No-23-26, Road No-90

Gulshan 2- Dhaka-1212. - Bangladesh

Phone: +88 09678431400 Ext. 300 / Mob.: +88 01824991890

E-Mail: [shipping.ecidhaka@elcorteingles.es](mailto:shipping.ecidhaka@elcorteingles.es)

[www.elcorteingles.es](http://www.elcorteingles.es) [[elcorteingles.es](http://elcorteingles.es)]

**From:** Ameek Hassan <[ameek@ntg.com.bd](mailto:ameek@ntg.com.bd)>

**Sent:** 12 November 2025 13:24

**To:** FAZILATUNNES KAKON <[shipping.ecidhaka@elcorteingles.es](mailto:shipping.ecidhaka@elcorteingles.es)>

**Cc:** 'Shayem' <[shayem@ntg.com.bd](mailto:shayem@ntg.com.bd)>; MAHBUBUR RAHMAN <[mahbubur.ecidhaka@elcorteingles.es](mailto:mahbubur.ecidhaka@elcorteingles.es)>; 'Ariful Islam' <[arifulislam@ntg.com.bd](mailto:arifulislam@ntg.com.bd)>; [amit.sajib@ntg.com.bd](mailto:amit.sajib@ntg.com.bd) <[amit.sajib@ntg.com.bd](mailto:amit.sajib@ntg.com.bd)>; MARK AMIT GOMES <[shipping03.ecidhaka@elcorteingles.es](mailto:shipping03.ecidhaka@elcorteingles.es)>

**Subject:** 62T8602 (90393801 & 90393801) - CARTON INCIDENT// BUYER - CASUAL BOYS & TODDLER SS26

Dear Mrs. Kakon

Greetings and hope you are having a good day.

Please find the attached carton incident for below Style & PO.

Kindly advise us further.

**Style – 62T8602**

**Dept. – 672**

**PO – 90393800**



Best Regards,  
**Ameek Hassan**  
 Executive, (M&M)  
 Fashion Asia Limited

Head Office: Gopalpur, Munnu Nagar, Tongi, Gazipur,  
 Factory: Tepirbari, Sreepur, Gazipur  
 Mobile: 01810157698, e-mail: [ameek@ntg.com.bd](mailto:ameek@ntg.com.bd),  
[www.ntg.com.bd](http://www.ntg.com.bd) [[ntg.com.bd](http://ntg.com.bd)]

Este mensaje, y en su caso, cualquier fichero anexo al mismo, puede contener información confidencial, siendo para uso exclusivo del destinatario, quedando prohibida su divulgación copia o distribución a terceros sin la autorización expresa del remitente. Si Vd. ha recibido este mensaje erróneamente, se ruega lo notifique al remitente y proceda a su borrado.

Gracias por su colaboración.

This message (including any attachments) may contain confidential information. It is intended for use by the recipient only. Any dissemination, copying or distribution to third parties without the express consent of the sender is strictly prohibited. If you have received this message in error, please delete it immediately and notify the sender.

Thank you for your collaboration.

Esta mensagem e, quando aplicável, qualquer anexo à mesma, pode conter informações confidenciais, sendo de uso exclusivo do destinatário, sendo proibida a sua cópia e divulgação ou distribuição a terceiros sem a autorização expressa do remetente. Se recebeu esta mensagem por equívoco, notifique o remetente e apague-a de imediato.

Obrigado pela sua colaboração.

11/13/25, 12:56 PM

[External] FW: 62T8602 (90393801 & 90393801) - CARTON INCIDENT// BUYER - CASUAL BOYS & TODDLER SS26 - Md Khai...

This message is from an EXTERNAL SENDER - please be CAUTIOUS, particularly with links and attachments.

**INSPECTION REPORT**

REPORT NUMBER: B12

REPORT DATE: 08-07-2025

PAGE: 6




Barcode 1




Barcode 2



Barcode 3



Barcode 4



Barcode 5



Barcode 6

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

**INSPECTION REPORT**

REPORT NUMBER: B12

REPORT DATE: 08-07-2025

PAGE: 7



Barcode 1



Barcode 2



Barcode 3



Barcode 4


The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

**INSPECTION REPORT**


REPORT NUMBER: B12

REPORT DATE: 08-07-2025

PAGE: 8



Barcode 31



Barcode 32

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

**INSPECTION REPORT**

REPORT NUMBER: B12

REPORT DATE: 08-07-2025

PAGE: 9



Barcode 1



Barcode 2

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

**Barcode**

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

PLEASE TYPE OR PRINT IN BLOCK LETTERS AND USE ONE INSPECTION REPORT PER INSPECTION

**1. GENERAL**

Inspection No.	INS-461297	Inspection Report Date	13.11.2025
Inspection Begin Date	12.11.2025	Inspection End Date	12.11.2025

To:	From: ITS LABTEST BANGLADESH LTD.
Email:	E-mail:

Inspection Partner	ITS LABTEST BANGLADESH LTD	Product family photo	
Inspection Partner File No.	<b>INS-461297</b>		
Inspection Partner Office	BANGLADESH		
Client	EL CORTE INGLES S.A.		
GECI Company	ECI		
GECI Office	BANGLADESH		
GECI BDM Name	MR. AKHTERUZZAMAN KHAN		
Category Manager Name	N/A		
GECI Merchandiser Name	MR. MINARUL ISLAM		
GECI QCM Name	MR. MAMUN UR RASHID		
GECI Department No.	0899		
Vendor	TEXEBO INTERNATIONAL PTE LTD.		
Factory	MATRIX STYLES LTD.		
Inspection Location City	NATIONAL UNIVERSITY, DEGER CHALA ROAD, GAZIPUR		
Inspection Location Country	BANGLADESH		
Previous inspection No. (only for RE-FRI)	<b>N/A</b>		
Style No.	<b>61B6414 + 61B6417</b>	Size	006+009+012+018+024+036
Product Type	GARMENT	Color	100 MX BLANCO + 100 MX BLANCO
Product description	CAMISETA GATITO PATCH + CAMISETA PAJARITO CON BORDADO		
P.O. No.	<b>90309701</b>	Service requested	FRI
PO#, Actual inspected No. of style / Total No. of Styles on PO	02 STYLES, 01 PO		
Combined sampling	YES	Inspection booking date (if needed)	05-11-25
Comments on Lab Test Report	<input checked="" type="checkbox"/> Pass (2025CI3568 + 25FM003218 = PASS) <input type="checkbox"/> Accepted by ECI <input type="checkbox"/> No Pass <input type="checkbox"/> N/A		

**Note:** When more than one option per field is possible, write them separately by a slash. (For example, for different P.O. No. write: PO1 / PO2 / PO3).

<b>OVERALL INSPECTION REPORT RESULT</b>	<b>PASS</b>
---	-------------

ITS Labtest Bangladesh Ltd.

Haidar Tower, House # 668, Choydana, Ward # 34, Gazipur City Corporation, Gazipur-1704, Bangladesh

Tel: +88 0966 677 6669

Web: [www.intertek.com](http://www.intertek.com)

**2. QUANTITY**

**Note:** When combined sampling, write the different style numbers in the same raw and the different quantities for each one.

Style No.	PO No.	Order Qty. (PCS)	Shipment Qty. (PCS)	Presented Qty. for inspection		Inspection Qty.			
				Units/ PCS	%	Packed		Not packed	
						Units/ PCS	%	Cartons	Units
61B6414	90309701	810	810	810	100	810	100	5	-
61B6417		620	620	620	100	620	100	4	
Total		1430	1430	1430	100	1430	100	9	-

Samples selected from carton numbers:	PO NO.	CARTON NO.
	90309701	1,2,3,4,5,6,7,8,9 = 9 CARTONS
	Total number of cartons opened for sampling:	

No. of re-packed cartons identified by stamps / closing tape:	01 OUT OF 9 SELECTED CARTONS WERE SEALED AFTER INSPECTION, REST OF THE SELECTED CARTONS WERE NOT SEALED AFTER INSPECTION BECAUSE THE FACTORY DID NOT REPACK THEM IMMEDIATELY.
---	---

Quantity remarks	N/A
------------------	-----

**3. INSPECTION RESULT SUMMARY**

**Note:** When combined sampling, write the different style numbers in the same raw and then its general result.

Style No.	Inspection Result	Fail Reason Write one option: PASS/ FAIL/ PENDING/ NOT APPLICABLE (N/A)						
		Quantity	Workman ship	Packing	Shipping Marks	Data measurements & Tests	Style/ Color conformity	REMARK
61B6414	PASS	PASS	PASS	PASS	PASS	PASS	PASS	-
61B6417	PASS	PASS	PASS	PASS	PASS	PASS	PASS	-

**PROBLEM REMARK:**

Inspection starting time: 10.00 AM	Inspection ending time: 03.20 PM
Inspector: ABUL HASNAT	Vendor/ Factory representative: MR. ANIS
AUTHORIZED BY,	
 Monir Hossain Head of Inspection, Softlines	

**4. INSPECTION CRITERIA****INSPECTION REPORT**

INS-461297

Golden sample	YES
GECI instruction/specification	YES
Completed QC File	YES
Other	

**5.1 WORKMANSHIP****Appearance and functional inspection findings (including labels & hangtags findings)**

**Note:** Use a table per style. Only in case of combined sampling, a table can be used for different styles.

Inspection method applied										
ANSI/ASQ Z1.4-2008, Single sampling plans for normal inspection						Level:	II			
Acceptable Quality Limit (AQL) for			Critical :	0	Major:	2.5	Minor:	4.0		
Sample size:		80 PCS								
Style No.	PO No.	Colors	Sample size	Code No.	Description			C M M		
61B6414	90309701	100 MX BLANCO	80	GW099	PUCKERING AT NECK (OBVIOUSLY)			- 01 -		
				GW074	BROKEN STITCH AT BOTTOM HEM (1CM)			- 01 -		
				GW009	DAMAGE AT FRONT EMBROIDERY AREA (OBVIOUSLY)			- 01 -		
				GW035	DIRTY SPOT AT FRONT (OBVIOUSLY)			- 01 -		
				GW111	LOOSENESS AT ARM HOLE (SLIGHTLY)			- - 01		
				GW064	POOR IRON AT SLEEVE, NECK (SLIGHTLY)			- - 02		
				GW101	TWISTED AT SIDE SEAM (SLIGHTLY)			- - 01		
				GW110	UNEVEN AT BOTTOM HEM (SLIGHTLY)			- - 01		
			TOTAL	80 PCS	Total defects			00 04 05		
							Maximum allowed	00 05 07		
							WORKMANSHIP RESULT	PASS		
Workmanship remarks										
Other defects observed but not counted in the AQL result:										

**5.2 WORKMANSHIP:**

Inspection method applied												
ANSI/ASQ Z1.4-2008, Single sampling plans for normal inspection						Level:	II					
Acceptable Quality Limit (AQL) for			Critical	0	Major:	2.5	Minor:	4.0				
Sample size:		80 PCS										
Style No.	PO No.	Colors	Sample size	Code No.	Description			C M M				
61B6417	90309701	100 MX BLANCO	80	GW076	SKIP STITCH AT BOTTOM HEM (0.7CM)			- 01 -				
				GW074	BROKEN STITCH AT SLEEVE RUFFLE (1CM)			- 01 -				
				GW009	DAMAGE AT MAIN LABEL ATTACH AREA (OBVIOUSLY)			- 01 -				
				GW099	PUCKERING AT NECK (SLIGHTLY)			- - 01				
				GW110	UNEVEN AT BOTTOM HEM (SLIGHTLY)			- - 01				
				GW064	POOR IRON AT SLEEVE RUFFLE AREA (SLIGHTLY)			- - 01				
				GW064	POOR IRON AT ARM HOLE (SLIGHTLY)			- - 01				
				GW035	DIRTY SPOT AT SLEEVE, BACK (SLIGHTLY)			- - 02				
		<b>TOTAL</b>	<b>80 PCS</b>				<b>Total defects</b>	<b>00 03 06</b>				
								<b>Maximum allowed</b>				
								<b>PASS</b>				

Workmanship remarks	
Other defects observed but not counted in the AQL result:	

**6. PACKING**

**Note:** Use a table per style. Only in case of combined sampling or when the same features are found for all styles, one table can be used for different styles.

Style No.: <b>61B6414 + 61B6417</b>	P.O. <b>90309701</b>
<b>6.1. Carton conformity</b>	CONFORM
Carton dimension found: L x W x H = 60 X 40 X 25 cm (maximum).	CONFORM
Carton weight found: 10.87 kgs (maximum).	CONFORM
Remarks:	
<b>6.2. Packaging</b>	
A. Individual packing conformity (plastic bags, inner box, alarms, etc.)	CONFORM
Remarks: 1. DURING INSPECTION PACKING SAMPLE WAS NOT AVAILABLE IN QA FOLDER, AFTER INSPECTON 1 PC PACKING SAMPLE KEPT IN QA FOLDER FOR CLIENT EVALUATION.	
B. Assortment	CONFORM
Assortment checked on 9 Cartons.	
Remarks:	
<b>PACKING RESULT</b>	
<b>PASS</b>	

**7. SHIPPING MARKS**

**Note:** Use a table per style. Only in case of combined sampling or when the same features are found for all styles, one table can be used for different styles.

Style No.: <b>61B6414 + 61B6417</b>	P.O. <b>90309701</b>
<b>7.1. Side labels conformity</b>	CONFORM
Remarks:	
<b>7.2. Shipping marks conformity</b>	CONFORM
Remarks:	
<b>SHIPPING MARK RESULT</b>	
<b>PASS</b>	

**8. DATA MEASUREMENTS & TESTS**

<b>8.1. Data measurements</b>		<b>WITHIN TOLERANCE</b>		
Sample size for data measurement		13 + 13 = 26 PCS		
Style	Size	Color	Sample size	Result
<b>61B6414 + 61B6417</b>		ALL	ALL	26 PCS
Remarks:				
<i>Please, see the attached size measurement sheet.</i>				

**8.2. Tests**

**CONFORM**

Style No.: **61B6414 + 61B6417**

PO: **90309701**

#	Test		Findings/Remarks					Result
	Garment Weight		STYLE	COLOR	FOUND (GSM)	%	REQUIRED (GSM)	
#	Sample size	04 PCS	<b>61B6414</b>	100 MX BLANCO	148/150	-1.33% / 0%	<b>150</b>	<b>CONFORM</b>
			<b>61B6417</b>	100 MX BLANCO	146/147	-2.66 %/ -2.0%		
	Test performed with factory equipment?		<input checked="" type="checkbox"/> Yes		<input type="checkbox"/> No			
If factory equipment used, calibration record			<input type="checkbox"/> Yes, period:		<input checked="" type="checkbox"/> No			

#	Test		Findings/Remarks					Result
	BARCODE		POLY STICKER BARCODE WAS FOUND: EAN-13 HANGTAG BARCODE WAS FOUND: EAN-13 CNC LABEL BARCODE WAS FOUND: EAN-13 PRE-PACK STICKER BARCODE WAS FOUND: CODE-128					
#	Sample size	13 + 13 = 26 PCS	<input type="checkbox"/> Yes		<input checked="" type="checkbox"/> No			<b>CONFORM</b>
	Test performed with factory equipment?		<input type="checkbox"/> Yes		<input checked="" type="checkbox"/> No			
	If factory equipment used, calibration record		<input type="checkbox"/> Yes, period:		<input type="checkbox"/> No			

#	Test		Findings/Remarks					Result
	METAL DETECTION							
#	Sample size	80+80 = 160PCS	<input type="checkbox"/> Yes		<input checked="" type="checkbox"/> No			<b>CONFORM</b>
	Test performed with factory equipment?		<input type="checkbox"/> Yes		<input checked="" type="checkbox"/> No			
	If factory equipment used, calibration record		<input type="checkbox"/> Yes, period:		<input checked="" type="checkbox"/> No			

#	Test		Findings/Remarks					Result
	MOISTURE CHECK		COLOR NAME	COMPOSITION		MOISTURE % CENTESIMAL FOUND (Max)	Aqua-Boy Standard Centesimal Value on Moisture Content (%) Required	
#	Sample size	13+13= 26 PCS		<b>61B6414</b> (100 MX BLANCO)	100% COTTON	35%	65%	<b>CONFORM</b>
				<b>61B6417</b> (100 MX BLANCO)	100% COTTON	22%	65%	
	Test performed with factory equipment?		<input checked="" type="checkbox"/> Yes		<input type="checkbox"/> No			

ITS Labtest Bangladesh Ltd.

Haidar Tower, House # 668, Choydana, Ward # 34, Gazipur City Corporation, Gazipur-1704, Bangladesh

Tel: +88 0966 677 6669

Web: [www.intertek.com](http://www.intertek.com)

	If factory equipment used, calibration record		<input type="checkbox"/> Yes, period:	<input checked="" type="checkbox"/> No		
#	Test		Findings/Remarks		Result	
	ALARM WORKING TEST			N/A		NOT APPLICABLE
	Sample size	N/A				
	Test performed with factory equipment?		<input type="checkbox"/> Yes			
	If factory equipment used, calibration record		<input type="checkbox"/> Yes, period:	<input type="checkbox"/> No		
#	Test		Findings/Remarks		Result	
	PULL TEST			N/A		NOT APPLICABLE
	Sample size	N/A				
	Test performed with factory equipment?		<input type="checkbox"/> Yes			
	If factory equipment used, calibration record		<input type="checkbox"/> Yes, period:	<input type="checkbox"/> No		
#	Test		Findings/Remarks		Result	
	PEEL OF TEST			N/A		NOT APPLICABLE
	Sample size	N/A				
	Test performed with factory equipment?		<input type="checkbox"/> Yes			
	If factory equipment used, calibration record		<input type="checkbox"/> Yes, period:	<input type="checkbox"/> No		
#	Test		Findings/Remarks		Result	
	ZIPPER CHECK			N/A		NOT APPLICABLE
	Sample size	N/A				
	Test performed with factory equipment?		<input type="checkbox"/> Yes			
	If factory equipment used, calibration record		<input type="checkbox"/> Yes, period:	<input type="checkbox"/> No		
DATA MEASUREMENTS & TESTS RESULT				PASS		

GRUPO

**9. STYLE/COLOR CONFORMITY****INSPECTION REPORT**

INS-461297

  
Total Quality. Assured.

**Note:** Use a table per style. Only in case of combined sampling, a table can be used for different styles.

Style No.: <b>61B6414 + 61B6417</b>	P.O. <b>90309701</b>		
<b>9.1. Style conformity</b>	CONFORM		
Remarks:			
<b>9.2. Material conformity (hand feeling)</b>	CONFORM		
Remarks:			
<b>9.3. Color conformity</b>	CONFORM		
6. FOUND LOT WISE COLOR SHADE VARIATION AS BELOW:			
COLOR	SHADE A	SHADE B	REMARKS
<b>61B6414</b> (100 MX BLANCO)	100% SELECTED SAMPLES SIMILAR WITH APPROVED PP SAMPLE.	N/A	IMAGE#01
<b>61B6417</b> (100 MX BLANCO)	100% SELECTED SAMPLES SIMILAR WITH APPROVED PP SAMPLE.	N/A	IMAGE#02
GREY SCALE EVALUATION DONE BASED ON AATCC GREY SCALE UNDER INSPECTION ROOM LIGHT ON SITE.			
<b>STYLE/COLOR CONFORMITY RESULT</b>			
<b>PASS</b>			

**10. NOTE**

Any problems found during inspection but accepted by merchandiser and QC manager from ECI.

Remarks: DURING INSPECTION 100% INSPECTED SAMPLE PRICES WERE FOUND \$ 179 WHICH WAS SIMILAR WITH APPROVED TRIMS CARD, BUT PO SHEET SHOWN PRICE 7.40
--

Production/ Defective sample(s) will be sent to GECI for reference by the Inspection Agency.

Style No.	Color	Size	Defect / Information	Total Quantity
<b>61B6414 + 61B6417</b>	ALL	ALL	MAJOR-07 PCS+GSM CUT GARMENTS - 02 PCS	09 PCS

Production/ Defective sample(s) to be kept at Inspection Agency for reference.

Style No.	Color	Size	Defect / Information	Quantity
<b>61B6417</b>	100 MX BLANCO	024	REFERENCE SAMPLE	01 PIECE

01 carton out of 09 selected cartons were sealed after inspection, rest of the selected cartons were not sealed after inspection because the factory did not repack them immediately.

ITS Labtest Bangladesh Ltd.

Haidar Tower, House # 668, Choydana, Ward # 34, Gazipur City Corporation, Gazipur-1704, Bangladesh

Tel: +88 0966 677 6669


Web: [www.intertek.com](http://www.intertek.com)

**11. INSPECTION ENVIRONMENT**

Lighting	<input type="checkbox"/> Day light	<input checked="" type="checkbox"/> Room lighting	<input type="checkbox"/> Sufficient	<input type="checkbox"/> Insufficient
Inspection place	<input type="checkbox"/> Warehouse	<input type="checkbox"/> Factory workshop	<input checked="" type="checkbox"/> Other: INSPECTION ROOM	
Inspection done on	<input checked="" type="checkbox"/> Table	<input type="checkbox"/> Other:		
Cleanliness	<input checked="" type="checkbox"/> Clean	<input type="checkbox"/> Dirty	<input type="checkbox"/> Other:	
Weather condition	<input type="checkbox"/> Rainy	<input checked="" type="checkbox"/> Dry	<input type="checkbox"/> Other:	
Observations				

**Disclaimer:**

"This report is for the exclusive use of the client of Intertek named in this report ("Client") and is provided pursuant to an agreement for services between Intertek and Client ("Client Agreement"). No other person may rely on the terms of this report. This report provides a summary of the findings and other applicable information found/gathered during the audit conducted at the specified facilities on the specified date only. Therefore, this report does not cover, and Intertek accepts no responsibility for, other locations that may be used in the supply chain of the relevant product or service. Further, as the audit process used by Intertek is a sampling exercise only, Intertek accepts no responsibility for any non-compliant issues that may be revealed relating to the operations of the identified facility at any other date. Intertek's responsibility and liability are also limited in accordance to the terms and conditions of the Client Agreement. Intertek assumes no liability to any party, for any loss, expense or damage occasioned by the use of this information other than to the Client and in accordance with the Client Agreement and these disclaimers. In case there is any conflict between the disclaimers stated herein and the applicable terms and conditions of Intertek incorporated into the Client Agreement, then these disclaimers shall prevail."



Shipping mark sticker



Broken stitch (M)

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

**Fabric hole at neck (M)**

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

ITS Labtest Bangladesh Ltd., Haidar Tower, House # 668, Choydana, Ward # 34, Gazipur City Corporation, Gazipur-1704, Bangladesh  
Tel: +88 0966 677 6669, Web: [www.intertek.com](http://www.intertek.com)



The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.