


VIEW FROM UPWIND (spinner and nose frame removed)



SECTION THROUGH BLADE 1 AXIS



AXONOMETRIC VIEW (not to scale)



NOTES

1. Necks Ø360 × 10 on the Ø530 × 10 shell: parked SLM stress 117 MPa (allow 323); fatigue 31.5 MPa (allow 42.1).
2. Neck flanges Ø430 × 25 carry the pitch bearing outer rings: 20 × M16 tapped on PCD 360; faces machined after stress relief, flat 0.05, square to the neck axis 0.05.
3. Rear gussets stop on the drum flange ring (x 200) so they clear the drum web; front gussets 68 long. Full penetration welds ISO 5817 B, 100 % MT, UT on neck welds.
4. Drum joint as Rev C: Ø360 spigot, 12 × M16 10.9 PCD 400, 280 Nm. FE check of the neck-to-shell weld before release (doc 37 §9).

Dimensions mm · ISO 2768-mK · ISO 8015 · first angle projection · edges broken 0.5 unles eview

12 kW WIND TURBINE M8 (ICELAND) · Ø8.0 m, COLLECTIVE PITCH · 8 m TOWER

HUB WELDMENT (COLLECTIVE PITCH)

DRAWING NO.	REV / DATE	SCALE (A3)
NM8-200	A · 2026-11-06	1:8
MATERIAL	**MASS (CALC.)**	**DRAWN / CHECKED**
S355NL, welded, stress relieved, machined	180 kg (budget)	Claude / not checked