Situation report — Trishuli / Bhote Koshi corridor, Nepal (26 Aug 2026 flood)

Flood date: 2026-08-25 22:00 UTC · analysed area 3,334 km² at 20 m · detector: AI flood-segmentation model (flood_unet.onnx) · radar tracks: RO85 (2026-08-16→2026-08-28), RO19 (2026-08-24→2026-09-05) · Sentinel-2 cloud-free overlap 7% of the area

1,364 ha
flooded or debris-covered
61 ha water · 1,303 ha debris/scour

2,610
buildings affected
of 74,869 mapped · 1,984 likely destroyed · 1,123 exposed nearby

67.5 km
road hit · 33/151 bridges
10.6 of 181.4 km primary road

126
settlements cut off
164 with a longer route · 778 still connected · 7,641 buildings in cut-off settlements

Who is cut off (road connection to nearest hospital/town lost)


Settlement	Buildings	Route before	Was served by
Unnamed settlement #664 (near नुवाकोट, 2.3 km)	391	1.23 km	Trishuli Hospital
गोल्जुङ	275	27.47 km	Rasuwa District Hospital
स्याप्रु बेसी	272	15.16 km	Rasuwa District Hospital
डाँडागाउँ	246	10.8 km	hospital (unnamed)
भैंसे	219	2.85 km	clinic (unnamed)
Unnamed settlement #663 (near बटार बजार, 2.9 km)	208	1.3 km	Trishuli Hospital
टिमुरे	197	26.4 km	Rasuwa District Hospital
Unnamed settlement #687 (near भैंसे, 0.8 km)	186	2.34 km	clinic (unnamed)

Longer route only: 164 settlements; largest: village (unnamed) (331 buildings, route now 2.7x longer); Unnamed settlement #294 (near रातमाटे, 2.1 km) (257 buildings, route now 1.5x longer); लिखु (252 buildings, route now 2.9x longer); Unnamed settlement #538 (near चौघडा, 1.6 km) (230 buildings, route now 1.9x longer); Unnamed settlement #552 (near चौघडा, 1.0 km) (228 buildings, route now 2.5x longer).

Downstream flood path: traced 90.11 km from the chosen upstream point; settlements in the susceptible corridor, in downstream order: Unnamed settlement #882 (near पाजुङ, 1.5 km) (8.28 km), Unnamed settlement #876 (near स्याप्रु बेसी, 0.8 km) (9.93 km), स्याप्रु बेसी (10.83 km), Unnamed settlement #849 (near गोगने, 0.8 km) (26.67 km), मैलुङ (29.35 km), Unnamed settlement #770 (near चिप्लेटी, 1.0 km) (31.41 km), Unnamed settlement #769 (near चिप्लेटी, 1.4 km) (32.26 km), Unnamed settlement #791 (near डाँडागाउँ, 1.5 km) (33.0 km), Unnamed settlement #822 (near डाँडागाउँ, 0.6 km) (34.07 km), Unnamed settlement #815 (near शान्ति बजार, 1.1 km) (38.39 km).

How reliable is this?

Two-track agreement covers 523 ha. Radar sees through cloud but cannot tell debris from other rough change with certainty; roads are blocked only if the mapped road (as of 2026-07-27) crosses the detected area, so unmapped roads, bridges that survived inside the mask and smaller-than-pixel damage are not captured. Satellites revisit every few days: this describes the scene as of the post-event pass, not the situation now. Verify before acting.



Educational prototype – not an operational tool. Satellite-derived estimates carry uncertainty; verify on the ground before acting.

Contains modified Copernicus Sentinel data 2026. Produced using Copernicus WorldDEM-30 © DLR e.V. 2010–2014 and © Airbus Defence and Space GmbH 2014–2018 provided under COPERNICUS by the European Union and ESA; all rights reserved. © OpenStreetMap contributors. Training data: Kuro Siwo – Bountos et al., NeurIPS 2024 Datasets & Benchmarks (CC BY). OSM snapshot: 2026-07-27 (pre-event). Generated automatically from the system's maps; no value is produced by a language model. Educational prototype – not an operational tool. Satellite-derived estimates carry uncertainty; verify on the ground before acting.

स्थिति प्रतिवेदन — Trishuli / Bhote Koshi corridor, Nepal (26 Aug 2026 flood)

बाढीको मिति: २०२६-०८-२५ २२:०० UTC · विश्लेषण गरिएको क्षेत्र ३३३४ वर्ग कि.मी. (२० मिटर विभेदन)

१३६४ हेक्टर
बाढी वा भग्नावशेषले ढाकेको
पानी ६१ हे. · भग्नावशेष/कटान १३०३ हे.

२६१०
प्रभावित भवन
नक्साङ्कित ७४८६९ मध्ये · पूर्ण क्षति हुन सक्ने १९८४ · नजिकै जोखिममा ११२३

६७.४६ कि.मी.
सडक प्रभावित · पुल ३३/१५१
मुख्य सडक १०.६ / १८१.३६ कि.मी.

१२६
सडक सम्पर्क टुटेका बस्ती
बाटो लामो भएका १६४ · सम्पर्क कायमै ७७८ · सम्पर्क टुटेका बस्तीमा भवन ७६४१


को को टाढा परेका छन् (नजिकको अस्पताल/सहरसँगको सडक सम्पर्क गुमेका)

बस्ती	भवन	पहिलेको दूरी	पहिले सेवा दिने ठाउँ
नाम नखुलेको बस्ती #६६४ (नुवाकोट नजिक, २.३ कि.मी.)	३९१	१.२३ कि.मी.	Trishuli Hospital
गोल्जुङ	२७५	२७.४७ कि.मी.	Rasuwa District Hospital
स्याप्रु बेसी	२७२	१५.१६ कि.मी.	Rasuwa District Hospital
डाँडागाउँ	२४६	१०.८ कि.मी.	अस्पताल (नाम नखुलेको)
भैंसे	२१९	२.८५ कि.मी.	क्लिनिक (नाम नखुलेको)
नाम नखुलेको बस्ती #६६३ (बटार बजार नजिक, २.९ कि.मी.)	२०८	१.३ कि.मी.	Trishuli Hospital
टिमुरे	१९७	२६.४ कि.मी.	Rasuwa District Hospital
नाम नखुलेको बस्ती #६८७ (भैंसे नजिक, ०.८ कि.मी.)	१८६	२.३४ कि.मी.	क्लिनिक (नाम नखुलेको)

बाढी बगेको बाटो (तल्लो भागतर्फ): ९०.११ कि.मी. पत्ता लगाइयो; जोखिमयुक्त करिडोरका बस्तीहरू (तलतल्लिर क्रमबद्ध): नाम नखुलेको बस्ती #८८२ (पाजुङ नजिक, १.५ कि.मी.) (८.२८ कि.मी.), नाम नखुलेको बस्ती #८७६ (स्याप्रु बेसी नजिक, ०.८ कि.मी.) (९.९३ कि.मी.), स्याप्रु बेसी (१०.८३ कि.मी.), नाम नखुलेको बस्ती #८४९ (गोगने नजिक, ०.८ कि.मी.) (२६.६७ कि.मी.), मैलुङ (२९.३५ कि.मी.), नाम नखुलेको बस्ती #७७० (चिप्लेटी नजिक, १.० कि.मी.) (३१.४१ कि.मी.), नाम नखुलेको बस्ती #७६९ (चिप्लेटी नजिक, १.४ कि.मी.) (३२.२६ कि.मी.), नाम नखुलेको बस्ती #७९१ (डाँडागाउँ नजिक, १.५ कि.मी.) (३३.० कि.मी.), नाम नखुलेको बस्ती #८२२ (डाँडागाउँ नजिक, ०.६ कि.मी.) (३४.०७ कि.मी.), नाम नखुलेको बस्ती #८१५ (शान्ति बजार नजिक, १.१ कि.मी.) (३८.३९ कि.मी.)।

सावधानी: उपग्रह-आधारित अनुमानमा अनिश्चितता हुन्छ; कारबाही गर्नुअघि स्थलगत पुष्टि गर्नुहोस्। यो चित्र उपग्रहले अन्तिम पटक हेरेको समयको हो, अहिलेको अवस्था होइन। यो शैक्षिक प्रोटोटाइप हो, सञ्चालनात्मक उपकरण होइन।

सबै अङ्क प्रणालीका नक्सा/गणनाबाट स्वचालित रूपमा लिइएका हुन्; कुनै भाषा मोडेलले अङ्क बनाएको होइन। (नेपाली पाठ टेम्प्लेटमा आधारित छ; प्रयोगअघि मूल नेपाली भाषीबाट समीक्षा आवश्यक।)



Contains modified Copernicus Sentinel data 2026. Produced using Copernicus WorldDEM-30 © DLR e.V. 2010–2014 and © Airbus Defence and Space GmbH 2014–2018 provided under COPERNICUS by the European Union and ESA; all rights reserved. © OpenStreetMap contributors. Training data: Kuro Siwo – Bountos et al., NeurIPS 2024 Datasets & Benchmarks (CC BY). OSM snapshot: 2026-07-27 (pre-event). Generated automatically from the system's maps; no value is produced by a language model. Educational prototype – not an operational tool. Satellite-derived estimates carry uncertainty; verify on the ground before acting.