



Supplier Excellence Audit Photo Report Template

for Consumer Goods & FNF



Document Reference:	Prepared by:	Document Owner:	Version:10	Issued:
SEP.063B (B of A & B)	Quality Team - Asia	Policy & Regs Team - FNF & GM	Authorised External	Feb 2021

<u>Report No: 18224</u>	<u>Facility name: VANTAGE RIVER TEXTILES</u>
<u>Auditor(s): Sok Daraty</u>	<u>Audit Date: 07- Sep- 2026</u>

General Photos Section


Factory main gate and name board	Security main gate
	
Factory building	Factory building
	




Supplier Excellence Audit Photo Report Template

for Consumer Goods & FNF

Security entries/exit recorded



CCTV



Warehouse enter door



Fabric warehouse / fabric racks



Warehouse storage condition



Fabric identification board





Supplier Excellence Audit Photo Report Template

for Consumer Goods & FNF

Fabric identification information



Fabric storage in the rack




Fabric storage in the rack/ Barcode scan



Fabric storage in the rack/ Barcode scan



Fabric storage in system



Humidity reader / recorded






Lux meter level



SOP information



Fabric inspection report





Supplier Excellence Audit Photo Report Template

for Consumer Goods & FNF

Defect reference aids for kids



Measurement tape



Inspection Munsell test



Fabric inspection calibration



Rejected area




Authorize person





Supplier Excellence Audit Photo Report Template for Consumer Goods & FNF

Fabric rejected compare vs recorded



Trim warehouse overview



Trim storage condition / board information



Trim storages information



Trim inspection table



Trim information board





Supplier Excellence Audit Photo Report Template for Consumer Goods & FNF

Trim inspection report




Inspected trim card



Trim rejected area



Trim rejected vs report



Cutting dept overview



Cutting sample





Supplier Excellence Audit Photo Report Template for Consumer Goods & FNF

Spreading machine




Spreading machine maintenance



Fabric spreading



Fabric spreading recorded /lots



Cut panel pile height




QC checking cut panel





Supplier Excellence Audit Photo Report Template for Consumer Goods & FNF

Cut panel compare vs approved pattern



QC checking cut panel



Lux meter



Cutting inspection report

VANTAGE RIVER TEXTILES CO., LTD.
DAILY IN PROCESS CUTTING INSPECTION REPORT

ITEM NO.	ITEM NAME	QTY	UNIT	REMARKS	DATE	TIME	INSPECTOR	QC
1	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5
2	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5
3	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5
4	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5
5	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5
6	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5
7	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5
8	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5
9	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5
10	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5

Inspector: [Signature] QC: [Signature]

Cutting inspection report

VANTAGE RIVER TEXTILES CO., LTD.
DAILY IN PROCESS CUTTING INSPECTION REPORT

ITEM NO.	ITEM NAME	QTY	UNIT	REMARKS	DATE	TIME	INSPECTOR	QC
1	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5
2	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5
3	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5
4	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5
5	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5
6	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5
7	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5
8	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5
9	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5
10	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.5

Inspector: [Signature] QC: [Signature]

Rejected bin





Supplier Excellence Audit Photo Report Template

for Consumer Goods & FNF

Approved hard pattern storages



Cutting panel storage



Cut bundle storage



Cut bundel



Sewing dept overview



Sewing dept overview





Supplier Excellence Audit Photo Report Template

for Consumer Goods & FNF

Pre-production preparation	Pre-production preparation
	
Sewing machine	Sewing machine
	
Critical operations / mock up	Inside machine check
	



Supplier Excellence Audit Photo Report Template for Consumer Goods & FNF

Maintenance machine

ឯកសាររក្សាទុករបស់ក្រុមហ៊ុន ជាន់ខ្ពស់ មីនី វេស្តធីស្ទ
VANTAGE RIVER TEXTILES CO., LTD.
MONTHLY MAINTENANCE REPORT របាយការណ៍ថែទាំម៉ាស៊ីនប្រចាំខែ

Machine Name:	Serial No.	ឈ្មោះម៉ាស៊ីន	លេខស៊េរី
DATE	DESCRIPTION	M/C Condition	Oil Position
10/08	OK	✓	✓
11/08	OK	✓	✓
12/08	OK	✓	✓
13/08	OK	✓	✓
14/08	OK	✓	✓
15/08	OK	✓	✓
16/08	OK	✓	✓
17/08	OK	✓	✓
18/08	OK	✓	✓
19/08	OK	✓	✓
20/08	OK	✓	✓
21/08	OK	✓	✓
22/08	OK	✓	✓
23/08	OK	✓	✓
24/08	OK	✓	✓
25/08	OK	✓	✓
26/08	OK	✓	✓
27/08	OK	✓	✓
28/08	OK	✓	✓
29/08	OK	✓	✓
30/08	OK	✓	✓
31/08	OK	✓	✓
01/09	OK	✓	✓
02/09	OK	✓	✓
03/09	OK	✓	✓
04/09	OK	✓	✓
05/09	OK	✓	✓
06/09	OK	✓	✓
07/09	OK	✓	✓
08/09	OK	✓	✓
09/09	OK	✓	✓
10/09	OK	✓	✓
11/09	OK	✓	✓
12/09	OK	✓	✓
13/09	OK	✓	✓
14/09	OK	✓	✓
15/09	OK	✓	✓
16/09	OK	✓	✓
17/09	OK	✓	✓
18/09	OK	✓	✓
19/09	OK	✓	✓
20/09	OK	✓	✓
21/09	OK	✓	✓
22/09	OK	✓	✓
23/09	OK	✓	✓
24/09	OK	✓	✓
25/09	OK	✓	✓
26/09	OK	✓	✓
27/09	OK	✓	✓
28/09	OK	✓	✓
29/09	OK	✓	✓
30/09	OK	✓	✓
01/10	OK	✓	✓
02/10	OK	✓	✓
03/10	OK	✓	✓
04/10	OK	✓	✓
05/10	OK	✓	✓
06/10	OK	✓	✓
07/10	OK	✓	✓
08/10	OK	✓	✓
09/10	OK	✓	✓
10/10	OK	✓	✓
11/10	OK	✓	✓
12/10	OK	✓	✓
13/10	OK	✓	✓
14/10	OK	✓	✓
15/10	OK	✓	✓
16/10	OK	✓	✓
17/10	OK	✓	✓
18/10	OK	✓	✓
19/10	OK	✓	✓
20/10	OK	✓	✓
21/10	OK	✓	✓
22/10	OK	✓	✓
23/10	OK	✓	✓
24/10	OK	✓	✓
25/10	OK	✓	✓
26/10	OK	✓	✓
27/10	OK	✓	✓
28/10	OK	✓	✓
29/10	OK	✓	✓
30/10	OK	✓	✓
31/10	OK	✓	✓
01/11	OK	✓	✓
02/11	OK	✓	✓
03/11	OK	✓	✓
04/11	OK	✓	✓
05/11	OK	✓	✓
06/11	OK	✓	✓
07/11	OK	✓	✓
08/11	OK	✓	✓
09/11	OK	✓	✓
10/11	OK	✓	✓
11/11	OK	✓	✓
12/11	OK	✓	✓
13/11	OK	✓	✓
14/11	OK	✓	✓
15/11	OK	✓	✓
16/11	OK	✓	✓
17/11	OK	✓	✓
18/11	OK	✓	✓
19/11	OK	✓	✓
20/11	OK	✓	✓
21/11	OK	✓	✓
22/11	OK	✓	✓
23/11	OK	✓	✓
24/11	OK	✓	✓
25/11	OK	✓	✓
26/11	OK	✓	✓
27/11	OK	✓	✓
28/11	OK	✓	✓
29/11	OK	✓	✓
30/11	OK	✓	✓
01/12	OK	✓	✓
02/12	OK	✓	✓
03/12	OK	✓	✓
04/12	OK	✓	✓
05/12	OK	✓	✓
06/12	OK	✓	✓
07/12	OK	✓	✓
08/12	OK	✓	✓
09/12	OK	✓	✓
10/12	OK	✓	✓
11/12	OK	✓	✓
12/12	OK	✓	✓
13/12	OK	✓	✓
14/12	OK	✓	✓
15/12	OK	✓	✓
16/12	OK	✓	✓
17/12	OK	✓	✓
18/12	OK	✓	✓
19/12	OK	✓	✓
20/12	OK	✓	✓
21/12	OK	✓	✓
22/12	OK	✓	✓
23/12	OK	✓	✓
24/12	OK	✓	✓
25/12	OK	✓	✓
26/12	OK	✓	✓
27/12	OK	✓	✓
28/12	OK	✓	✓
29/12	OK	✓	✓
30/12	OK	✓	✓
31/12	OK	✓	✓

Oil stain check

ឯកសាររក្សាទុករបស់ក្រុមហ៊ុន ជាន់ខ្ពស់ មីនី វេស្តធីស្ទ
VANTAGE RIVER TEXTILES CO., LTD.
MONTHLY MAINTENANCE REPORT របាយការណ៍ថែទាំម៉ាស៊ីនប្រចាំខែ

Machine Name:	Serial No.	ឈ្មោះម៉ាស៊ីន	លេខស៊េរី
DATE	DESCRIPTION	M/C Condition	Oil Position
10/08	OK	✓	✓
11/08	OK	✓	✓
12/08	OK	✓	✓
13/08	OK	✓	✓
14/08	OK	✓	✓
15/08	OK	✓	✓
16/08	OK	✓	✓
17/08	OK	✓	✓
18/08	OK	✓	✓
19/08	OK	✓	✓
20/08	OK	✓	✓
21/08	OK	✓	✓
22/08	OK	✓	✓
23/08	OK	✓	✓
24/08	OK	✓	✓
25/08	OK	✓	✓
26/08	OK	✓	✓
27/08	OK	✓	✓
28/08	OK	✓	✓
29/08	OK	✓	✓
30/08	OK	✓	✓
31/08	OK	✓	✓
01/09	OK	✓	✓
02/09	OK	✓	✓
03/09	OK	✓	✓
04/09	OK	✓	✓
05/09	OK	✓	✓
06/09	OK	✓	✓
07/09	OK	✓	✓
08/09	OK	✓	✓
09/09	OK	✓	✓
10/09	OK	✓	✓
11/09	OK	✓	✓
12/09	OK	✓	✓
13/09	OK	✓	✓
14/09	OK	✓	✓
15/09	OK	✓	✓
16/09	OK	✓	✓
17/09	OK	✓	✓
18/09	OK	✓	✓
19/09	OK	✓	✓
20/09	OK	✓	✓
21/09	OK	✓	✓
22/09	OK	✓	✓
23/09	OK	✓	✓
24/09	OK	✓	✓
25/09	OK	✓	✓
26/09	OK	✓	✓
27/09	OK	✓	✓
28/09	OK	✓	✓
29/09	OK	✓	✓
30/09	OK	✓	✓
01/10	OK	✓	✓
02/10	OK	✓	✓
03/10	OK	✓	✓
04/10	OK	✓	✓
05/10	OK	✓	✓
06/10	OK	✓	✓
07/10	OK	✓	✓
08/10	OK	✓	✓
09/10	OK	✓	✓
10/10	OK	✓	✓
11/10	OK	✓	✓
12/10	OK	✓	✓
13/10	OK	✓	✓
14/10	OK	✓	✓
15/10	OK	✓	✓
16/10	OK	✓	✓
17/10	OK	✓	✓
18/10	OK	✓	✓
19/10	OK	✓	✓
20/10	OK	✓	✓
21/10	OK	✓	✓
22/10	OK	✓	✓
23/10	OK	✓	✓
24/10	OK	✓	✓
25/10	OK	✓	✓
26/10	OK	✓	✓
27/10	OK	✓	✓
28/10	OK	✓	✓
29/10	OK	✓	✓
30/10	OK	✓	✓
31/10	OK	✓	✓
01/11	OK	✓	✓
02/11	OK	✓	✓
03/11	OK	✓	✓
04/11	OK	✓	✓
05/11	OK	✓	✓
06/11	OK	✓	✓
07/11	OK	✓	✓
08/11	OK	✓	✓
09/11	OK	✓	✓
10/11	OK	✓	✓
11/11	OK	✓	✓
12/11	OK	✓	✓
13/11	OK	✓	✓
14/11	OK	✓	✓
15/11	OK	✓	✓
16/11	OK	✓	✓
17/11	OK	✓	✓
18/11	OK	✓	✓
19/11	OK	✓	✓
20/11	OK	✓	✓
21/11	OK	✓	✓
22/11	OK	✓	✓
23/11	OK	✓	✓
24/11	OK	✓	✓
25/11	OK	✓	✓
26/11	OK	✓	✓
27/11	OK	✓	✓
28/11	OK	✓	✓
29/11	OK	✓	✓
30/11	OK	✓	✓
31/11	OK	✓	✓
01/12	OK	✓	✓
02/12	OK	✓	✓
03/12	OK	✓	✓
04/12	OK	✓	✓
05/12	OK	✓	✓
06/12	OK	✓	✓
07/12	OK	✓	✓
08/12	OK	✓	✓
09/12	OK	✓	✓
10/12	OK	✓	✓
11/12	OK	✓	✓
12/12	OK	✓	✓
13/12	OK	✓	✓
14/12	OK	✓	✓
15/12	OK	✓	✓
16/12	OK	✓	✓
17/12	OK	✓	✓
18/12	OK	✓	✓
19/12	OK	✓	✓
20/12	OK	✓	✓
21/12	OK	✓	✓
22/12	OK	✓	✓
23/12	OK	✓	✓
24/12	OK	✓	✓
25/12	OK	✓	✓
26/12	OK	✓	✓
27/12	OK	✓	✓
28/12	OK	✓	✓
29/12	OK	✓	✓
30/12	OK	✓	✓
31/12	OK	✓	✓


Roving QC checking



Roving QC checking SPI



Roving QC documents



Approved sample / First output sample






Lux meter



End-line QC report



Approved trim card





Supplier Excellence Audit Photo Report Template for Consumer Goods & FNF


Target board



Top 3 defects

Defect Type	Count	Defect Type	Count	Defect Type	Count
Defect Type 1	Count 1	Defect Type 2	Count 2	Defect Type 3	Count 3
Defect Type 4	Count 4	Defect Type 5	Count 5	Defect Type 6	Count 6
Defect Type 7	Count 7	Defect Type 8	Count 8	Defect Type 9	Count 9
Defect Type 10	Count 10	Defect Type 11	Count 11	Defect Type 12	Count 12

Top 3 defects



QC baskets



Fushing machine



Maintenance machine

Maintenance Type	Count	Maintenance Type	Count	Maintenance Type	Count
Maintenance Type 1	Count 1	Maintenance Type 2	Count 2	Maintenance Type 3	Count 3
Maintenance Type 4	Count 4	Maintenance Type 5	Count 5	Maintenance Type 6	Count 6
Maintenance Type 7	Count 7	Maintenance Type 8	Count 8	Maintenance Type 9	Count 9
Maintenance Type 10	Count 10	Maintenance Type 11	Count 11	Maintenance Type 12	Count 12



Supplier Excellence Audit Photo Report Template for Consumer Goods & FNF

SOP



Folding table / End-line table



Folding standard



Snap attachments area



Snap attachment machine



Maintenance machine





Supplier Excellence Audit Photo Report Template for Consumer Goods & FNF


Two hours pull test



Pre-product test



Supplier data sheet




Mock up report



Caliper / Calibration



Pulling test operator





Supplier Excellence Audit Photo Report Template for Consumer Goods & FNF

Pulling machine



Calibration recorded




Pulling test



Caliper check



Supplier training recorded



Needle detector






Calibration report



9 points system



Needle detection SOP





Supplier Excellence Audit Photo Report Template

for Consumer Goods & FNF


Rejection box



Security at packing carton




In & Out recorded



Policy and authorize person



After needle detection overview



Pre-final teams






Supplier Excellence Audit Photo Report Template

for Consumer Goods & FNF

Pre-final report



Weight scale / Calibration recorded




Carton warehouse condition



Carton warehouse condition



Carton storage information



Humidity reader / recorded





Supplier Excellence Audit Photo Report Template for Consumer Goods & FNF


Samples documents storage



Approved sample



Approved trim card / documents




Jump sizes set/recorded



Approved marker



PP comments from customer







Supplier Excellence Audit Photo Report Template

for Consumer Goods & FNF

Mini marker



Mini marker




Sample at sewing line



Lab room



Lab room overview







Washing machine





Supplier Excellence Audit Photo Report Template

for Consumer Goods & FNF


Washing machine / calibration	GSM scale / GSM cutter
	
Crocking machine	Calibration
	
Metal ruler / calibration	Shrinkage check
	




Supplier Excellence Audit Photo Report Template

for Consumer Goods & FNF


Testing report



Testing report



Testing report



SOP



Light box in dark room



Light box in dark room





Supplier Excellence Audit Photo Report Template for Consumer Goods & FNF

Calibration recorded



Time usage recorded



Calibration certificate



SOP information / Authorize person



Authorize person / Lab Certified



Sharp tools kept in lockable cabinet






Supplier Excellence Audit Photo Report Template

for Consumer Goods & FNF

Sharp tools control log




Sharp tools control log



Sharp tools kept in lockable cabinet



Tape cutter / sharp tools control log



Needle exchange room



Needle exchange SOP





Supplier Excellence Audit Photo Report Template for Consumer Goods & FNF

Needle exchange SOP



Needle exchange SOP



Used / Broken needle report



Used / Broken needle report



Needle inventory report



Needle inventory report






Supplier Excellence Audit Photo Report Template

for Consumer Goods & FNF

Missing part needle record



Needle kept in cabinet



Carton warehouse condition



Small magnet



Big magnet



Clinic room





Supplier Excellence Audit Photo Report Template for Consumer Goods & FNF

Clinic room	Doctor corticate
	
Finger scan	First aid box
	
Fire extinguisher / fire alarm	Fire evacuation plan
	



Supplier Excellence Audit Photo Report Template for Consumer Goods & FNF

Two hours complete documents



PP meeting report / Pilo run report




Factory tax license



Factory business license



Environments certificate



Disposal - Environments certificate





Supplier Excellence Audit Photo Report Template for Consumer Goods & FNF

Wrap certificate




Weight scale / Calibration recorded




Pest control certificate




Carton warehouse condition



Carton storage information




Email complains from customer / CAP





Supplier Excellence Audit Photo Report Template for Consumer Goods & FNF


Product recall produces



QC organization chart



Quality manual




QC training plan

VANTAGE RIVER TEXTILES Yearly Training Summary											
Sl. No.	Training Topic	Training Date	Training Time	Training Location	Training Method	Training Material	Training Cost	Training Result	Training Feedback	Training Remarks	Training Signature
1	Quality Control Training	2023-01-01	09:00 AM	Factory Floor	On-site	Quality Control Manual	100,000	Good	Good	Good	Good
2	Quality Control Training	2023-01-01	09:00 AM	Factory Floor	On-site	Quality Control Manual	100,000	Good	Good	Good	Good
3	Quality Control Training	2023-01-01	09:00 AM	Factory Floor	On-site	Quality Control Manual	100,000	Good	Good	Good	Good
4	Quality Control Training	2023-01-01	09:00 AM	Factory Floor	On-site	Quality Control Manual	100,000	Good	Good	Good	Good
5	Quality Control Training	2023-01-01	09:00 AM	Factory Floor	On-site	Quality Control Manual	100,000	Good	Good	Good	Good
6	Quality Control Training	2023-01-01	09:00 AM	Factory Floor	On-site	Quality Control Manual	100,000	Good	Good	Good	Good
7	Quality Control Training	2023-01-01	09:00 AM	Factory Floor	On-site	Quality Control Manual	100,000	Good	Good	Good	Good
8	Quality Control Training	2023-01-01	09:00 AM	Factory Floor	On-site	Quality Control Manual	100,000	Good	Good	Good	Good
9	Quality Control Training	2023-01-01	09:00 AM	Factory Floor	On-site	Quality Control Manual	100,000	Good	Good	Good	Good
10	Quality Control Training	2023-01-01	09:00 AM	Factory Floor	On-site	Quality Control Manual	100,000	Good	Good	Good	Good
11	Quality Control Training	2023-01-01	09:00 AM	Factory Floor	On-site	Quality Control Manual	100,000	Good	Good	Good	Good
12	Quality Control Training	2023-01-01	09:00 AM	Factory Floor	On-site	Quality Control Manual	100,000	Good	Good	Good	Good

Fire drill certificate



Fire drill training





Supplier Excellence Audit Photo Report Template for Consumer Goods & FNF

Mandatory Photos for Component & Button Attach Section


In-house pull force hourly reports.	Mock Attachment Strips showing Pull Force Test has been done for every metal attachment order
	
Metal attachment Machine calibration Validity	Metal Detection Zone to be isolated with Proper Walls or Hardboards - Fencing will not be allowed- Has to be an airport security system.
	
SPC Chart - manual handwritten input of hourly / 2 hourly data and graph for metal attachment- Auditor to Check the records of production with metal attachments.	Separate Metal attachment Area- Dedicated Zone
	



Supplier Excellence Audit Photo Report Template for Consumer Goods & FNF

If the Metal Attachment machine is Rented, the vendor needs to provide the service agreement and the proof to the CB. The rented machine has to be from our Preferred supplier.

Data/Technical Sheet for Metal Items for attachment from Supplier



NC Photos Section

Clause: GRCG 7.4 (Major)

The factory has a product identification and traceability system in place, with identification maintained throughout the production process. Traceability records are maintained to support product identification at retail and shipper/carton levels,

Clause: GRCG 7.4 (Major)

The factory has a product identification and traceability system in place, with identification maintained throughout the production process. Traceability records are maintained to support product identification at retail and shipper/carton levels,





Supplier Excellence Audit

Photo Report Template

for Consumer Goods & FNF

Clause: GRCG 7.4 (Major) The factory has a product identification and traceability system in place, with identification maintained throughout the production process. Traceability records are maintained to support product identification at retail and shipper/carton levels,	Clause: GRCG 7.4 (Major) The factory has a product identification and traceability system in place, with identification maintained throughout the production process. Traceability records are maintained to support product identification at retail and shipper/carton levels,
	SEP.063B -EXT- Supplier Excellence Report Summary Template Consumer Goods & FNF Version: 10 FOR INTERNAL AND AUTHORISED EXTERNAL DISTRIBUTION or EXTERNAL COMMERCIAL IN CONFIDENCE UNCONTROLLED OUTSIDE OF WOOLWORTHS' PLATFORMS



Supplier Excellence Audit Photo Report Template

for Consumer Goods & FNF

	
Clause:C- PCC 5.5 (Minor) The factory does not have a documented or systematic monthly inspection program for glass, brittle plastic, wood, and ceramic items. Several damaged items were observed in the production area, indicating inconsistent control and an increased risk of product contamination.	