


AI Vision Inspection Report

7/9/2026, 10:33:38 pm



Component:	Shaft / elongated part
AI confidence:	86%
Calibration:	Auto square reference (50 mm)
Scale:	0.1157 mm/pixel
Overall length:	27.8 mm
Width / diameter:	8.6 mm
Uncertainty:	±0.23 mm*
Inspection:	PASS
Defect check:	No obvious gross geometric abnormality detected in the 2D silhouette.
Standards:	No fastener standard match applied.

*Uncertainty is an approximate image-edge error model, not aerospace-grade metrology.

Measured values use the detected reference scale. AI-estimated values are explicitly labelled.

Limitations: perspective, lens distortion, hidden depth, surface roughness and fine thread geometry are not reliably measured from one phone image.