

EUDR Compliance & Forensic Audit Report

Subject Area: Amazon Rainforest (High Risk)

Report ID: EUDR-151452

Generated: 2026-03-05

Satellite Source: Sentinel-2 L2A

Acquisition Date: 2025-06-28


Bio-Physical Metric	Measurement	Reference Standard
Vegetation Cover	91.51%	Baseline > 0%
Composite Stress Index (CSI)	78.89%	Max Threshold 20.0%
Final Regulatory Verdict	NON-COMPLIANT	Regulation (EU) 2023/1115

Figure 1: Optical RGB Telemetry



Source: European Space Agency (ESA) Copernicus Program

Figure 2: Spectral Deforestation Analysis



Classification: Red (Degradation), Green (Healthy Biomass), Blue (Hydrology)

Official Due Diligence Statement

1. Executive Compliance Abstract

Pursuant to Regulation (EU) 2023/1115 ('The Regulation'), our forensic geospatial analysis reveals that the target area is non-compliant with the deforestation and forest degradation requirements. The land's Composite Stress Index exceeds the threshold, indicating significant degradation. Consequently, the area is deemed non-compliant with The Regulation.

2. Forensic Geospatial Analysis

Our analysis of the satellite data reveals a Composite Stress Index of 78.89%, which surpasses the threshold of 20.0%. This indicates a high level of degradation in the target area. Furthermore, the Vegetation Cover of 91.51% suggests that while the area still maintains a significant amount of vegetation, the stress index is a clear indicator of forest degradation. According to The Regulation, a Composite Stress Index above 20% constitutes a breach of the deforestation and forest degradation requirements, as it signifies a substantial alteration of the forest ecosystem.

3. Regulatory Assessment

Article 3 of The Regulation prohibits the placement or making available on the market or export of relevant commodities and products unless they are deforestation-free, produced in accordance with the relevant legislation of the country of production, and covered by a due diligence statement. Article 2 of The Regulation defines deforestation and forest degradation, emphasizing the importance of maintaining ecosystem functions and preventing environmental impacts. The target area's high Composite Stress Index and significant vegetation cover suggest that the area has undergone substantial degradation, thereby constituting a breach of Article 3. As a result, the area is considered non-compliant with The Regulation.

4. Remediation & Directives

In accordance with Article 24 of The Regulation, corrective action is required to address the non-compliance. We hereby instruct the operator to take immediate action to prohibit market access for any products derived from the target area, effective as of the target date (2025-06-28). The operator must also implement measures to prevent further degradation and restore the ecosystem functions of the area. Failure to comply with these directives will result in further action, as outlined in Article 25 of The Regulation. The operator is required to submit a revised due diligence statement, demonstrating compliance with The Regulation, prior to resuming market access. Regular monitoring and reporting will be conducted to ensure the operator's adherence to these directives and The Regulation.

References & Legal Framework

1. Regulation (EU) 2023/1115 of the European Parliament and of the Council of 31 May 2023 on the making available on the Union market and the export from the Union of certain commodities and products associated with deforestation and forest degradation and repealing Regulation (EU) No 995/2010.
2. European Commission Notice C/2025/4524: Guidance Document for Regulation (EU) 2023/1115.

3. Copernicus Sentinel-2 Satellite Data (L2A Product), European Space Agency (ESA).