

SitePulse — AI Explained Audit Report

Comprehensive website quality and security analysis with AI explanations

<https://cityhangaround.com/> 10/1/2026, 9:35:04 AM 553.2s total

OVERALL SCORE

74

CRAWLER

100

SEO

75

SECURITY

40

SSLTLS

100

BROKENLINKS

96

FUNCTIONAL

100

ACCESSIBILITY

98

PERFORMANCE

32

Findings Summary

● Critical: 1 ● High: 5 ● Medium: 27 ● Low: 26

Functional

completed 100 66.0s

TOTALTESTS

14

PASSED

14

FAILED

0

SKIPPED

0

WARNINGS

1

AVERAGEDURATION

4312

TESTTYPES

navigation,interaction,resource,console,responsive

MEDIUM func-images-load via playwright

13 broken images found

<https://cityhangaround.com/>

AI EXPLANATION for MEDIUM — func-images-load

What it means

The audit found 13 images that fail to load on the homepage. This indicates that the image files are missing, the URLs are incorrect, or the server is blocking access. Broken images can confuse visitors, break page layout, and negatively affect SEO.

Why it matters

Missing images degrade the visual experience and can make the site appear unprofessional. They may also impact search engine rankings, as search engines consider image availability in their algorithms. Users may lose trust if key visuals are absent.

Recommended fix

Verify the image source URLs and ensure the files exist on the server. Replace broken links with correct paths or upload missing images. Update the markup to point to the correct image locations and test that all images load.

Accessibility

completed 98 67.0s

TOTALVIOLATIONS
9

CRITICAL
1

SERIOUS
2

MODERATE
5

MINOR
1

TOTALPASSES
311

INCOMPLETECHECKS
9

PAGESCHECKED
8

TOTALPAGESAVAILABLE
19

TOTALCHECKS
320


SCORINGMETHOD
pass-ratio-weighted

SCORINGBREAKDOWN
[object Object]

CRITICAL image-alt via axe-core

Ensure elements have alternative text or a role of none or presentation

<https://cityhangararound.com/hyderabad/banjara-hills/budget-hotels/guest-inn-suites-castle-hotel/>



AI EXPLANATION for CRITICAL — image-alt

What it means

The report flags an element that lacks alternative text or a role of none/presentation. Without alt text, screen readers cannot convey the image content to visually impaired users, and search engines miss the image context. This violates accessibility guidelines and can reduce discoverability.

Why it matters

Users who rely on assistive technologies cannot understand the image, leading to a poor experience. Search engines also use alt text for indexing, so missing alt can hurt SEO. Compliance with accessibility standards is often required by law and best practice.


Recommended fix

Add descriptive alt attributes to the affected element, describing the image content. If the image is purely decorative, set role="presentation" or alt="" to indicate it should be ignored by assistive technologies. Validate the changes with an accessibility checker.

HIGH color-contrast via axe-core

Ensure the contrast between foreground and background colors meets WCAG 2 AA minimum contrast ratio thresholds

<https://cityhangararound.com/>



AI EXPLANATION for HIGH — color-contrast

What it means

The audit identified five elements where the foreground and background colors do not meet WCAG 2 AA contrast requirements. Low contrast makes text hard to read for users with visual impairments and can lead to accessibility violations. Adjusting the color palette or CSS to increase contrast will improve readability and compliance.

Why it matters

Users with low vision or color blindness may be unable to read text, reducing usability and accessibility. Search engines and regulatory bodies increasingly enforce WCAG compliance, so failing to meet contrast standards can result in penalties or lower rankings. A clear visual hierarchy also enhances overall user experience.


Recommended fix

Use a contrast checker to determine the required color values and adjust the CSS for the affected elements. Replace low-contrast colors with higher contrast combinations that meet the 4.5:1 ratio for normal text. Re-test to confirm compliance.

HIGH scrollable-region-focusable via axe-core

Ensure elements that have scrollable content are accessible by keyboard in Safari

<https://cityhangararound.com/>



AI EXPLANATION for HIGH — scrollable-region-focusable

What it means

This finding indicates that a scrollable element on the page cannot be focused using the keyboard in Safari. The element lacks the necessary attributes to allow users to navigate into it with a keyboard or assistive technology.

Why it matters

Keyboard users, including those who rely on screen readers or other assistive devices, will be unable to access or interact with the scrollable content. This reduces accessibility and can prevent users from viewing important information.

Recommended fix

Add a `tabindex="0"` attribute to the scrollable container or wrap the content in a focusable element. Ensure the element has a role such as "region" and appropriate `aria-label` if needed, so that Safari and other browsers allow keyboard focus.

MEDIUM region via axe-core

Ensure all page content is contained by landmarks

<https://cityhangararound.com/>

AI EXPLANATION for MEDIUM — region

What it means

The page contains content that is not wrapped in landmark elements such as header, nav, main, or footer. Landmark regions help assistive technologies identify and navigate distinct sections of a page.

Why it matters

Without landmarks, screen reader users may have difficulty quickly locating navigation, main content, or other key areas, leading to a confusing or inefficient browsing experience.

Recommended fix

Wrap each major section of the page in the appropriate landmark element (e.g., `<header>`, `<nav>`, `<main>`, `<footer>`) or add `aria-label` attributes to custom elements to define them as landmarks. Ensure that all page content is contained within these landmarks.

MEDIUM heading-order via axe-core

Ensure the order of headings is semantically correct

<https://cityhangararound.com/>

AI EXPLANATION for MEDIUM — heading-order

What it means

The headings on the page are not in a logical hierarchical order; for example, an H3 may appear before an H2 or an H1 may be followed by an H4 without an intervening H2.

Why it matters

Screen readers and other assistive technologies use heading order to build a navigable outline of the page. Incorrect ordering can confuse users and make it harder to understand the structure of the content.

Recommended fix

Review the heading hierarchy and adjust the heading levels so that they follow a logical sequence (H1, H2, H3, etc.). If a lower-level heading is needed before a higher-level one, consider restructuring the content or using appropriate heading levels to maintain a clear hierarchy.

MEDIUM landmark-one-main via axe-core

Ensure the document has a main landmark

<https://cityhangararound.com/>

AI EXPLANATION for MEDIUM — landmark-one-main

What it means

The page is missing a main landmark, such as a <main> element or an element with role="main" that identifies the primary content area.

Why it matters

Assistive technologies use landmarks to let users quickly navigate to the main content. Without a main landmark, users may have to scan the entire page, reducing accessibility and potentially impacting SEO.

Recommended fix

Wrap the primary content of the page in a <main> element or add role="main" to an existing container. Ensure the element is the only main landmark on the page and that it is placed near the top of the DOM.

MEDIUM landmark-unique via axe-core

Ensure landmarks are unique

https://cityhangararound.com/hyderabad/banjara-hills/budget-hotels/guest-inn-suites-castle-hotel/

 **AI EXPLANATION** for MEDIUM — landmark-unique

What it means

The page contains duplicate landmark elements (e.g., two <nav> or two <header> tags) that share the same role.

Why it matters

Duplicate landmarks confuse screen readers and other assistive tools, making it harder for users to navigate the page efficiently. It can also lead to inconsistent behavior across browsers.

Recommended fix

Identify the duplicate landmark elements and remove or rename one of them. If both are needed, change one to a different role or remove the role attribute so that only one landmark of each type remains.

MEDIUM page-has-heading-one via axe-core

Ensure that the page, or at least one of its frames contains a level-one heading

https://cityhangararound.com/hyderabad/banjara-hills/budget-hotels/guest-inn-suites-castle-hotel/

 **AI EXPLANATION** for MEDIUM — page-has-heading-one

What it means

The page does not contain a level-one heading (<h1>) or any frame on the page has one.

Why it matters

A level-one heading provides the main title and context for the page, which screen readers announce to users and search engines use for indexing. Without it, users may not understand the page's purpose and SEO can suffer.

Recommended fix

Add a descriptive <h1> element at the top of the page (or within a frame if the page uses frames). Ensure the heading accurately reflects the page's content and is unique on the page.

LOW image-redundant-alt via axe-core

Ensure image alternative is not repeated as text

https://cityhangararound.com/

Performance

completed 32 213.9s

PERFORMANCESCORE
32

FCP
2.1 s

FCPMS
2100

LCP
9.8 s

LCPPMS
9800

TOTALBLOCKINGTIME
11,240 ms

TOTALBLOCKINGTIMEMS
240

CLS
0.094

CLSVALUE
0.09417347099695009

SPEEDINDEX
9.8 s

SPEEDINDEXMS
9800

TTI
16.7 s

TTIMS
16700

TTFB
Root document took
530 ms

TTFBMS
534

SOURCE
lighthouse

LIGHTHOUSEVERSION
13.4.1

URL
https://cityhangararound.com/

REQUESTCOUNT
57

TOTALBYTEWEIGHT
Total size was 1,018 KiB

MEDIUM

Moderate TTFB: Root document took 530 ms

https://cityhangararound.com/

🔍 AI EXPLANATION for MEDIUM — finding

What it means

The Time to First Byte (TTFB) for the root document is 530 milliseconds, which is considered moderate. TTFB measures how long it takes the server to start sending data after a request is made. A higher TTFB indicates that the server or network is taking longer to respond.

Why it matters

A moderate TTFB can make the site feel slower to users, especially on mobile or slower connections. Search engines use TTFB as part of their ranking signals, so a slower response may negatively impact SEO. Users who experience delays are more likely to abandon the page.

Recommended fix

Improve server response time by enabling caching, optimizing database queries, and reducing server-side processing. Deploy a Content Delivery Network (CDN) to serve static assets closer to users. Consider upgrading hosting resources or using a more efficient backend framework.

HIGH

Poor LCP: 9.8 s

<https://cityhangaround.com/>

🔍 AI EXPLANATION for HIGH — finding

What it means

The Largest Contentful Paint (LCP) is 9.8 seconds, which is classified as poor. LCP measures the time until the largest visible element on the page is fully rendered. A value this high indicates that users must wait a long time before seeing meaningful content.

Why it matters

LCP is a core Web Vitals metric that directly influences user perception of page speed and can affect search engine rankings. A slow LCP can increase bounce rates and reduce conversions, especially for visitors on mobile devices. Users may also experience frustration if the page feels unresponsive.

Recommended fix

Optimize critical rendering by deferring non-essential JavaScript and CSS, and by inlining critical CSS. Compress and resize images, use modern formats like WebP, and enable lazy loading for offscreen images. Preload key resources, reduce third-party scripts, and consider using a CDN to serve assets faster.

MEDIUM

Moderate CLS: 0.094

<https://cityhangaround.com/>

🔍 AI EXPLANATION for MEDIUM — finding

What it means

The Cumulative Layout Shift (CLS) score is 0.094, which falls into the moderate range. CLS measures visual stability by tracking unexpected layout shifts during page load. A moderate CLS indicates that some elements are moving around as the page renders.

Why it matters

Layout shifts can cause users to click the wrong button or lose focus, leading to a poor user experience. CLS is part of Core Web Vitals, so a higher score can negatively affect SEO rankings. Users may perceive the site as unprofessional or buggy if content moves unexpectedly.

Recommended fix

Reserve space for images, videos, and ads by specifying width and height or using CSS aspect-ratio. Avoid inserting content above existing content unless it is a deliberate layout change. Use font-display: swap for custom fonts to prevent layout jumps, and ensure that dynamic content is loaded in a way that does not shift the layout.

Security

completed 40 53.9s

SOURCE

owasp-zap + header-analysis

ZAPAVAILABLE

true

ZAPUSED

true

ZAPVERSION

2.17.0

ZAPALERTCOUNT

27

HEADERSCHECKED

7

TOTALFINDINGS

20

CRITICAL

0

HIGH

2

MEDIUM

8

LOW

8

INFORMATIONAL

2

HASHTTPS

true

HTTPSTATUS

0

HIGH

missing-hsts via header-analysis

Missing HSTS header

💡 Add strict-transport-security header to improve security

<https://cityhangaround.com/>

 **AI EXPLANATION** for HIGH — missing-hsts

What it means

The site does not send an HSTS (HTTP Strict Transport Security) header, which tells browsers to only use HTTPS for future requests.

Why it matters

Without HSTS, users could be tricked into connecting over plain HTTP, exposing them to man-in-the-middle attacks and SSL stripping. It also reduces trust signals for browsers that flag sites lacking HSTS.

Recommended fix

Add a Strict-Transport-Security header such as `Strict-Transport-Security: max-age=31536000; includeSubDomains; preload` to enforce HTTPS for all connections.

HIGH missing-csp via header-analysis

Missing CSP header

 Add content-security-policy header to improve security

<https://cityhangararound.com/>

 **AI EXPLANATION** for HIGH — missing-csp

What it means

The site is missing a Content-Security-Policy header, which restricts where resources can be loaded from and helps prevent script injection.

Why it matters

Without CSP, attackers can inject malicious scripts via XSS or other injection vectors, compromising user data and site integrity. It also limits the ability to mitigate other content-based attacks.

Recommended fix

Add a Content-Security-Policy header, e.g., `Content-Security-Policy: default-src 'self'; script-src 'self'; style-src 'self' 'unsafe-inline';` and adjust as needed to allow legitimate resources.

MEDIUM 10020 via owasp-zap

Missing Anti-clickjacking Header

<https://cityhangararound.com/>

 **AI EXPLANATION** for MEDIUM — 10020

What it means

The site lacks an anti-clickjacking header such as X-Frame-Options or CSP frame-ancestors, allowing it to be embedded in other sites' frames.

Why it matters

Embedding the site in a frame can enable clickjacking attacks, where users unknowingly interact with malicious overlays. This can lead to credential theft or unintended actions.

Recommended fix

Add an anti-clickjacking header, for example `X-Frame-Options: SAMEORIGIN` or a CSP rule `frame-ancestors 'self';` to prevent framing by other domains.

MEDIUM 10038 via owasp-zap

Content Security Policy (CSP) Header Not Set

<https://cityhangararound.com/>

 **AI EXPLANATION** for MEDIUM — 10038

What it means

The site does not send a Content Security Policy (CSP) header. CSP tells browsers which sources of content are trusted and which are blocked, helping to prevent malicious code from running.

Why it matters

Without a CSP, attackers can inject or execute arbitrary scripts, increasing the risk of cross-site scripting (XSS) attacks and data theft. It also reduces the effectiveness of other security controls.

Recommended fix

Add a Content-Security-Policy header that defines allowed sources, such as `default-src 'self'; script-src 'self' https://trusted.cdn.com; style-src 'self' https://trusted.cdn.com;`. Test the policy in report-only mode before enforcing it.

MEDIUM 90003 via owasp-zap

Sub Resource Integrity Attribute Missing

<https://cityhangararound.com/>

 **AI EXPLANATION** for MEDIUM — 90003

What it means

External scripts or styles are loaded without a Sub-resource Integrity (SRI) attribute. SRI verifies that the fetched resource matches a known hash, ensuring it hasn't been tampered with.

Why it matters

If an attacker modifies a third-party resource, the site could unknowingly execute malicious code, compromising users and the site's integrity.

Recommended fix

Generate cryptographic hashes (e.g., SHA-384) for each external resource and add an integrity attribute to the corresponding `<script>` or `<link>` tags, along with `crossorigin="anonymous"`.

MEDIUM missing-x-content-type-options via header-analysis

Missing X-Content-Type-Options header

💡 Add x-content-type-options header to improve security
<https://cityhangaround.com/>

🔗 **AI EXPLANATION** for MEDIUM — missing-x-content-type-options

What it means

The site is missing the X-Content-Type-Options header. This header instructs browsers not to MIME-sniff content types, which can prevent certain types of attacks.

Why it matters

Without it, browsers may interpret files (like scripts or styles) as executable code even if they are served with an incorrect MIME type, opening the door to cross-site scripting and other exploits.

Recommended fix

Add the header X-Content-Type-Options: nosniff to all responses. This can be configured in the web server or application framework settings.

MEDIUM missing-x-frame-options via header-analysis

Missing X-Frame-Options header

💡 Add x-frame-options header to improve security
<https://cityhangaround.com/>

🔗 **AI EXPLANATION** for MEDIUM — missing-x-frame-options

What it means

The site does not send an X-Frame-Options HTTP header, which tells browsers whether the page is allowed to be displayed inside an iframe on other sites. Without this header, any site can embed the page, potentially tricking users into interacting with it in a hidden frame.

Why it matters

Embedding a page in a malicious frame can lead to clickjacking attacks, where users unknowingly click on hidden buttons or links that perform unwanted actions. This can compromise user accounts, steal credentials, or spread malware. It also undermines user trust in the site's security posture.

Recommended fix

Add an X-Frame-Options header to the server response. Use "SAMEORIGIN" to allow framing only by the same domain, or "DENY" to block framing entirely. Alternatively, implement a Content-Security-Policy frame-ancestors directive for finer control.

MEDIUM sensitive-url via crawl-analysis

URL may contain sensitive data: <https://cityhangaround.com/forgot-password>
<https://cityhangaround.com/forgot-password>

🔗 **AI EXPLANATION** for MEDIUM — sensitive-url

What it means

The URL path "forgot-password" is exposed in the browser address bar, indicating a page that handles password reset requests. This makes it obvious to attackers that the site has a password reset feature and can be targeted for brute-force or phishing attempts.

Why it matters

Exposing sensitive actions in URLs can aid attackers in crafting targeted attacks, such as phishing emails that mimic the reset flow or automated scripts that try to guess user accounts. It also increases the risk of leaking sensitive data if the URL is logged or shared inadvertently.

Recommended fix

Move the password reset logic to a POST endpoint that does not expose the action in the URL. Use a token-based reset link that is sent via email and expires quickly. Ensure the reset form is served over HTTPS and that any sensitive data is transmitted only in the request body.

MEDIUM sensitive-url via crawl-analysis

URL may contain sensitive data: <https://cityhangaround.com/auth/google>
<https://cityhangaround.com/auth/google>

🔗 **AI EXPLANATION** for MEDIUM — sensitive-url

What it means

The URL "auth/google" reveals that the site uses Google OAuth for authentication. This path is publicly visible and can be used by attackers to attempt unauthorized access or to discover the authentication flow.

Why it matters

Publicly exposing authentication endpoints can help attackers identify potential vulnerabilities, such as misconfigured redirect URIs or weak client secrets. It also increases the surface area for phishing or credential stuffing attacks targeting the OAuth flow.

Recommended fix

Implement the OAuth flow using secure, POST-based redirects and ensure that any tokens or state parameters are not included in the URL query string. Use HTTPS exclusively, set the "SameSite" and "Secure" flags on cookies, and validate the "state" parameter to protect against CSRF. Consider using a more generic endpoint name or obfuscating the path if feasible.

MEDIUM sensitive-url via crawl-analysis

URL may contain sensitive data: <https://cityhangaround.com/auth/facebook>

🔗 AI EXPLANATION for MEDIUM — sensitive-url

What it means

The URL https://cityhangaround.com/auth/facebook appears to be used for authentication via Facebook. Because it is exposed publicly, it may inadvertently reveal sensitive information such as tokens, session identifiers, or user data if not properly protected.

Why it matters

Exposing sensitive data in a URL can lead to security vulnerabilities, including credential leakage or unauthorized access. Users may lose trust if they suspect their personal information is at risk, and the site could face compliance or legal issues.

Recommended fix

Ensure that any authentication URLs do not contain sensitive query parameters or tokens. Use secure, server-side handling for authentication flows, and consider redirecting to a dedicated login page that does not expose sensitive data in the URL.

LOW 10010 via owasp-zap

Cookie No HttpOnly Flag

https://cityhangaround.com/

LOW 10017 via owasp-zap

Cross-Domain JavaScript Source File Inclusion

https://cityhangaround.com/

LOW 10035 via owasp-zap

Strict-Transport-Security Disabled

https://cityhangaround.com/

LOW 10096 via owasp-zap

Timestamp Disclosure - Unix

https://cityhangaround.com/

LOW 10037 via owasp-zap

Server Leaks Information via "X-Powered-By" HTTP Response Header Field(s)

https://cityhangaround.com/

LOW missing-x-xss-protection via header-analysis

Missing X-XSS-Protection header

💡 Add x-xss-protection header to improve security

https://cityhangaround.com/

LOW missing-referrer-policy via header-analysis

Missing Referrer-Policy header

💡 Add referrer-policy header to improve security

https://cityhangaround.com/

LOW missing-permissions-policy via header-analysis

Missing Permissions-Policy header

💡 Add permissions-policy header to improve security

https://cityhangaround.com/

INFORMATIONAL 10027 via owasp-zap

Information Disclosure - Suspicious Comments

https://cityhangaround.com/

INFORMATIONAL 10109 via owasp-zap

Modern Web Application

https://cityhangaround.com/

SslTls

completed 100 33.7s

SOURCE

sslyze

SSLYZEAVAILABLE

true

SSLYZEVERSION

detected

TOTALFINDINGS

0

CRITICAL

HIGH

MEDIUM

LOW

0

0

0

0

No findings

Seo

completed

75

0.4s

PAGESANALYZED

18

TOTALPAGESDISCOVERED

18

TITLELENGTH

71

DESCRIPTIONLENGTH

169

HASKEYWORDS

false

H1COUNT

4

HEADINGLEVELS

h1, h2, h3, h4, h5, h6

HASCANONICAL

false

OGTAGSPRESENT

0

OGTAGSTOTAL

5

TWTTERTAGSPRESENT

0

IMAGESTOTAL

651

IMAGESWITHOUTALT

34

PAGESMISSINGH1

17

INTERNALLINKS

1313

EXTERNALLINKS

15

AVERAGEWORDCOUNT

118

PAGESWITHCONTENT

18

HASSITEMAP

true

HASROBOTSMETA

false

LOW long-title

Title is too long (71 chars) - may be truncated in SERPs

LOW long-description

Meta description is too long (169 chars)

MEDIUM multiple-h1

Multiple H1 tags found (4)

🔧 AI EXPLANATION for MEDIUM — multiple-h1

What it means

The page contains four H1 elements instead of the recommended single H1. Search engines use the H1 to understand the main topic of a page; having multiple can dilute that signal and confuse crawlers. It may also affect how the page is displayed in search results. Fix by keeping only one H1 and moving the other headings to H2 or H3 levels.

Why it matters

Search engines expect a single H1 to identify the primary topic; multiple H1s can split keyword focus and reduce the page's SEO effectiveness. It can also confuse users and accessibility tools that rely on a clear heading hierarchy. A single, well-crafted H1 improves ranking signals and user experience.

Recommended fix

Consolidate the four H1 tags into one main heading that reflects the page's core topic. Reassign the remaining headings to appropriate H2 or H3 levels to maintain a logical structure. Verify the change with a browser inspector or SEO tool to ensure only one H1 remains.

MEDIUM missing-canonical

No canonical URL specified

🔧 AI EXPLANATION for MEDIUM — missing-canonical

What it means

The site does not specify a canonical URL for its pages. Without a canonical tag, search engines may treat different URLs as separate pages, leading to duplicate content issues and split ranking signals.

Why it matters

Duplicate content can dilute page authority, cause ranking confusion, and make it harder to manage which version of a page appears in search results. It also hampers the ability to consolidate link equity and track analytics accurately.

Recommended fix

Add a rel="canonical" link tag in the head of each page pointing to the preferred URL. Ensure the canonical URL matches the canonical version you want search engines to index. Test the implementation with a browser or SEO tool to confirm the tag is present.

LOW missing-og-tags

Missing Open Graph tags: og:title, og:description, og:image, og:url, og:type

LOW missing-twitter-tags

Most Twitter Card tags are missing

LOW images-no-alt
34 images missing alt text

MEDIUM pages-missing-h1
17 of 18 pages missing H1 tag

 **AI EXPLANATION** for MEDIUM — pages-missing-h1

What it means

Seventeen out of eighteen pages lack an H1 heading. H1 tags help search engines and users quickly identify the main topic of a page, and they are also important for accessibility.

Why it matters

Missing H1 can hurt SEO performance by reducing the page’s relevance signals and can make the content harder to navigate for screen readers and other assistive technologies.

Recommended fix

Add a unique H1 to each page that accurately describes its content. Use descriptive, keyword-relevant text and maintain a clear heading hierarchy with H2/H3 tags for subtopics. Verify the changes with a browser inspector or SEO audit tool.

BrokenLinks

completed 96 40.4s

TOTALDISCOVERED 252	TOTALCHECKED 150	SAMPLED true	BROKENCOUNT 8
REDIRECTCOUNT 12	WORKINGCOUNT 130	SKIPPEDBYLIMIT 102	SKIPPEDBYFILTER 4
EXTERNALLINKS 15	INTERNALLINKS 224	COVERAGENOTE Priority-sampled 150 of 252 discovered URLs. 102 URLs were not checked.	

MEDIUM broken-link via link-checker

Broken link: <https://cityhangaround.com/agar/badagaon/education/battle-arena-page/education/note-book> (Status: 404)

<https://cityhangaround.com/agar/badagaon/education/battle-arena-page/education/note-book>

 **AI EXPLANATION** for MEDIUM — broken-link

What it means

The link <https://cityhangaround.com/agar/badagaon/education/battle-arena-page/education/note-book> returns a 404 status, indicating that the requested page does not exist on the server.

Why it matters

Broken links frustrate users, reduce site credibility, and negatively impact search engine rankings. They can also waste crawl budget and lead to lost traffic.

Recommended fix

Verify the correct URL for the intended resource and update the link accordingly. If the page has been removed, either delete the link or set up a 301 redirect to a relevant page to preserve user flow.

MEDIUM broken-link via link-checker

Broken link: <https://cityhangaround.com/dibai/mahadev-chauraha-railway-road/bath-soap/jitin-sai-traders/bath-soap/lux-bathing-bar-100-gm-5> (Status: 404)

<https://cityhangaround.com/dibai/mahadev-chauraha-railway-road/bath-soap/jitin-sai-traders/bath-soap/lux-bathing-bar-100-gm-5>

 **AI EXPLANATION** for MEDIUM — broken-link

What it means

The URL <https://cityhangaround.com/dibai/mahadev-chauraha-railway-road/bath-soap/jitin-sai-traders/bath-soap/lux-bathing-bar-100-gm-5> returns a 404 error, meaning the requested resource cannot be found.

Why it matters

A 404 error can confuse visitors, reduce trust in the site, and harm search engine visibility. It also wastes bandwidth and can affect overall site performance.

Recommended fix

Check whether the product page still exists and correct the URL if it has changed. If the product is no longer available, remove the link or redirect it to a relevant category or search page to maintain a smooth user experience.

MEDIUM broken-link via link-checker

Broken link: <https://cityhangaround.com/dibai/mahadev-chauraha-railway-road/washing-powder/jitin-sai-traders/washing-powder/surf-excel-detergent-1-kg> (Status: 404)

<https://cityhangaround.com/dibai/mahadev-chauraha-railway-road/washing-powder/jitin-sai-traders/washing-powder/surf-excel-detergent-1-kg>

 **AI EXPLANATION** for MEDIUM — broken-link

What it means

The link points to a page that no longer exists, returning a 404 Not Found error. This indicates that the resource has been removed or the URL is incorrect.

Why it matters

Users clicking the link will encounter a dead end, leading to frustration and a perception of poor site maintenance. Search engines also penalize sites with many broken links, which can hurt rankings and visibility.

Recommended fix

Verify the correct URL for the product and update the link accordingly. If the product is no longer available, remove the link or replace it with a relevant alternative. Consider setting up a 301 redirect if the page has moved to preserve link equity.

MEDIUM broken-link via link-checker

Broken link: <https://cityhangaround.com/dibai/mahadev-chauraha-railway-road/indian-masala/jitin-sai-traders/indian-masala/dhaniya-powder-250-gm> (Status: 404)

<https://cityhangaround.com/dibai/mahadev-chauraha-railway-road/indian-masala/jitin-sai-traders/indian-masala/dhaniya-powder-250-gm>

 **AI EXPLANATION** for MEDIUM — broken-link

What it means

This hyperlink leads to a non-existent page, resulting in a 404 error. The target resource is missing or the URL is malformed.

Why it matters

Broken links degrade user experience and can signal neglect to visitors, potentially reducing trust. They also negatively impact SEO by creating crawl errors and diluting link authority.

Recommended fix

Locate the correct URL for the dhaniya powder product and update the link. If the product has been discontinued, remove the link or replace it with a similar item. Implement a 301 redirect if the content has moved to maintain link value.

MEDIUM broken-link via link-checker

Broken link: <https://cityhangaround.com/alirajpur/khandala/gymbag-grooming/approved-gym-listing/gymbag-grooming/gym-equipment> (Status: 404)

<https://cityhangaround.com/alirajpur/khandala/gymbag-grooming/approved-gym-listing/gymbag-grooming/gym-equipment>

 **AI EXPLANATION** for MEDIUM — broken-link

What it means

The link directs to a page that does not exist, returning a 404 Not Found status. This indicates that the gym equipment page is missing or the URL is incorrect.

Why it matters

Users searching for gym equipment will be met with a dead link, harming usability and potentially driving them away. Search engines treat broken links as a sign of poor site quality, which can lower rankings.

Recommended fix

Find the correct URL for the gym equipment listing and update the link. If the page has been removed, delete the link or replace it with a relevant alternative. Use a 301 redirect if the content has moved to preserve link equity.

MEDIUM broken-link via link-checker

Broken link: <https://cityhangaround.com/dibai/mahadev-chauraha-railway-road/cooking-oil/jitin-sai-traders/cooking-oil/fortune-refind-oil-1-liter> (Status: 404)

<https://cityhangaround.com/dibai/mahadev-chauraha-railway-road/cooking-oil/jitin-sai-traders/cooking-oil/fortune-refind-oil-1-liter>

 **AI EXPLANATION** for MEDIUM — broken-link

What it means

The link points to a page that no longer exists, returning a 404 Not Found error. This indicates that the resource has been removed or the URL is incorrect.

Why it matters

Users clicking the link will encounter a dead end, which can frustrate them and reduce trust in the site. Search engines also penalize sites with many broken links, potentially lowering rankings.

Recommended fix

Locate the correct URL for the product or page and update the link. If the product is no longer available, remove the link or replace it with a relevant alternative. Consider setting up a 301 redirect if the content has moved.

MEDIUM broken-link via link-checker

Broken link: <https://cityhangaround.com/dibai/mahadev-chauraha-railway-road/indian-spices/jitin-sai-traders/indian-spices/mirch-powder-250-gm> (Status: 404)

<https://cityhangaround.com/dibai/mahadev-chauraha-railway-road/indian-spices/jitin-sai-traders/indian-spices/mirch-powder-250-gm>

 **AI EXPLANATION** for MEDIUM — broken-link

What it means

This URL returns a 404 error, meaning the page cannot be found. The link is broken due to a missing or incorrectly typed resource.

Why it matters

Broken links degrade user experience and can hurt SEO by creating crawl errors. They also signal to users that the site may be poorly maintained.

Recommended fix

Verify the correct product URL and update the link accordingly. If the product has been discontinued, remove the link or replace it with a similar item. Implement a redirect if the content has moved to a new location.

MEDIUM broken-link via link-checker

Broken link: <https://cityhangaround.com/dibai/mahadev-chauraha-railway-road/indian-pickle/jitin-sai-traders/indian-pickle/mango-pickle-1-kg> (Status: 404)

<https://cityhangaround.com/dibai/mahadev-chauraha-railway-road/indian-pickle/jitin-sai-traders/indian-pickle/mango-pickle-1-kg>

 **AI EXPLANATION** for MEDIUM — broken-link

What it means

The link leads to a 404 Not Found page, indicating the resource is missing or the URL is wrong.

Why it matters

Users will be directed to a dead page, causing frustration and potentially driving them away. Search engines may lower the site's authority due to broken links.

Recommended fix

Find the correct URL for the mango pickle product and update the link. If the product is no longer sold, delete the link or replace it with a related item. Add a 301 redirect if the page has moved to a new address.

LOW redirect-link via link-checker

Redirect: <https://cityhangaround.com/auth/google> → [https://accounts.google.com/v3/signin/identifier?opparams=%253F&dsh=S-718549142%3A1790827622105480&client_id=688878155235-las7p5a9sora9vp91aai0c2lstfebdtl.apps.googleusercontent.com&o2v=1&redirect_uri=https%3A%2F%2Fcityhangaround.com%2Fauth%2Fgoogle%2Fcallback&response_type=ccGT0Djg0sx4kH3G6D85HB__9xPw5wKHi--0rBldxBy818VY9Er15is5W9YKNEdARMhKa4TkZLVANxRyLThTD4B2wHkkZITW9IN41upjkov35VndSLAuE_m0j-awmDowFIZPWAwx7rSgXFiU047RreW5nPym-3ccvxV_FHonwZwz5oyCnSK-Z-5HM55bprr--xgCJhrf32kwCZX3a1o7MIHkV-qSSe8ZNRQ68UI7Zae-_kZn1PJRm1yadHblslonfYcDlVlnB_MjtnRsBSAPoh5WQGpgvflsW3x9HKzGjz-B_rLKb_GSEhURvZVvO3Da3JtYsrlPGebAvrvfz68i5nS7DQPgj1BEjubHTYKoS7J-zDEheTV0UsM6sp39AC884HaG9h1bCnWfUvHSIUxg36CZ7G980ngGm842TocXDCdnbQb5Jw6XykXSA%26flowName%3DGeneralOAuthFlow%26as%3DS-718549142%253A1790827622105480%26client_id%3D688878155235-las7p5a9sora9vp91aai0c2lstfebdtl.apps.googleusercontent.com%23&app_domain=https%3A%2F%2Fcityhangaround.com&rart=ANGoxcf4eW8eRgCGf6DAQuv9eD_ev4DQEAS9cWwXluYzsq1F7MHFFAgOBi5Ssd-8bcJyt\\$4GOs9Xlgkha3nOLL2QYZMk9uUvzyI](https://accounts.google.com/v3/signin/identifier?opparams=%253F&dsh=S-718549142%3A1790827622105480&client_id=688878155235-las7p5a9sora9vp91aai0c2lstfebdtl.apps.googleusercontent.com&o2v=1&redirect_uri=https%3A%2F%2Fcityhangaround.com%2Fauth%2Fgoogle%2Fcallback&response_type=ccGT0Djg0sx4kH3G6D85HB__9xPw5wKHi--0rBldxBy818VY9Er15is5W9YKNEdARMhKa4TkZLVANxRyLThTD4B2wHkkZITW9IN41upjkov35VndSLAuE_m0j-awmDowFIZPWAwx7rSgXFiU047RreW5nPym-3ccvxV_FHonwZwz5oyCnSK-Z-5HM55bprr--xgCJhrf32kwCZX3a1o7MIHkV-qSSe8ZNRQ68UI7Zae-_kZn1PJRm1yadHblslonfYcDlVlnB_MjtnRsBSAPoh5WQGpgvflsW3x9HKzGjz-B_rLKb_GSEhURvZVvO3Da3JtYsrlPGebAvrvfz68i5nS7DQPgj1BEjubHTYKoS7J-zDEheTV0UsM6sp39AC884HaG9h1bCnWfUvHSIUxg36CZ7G980ngGm842TocXDCdnbQb5Jw6XykXSA%26flowName%3DGeneralOAuthFlow%26as%3DS-718549142%253A1790827622105480%26client_id%3D688878155235-las7p5a9sora9vp91aai0c2lstfebdtl.apps.googleusercontent.com%23&app_domain=https%3A%2F%2Fcityhangaround.com&rart=ANGoxcf4eW8eRgCGf6DAQuv9eD_ev4DQEAS9cWwXluYzsq1F7MHFFAgOBi5Ssd-8bcJyt$4GOs9Xlgkha3nOLL2QYZMk9uUvzyI)

<https://cityhangaround.com/auth/google>

LOW redirect-link via link-checker

Redirect: <https://cityhangaround.com/auth/facebook> → https://www.facebook.com/login.php?skip_api_login=1&api_key=1112075843555936&kid_directed_site=0&app_id=1112075843555936&signed_next=1&next=https%3A%2F%2Fwww.facebook.com%2Fv23.0%2Fdia0a7b-4c39-9a82-146dc6a71ab1%26tp%3Dunspecified&cancel_url=https%3A%2F%2Fcityhangaround.com%2Fauth%2Ffacebook%2Fcallback%3Ferror%3Daccess_denied%26error_code%3D200%3F

<https://cityhangaround.com/auth/facebook>

LOW redirect-link via link-checker

Redirect: <https://cityhangaround.com/events/create> → <https://cityhangaround.com/login>

<https://cityhangaround.com/events/create>

LOW redirect-link via link-checker

Redirect: <https://cityhangaround.com/admin/page/create> → <https://cityhangaround.com/login>

<https://cityhangaround.com/admin/page/create>

LOW redirect-link via link-checker

Redirect: <https://cityhangaround.com/user/subscriptions/view> → <https://cityhangaround.com/login>

<https://cityhangaround.com/user/subscriptions/view>

LOW redirect-link via link-checker

Redirect: <https://cityhangaround.com/blog/create> → <https://cityhangaround.com/login>

<https://cityhangaround.com/blog/create>

LOW redirect-link via link-checker

Redirect: <https://cityhangaround.com/products/create> → <https://cityhangaround.com/login>

<https://cityhangaround.com/products/create>

LOW redirect-link via link-checker

Redirect: <https://cityhangaround.com/home> → <https://cityhangaround.com/login>

<https://cityhangaround.com/home>

LOW redirect-link via link-checker

Redirect: <https://cityhangaround.com/profile> → <https://cityhangaround.com/login>
<https://cityhangaround.com/profile>

LOW redirect-link via link-checker

Redirect: <https://cityhangaround.com/videos> → <https://cityhangaround.com/login>
<https://cityhangaround.com/videos>

LOW redirect-link via link-checker

Redirect: <https://cityhangaround.com/about/page/view> → <https://cityhangaround.com/login>
<https://cityhangaround.com/about/page/view>

LOW redirect-link via link-checker

Redirect: <https://cityhangaround.com/policy/page/view> → <https://cityhangaround.com/login>
<https://cityhangaround.com/policy/page/view>

Recommendations

- **HIGH:** Missing HSTS header
- **HIGH:** Missing CSP header
- **CRITICAL:** Ensure elements have alternative text or a role of none or presentation
- **HIGH:** Ensure the contrast between foreground and background colors meets WCAG 2 AA minimum contrast ratio thresholds
- **HIGH:** Ensure elements that have scrollable content are accessible by keyboard in Safari
- **HIGH:** Poor LCP: 9.8 s