







Corrected ISO 52016-1 against a matched EnergyPlus reference

AUS_VIC_Melbourne-Essendon.Fields.958660_TMYx.2011-2025.epw · each engine against a reference matched to it · EnergyPlus 24.1.0

Baseline engine, matched reference



Corrected engine, matched reference



Percentage differences are relative to the EnergyPlus reference. Each row is on its own scale — the corrected loads are about a fifteenth of the baseline ones, and a shared axis would show the size of the corrections rather than the quality of the agreement. Both references carry the three IDF repairs described in validation_corrected.md.