DEMO DATA: this report was generated from a synthetic field, not a real survey.

Crop Health Report · ಬೆಳೆ ಆರೋಗ್ಯ ವರದಿ

Pandavapura Paddy Plot · Suresh Kumar · Farmer ID MDY-003 · Pandavapura, Mandya

Survey s_10a30cce
03 Nov 2026, 04:00 UTC


Summary · ಸಾರಾಂಶ

Field area	Areas to inspect	Suspicious area	Share of crop
11325 m²	**9**	**1110 m²**	**9.8%**

9 area(s) covering 9.8% of your crop (1110 m²) look unusual and should be inspected on the ground.

ನಿಮ್ಮ ಬೆಳೆಯ 9.8% ಭಾಗದಲ್ಲಿ (9 ಪ್ರದೇಶಗಳು) ಅಸಾಮಾನ್ಯತೆ ಕಂಡುಬಂದಿದೆ. ಹೊಲದಲ್ಲಿ ಪರಿಶೀಲಿಸಿ.

Field map · ಜಮೀನಿನ ನಕ್ಷೆ



Numbered circles mark areas to inspect. Brighter colour means a stronger deviation from this field's normal appearance.

Areas to inspect · ಪರಿಶೀಲಿಸಬೇಕಾದ ಪ್ರದೇಶಗಳು

#	Priority	Area	Confidence	What the pattern suggests	Ground check
1 h_8a0adc7b	LOW / abiotic	19 m²	high	Inspect on the ground to confirm the cause.	Pending
2 h_4f441f80	LOW / abiotic	10 m²	high	Inspect on the ground to confirm the cause.	Pending
3 h_2f221f02	LOW / abiotic	8 m²	high	striping	Pending
4 h_d6e12a3d	LOW / abiotic	12 m²	high	striping	Pending
5 h_a62055e4	LOW / abiotic	6 m²	high	striping	Pending
6 h_3f1d6749	LOW / abiotic	12 m²	high	Inspect on the ground to confirm the cause.	Pending
7 h_d350a25c	LOW / abiotic	6 m²	high	striping	Pending
8 h_237c7b73	LOW / abiotic	69 m²	high	Inspect on the ground to confirm the cause.	Pending
9 h_810a34d4	LOW / abiotic	967 m²	high	large_smooth_zone	Pending

Important. Hotspots indicate potential crop anomalies and require field verification. They are not a diagnosis.
ಇವು ಸಂಭವನೀಯ ಸಮಸ್ಯೆ ಪ್ರದೇಶಗಳು ಮಾತ್ರ. ಕೀಟ ಅಥವಾ ರೋಗವನ್ನು ಖಚಿತಪಡಿಸಲು ಹೊಲದಲ್ಲಿ ಪರಿಶೀಲನೆ ಅಗತ್ಯ.

Priority shows how urgently to inspect, not how severe a disease is. Confidence reflects image quality, agreement between the texture and vegetation-index signals, and area size; it is not a probability of damage. Kannada text is illustrative and pending review by a Kannada-speaking agricultural expert.