STAND-IN IMAGERY: shown to demonstrate the pipeline; this field has no ground-verified pest or disease records.

Crop Health Report · ಬೆಳೆ ಆರೋಗ್ಯ ವರದಿ

Kikkeri Paddy Plot A · Ramesh Gowda · Farmer ID MDY-001 · Kikkeri, Mandya

Survey s_a57e1c46
03 Nov 2026, 04:29 UTC


Summary · ಸಾರಾಂಶ

Field area	Areas to inspect	Suspicious area	Share of crop
530 m²	**1**	**137 m²**	**25.9%**

1 area(s) covering 25.9% of your crop (137 m²) look unusual and should be inspected on the ground.

ನಿಮ್ಮ ಬೆಳೆಯ 25.9% ಭಾಗದಲ್ಲಿ (1 ಪ್ರದೇಶಗಳು) ಅಸಾಮಾನ್ಯತೆ ಕಂಡುಬಂದಿದೆ. ಹೊಲದಲ್ಲಿ ಪರಿಶೀಲಿಸಿ.

Field map · ಜಮೀನಿನ ನಕ್ಷೆ



Numbered circles mark areas to inspect. Brighter colour means a stronger deviation from this field's normal appearance.

Areas to inspect · ಪರಿಶೀಲಿಸಬೇಕಾದ ಪ್ರದೇಶಗಳು

#	Priority	Area	Confidence	What the pattern suggests	Ground check
1 h_7e173c1a	HIGH priority	137 m²	high	Inspect on the ground to confirm the cause.	Pending

Important. Hotspots indicate potential crop anomalies and require field verification. They are not a diagnosis.
ಇವು ಸಂಭವನೀಯ ಸಮಸ್ಯೆ ಪ್ರದೇಶಗಳು ಮಾತ್ರ. ಕೀಟ ಅಥವಾ ರೋಗವನ್ನು ಖಚಿತಪಡಿಸಲು ಹೊಲದಲ್ಲಿ ಪರಿಶೀಲನೆ ಅಗತ್ಯ.

Priority shows how urgently to inspect, not how severe a disease is. Confidence reflects image quality, agreement between the texture and vegetation-index signals, and area size; it is not a probability of damage. Kannada text is illustrative and pending review by a Kannada-speaking agricultural expert.