DEMO DATA: this report was generated from a synthetic field, not a real survey.

Crop Health Report · ಬೆಳೆ ಆರೋಗ್ಯ ವರದಿ

Kikkeri Paddy Plot B · Ramesh Gowda · Farmer ID MDY-001 · Kikkeri, Mandya

Survey s_fbf70123
03 Nov 2026, 04:00 UTC


Summary · ಸಾರಾಂಶ

Field area	Areas to inspect	Suspicious area	Share of crop
11325 m²	**17**	**509 m²**	**4.5%**

17 area(s) covering 4.5% of your crop (509 m²) look unusual and should be inspected on the ground.

ನಿಮ್ಮ ಬೆಳೆಯ 4.5% ಭಾಗದಲ್ಲಿ (17 ಪ್ರದೇಶಗಳು) ಅಸಾಮಾನ್ಯತೆ ಕಂಡುಬಂದಿದೆ. ಹೊಲದಲ್ಲಿ ಪರಿಶೀಲಿಸಿ.

Field map · ಜಮೀನಿನ ನಕ್ಷೆ



Numbered circles mark areas to inspect. Brighter colour means a stronger deviation from this field's normal appearance.

Areas to inspect · ಪರಿಶೀಲಿಸಬೇಕಾದ ಪ್ರದೇಶಗಳು

#	Priority	Area	Confidence	What the pattern suggests	Ground check
1 h_839fb1c2	HIGH priority	19 m²	high	Inspect on the ground to confirm the cause.	Pending
2 h_8a86190a	HIGH priority	35 m²	high	Inspect on the ground to confirm the cause.	Pending
3 h_71ec44fc	HIGH priority	23 m²	high	Inspect on the ground to confirm the cause.	Pending
4 h_3e58fff9	HIGH priority	37 m²	high	Inspect on the ground to confirm the cause.	Pending
5 h_ffda70f9	HIGH priority	39 m²	high	Inspect on the ground to confirm the cause.	Pending
6 h_f716587a	HIGH priority	29 m²	high	Inspect on the ground to confirm the cause.	Pending
7 h_99c96785	HIGH priority	21 m²	high	Inspect on the ground to confirm the cause.	Pending
8 h_9b1dc873	HIGH priority	10 m²	high	Inspect on the ground to confirm the cause.	Pending
9 h_797c681d	MEDIUM priority	15 m²	medium	Inspect on the ground to confirm the cause.	Pending

10 h_e9c666b6	LOW / abiotic	12 m²	high	striping	Pending
11 h_7a598554	LOW / abiotic	6 m²	medium	striping	Pending
12 h_dbbeda63	LOW / abiotic	23 m²	high	Inspect on the ground to confirm the cause.	Pending
13 h_8b73d356	LOW / abiotic	15 m²	high	Inspect on the ground to confirm the cause.	Pending
14 h_b5122b02	LOW / abiotic	17 m²	high	Inspect on the ground to confirm the cause.	Pending
15 h_72fd5bb6	LOW / abiotic	6 m²	high	striping	Pending
16 h_4171d037	LOW / abiotic	8 m²	high	striping	Pending
17 h_40c6d904	LOW / abiotic	193 m²	high	large_smooth_zone	Pending

Important. Hotspots indicate potential crop anomalies and require field verification. They are not a diagnosis.
ಇವು ಸಂಭವನೀಯ ಸಮಸ್ಯೆ ಪ್ರದೇಶಗಳು ಮಾತ್ರ. ಕೀಟ ಅಥವಾ ರೋಗವನ್ನು ಖಚಿತಪಡಿಸಲು ಹೊಲದಲ್ಲಿ ಪರಿಶೀಲನೆ ಅಗತ್ಯ.

Priority shows how urgently to inspect, not how severe a disease is. Confidence reflects image quality, agreement between the texture and vegetation-index signals, and area size; it is not a probability of damage. Kannada text is illustrative and pending review by a Kannada-speaking agricultural expert.