DEMO DATA: this report was generated from a synthetic field, not a real survey.

Crop Health Report · ಬೆಳೆ ಆರೋಗ್ಯ ವರದಿ

Kikkeri Paddy Plot A · Ramesh Gowda · Farmer ID MDY-001 · Kikkeri, Mandya

Survey FARM-001-S01
02 Nov 2026, 17:09 UTC


Summary · ಸಾರಾಂಶ

Valid crop area	Areas to inspect	Suspicious area	Share of crop
1362 m²	**4**	**52 m²**	**3.83%**

4 area(s) covering 3.83% of your crop (52 m²) look unusual and should be inspected on the ground.

ನಿಮ್ಮ ಬೆಳೆಯ 3.83% ಭಾಗದಲ್ಲಿ (4 ಪ್ರದೇಶಗಳು) ಅಸಾಮಾನ್ಯತೆ ಕಂಡುಬಂದಿದೆ. ಹೊಲದಲ್ಲಿ ಪರಿಶೀಲಿಸಿ.

Field map · ಜಮೀನಿನ ನಕ್ಷೆ



Numbered circles mark areas to inspect. Brighter colour means a stronger deviation from this field's normal appearance.

Areas to inspect · ಪರಿಶೀಲಿಸಬೇಕಾದ ಪ್ರದೇಶಗಳು

#	Priority	Area	Confidence	What the pattern suggests	Ground check
1 HS_001	HIGH	17 m² (1.23%)	HIGH	Pattern consistent with localised stress. Inspect for pest damage and other causes.	Pending
2 HS_002	HIGH	16 m² (1.2%)	HIGH	Pattern consistent with localised stress. Inspect for pest damage and other causes.	Pending
3 HS_003	HIGH	11 m² (0.83%)	HIGH	Pattern consistent with localised stress. Inspect for pest damage and other causes.	Pending
4 HS_004	HIGH	8 m² (0.56%)	HIGH	Pattern consistent with localised stress. Inspect for pest damage and other causes.	Pending

Important. Hotspots indicate potential crop anomalies and require field verification. They are not a diagnosis.
ಇವು ಸಂಭವನೀಯ ಸಮಸ್ಯೆ ಪ್ರದೇಶಗಳು ಮಾತ್ರ. ಕೀಟ ಅಥವಾ ರೋಗವನ್ನು ಖಚಿತಪಡಿಸಲು ಹೊಲದಲ್ಲಿ ಪರಿಶೀಲನೆ ಅಗತ್ಯ.

Priority shows how urgently to inspect, not how severe a disease is. Confidence reflects image quality, agreement between the image and spectral analyses, and area size; it is not a probability of damage. Model agriscout-anomaly-v0.2. Kannada text is illustrative and pending review by a Kannada-speaking agricultural expert.