




A-A

DCN #	Date	(Location/Sheet) Change Description; A=Added W=Was D=Deleted
ECN - ELN27568-AE	2020-06-01	

Material: KS M6614 B III 605 (1994) (RUBBER CR12D-M1)

Tensile strength: 140kg/cm² (Min)

Hardness: Hs 70±5

Elongation rate: 300% (Min)

Anti-ozone: there should be no crack under condition of 50ppm, 40°C and 20% of elongation rate during 20hr

Color: Black

Refer to the Part Version Report for the correct document issue		
Symbols, designations and general drawing methods STD 101-0005	View placement Reference arrow method: ISO 128-30:2001	Document release status RELEASED
The copying distribution and utilization of this document as well as the communication of its contents to others without expressed authorization is prohibited. Offenders will be held liable for payment of damages. All rights reserved in the event of the grant of patent, utility model or ornamental design registration.		Document title CLAMP HAMMER & SHEAR
VOLVO Construction Equipment		Document type DRAWING
		Owner domain:Document prefix
		Document No 14775844
		Issue ---
		Sheet No 1 / 1

Format: A3

8 7 6 5 4 3 2 1

DCN # Date (Location/Sheet) Change Description; A=Added W=Was D=Deleted

ECN - ELN27568-AE 2020-06-01

Material: KS M6614 B III 605 (1994) (RUBBER CR12D-M1)

Tensile strength: 140kg/cm² (Min)

Hardness: Hs 70±5

Elongation rate: 300% (Min)

Anti-ozone: there should be no crack under condition of 50ppm, 40°C and 20% of elongation rate during 20hr

Color: Black

Refer to the Part Version Report for the correct document issue

Symbols, designations and general drawing methods STD 101-0005	View placement Reference arrow method: ISO 128-30:2001	Document release status RELEASED	
The copying distribution and utilization of this document as well as the communication of its contents to others without expressed authorization is prohibited. Offenders will be held liable for payment of damages. All rights reserved in the event of the grant of patent, utility model or ornamental design registration.		Document title CLAMP HAMMER & SHEAR	
VOLVO Construction Equipment		Document type DRAWING	
		Owner domain:Document prefix	
		Document No 14775844	Issue ---

Format: A3

8 7 6 5 4 3 2 1

DCN # Date (Location/Sheet) Change Description; A=Added W=Was D=Deleted

ECN - ELN27568-AE 2020-06-01

Material: KS M6614 B III 605 (1994) (RUBBER CR12D-M1)

Tensile strength: 140kg/cm² (Min)

Hardness: Hs 70±5

Elongation rate: 300% (Min)

Anti-ozone: there should be no crack under condition of 50ppm, 40°C and 20% of elongation rate during 20hr

Color: Black

Refer to the Part Version Report for the correct document issue

Symbols, designations and general drawing methods STD 101-0005	View placement Reference arrow method: ISO 128-30:2001	Document release status RELEASED	
The copying distribution and utilization of this document as well as the communication of its contents to others without expressed authorization is prohibited. Offenders will be held liable for payment of damages. All rights reserved in the event of the grant of patent, utility model or ornamental design registration.		Document title CLAMP HAMMER & SHEAR	
VOLVO Construction Equipment		Document type DRAWING	
		Owner domain:Document prefix	
		Document No 14775844	Issue ---

Format: A3

8 7 6 5 4 3 2 1

DCN # Date (Location/Sheet) Change Description; A=Added W=Was D=Deleted

ECN - ELN27568-AE 2020-06-01

Material: KS M6614 B III 605 (1994) (RUBBER CR12D-M1)

Tensile strength: 140kg/cm² (Min)

Hardness: Hs 70±5

Elongation rate: 300% (Min)

Anti-ozone: there should be no crack under condition of 50ppm, 40°C and 20% of elongation rate during 20hr

Color: Black

Refer to the Part Version Report for the correct document issue

Symbols, designations and general drawing methods STD 101-0005	View placement Reference arrow method: ISO 128-30:2001	Document release status RELEASED	
The copying distribution and utilization of this document as well as the communication of its contents to others without expressed authorization is prohibited. Offenders will be held liable for payment of damages. All rights reserved in the event of the grant of patent, utility model or ornamental design registration.		Document title CLAMP HAMMER & SHEAR	
VOLVO Construction Equipment		Document type DRAWING	
		Owner domain:Document prefix	
		Document No 14775844	Issue ---

Format: A3

8

7

6

5

4

3

2

1

F

E

D

C

B

A

Format: A3

DCN #	Date	(Location/Sheet) Change Description; A=Added W=Was D=Deleted
ECN - ELN27568-AE	2020-06-01	

Material: KS M6614 B III 605 (1994) (RUBBER CR12D-M1)

Tensile strength: 140kg/cm² (Min)

Hardness: Hs 70±5

Elongation rate: 300% (Min)

Anti-ozone: there should be no crack under condition of 50ppm, 40°C and 20% of elongation rate during 20hr

Color: Black

Refer to the Part Version Report for the correct document issue			
Symbols, designations and general drawing methods STD 101-0005	View placement Reference arrow method: ISO 128-30:2001	Document release status RELEASED	
The copying distribution and utilization of this document as well as the communication of its contents to others without expressed authorization is prohibited. Offenders will be held liable for payment of damages. All rights reserved in the event of the grant of patent, utility model or ornamental design registration.		Document title CLAMP HAMMER & SHEAR	
		Document type DRAWING	
		Owner domain: Document prefix	
		Document No 14775844	Issue ---

[illegible]

4		3		2		1	
DCN #		Date	(Location/Sheet) Change Description; A=Added W=Was D=Deleted				
ECN - ELN27568-AE		2020-06-01					

Material: KS M6614 B III 605 (1994) (RUBBER CR12D-M1)

Tensile strength: 140kg/cm² (Min)

Hardness: Hs 70±5

Elongation rate: 300% (Min)

Anti-ozone: there should be no crack under condition of 50ppm, 40°C and 20% of elongation rate during 20hr

Color: Black

Refer to the Part Version Report for the correct document issue			
Symbols, designations and general drawing methods STD 101-0005	View placement Reference arrow method: ISO 128-30:2001	Document release status RELEASED	
The copying distribution and utilization of this document as well as the communication of its contents to others without expressed authorization is prohibited. Offenders will be held liable for payment of damages. All rights reserved in the event of the grant of patent, utility model or ornamental design registration.		Document title CLAMP HAMMER & SHEAR	
VOLVO Construction Equipment		Document type DRAWING	
		Owner domain: Document prefix	
		Document No 14775844	Issue ---

Top view of the rubber clamp. The overall width is 135 mm. The distance between the centers of the two circular holes is 90 ±0.5 mm. The height of the part is 45 mm. The holes have a diameter of 26 mm (2 × Ø26). Section lines A-A are indicated at both ends.

A-A

Cross-sectional view A-A of the rubber clamp. The total width is 135 mm. The height is 35 mm. The bottom edge features a semi-circular cutout with a radius of R27^{+0.5}₀. The top surface has chamfers: 2 x C3 on the outer edges and 2 x C1 on the inner edges. The central portion of the cross-section is hatched to indicate it is made of a different material or is a core.

DCN #	Date	(Location/Sheet) Change Description; A=Added W=Was D=Deleted
ECN - ELN27568-AE	2020-06-01	

Material: KS M6614 B III 605 (1994) (RUBBER CR12D-M1)

Tensile strength: 140kg/cm² (Min)

Hardness: Hs 70±5

Elongation rate: 300% (Min)

Anti-ozone: there should be no crack under condition of 50ppm, 40°C and 20% of elongation rate during 20hr

Color: Black

Refer to the Part Version Report for the correct document issue			
Symbols, designations and general drawing methods STD 101-0005	View placement Reference arrow method: ISO 128-30:2001	Document release status RELEASED	
 Construction Equipment		Document title CLAMP HAMMER & SHEAR	
		Document type DRAWING Owner domain: Document prefix	
		Document No 14775844	Issue ---
		Sheet No 1 / 1	