

Justin Brundage website usability audit

Annotated technical review

Start with narrow-screen access. Restore the missing primary navigation and wrap the homepage footer links. Then fix image loading, contact behavior, keyboard focus, and small-text contrast.

Audited origin: <https://www.jkbrundage.com>

Live evidence: October 1, 2026, 20:09-20:27 UTC

Annotated edition: October 2, 2026

Status and scope

This is a dated audit of the public site. Production was not rechecked for this annotated edition. The separate local preview uses a local Tailwind dependency and an existing portrait fallback for the missing hero. Neither proves a repair on the live site.

The review covers technical layout, navigation, accessibility risks, and functionality. It does not evaluate campaign messaging and is not a full accessibility certification.

Priority list

- 1. Primary navigation disappears below 1024 px** - High
- 2. Homepage footer links overflow the viewport** - High
- 3. Homepage hero image is missing** - Medium
- 4. Two Community images fail to load** - Medium
- 5. The contact link names a fragment that does not exist** - Medium
- 6. Blog expansion loses visible keyboard focus** - Medium
- 7. Several small text styles have low contrast** - Medium
- 8. The contact form depends on a configured email app** - Needs verification
- 9. Unfinished citation tokens appear in Community text** - Low

Numbers on the three annotated plates match the finding numbers. All screen pixels come from the preserved live audit; added outlines identify the area under discussion.

Plate 1 Navigation and reflow

Findings 1, 2, and 7: missing narrow-screen navigation, clipped footer links, and low-contrast footer text.

JUSTIN BRUNDAGE WEBSITE USABILITY AUDIT

01 Navigation and reflow

Narrow desktop-window profiles, not touch-device emulation

1

BRUNDAGE FOR SCHOOL BOARD

About Justin Brundage

A Timeline of Education, Leadership, and Public Service

Graduated Medical Lake High School

Completed high school education in Washington State, setting the foundation for

1 Restore navigation at narrow widths

390 CSS px / 150% zoom. The header shows only the logo on this inner page. Add an accessible menu or a wrapping link list.

Justin Brundage for Concrete

BRUNDAGE FOR SCHOOL BOARD

GET INVOLVED

JUSTIN BRUNDAGE

Concrete School Board Deputy Director #4 At-Large

2

ABOUT POLICY COMMUNITY BLOG CON

Paid for by Justin Brundage

Concrete, WA 98237

7

2026 Justin Brundage for Washington. All rights reserved.

Paid for by Justin Brundage.

2 Wrap footer links 7 Improve contrast

390 CSS px / 150% zoom. Footer links extend beyond the page; subdued text also needs more contrast. The horizontal scrollbar is original evidence.

Live evidence: October 1, 2026 | jkbrundage.com | Numbers match the report

Live site evidence: October 1, 2026. Annotation edition: October 2, 2026. View the web edition for full-size plates and original screenshots.

The narrow profiles were ordinary resized Chromium windows: 390 CSS px at 150% zoom and 320 CSS px at 200%. They test reflow, not mobile hardware.


Plate 2 Image loading and unfinished tokens

Findings 3, 4, and 9: missing hero image, failed Community images, and unfinished citation tokens.

JUSTIN BRUNDAGE WEBSITE USABILITY AUDIT

02 Image loading and unfinished tokens

Desktop profile: 1440 CSS px / 80% browser zoom




3 Missing hero image

The request for hero.jpg returned 404 in the live audit. Restore the intended asset and check its crop.

Preview distinction

The separate local preview uses an existing portrait fallback. That does not verify a production repair.



4 Broken image slots

Two external placeholder images failed in the tested browser. Use working local assets or remove unused regions.

9 Raw citation markers

Five [cite: 1] tokens remained in the rendered text. Replace them with meaningful references or remove the unfinished tokens.

Live evidence: October 1, 2026 | jkbrundage.com | Numbers match the report

Live site evidence: October 1, 2026. Annotation edition: October 2, 2026. View the web edition for full-size plates and original screenshots.

The local preview portrait fallback is a separate presentation choice. Restore and verify the intended live hero before closing finding 3.


Plate 3 Contact and keyboard behavior

Findings 5, 6, 7, and 8: unmatched fragment, invisible or lost focus, low-contrast text, and email-app dependency.

JUSTIN BRUNDAGE WEBSITE USABILITY AUDIT

03 Contact and keyboard behavior

Contact: 1180 CSS px / 100% zoom | Blog: 320 CSS px / 200% zoom




5 Repair the missing fragment target

The contact link ends in #get-involved, but no matching element existed. This comes from the recorded DOM check; the screenshot shows the destination.

8 Explain the email-app handoff

The form uses mailto. Delivery was not tested. Explain what the button does and provide a direct email fallback.



6 Make focus visible and restore it

The focused See More summary had a transparent outline. Closing with Show Less left focus on BODY. Add :focus-visible and return focus to the summary.

7 Darken small amber text

Amber on white measured 3.19:1; target at least 4.5:1 for normal-size text.

Live evidence: October 1, 2026 | jkbrundage.com | Numbers match the report

Live site evidence: October 1, 2026. Annotation edition: October 2, 2026. View the web edition for full-size plates and original screenshots.

The missing fragment, transparent focus outline, focus on BODY, and mailto dependency were verified with recorded live DOM checks. The screenshots show the affected areas; pixels alone do not prove those behaviors.

Findings 1 to 3

1 Primary navigation disappears below 1024 px

High | All six pages

Evidence: live site, October 1, 2026. 320 px at 200%; 390 px at 150%; boundary 1023 / 1024 px at 100%.

Observed: The desktop navigation is hidden below the 1024 px breakpoint, with no replacement menu. On inner pages, the header leaves only the home logo.

Reproduce: Open About at a 390 CSS-pixel viewport. Check the header for a way to reach Policy, Community, Blog, and Contact. Compare Home at 1023 and 1024 px.

Fix: Add a keyboard-operable mobile menu or an always-visible wrapping link list. Give a menu button an accessible name, aria-expanded, and aria-controls; keep focus and dismissal predictable.

Pass check: Every main page can be reached by keyboard and pointer at 320, 390, 768, and 1023 px. Focus remains visible and no links overlap.

2 Homepage footer links overflow the viewport

High | Home

Evidence: live site, October 1, 2026. 320 px at 200%; 390 px at 150%.

Observed: At the 390 px profile, document width was 418 px versus 380 px of content width. At 320 px, it was 384 versus 312 px. The footer navigation is visibly clipped on both sides.

Reproduce: Scroll Home to the footer at each narrow profile and inspect the first and last navigation links. Compare document scrollWidth with documentElement clientWidth.

Fix: Let the footer link row wrap, use a responsive grid, or stack links. Remove widths or no-wrap rules that force the row beyond its container.

Pass check: No horizontal page scrolling is needed; every footer link is fully visible and usable at both profiles.

3 Homepage hero image is missing

Medium | Home

Evidence: live site, October 1, 2026. 1440 px at 80%; also recorded at 320 and 390 px.

Observed: The live /static/pictures/hero.jpg request returned HTTP 404. The image had naturalWidth 0, and the hero displayed a large dark area with faint fallback text.

Reproduce: Load Home, inspect the hero, and check the image request and decoded dimensions.

Fix: Point the image to the intended existing asset, or deploy the missing file. Verify image sizing, useful alt text, and crop at narrow and wide widths.

Pass check: The intended image returns successfully and decodes; its crop and surrounding text remain usable.

Findings 4 to 6

4 Two Community images fail to load

Medium | Community

Evidence: live site, October 1, 2026. 1180 px at 100%; 1440 px at 80%.

Observed: Both external placeholder image slots were broken in the tested browser. Their decoded widths were zero; large blank card regions remained visible.

Reproduce: Open Community and inspect both card images after loading finishes.

Fix: Use approved working local images, or remove the unused image regions. Keep appropriate alternative text and explicit dimensions.

Pass check: Both intended images decode and display, or the empty regions are deliberately removed without losing useful text.

5 The contact link names a fragment that does not exist

Medium | Home to Contact

Evidence: live site, October 1, 2026. 1180 px at 100%.

Observed: Activating the homepage contact link opened `contact.html#get-involved` at the top. The live DOM contained no element matching `get-involved`.

Reproduce: Activate the Home button labeled Support the Campaign, then inspect the destination fragment and matching element.

Fix: Add `id="get-involved"` to the intended contact section, with scroll margin for the sticky header, or remove the unused fragment if the top is the intended destination.

Pass check: The destination matches the link intention and is visible below the header. Test keyboard navigation as well as pointer activation.

6 Blog expansion loses visible keyboard focus

Medium | Blog

Evidence: live site, October 1, 2026. 320 px at 200%.

Observed: Tabbing to See More produced a transparent outline with no box shadow. Expansion worked, but using the bottom Show Less button collapsed the section and left focus on BODY.

Reproduce: Tab to See More, expand with Enter, reach the bottom Show Less button, and activate it. Check the visible focus indicator and `document.activeElement`.

Fix: Add a high-contrast `:focus-visible` style to the summary and controls. When the bottom button closes the details element, explicitly return focus to its summary.

Pass check: The focused control is always visibly identifiable, and collapse returns focus to See More without an unexpected jump.

Findings 7 to 9

7 Several small text styles have low contrast

Medium | Home and Blog

Evidence: live site, October 1, 2026. Computed styles recorded on live pages; screenshot examples at 320 and 390 px.

Observed: Recorded ratios were 3.19:1 for amber on white, 2.89:1 on light gray, 3.07:1 on a pale badge, and 3.94:1 for homepage footer text. These small text styles fall below 4.5:1.

Reproduce: Inspect the computed foreground and effective background colors for small amber labels, See More, and the homepage footer; calculate contrast.

Fix: Darken text on light backgrounds and lighten subdued footer text. Check default, hover, and focus states rather than changing only one selector.

Pass check: Normal-size text reaches at least 4.5:1 against its actual background; visible focus also has sufficient contrast.

8 The contact form depends on a configured email app

Needs verification | Contact

Evidence: live site, October 1, 2026. 1180 px at 100%; structure inspected without submitting.

Observed: The form uses a mailto action with POST and text/plain. No site delivery endpoint or visible explanation of the email-app handoff was found. Delivery was not tested.

Reproduce: Inspect the form action and the instructions beside Send Message. Do not infer delivery from the presence of a form.

Fix: Clearly explain that the action opens an email draft and provide the direct email link as a fallback. A server-backed form requires a separately approved delivery integration and end-to-end test.

Pass check: The user knows what happens before activating the button. Confirm the chosen flow across supported clients; do not show a sent confirmation unless delivery is actually established.

9 Unfinished citation tokens appear in Community text

Low | Community

Evidence: live site, October 1, 2026. 1180 px at 100%; 1440 px at 80%.

Observed: Five literal [cite: 1] markers were present in visible page text.

Reproduce: Read the Community introduction and card text, or search the rendered text for [cite:.

Fix: Replace each token with a real accessible reference where needed, or remove the unfinished token after checking the underlying source.

Pass check: No raw citation tokens remain. Any references are meaningful links with readable labels.

Recheck and evidence limits

Repeat on the public site

1. Record the date, final public URL, browser version, CSS viewport, and zoom.
2. Check all six pages at 320, 390, 768, 1023, 1024, and 1440 px. Check links, image decoding, and horizontal scrolling.
3. Test keyboard navigation and Blog expansion/collapse with visible focus.
4. Verify the Contact fragment and instructions. Test actual delivery only with approval and an agreed test recipient.
5. Recalculate text contrast and inspect Community references. Save fresh evidence before closing any live finding.

What already worked

Desktop navigation appeared at the 1024 px breakpoint. Contact fields had labels and required-field semantics. Blog expansion and collapse changed the visible content, although focus behavior needed repair.

What this audit does not establish

This edition reorganizes the completed October 1 audit and does not claim a fresh browser check on October 2. Screenshots and limited DOM checks do not establish full screen-reader behavior, touch-device behavior, real email delivery, performance across networks, or complete WCAG compliance. No form was submitted, email sent, or production file changed.

Local preview status

The separate preview localizes a Tailwind dependency and substitutes the existing jbrundage.jpg portrait for the missing hero. The intended live hero remains a production recheck item. Findings 1, 2, and 4 through 9 were not addressed by those two portability changes.

Source and provenance

The original browser was Chromium 151.0.7922.173 on Debian GNU/Linux 13. The live audit used normal window resizing and browser zoom, not touch-device emulation. The main matrix covered six pages at three widths, plus the 1023/1024 px boundary and interaction checks.

Public source snapshot used for diagnosis:
[EngSmallz/BrundageForCommunity at commit 9fccd18](#)
Source inspection is not deployment verification.