
AUTOINSPECT / Inspection report


Visual quality intelligence | PatchCore baseline

Inspection	90101486f9774762821c1d3fe0076559
Timestamp (UTC)	2026-10-09T18:43:11.855510+00:00
Source image	bent.png
Model	PatchCore / ResNet18
Decision	REVIEW
Anomaly score	0.898415 (threshold 0.500000)
Processing time	11.13 seconds

Uploaded component



Anomaly overlay



Interpretation

Anomaly detected - review required. Red regions show higher anomaly response. The score is not a probability or a measurement of defect severity.

Model scope

Trained on MVTec AD metal_nut images. No defect classification or automotive acceptance validation. A known scratch sample is missed by this baseline. Human review and representative validation are required for production decisions.

Attribution: MVTec AD (Bergmann et al.), CC BY-NC-SA 4.0. Educational, noncommercial prototype.