





3S-6S LiPo Input, Clamping & Reverse Polarity Protection



Mounting holes





SWD Debug / Firmware Flashing




Primary IMU: ICM-42688-P 6-Axis MotionTracking (SPI)

Barometer: BMP390 High-Precision Altimeter (I2C1)


Blackbox: Winbond W25Q128 16MB Flash (SPI3)



USB Type-C Interface & VBUS Isolation



Avionics System Interfaces: 4-in-1 ESC, GPS/Mag, Telemetry, RC



Status Indication

