



TOP SIDE LAYER 1

FAB DRAWING
ATMOSIC TECHNOLOGIES
ATM3-ESL
17/12/2019


SIZE	QTY	SYM	PLATED	THR/PRTL	TOL
10	446	+	YES	THR	+/-3
125	4	X	YES	THR	+/-3
8	247	□	YES	THR	+0/-8
63	5	◇	YES	THR	+/-3
30 x 90	2	⧖	YES	THR	+/-3
6	27	⋈	YES	THR	+0/-6
30 x 160	2	+A	YES	THR	+/-3
42	8	+B	YES	THR	+/-3
40	40	+C	YES	THR	+/-3

NOTES: (UNLESS OTHERWISE SPECIFIED)

1) FINISHED BOARD THICKNESS TO BE 62 MILS +/- 10%.
2) SOLDERMASK TO BE LPI, COLOR : GREEN. BOTH SIDES.
3) PLATING: IMMERSION GOLD.
4) SILKSCREEN: TOP SIDE, COLOR: WHITE.
5) SEE DRILL CHART FOR FINISHED HOLE SIZES.
6) HOLE TOLERANCE IS +/- 3 MILS UNLESS OTHERWISE SPECIFIED.
7) SEE FILM FOR LAYER SEQUENCE.
8) THIS IS A 4 LAYER BOARD.
9) TRACE WIDTHS IN ARTWORK ARE FINISHED SIZES. DO NOT DEVIATE WITHOUT PRIOR AUTHORIZATION FROM ATMOSIC TECHNOLOGIES.
10) REMOVE UNUSED PADS FROM INTERNAL LAYERS.
11) BOW AND TWIST: .75% MAX ALLOWABLE .
12) COPPER THICKNESSES SHOWN ARE BEFORE PLATING.
13) FABRICATE PER IPC-6012 CLASS 2 (LATEST REVISION) UNLESS OTHERWISE SPECIFIED. PCB FAB MUST BE ROSH COMPLIANT.
14) MATERIAL: FR4 , 140 DEGREE C MIN, Tg = 150, Td = 330.
15) TEARDROPS: OK TO ADD AS NEEDED TO MEET .002 MIN .TRACE INTERCONNECTS AS PER IPC-6012 CLASS 2.
16) PCB IS A CONTROLLED IMPEDANCE DESIGN. TRACES OF 9 MIL WIDTH SHALL BE 50 OHM +/- 10%.




Clearance Check	False error : 31	Gao-Fu Technology Corp.	JOB NAME	ATM_ESL_SCH_V12	
Connectivity Check	False error : 0	http://www.gaofu.com.tw	LAYER	ARTWORK-TOP	
Plane Check	False error : 0	886-3-6682475	DATE	2019.12.17	4 LAYER



TOP SIDE LAYER 1

ATMOSIC TECHNOLOGIES
ATM3-ESL
17/12/2019


Clearance Check	False error : 31	Gao-Fu Technology Corp.	JOB NAME	ATM_ESL_SCH_V12
Connectivity Check	False error : 0	http://www.gaofu.com.tw	LAYER	ARTWORK-TOP
Plane Check	False error : 0	886-3-6682475	DATE	2019.12.17 4 LAYER



GROUND PLANE LAYER 2

ATMOSIC TECHNOLOGIES
ATM3-ESL
17/12/2019


Clearance Check	False error : 31	Gao-Fu Technology Corp.	JOB NAME	ATM_ESL_SCH_V12
Connectivity Check	False error : 0	http://www.gaofu.com.tw	LAYER	LAYER 2
Plane Check	False error : 0	886-3-6682475	DATE	2019.12.17 4 LAYER



POWER PLANE LAYER 3

ATMOSIC TECHNOLOGIES
ATM3-ESL
17/12/2019


Clearance Check	False error : 31	Gao-Fu Technology Corp.	JOB NAME	ATM_ESL_SCH_V12
Connectivity Check	False error : 0	http://www.gaofu.com.tw	LAYER	LAYER 3
Plane Check	False error : 0	886-3-6682475	DATE	2019.12.17 4 LAYER



BOTTOM SIDE LAYER 4

ATMOSIC TECHNOLOGIES
ATM3-ESL
17/12/2019


Clearance Check	False error : 31	Gao-Fu Technology Corp.	JOB NAME	ATM_ESL_SCH_V12
Connectivity Check	False error : 0	http://www.gaofu.com.tw	LAYER	BOTTOM-LAYER
Plane Check	False error : 0	886-3-6682475	DATE	2019.12.17 4 LAYER



BOTTOM SIDE SOLDERMASK

ATMOSIC TECHNOLOGIES
ATM3-ESL
17/12/2019


Clearance Check	False error : 31	Gao-Fu Technology Corp.	JOB NAME	ATM_ESL_SCH_V12
Connectivity Check	False error : 0	http://www.gaofu.com.tw	LAYER	SOLDER MASK-BTM
Plane Check	False error : 0	886-3-6682475	DATE	2019.12.17 4 LAYER



TOP SIDE SOLDERMASK

ATMOSIC TECHNOLOGIES
ATM3-ESL
17/12/2019


Clearance Check	False error : 31	Gao-Fu Technology Corp.	JOB NAME	ATM_ESL_SCH_V12	
Connectivity Check	False error : 0	http://www.gaofu.com.tw	LAYER	SOLDER MASK-TOP	
Plane Check	False error : 0	886-3-6682475	DATE	2019.12.17	4 LAYER



BOTTOM SIDE SOLDERPASTE

ATMOSIC TECHNOLOGIES
ATM3-ESL
17/12/2019


Clearance Check	False error : 31	Gao-Fu Technology Corp.	JOB NAME	ATM_ESL_SCH_V12
Connectivity Check	False error : 0	http://www.gaofu.com.tw	LAYER	SMD Paste Mask-BTM
Plane Check	False error : 0	886-3-6682475	DATE	2019.12.17 4 LAYER



TOP SIDE SOLDERPASTE

ATMOSIC TECHNOLOGIES
ATM3-ESL
17/12/2019


Clearance Check	False error : 31	Gao-Fu Technology Corp.	JOB NAME	ATM_ESL_SCH_V12
Connectivity Check	False error : 0	http://www.gaofu.com.tw	LAYER	SMD Paste Mask-TOP
Plane Check	False error : 0	886-3-6682475	DATE	2019.12.17 4 LAYER



BOTTOM SIDE SILKSCREEN

ATMOSIC TECHNOLOGIES
ATM3-ESL
17/12/2019

Clearance Check	False error : 31	Gao-Fu Technology Corp.	JOB NAME	ATM_ESL_SCH_V12
Connectivity Check	False error : 0	http://www.gaofu.com.tw	LAYER	[illegible]
Plane Check	False error : 0	886-3-6682475	DATE	2019.12.17 4 LAYER



TOP SIDE SILKSCREEN

ATMOSIC TECHNOLOGIES
ATM3-ESL
17/12/2019

Clearance Check	False error : 31	Gao-Fu Technology Corp.	JOB NAME	ATM_ESL_SCH_V12	
Connectivity Check	False error : 0	http://www.gaofu.com.tw	LAYER	SILKSCREEN-TOP	
Plane Check	False error : 0	886-3-6682475	DATE	2019.12.17	4 LAYER