



Rule #5 — Wall stud service hole @296

Example: HG260001 | plan GF-LBW-70.075 | frame L4 | stick S11

Service hole @296 — emitted on every wall stud, but Detailer is selective about WHICH studs.



CODEC EMITS

(extra)
Detailer
doesn't
have these

DETAILER REF

(missing)
codec
should have
emitted these

Stick totals on this example:

- Matched ops: 6
- Extras (codec emits, Detailer doesn't): 2
- Missing (Detailer has, codec doesn't): 0

How to read:

- Top strip = ops the CODEC currently emits but Detailer's reference doesn't have (red = wrong-emit).
- Bottom strip = ops Detailer's reference has but the CODEC doesn't emit (red = miss).
- The yellow bar in the middle = the stick body, drawn to scale.
- Spans (Swage/LipNotch/InnerNotch) are coloured rectangles.
- Points (InnerDimple/Bolt/Web) are vertical lines + dots.