Defect detection in electroluminescence images of solar modules

W281 Computer Vision Final Project

Aswin Thiruvengadam, Alexander To, Andi Morey Peterson, and Dan Ortiz

Introduction

The detection of anomalies and defects within images is an important application of computer vision for manufacturers and researchers. It enables fast, repeatable, and automated identification and measurement of defects. In this project, we developed techniques to identify common manufacturing defects found in electroluminescence solar modules and solar cell images, taken from a commercial manufacturing line and made publicly available for research and development.

Electroluminescence (EL) is a physical property of semiconductor materials whereby photons are emitted from the bulk semiconductor material as a result of radiative recombination induced by an applied external electric field. This process is commonly used in digital watches and car dashboards for night time display illumination. It is also used as an imaging and inspection technique in solar cell manufacturing as the map of radiative recombination across the device can reveal manufacturing defects in the solar cell and/or module not visible to the human eye. The purpose of this project is to analyze EL images of silicon solar cells in order to detect and classify common defects discovered in production.

Executive Summary

A multi-class classifier was built by scoring the output of 6 separate binary classifiers, trained to detect whether a particular defect class was present in the given image or not. This was a particularly challenging task since:

- The images had multiple defect classes per image.
- The dataset was poorly organized, annotated incorrectly, and some classes were not distinct enough to warrant separate classes (for instance closed, isolated and resistive cracks).
- The images were inconsistently cropped.
- The dataset featured two types of wafer material (muticrystalline vs monocrystalline), which introduced features difficult to distinguish from defect instances.

Nevertheless, in this work an attempt was made to overcome the data issues. Over 10,000 images were reviewed, and over 2000 images were identified and removed as having false or incorrect annotations. Since every image could not be fully verified, the report presents two comparisons throughout:

- The single defect identification vs a non-defected cell.
- The single defect identification vs. all other classes.

This can serve as a rough approximation for the the upper and lower bounds of the classifier given our constraints due to poor data quality. Since the classification versus a clean cell is arguably the simplest classification task since the clean cell can be thought of as the 'ground truth' image, free of any defects, any deviation from this 'clean' image should be relative easy to classify in the absence of other defects. The more complicated classification task is to distinguish against all other defect classes, and hence this serves as the approximate 'lower bound' on performance. The true potential of each classification model and feature extraction pipeline can only truly assessed with clean data, and so because we lack the resources to fully check the dataset, we use these bounds throughout this work to give guidelines on what we believe is a reasonable approximation for the overall effectiveness of the feature extraction methods presented herein.

The best classifier for each defect class as evaluated on our test set is summarized below:

Defect Class	Transforms	Classifier Model	Balanced Accuracy Score (Test Data) vs. Clean	Balanced Accuracy Score (Test Data) vs. All Others
Closed Cracks	Sato Vesselness Filter, PCA	Gradient Boosting Classifier	82.042	77.434
Isolated Cracks	Gaussian Blur, PCA	Gradient Boosting Classifier	88.749	82.8
Resistive Cracks	Bussbar removal, FFT Butterworth Bandpass, PCA	Extra Trees Classifier	80.646	72.678
Bright Spots	Gaussian Blur, Fourier Transform	Logistic Regression	99.429	96.690
Corrosion	PCA / Eigenface, Cosine Similarity	Logistic Regression	100.0	99.550
Front Grid Interruptions and Near Solder Pads	Sobel Filter	Gradient Boosting Classifier	70.153	64.254

Our overall balanced accuracy score is

Defect Class	Balanced Accuracy Score (Test Data) vs. Clean	Balanced Accuracy Score (Test Data) vs. All Others
Complete Classifier	80.73	76.91

Whilst we feel that stronger performance is likely obtainable with cleaner data, we were not able to fully verify all images in the dataset and we were therefore unable to fully verify this claim.

Future approaches to improve the classifier could focus on isolation of the cell from the cell boarders to overcome the issue of the border edge confusing the classifier. Similarly, methods of distinguishing the darker clusters due to multicrystalline texture will help with more accuracte thresholding and crack detection techniques. A more successful approach may be to approach the task as an object detection problem, which seeks to place bounding boxes around the image. Alternatively, a 'ground truth' image estimation and subtraction may also be an effective approach to highlight anomolies, which can then be separately classified using the filters developed herein.

The Data

Our dataset consists of a publicly available dataset of 16,808 real and 256 simulated images of solar cells (17,064 individual images in total), sourced from 368 full module images via cropping. The 16,808 real images are taken from a publicly available dataset, which was recently published as part of a study of various semantic segmentation models used to highlight the defective regions within each image, where present. Some summary details of the dataset are provided below.

The images were captured using either a 16 MM CMOS sensor with a 950 nm long-pass filter, or a 8 MP Si CCD sensor with 850 nm long-pass filter. The long pass filter is used to filter any background signal unrelated to the radiative emission from the sample.

Each image is in jpeg format with each cropped cell having dimension 406 x 406 pixels. As EL images measure 'counts', there are no color channels to these images as each image is effectively a map of luminescent intensity.

A publicly available fork of the original repository can be accessed from: https://github.com/atox120/UCF-EL-Defect

A small portion of the images were rotated 90 degrees, so code was written to handle this rotation so all images were oriented so that the busbars ran across the cell horizontally. In addition, images had varying degrees of visibility to the edges of the solar cell. Some had all four edges visible, some only two. None of the defects needed the edge of the solar cell as part of the feature detection; therefore, another function allowed the cropping of the images (approximately twenty-five pixels on all sides of the image) to ensure no edges were in view of the image. Lastly, a few masking functions were created so that the busbars

could be completed removed (depending on the nature of the defect, one may want to remove the busbars, one may want to keep them)

A note on dataset quality.

Unfortunately, significant issues with the dataset quality were identified, which complicated the initial EDA, feature development and development of classifiers (as models trained poorly on the mislabelled instances). As a result, the team undertook significant review of the dataset, in order rectify the common issues experienced such as:

- 1. Mislabelled defects, whereby a defect was labeled with the incorrect label.
- 2. Missing labels of defects which were present.

The following list is a summary of the number of files reviewed and corrections made per class:

- Non Defected: 5237 Images reviewed, 779 false instances removed.
- Resistive Cracks: 3088 Images reviewed, 485 false instances removed.
- Closed Cracks: 2641 Images reviewed, 584 false instances removed.
- Bright Spot: 248 Images reviewed, 68 false instances removed.
- Corrosion: 68 Images reviewed, 28 false instances removed.
- Isolated Cracks: 1756 Images reviewed, 436 false instances removed.
- Front Grid Interruptions/Near Solder Pad: 1570 images verified images.

The Defects

A summary of the final number of instances per defect class is shown below:

```
import os
import sys
import copy
import time
import numpy as np
sys.path.append(os.path.join(os.path.abspath(""), ".."))
import matplotlib.pyplot as plt

from app.utils import ImageWrapper
from app.custom import RemoveBusBars, Orient
from app.transforms import FFT, IFFT, CreateOnesMask, PCA, MaskedFFT, DownsampleBlur, Butter
from app.filters import CreateKernel, Convolve, Canny, HOG, Sato, ThresholdMultiotsu
from app.imager import ImageLoader, DefectViewer, Show, Exposure

from sklearn.ensemble import ExtraTreesClassifier
```

```
In [29]: def show_example_image(defect_class='None', seed=0):
```

```
""" Function to load and display a few images. Wraps the underlying classes"""
# Load images
iml = ImageLoader()
defect_categories = iml.defect_classes
# Filter out the not required defect categories
not_defect_class = [x for x in defect_categories if x != defect_class]
# Load defect instances, all other instances, and clean samples
defects = (DefectViewer() << (ImageLoader(defect_class=defect_class) << 10))</pre>
all others = (DefectViewer() << (ImageLoader(defect class=not defect class) << 10))
clean = (DefectViewer() << (ImageLoader(defect_class='None') << 10))</pre>
# Step to remove any files in the defect class with multiple annotations in the all_other
# This is so that the same filename cannot exist in the defect and the all others class,
# would confuse a classifier.
single_defect = defects - all_others
_ = Show(num_images=1, seed=seed) << single defect</pre>
return
```

The below code shows the final number of unique files per class in the cleaned up dataset.

```
In [30]: # Instantiate class
iml = ImageLoader()
   _ = iml.load_n(1) # Load a token image, in order to create the main df
#Remove defects not used in this sample

defects_df = iml.final_samples

defects_df = defects_df[defects_df['defect_class'] != 'Unknown']

defects_df = defects_df[defects_df['defect_class'] != 'BeltMarks']

defects_df = defects_df[defects_df['defect_class'] != 'Disconnected']

defects_df = defects_df[defects_df['defect_class'] != 'HighlyResistive']

defects_df.groupby(['defect_class']).agg('count')['filename'].reset_index()
```

Out[30]:		defect_class	filename
	0	BrightSpot	58
	1	Closed	943
	2	Corrosion	28
	3	FrontGridInterruption	406
	4	Isolated	357
	5	NearSolderPad	3602
	6	None	3243
	7	Resistive	977

In the above table, we have omitted the classes 'Beltmarks' since there were only 16 examples of this class, and the 'Unknown' class was a catch-all class for a range of different defects which could not be properly identified. 'Highly Resistive' and 'Disconnected' were also omitted due constraints on our ability to validate each and every defect class.

Data Splits for Train, Development and Testing


The data was separated into train, validation, and test sets. The train/validation versus the test datasets were split using the standard 80/20 split. The train and validation test were then split again 80/20 for initial development and validation. When doing initial model building, training data was used to build both the feature detection algorithms and the individual classifiers. The validation datasets were used in reporting the individual model capabilities in the eda_.ipynb notebooks, i.e., all scores presented in that work are validation scores. The test dataset was reserved for the final 6-way combined classifier reported at the end of this report, and the only time this data was used was when running the model.ipynb notebook.

Front Grid Interruption and Near Solder Pad

The Front Grid Interruption defect is best described as "darkened rectangles appearing along the printed metal fingers". These are caused where by a break in current flow along the finger, and the location of the break determines the classification.

Near Solder Pad defects are very similar to Front Grid Interruption; however, these rectangles have a shaded region adjacent to the busbar and are caused by a different mechanism. A front grid interruption occurs in between the busbar region, and is caused by for instance contamination during processing. This issue presents as a darkened vertical line and are treated as a combined class in this work.

```
In [31]: show_example_image(['FrontGridInterruption', 'NearSolderPad'], seed=16)
```




Corrosion

Corrosion defects present as darkened regions starting at the busbar and extending perpendicularly along the finger, and typically extending farther from the centre than at the edges of the contact. Corrosion occurs due to moisture ingress into the encapsulated module, and is usually a result of accelerated environmental degradation testing, or exposure in the field.

Corrosion presents a unique pattern in the centre of the cell, as is shown below.


```
In [32]: show_example_image('Corrosion', seed=1)
```



Highly Resistive

Highly resistive interconnects are bright along portions of the busbar, and darkened along others. The longer the resistive region, the brighter the extended region perpendicular to the busbar, since the same amount of source current is not concentrated in a smaller area. Due to time limitations, this particularly large class was not able to reviewed for labelling accuracy, and so was omitted.


```
In [33]: show_example_image('HighlyResistive', seed=1)
```



Bright Spot

Bright spots are caused by concentrated regions of current flow due to other regions of the cell being highly resistive, likely due to poor contact formation, which results in the brighter regions having better contact than the adjacent regions.


```
In [34]: show_example_image('BrightSpot', seed=1)
```



Resistive Cracks

Resistive crack category is one of three types of crack defects. This crack, resistive cracks, is determined by darkened regions extending from closed crack line or have a gradient intensity which is darkest at the crack edge. These are caused by cracks which partially isolate current flow in that region, hence the darkened appearance.


```
In [35]: show_example_image('Resistive', seed=2)
```



Closed Cracks

Closed cracks thin dark crack lines. They do not necessarily obstruct current flow into the bulk material, hence no darkened gradient extends from the crack line. However since the exposed crack edge is highly re-combinative, no luminescence occurs in these regions and hence they appear as thin dark lines.


```
In [36]: show_example_image('Closed', seed=4)
```



Isolated Cracks

Isolated cracks are cracks which separate/isolate two individual sections of the cell with darkened regions extending from the crack. They also have a uniform intensity across the darkened regions. These occur during mishandling, which results in a cleaving of the wafer material which creates a complete electrical isolation of the cracked wafer.

```
In [37]: show_example_image('Isolated', seed=9)
```




In the previous analysis, a few examples of cracks with multiple instances per image were shown. Since we did not aim to filter the dataset to having image with only one defect type present (since this would entail too much specialised expertise/domain knowledge to correctly identify the crack and time), it is likely our model training suffered from being shown multiple defects per image, but not being able to attribute these to their correct classes.

No Defects

Below is a sample image of a solor cell with no visual defects that supplied as our ground truth.

```
In [38]: show_example_image('None', seed=2)
```



Feature Detection

The approach for feature detection for this project was to treat every defect as a separate feature and a unique feature detection algorithm would be deployed as such. It is worth noting that this was a trial and error process and this report only contains the final detectors selected prior to classification. Detail code for the selected algorithms can be found in the notebooks folder with files starting with eda_<defect name>.ipynb . This report offers no commentary on what algorithms did not achieve desirable results, and those reports can be found in the notebooks folder.

To make this report easier to read, and to make each model and algorithm to execute similarly, a common code base was written for this project and can be found in the app folder. This code was written in a way that algorithms can chain transformations for several hundred or thousand images into short code blocks.

Examples of how the image.py, filter.py, and transform.py work with the shift operators can be found in 99_archive/shorthand_examples.ipynb file.

Front Grid Interruptions and Near Solder Pad

As descripted in the data section of this report, there was many images that are not annotated correctly (i.e. they were incorrectly labeled) and the defects Front Grid Interruptions and Near Solder Pad suffered this issue the most. This is likely due to how similar they are in nature; even humans have a hard time categorizing these defects. Therefore, for this project, the two defects were combined and the model will


now give a binary response for: "Yes - This image contains a front grid interruption or near solder pad or both" versus "No - this image does not contain a front grid interruption or near solder pad defect."

For feature detection - several methodologies were used, such as a simple edge detection kernel, kanny filters, and a Fourier transform (to detect specific frequencies of these defects). However, none proved to be better models than the sobel filter as shown below.

For the full eda, model evaluation and analysis, please see the eda_frontgrid.ipynb and eda_nearsolderpad.ipynb notebooks.

```
In [39]:
                                    # Grab Images
                                    fgi_defect_classes = ['FrontGridInterruption', 'NearSolderPad']
                                    fgi_nsp_defect = (DefectViewer(row_chop=25, col_chop=25) << (ImageLoader(defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=fgi_defect_class=
                                    #fgi_nsp_defect.category = fgi_defect_classes
                                     # Orient and run through Sobel Filter on Axis 0
                                     fgi_nsp_defect_oriented = Orient(num_jobs=2) <<fgi_nsp_defect</pre>
                                     defect_kernel = CreateKernel(kernel='sobel', axis=0) << fgi_nsp_defect_oriented</pre>
                                    fgi_nsp_sobel = Convolve() << defect_kernel</pre>
                                     # Plot images
                                     plt.figure(figsize=(8, 15))
                                     plt.subplot(121)
                                    plt.imshow(fgi_nsp_defect.images[6], cmap='Greys_r')
                                     plt.title("Raw Image of Front Grid Interruption\nNear Solder Pad", size=12)
                                     plt.subplot(122)
                                    plt.imshow(fgi_nsp_sobel[1].images[6], cmap='Greys_r')
                                     plt.title("After Sobel Filter", size=12)
```

Out[39]: Text(0.5, 1.0, 'After Sobel Filter')




Corrosion

Due to the similar nature of the corrosion defect from one image to the other, and because it occurs on all of the busbars when the defect occurs, removing the busbars was not recommended. Instead, a Principal Component Analysis was completed to possibly reduce dimensions.

For the full eda, model evaluation and analysis, please see the eda_corrosion.ipynb notebook.

```
In [40]:
          # Run PCA analysis on 20 components and plot the variance
          n components = 20
          PCA_class_defect = PCA(transpose=True, n_components=n_components, whiten=True)
          corrosion defect class='Corrosion'
          corrosion_defect = (DefectViewer(row_chop=25, col_chop=25) << (ImageLoader(defect_class=correction)</pre>
          corrosion_defect.category = corrosion_defect_class
          clean = Orient(num_jobs=2) << (DefectViewer(row_chop=25, col_chop=25) << (ImageLoader(defect)</pre>
          # calculate the transform on the images
          PCA_class_defect << corrosion_defect</pre>
          # Total explained Variance
          exp_var = PCA_class_defect.explained_variance_ratio[0]
          total_exp_var = np.sum(exp_var)
          print(f'{n_components} principal components explain {total_exp_var * 100:.2f} % of the total
          # PLot
          # Define X axis intervals:
          x=np.arange(1, n_components + 1)
          # Cumulative variance:
          y1 = exp_var * 100
          y2 = np.cumsum(y1)
          fig, ax1 = plt.subplots(figsize=(12, 6))
          ax2 = ax1.twinx()
          ax1.bar(x, y1, color = 'g')
          ax2.plot(x, y2, color = 'b')
          ax1.set xlabel('Principal Component Number')
          ax1.set xticks(x)
          ax1.set_ylabel('Explained Variance %', color='g')
          ax2.set_ylabel('Cumlative Explained Variance %', color='b')
```

20 principal components explain 98.90 % of the total variance Out[40]: Text(0, 0.5, 'Cumlative Explained Variance %')




Because the first component explained over 70% of the variance of the corrosion images, a cosine simialarity analysis was completed.

```
In [41]:
          from sklearn.metrics.pairwise import cosine_similarity
          def get_cosine_similarity(template, img_array):
              """ Returns the cosine similarity of the top N eigenfaces."""
              #Get dims
              N, H, W = img_array.images.shape
              #Reshape images
              reshaped = img_array.images.reshape(N, H * W)
              # Reshape template
              stacked face = template.reshape(len(template), H*W)
              # Calculate similarity
              sim_scores = cosine_similarity(stacked_face, reshaped)
              sim_scores = np.sum(np.asarray(sim_scores), axis=0) #Sum all PCA components for each image
              return sim scores
          eigenfaces = PCA_class_defect.eigenfaces[0]
          sim scores clean = get cosine similarity(eigenfaces, clean[-1])
          sim_scores_defect = get_cosine_similarity(eigenfaces, corrosion_defect)
          # Calculate the average of all images within each category.
          average_corrosion = np.mean(corrosion_defect.images, axis=0)
          print('Average Corroded Cell')
          plt.imshow(average_corrosion, cmap='Greys_r')
```

```
print("Average of scores for 1st component defected images:")
print(round(np.mean(sim_scores_defect),5))
```


Average Corroded Cell Average of scores for 1st component defected images: -1.00668



```
# Calculate the average of all images within each category.
average_clean = np.mean(clean[-1].images, axis=0)
print('Average Clean Cell')
plt.imshow(average_clean, cmap='Greys_r')

print("Average of scores for 1st component for clean images:")
print(round(np.mean(sim_scores_clean),5))
```

Average Clean Cell Average of scores for 1st component for clean images: -1.04663




Bright Spot

There are many options in Bright Spot feature detection - due to the high contrast nature of the spots in comparison to the background image of the solar cell. One method developed was to do a Fourier transform of the images extract the bright spot feature.

For the full eda, model evaluation and analysis, please see the eda_brightspot.ipynb notebook.

```
In [43]:
                                    # Grab Brightspot Images
                                    brightspot_defect_class='BrightSpot'
                                    brightspot_defect = (DefectViewer(row_chop=25, col_chop=25) << (ImageLoader(defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightspot_defect_class=brightsp
                                    brightspot_defect.category = brightspot_defect_class
                                    # Mean Exposure and run a Gaussian Blur
                                    brightspot_defect_blur = Convolve() << (CreateKernel(dim=2, kernel='gaussian', size=5, std=8)</pre>
                                    fourier_defect = (FFT(dim=2) << brightspot_defect_blur)</pre>
                                    # Plot images
                                    plt.figure(figsize=(15, 24))
                                    plt.subplot(131)
                                    plt.imshow(brightspot_defect.images[1], cmap='Greys_r')
                                    plt.title("Raw Bright Spots", size=12)
                                    plt.subplot(132)
                                    plt.imshow(brightspot_defect_blur[1].images[1], cmap='Greys_r')
                                    plt.title("After Gaussian Blur", size=12)
                                    plt.subplot(133)
                                    plt.imshow(fourier_defect[-2].images[1], cmap='Greys_r')
                                    plt.title("Fourier Transform", size=12)
```

Out[43]: Text(0.5, 1.0, 'Fourier Transform')



Resistive Cracks

Resistive cracks have both a crack (high frequency component) and a color gradient (low frequency component). These features required the reduction of noise while enhancing these features for the classifier. The following steps were taken to process the images.

- Removal of Bus bars: The bus bars provide a strong linear signal in Fourier space and were thus removed prior to the FFT transformation. Solar panels can have multiple bus bars per cell (depending on the model) and the bus bars are not an important characteristic for a resistive crack. Therefore we believe removing them would provide a better chance for model generalization.
- Application of Butterworth Band pass filter in Fourier space: TA butterworth bandpass filter was used to remove all the mid-range frequencies while maintaining highs and lows of the image to retain the crack and the color gradient features. Finding the right filter was challenging as higher orders induced artifacts in the inverse fft.
- Application of Hanninf Window on IFFT: This was done to reduce artifacts around the edge once the image was brought back into pixle space.


After image processing, multiple different classifiers were assessed manually and the images were passed through too identify any other high potential classifiers. Depending on the run, both the CNN and the Extra Tree Classifier yielded the best performance.

Note: For the full eda, model evaluation and analysis, please see the eda resistive.ipynb notebook.

```
In [44]:
          ## Grab the Resistive defects
          n \text{ samples} = 10
          seed = 1234
          defect = (DefectViewer(row_chop=25, col_chop=25) << (ImageLoader(defect_class='Resistive') <</pre>
          defect.category = 'Resistive'
          ## Orienting and removing busbars
          oriented_defect = Orient(num_jobs=20) << defect</pre>
          nobus_defect = RemoveBusBars() << oriented_defect</pre>
          ## Generating Butterworth Bandpass Filter
          x = nobus_defect[-1]
          btw = Butterworth(((\sim x)[0]))
          mask = btw.bandpass(3, 15, 1, 1)
          ## Applying the band pass filter during the transformation
          f = FFT(dim=2) << nobus defect
          iff = IFFT(mask) << f</pre>
          # Plot images
          print("Feature Detection Used in Final Model")
          plt.figure(figsize=(15, 24))
          plt.subplot(141)
          plt.imshow(defect.images[0], cmap='Greys r')
          plt.title("Raw Closed Crack", size=12)
          plt.subplot(142)
          plt.imshow((~(nobus_defect)[1])[0], cmap='Greys_r')
          plt.title("After Busbar Removal", size=12)
          plt.subplot(143)
          plt.imshow(mask, cmap='Greys r')
```

```
plt.title("Butterworth Bandpass Filter", size=12)
plt.subplot(144)
plt.imshow((~(iff[-1]))[0], cmap='Greys_r')
plt.title("Fully Processed Image", size=12)
```

Feature Detection Used in Final Model Out[44]: Text(0.5, 1.0, 'Fully Processed Image')



Closed Cracks

Various filters and filtering algorithms were trialled to isolate closed cracks. These include:

- Applying a sato vesselness filter to highlight cracks
- Thresholding the image, to remove lower strength signals, and to accentuate the cracks from the background.
- Applying a cross shaped mask to the FFT magnitude and then transforming the image back to remove busbars and vertical lines.

Chained sequences of these filters/transforms were applied, see below as examples.

Note: For the full eda, model evaluation and analysis, please see the eda_closed.ipynb notebook.

```
# Grab Closed Crack Images
closed_defect_class='Closed'
closed_defect = (DefectViewer(row_chop=25, col_chop=25) << (ImageLoader(defect_class=closed_closed_defect.category = closed_defect_class


# Apply Sato Filter and threshold image
__, sato = (Sato(sigmas=[1,2]) << closed_defect)
__, sato_stretch = Exposure('stretch') << sato
images = ThresholdMultiotsu(classes=4, threshold=1, digitize=False) << sato_stretch

# Plot images
print("Feature Detection Used in Final Model")
plt.figure(figsize=(15, 24))
plt.subplot(141)
plt.imshow(closed_defect.images[2], cmap='Greys_r')</pre>
```

```
plt.title("Raw Closed Crack", size=12)
plt.subplot(142)
plt.imshow(sato.images[2], cmap='Greys_r')
plt.title("After Sato Filter", size=12)
plt.subplot(143)
plt.imshow(sato_stretch.images[2], cmap='Greys_r')
plt.title("After Stretching Image", size=12)
plt.subplot(144)
plt.imshow(images[1].images[2], cmap='Greys_r')
plt.title("After Multi Otsu Threshold", size=12)
```

Feature Detection Used in Final Model

Out[45]: Text(0.5, 1.0, 'After Multi Otsu Threshold')





The threshoding was most effective against multicrystalline wafers, as it helped remove the background defect clusters. in the above image, this is a monocrystalline wafer and so there is not much difference. Please see full eda for further examples. Below is an example of a FFT masking step, which in the end wasn't used in the final pipeline since it only performed well in the CNN classifier.

```
In [46]:
          import cv2
          # Function to make masks
          def create mask(half width, shape, mtype):
            # Create a vertical mask
              if mtype == 'vertical':
                  in_mask = np.zeros(shape)
                  midpoint = in mask.shape[1] // 2
                  top_left = (midpoint - half_width, 0)
                  bottom_right = (midpoint + half_width, shape[0])
                  cv2.rectangle(in mask, top left, bottom right, (255, 255, 255), -1)[0]
                  in mask = in mask / 255
            # Create a horizontal mask
              if mtype == 'horizontal':
                  in mask = np.zeros(shape)
                  midpoint = in mask.shape[0] // 2
                  top_left = (0, midpoint - half_width)
                  bottom_right = (shape[1], midpoint + half_width)
```

```
cv2.rectangle(in_mask, top_left, bottom_right, (255, 255, 255), -1)[0]
        in mask = in mask / 255
    return in_mask
print("Applying FFT detection - Not used as didn't provide better results on training data,
# Apply maks to FFT transformed image
# Make masks
vertical = 1 - create_mask(4, closed_defect.images[0].shape,'vertical')
horizontal = 1 - create mask(4, closed defect.images[0].shape,'horizontal')
cross = vertical + horizontal - 1
cross[cross < 1] = 0
_, vertical_ = (Exposure('mean_norm') << (MaskedFFT(mask=vertical, window=False) << closed_delta
_, horizontal_ = (Exposure('mean_norm') <<(MaskedFFT(mask=horizontal, window=False) << close
_, cross_ = (Exposure('mean_norm') << (MaskedFFT(mask=cross, window=False) << closed_defect)
# Plot images
plt.figure(figsize=(15, 24))
plt.subplot(141)
plt.imshow(closed defect.images[2], cmap='Greys r')
plt.title("Raw Closed Crack", size=12)
plt.subplot(142)
plt.imshow(vertical_.images[2], cmap='Greys_r')
plt.title("After Vertical Filter", size=12)
plt.subplot(143)
plt.imshow(horizontal_.images[2], cmap='Greys_r')
plt.title("After Horizontal Filter", size=12)
plt.subplot(144)
plt.imshow(cross_.images[2], cmap='Greys_r')
plt.title("After Cross Filter", size=12)
```

Applying FFT detection - Not used as didn't provide better results on training data, despite providing good results with a CNN





Isolated Cracks

Various filters and filtering algorithms were trialled to highlight isolated cracks. These include:


- Blurring the image, to remove thin lines such as closed cracks.
- Thresholding the image, to highlight the dark regions created by the isolated cracks.
- Using a farid filter and a peak finding algorithm to mask out dark regions created by busbars.

Chained sequences of these filters/transforms were applied,

For the full eda, model evaluation and analysis, please see the eda_isolated.ipynb notebook. The summary from that notebook is copied below.

```
In [47]:
                                from app.transforms import FFT, IFFT, CreateOnesMask, PCA, DownsampleBlur, MaskedFFT
                                # Grab Isolated Crack Images
                                isolated defect class='Isolated'
                                isolated_defect = (DefectViewer(row_chop=25, col_chop=25) << (ImageLoader(defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_class=isolated_defect_cl
                                isolated_defect.category = isolated_defect_class
                                # Invert Images
                                original, inverted = Exposure('invert') << isolated defect
                                #Apply Downsample Blur
                                inverted blurred = Exposure('invert') << (DownsampleBlur(sigma=3, size=17) << isolated defe</pre>
                                # Plot images
                                print("Feature Detection Used in Final Model")
                                plt.figure(figsize=(15, 24))
                                plt.subplot(131)
                                plt.imshow(isolated_defect.images[2], cmap='Greys_r')
                                plt.title("Raw Isolated Crack", size=12)
                                plt.subplot(132)
                                plt.imshow(inverted.images[2], cmap='Greys_r')
                                plt.title("After Inverting Images", size=12)
                                plt.subplot(133)
                                plt.imshow(inverted_blurred[-1].images[2], cmap='Greys_r')
                                plt.title("After Downsample Blur", size=12)
```

Feature Detection Used in Final Model Out[47]: Text(0.5, 1.0, 'After Downsample Blur')



Classification Models

In [49]:

num samples = 2000

As described before - each defect will contain its own classifier and can appear with multiple defects. For example, near solder pad defects often occur with various cracking defects. How each classifier was built is described below. Specific code regarding classifiers that were not selected for the final model are found in the respective eda_ files.

```
from app.models import Classifier
from app.model_features import grid_interruption, brightspots, closed, isolated, get_samples
from sklearn.linear_model import LogisticRegression
from sklearn.ensemble import GradientBoostingClassifier
```

Front Grid Interruption and Near Solder Pads

```
fgi_defect_classes = ['FrontGridInterruption', 'NearSolderPad']
fgi_defect, not_fgi = get_samples(fgi_defect_classes, num_samples, complimentary=True)

In [50]:
# Base model on raw data
title = 'Base model Front Grid Interruption / Near Solder Pad vs. No FGI or NSP'
model_params = {'penalty': '12', 'seed': 4156, 'pca_dims': None, 'max_iter' : 100}
cla = Classifier(fgi_defect, not_fgi, LogisticRegression, None)
score = cla.fit_cv(**model_params)
print(title, " ", score)
```

Base model Front Grid Interruption / Near Solder Pad vs. No FGI or NSP 0.685643564356 /opt/conda/lib/python3.8/site-packages/sklearn/linear_model/_logistic.py:763: ConvergenceWarn ing: lbfgs failed to converge (status=1): STOP: TOTAL NO. of ITERATIONS REACHED LIMIT.

Increase the number of iterations (max iter) or scale the data as shown in:

```
https://scikit-learn.org/stable/modules/preprocessing.html
Please also refer to the documentation for alternative solver options:
   https://scikit-learn.org/stable/modules/linear_model.html#logistic-regression
n_iter_i = _check_optimize_result(
```

```
In [51]:
# Convert the data to the required format for grid interruption
fgi_defect_ = grid_interruption(fgi_defect, num_jobs=20)
not_fgi_ = grid_interruption(not_fgi, num_jobs=20)
```

```
In [52]: # Train a Gradient boosted classifier
    title = 'Graidient Boosted Classifier: Front Grid Interruption / Near Solder Pad vs. No FGI of pca_dims = min(100, num_samples)
    params = {'seed': 14376,'n_estimators': 600, 'max_depth': 4, 'learning_rate': 0.05, 'pca_dims cla = Classifier(fgi_defect_, not_fgi_, GradientBoostingClassifier, None)

# When done, return the score
    score = cla.fit_cv(**params)
    print(title, " ", score)
```

Graidient Boosted Classifier: Front Grid Interruption / Near Solder Pad vs. No FGI or NSP 0.7152190358297228

Results vs Clean:

Front Grid Int. / Near Solder vs Clean	Best Score	Transform
Logistic Regression	None	67
Gradient Boosting Classifier	PCA	78
Gradient Boosting Classifier	PCA + Sobel	79
CNN	PCA + Sobel	79.5

Results vs all other defects:

Front Grid Int. / Near Solder vs All Others	Best Score	Transform
Logistic Regression	None	65
Gradient Boosting Classifier	PCA	67
Gradient Boosting Classifier	PCA + Sobel	73
CNN	PCA + Sobel	66

Despite the high expetation of performance of the CNN, the final classifier selected for the final model is the gradient boosting classifier, with PCA + Sobel filtering. When compared with other defect classes, the CNN did not outperform other classifiers.

For more detailed code on these trial runs see eda_frontgrid.ipynb .

Bright Spots

With this type of defect, and its sharp contrast, a baseline classifier was building using raw images in which images with defect was compared with images without the defect (including images with other major defects). Because of its good performance, only one other classifier was constructed -- a logistics regrestion classifier:

```
In [67]:
          # Convert the data to the required format for grid interruption
          fgi_defect_ = grid_interruption(fgi_defect, num_jobs=8)
          not fgi = grid interruption(not fgi, num jobs=8)
In [68]:
          num_samples = 250
          defect_classes = ['BrightSpot']
          brightspot_defect, not_brightspot = get_samples(defect_classes, num_samples, complimentary=T
In [69]:
          # Base model on raw data
          title = 'Base model Bright Spots vs. No Bright Spots'
          model_params = {'penalty': '12', 'seed': 1234, 'pca_dims': None, 'max_iter' : 500}
          cla = Classifier(brightspot_defect, not_brightspot, LogisticRegression, None)
          score = cla.fit_cv(**model_params)
          print(title, " ", score)
         Base model Bright Spots vs. No Bright Spots 0.9343715239154616
In [70]:
          title = 'After Gaussian blur and Fourier Bright Spots vs. No Bright Spots'
          brightspot_ = brightspots(brightspot_defect, num_jobs=20)
          not_brightspot_ = brightspots(not_brightspot, num_jobs=20)
          cla = Classifier(brightspot_, not_brightspot_, LogisticRegression, None)
          score = cla.fit_cv(**model_params)
          print(title, " ", score)
         0 were rejected
         0 were rejected
         Exception in thread Thread-1:
         Traceback (most recent call last):
           File "/opt/conda/lib/python3.8/threading.py", line 932, in bootstrap inner
             self.run()
           File "/workspace/notebooks/../app/utils.py", line 156, in run
             self.results = self.func(*self.args)
           File "/opt/conda/lib/python3.8/multiprocessing/connection.py", line 250, in recv
             buf = self. recv bytes()
           File "/opt/conda/lib/python3.8/multiprocessing/connection.py", line 414, in _recv_bytes
             buf = self. recv(4)
           File "/opt/conda/lib/python3.8/multiprocessing/connection.py", line 383, in recv
             raise EOFError
         After Gaussian blur and Fourier Bright Spots vs. No Bright Spots 0.9827586206896552
```

Bright spots, with raw data, was already predicting high on train data (>93% accuracy). The feature detection of using Gaussian blur and Fourier analysis was not necessiary though does do better than the raw analysis.

Results vs all other defects:

Brightspots vs All Others	Score
Raw Files	93.4
Logistic Regression	98.3

Corrosion

```
In [54]:
    num_samples = 50
    defect_classes = ['Corrosion']
    corrosion_defect, not_corrosion = get_samples(defect_classes, num_samples, complimentary=True)

In [55]:
# Base model on raw data
    title = 'Base model Corrosion vs. No Corrosion'
    model_params = {'penalty': '12', 'seed': 4156, 'pca_dims': None, 'max_iter' : 500}
    cla = Classifier(corrosion_defect, not_corrosion, LogisticRegression, None)
    score = cla.fit_cv(**model_params)
    print(title, " ", score)
```

Base model Corrosion vs. No Corrosion 1.0

Base model with corrosion versus non corrosion scored perfect at 100%. Due to this high accuracy, no more feature detection was needed in the model build. These results are not unexpected as the examples of corrosion in this dataset all had the same number of busbars, the photos were taken at the same focal point distance / luminosity, and corrosion does not occur with any other defect. The PCA analysis also showed that the first principal component accounted for >75% of the total variation, we can infer that the corrosion defects are very similar to each other. Not in this report, the team investigated using cosine_similarity to the eigenfaces as a feature detection methodology in the future. (see eda_corrosion.ipynb).

Closed Cracks

A classifier for closed cracks was developed comparing the accuracy of a binary classifer to classify isolated cracks vs a clean image or an isolated crack vs all other potential defects was trialled. The best validation scores for each algorithm and the pipeline producing those scores are shown below. Note where 'None' is listed, this signifies that the best scores were obtained by simply feeding the raw images into the model without any feature extraction or PCA.

```
In [56]: | num_samples = 500
          defect classes = ['Closed']
          closed defect, not closed = get samples(defect classes, num samples, complimentary=True)
In [57]:
          # Base model on raw data
          title = 'Base model Closed Crackes vs. No Closed Cracks'
          model_params = {'penalty': '12', 'seed': 1234, 'pca_dims': None, 'max_iter' : 200}
          cla = Classifier(closed_defect, not_closed, LogisticRegression, None)
          score = cla.fit_cv(**model_params)
          print(title, " ", score)
         Base model Closed Crackes vs. No Closed Cracks 0.6730769230769231
         /opt/conda/lib/python3.8/site-packages/sklearn/linear model/ logistic.py:763: ConvergenceWarn
         ing: lbfgs failed to converge (status=1):
         STOP: TOTAL NO. of ITERATIONS REACHED LIMIT.
         Increase the number of iterations (max iter) or scale the data as shown in:
             https://scikit-learn.org/stable/modules/preprocessing.html
         Please also refer to the documentation for alternative solver options:
             https://scikit-learn.org/stable/modules/linear_model.html#logistic-regression
           n_iter_i = _check_optimize_result(
In [58]:
          #Best model - see eda closed.ipynb for more models
          title = 'After PCA, Sato and Thresholding Closed Cracks vs. No Closed Cracks'
          closed_ = closed(closed_defect, num_jobs=20)
          not_closed_ = closed(not_closed, num_jobs=20) ##TODO - Need to check if this is correct
          model_params = {'n_estimators': 300, 'max_depth': 4, 'learning_rate': 0.1, 'pca_dims': min(1)
          cla = Classifier(closed defect, not closed, GradientBoostingClassifier, None)
          score = cla.fit cv(**model params)
          print(title, " ", score)
         0 images were rejected
         /workspace/notebooks/../app/imager.py:787: RuntimeWarning: invalid value encountered in true
         divide
           out img = (in imgs - all min) / (all max - all min)
         Failed on count 367
         1 images were rejected
         After PCA, Sato and Thresholding Closed Cracks vs. No Closed Cracks 0.7160778803693295
         Results vs Clean:
                                Isolated vs Clean
                                                         Best Score
                                                                         Transform
```

None

PCA + Sato

PCA + Sato + Thresholding

69.3

82.1

80.7

90

Results vs all other defects:

KMeans

CNN

Logistic Regression

Gradient Boosting Classifier PCA

Isolated vs All Others	Best Score	Transform
KMeans	None	61.77
Logistic Regression	None	65.7
Gradient Boosting Classifier	PCA + Sato	71.2
CNN	CNN w/PCA + Sato + Thresholding + fft	75

Note: a variance in the Logistic Regression score above and that presented in the summary table is likely due to the data sampled (above 500 samples, in the notebook 1200 samples) and the fact that in the case of the base model without PCA, there were convergence issues. Therefore the scores in the table should be treated as the more representative value, and the code above mainly for illustration.

Despite the strong performance of the CNN, the final classifier selected for the final model is the grdient boosting classifier, with PCA + Sato filtering. This is because we prioritised the performance on the defect vs all other classification task over the arguably simple vs. clean classification, and since the CNN was provided as a point of comparison.

An analysis of the misclassified images showed that the model struggled to distinguish the multicystalline defect clusters from genuine cracks. Similarly, the model also struggled to differentiate the cell boundaries from a crack. This could potentially be overcome with cropping/windowing the image, but no further gains in classifier accuracy were found. Future gains could potentially be realised by further revision of the dataset to ensure that the model has accurate labels, since this would help the model during training better 'learn' the features to assist with classification. Similarly, more robust methods of cropping and identifying the active regions will help distinguish the cell edge from being a crack. The most complicated required enhancement would be a model to segment/filter and disregard defect clusters in multicrystalline wafers, whic were often confused for cracks.

Please the eda closed.ipynb notebook for details on these results.

Isolated Cracks

A classifier comparing the accuracy of a binary classifer to classify isolated cracks vs a clean image or an isolated crack vs all other potential defects was also trialled.

```
title = 'Base model Isolated Crackes vs. No Isolated Cracks'
model_params = {'n_clusters' : 2, 'seed': 4156, 'pca_dims': None, 'max_iter':400}
cla = Classifier(isolated_defect, not_isolated, KMeans, None)
score = cla.fit_cv(**model_params)
print(title, " ", score)
```

Base model Isolated Crackes vs. No Isolated Cracks 0.6602564102564102

```
In [65]: #Best model - see eda_isolated.ipynb for more models
   title = 'After PCA and Guassian Blur Isolated Cracks vs. No Isolated Cracks'
   isolated_ = isolated(isolated_defect, num_jobs=20)
   not_isolated_ = isolated(not_isolated, num_jobs=20)
   model_params = {'seed': 4156, 'n_estimators': 300, 'max_depth': 4, 'learning_rate': 0.1, 'pcccla = Classifier(isolated_, not_isolated_, GradientBoostingClassifier, None)
   score = cla.fit_cv(**model_params)
   print(title, " ", score)
```

After PCA and Guassian Blur Isolated Cracks vs. No Isolated Cracks 0.796474358974359 In the detailed EDA the following classifiers were used:

KMeans, Logistic Regression, CNN and Gradient Boosting Classifier.

The best scores for each algorithm and the pipeline producing those scores are shown below.

Results vs Clean:

Isolat	ted vs Clean	Best Score	Transform
KMeans		PCA + Gaussian Blur	65.4
Logistic Re	egression	PCA	81.7
Gradient B	oosting Classifier	PCA + Gaussian Blur	89.0
CNN		PCA + Gaussian Blur	91.0

Results vs all other defects:

Isolated vs All Others	Best Score	Transform
KMeans	PCA + Gaussian Blur	51.9
Logistic Regression	PCA	72.0
Gradient Boosting Classifier	PCA	82.8
CNN	PCA + Gaussian Blur	82.0

Future work to improve the classifier could focus on two potential approaches:

• Segmentation of the multicrystalline texture against the other defects.

• Proper handling of the poor border crop.

Best pipeline:

PCA + Gaussian Blur, using a Gradient Boosting Classifier

Again please the eda_isolated.ipynb notebook for details on these results.

Resitive Cracks

A classifier for resitive cracks was developed by comparing the accuracy of the multiple binary classifiers tested to classify resitive cracks agains both clean and all other potential defects. The best validation scores for each algorithm and the pipeline producing those scores are shown below. The completed work can be viewied in the eda closed.ipynb notebook.

```
In [59]:
          # Get Data
          num_samples = 100
          resistive_defect_classes = ['Resistive']
          resistive_defect, not_resistive = get_samples(resistive_defect_classes, num_samples, complime
          # Base model on raw data
          title = 'Base Resistive vs. No Resistive with PCA and Logistic Regression'
          model_params = {'penalty': 'l2', 'seed': 14376, 'pca_dims': 100}
          cla = Classifier(resistive defect, not resistive, LogisticRegression, None)
          score = cla.fit_cv(**model_params)
          print(title, " ", score)
         Base Resistive vs. No Resistive with PCA and Logistic Regression 0.6403508771929824
         /opt/conda/lib/python3.8/site-packages/sklearn/linear_model/_logistic.py:763: ConvergenceWarn
         ing: lbfgs failed to converge (status=1):
         STOP: TOTAL NO. of ITERATIONS REACHED LIMIT.
         Increase the number of iterations (max iter) or scale the data as shown in:
             https://scikit-learn.org/stable/modules/preprocessing.html
         Please also refer to the documentation for alternative solver options:
             https://scikit-learn.org/stable/modules/linear model.html#logistic-regression
           n iter i = check optimize result(
In [60]:
          # Train a Gradient boosted classifier
          # Transform the Data
          oriented_resistive_defect = Orient(num_jobs=20) << resistive_defect</pre>
          nobus resistive defect = RemoveBusBars() << oriented resistive defect</pre>
          oriented_not_resistive = Orient(num_jobs=20) << not_resistive</pre>
          nobus not resistive = RemoveBusBars() << oriented not resistive</pre>
          x = nobus resistive defect[-1]
          btw = Butterworth(((\sim x)[0]))
```

```
mask = btw.bandpass(3, 15, 1, 1)


band_resistive_defect = IFFT(mask) << (FFT(dim=2, axis=(-2, -1)) << nobus_resistive_defect)
band_not_resistive = IFFT(mask) << (FFT(dim=2, axis=(-2, -1)) << nobus_not_resistive)

title = 'Base Resistive vs. No Resistive with Butterworth Filter'
model_params = {'max_features': 0.1, 'min_samples_split': 8, 'random_state': 32}
cla = Classifier(band_resistive_defect[-1], band_not_resistive[-1], ExtraTreesClassifier, No score = cla.fit_cv(**model_params)
print(title, " ", score)</pre>
```


Base Resistive vs. No Resistive with Butterworth Filter 0.744360902255639

Summary of training results

```
In [61]: # Resistive Cracks vs Clean
   import matplotlib.image as mpimg
   img = mpimg.imread(os.path.join(os.path.abspath(""), 'images/resistive-clean.png'))
   plt.rcParams["figure.figsize"] = (20,10)
   plt.axis('off')
   imgplot = plt.imshow(img)
   plt.show()
```



```
In [62]:
# Resistive Cracks vs All Other Classes
img = mpimg.imread(os.path.join(os.path.abspath(""), 'images/resistive_all.png'))
plt.rcParams["figure.figsize"] = (20,10)
plt.axis('off')
imgplot = plt.imshow(img)
plt.show()
```



During model assessment, Extra Tree Classifier with a Band Pass filter outperformed all other assessed models. However repeate testing showed that Extra Tree Classifier and CNN's perofrmance would swap depending on the training and validation run. The Extra Tree Classifier was chosen for the final model because it performed well and is not a neural network (i.e. simpler).

The resistive crack is tricky to classify as it contains both the high frequency crack with a low frequency gradient. Balancing the preprocessing to prioritize the presence of these defects. Additional areas where exploration would be interesting are:

• Using a progressive model to identify and crop out section of a crack and then run that section through a classifier to classifiy which crack it was. This would only allow the model to learn the area specifically around the crack and reduce noise from the rest of the panel.

• Experiment with lighter vignetting (hanning window). The edge vignetting can cause a loss of information, especially around the edges of the iamge. There may be a better balance of feature extracting and reduction of risk of introducing artifacts during the transformations.

Results

Once the final feature selection was selected and classifiers determined, a six-way combined classifier was created. The rough operation of the classifier is as follows:

- Datasets are created calling the ImageLoader and DefectViewer classes.
- The best pipeline of transformations for each class is stored in the model_features.py file.
- The parameters for each individual classifier pipeline is then input into the model.
- A loop is then initiated whereby each dataset is loaded, filtered for the correct classes and the transformations applied. The scores for each individual classifier are recorded.
- The scores are then concatenated together and scored using the VectorClassifier class. The balanced accuracy score is used.

The Vector Classifier Class

This was a custom class created to combine the individual classifiers and data pipelines for each defect into a single score metric, effectively creating a score for a multiclass classifier. As input, the class takes a one-hot encoded vector with either 1 (defect present) or 0 (defect not present). The class takes in a list of classifier pretrained models and classified pipelines, and applies pipelines transforms to the test data to extract the features for each class. The then the predict method of the classifier object is called to generate the predicted labels for each image.

The true and predicted y's are stored as arrays and the "overall" score is a balanced accuracy score of this flattened array vs the true image labels. Code for the execution of this combined model is in model.ipynb, Presented therein are comparisons for each pipeline comparing the performance vs. clean (non-defected) images and vs. all other classes combined separately. The source code for the classifier is in models.py.

In contrast to the eda_<defect_class>.ipynb notebooks, the scores presented below are calculated on the TEST set.

Category	Vs. All Others	Vs. Clean
Closed	77.435	82.042
Isolated	82.806	88.749
Bright Spot	96.690	99.429
Corrosion	99.550	100.0

Category	Vs. All Others	Vs. Clean
Resistive	72.678	80.646
Front Grid Interuption & Near Solder Pad	64.254	70.153
Overall	76.913	80.727

Conclusion

Given the restrictions of flawed annotated datasets from the original paper, the results in the high 70% were higher than originally anticipated. However, this could be due that some of the defects only "occured" on similar style of solar cells. This was likely an artifact from data collection on the authors' part. For example, the majority of the corrosion defects had five busbars even though images could have as little as two busbars. This could make this model much less generalizable because corrosion can happen on any type of solar cell, regardless of how many busbars are present.

Nevertheless, the filters for the cracks and finger interruptions are likely to be more robust to data sampling, since this data was collected more broadly and there were many examples of these defects. Generally speaking, the variations in solar cells is relatively small since they are a product built to industry standards. Further, the types of defects are not likely to change over time - find grid interruptions will likely remain straight lines (as the grid lines will likely remain straight), cracks will still present as they do provided the substrate material remains silicon - and so on. Therefore, we could expect that until there is a major change in solar cell design, our model will generalize reasonably well.

It is difficult to make a direct comparison on classifier performance, since there are two main issues with our approach vs that of the original authors:

- The authors of the original paper presented scores on an object segmentation task, and they segmented each defect per image. On the other hand, we created a classifier for a concatenated 'binary classification' objective, and thus the accuracy metrics refer to two different classification tasks.
- Both this work and that of the original authors suffered from incorrect data annotations, which hampers the ability for the classifier/model to 'learn' the distinguishing features of each class. Thus although we used the same data and train/test split, because we filtered some of the data where the original authors had not, a direct comparison cannot be made.

To improve the model in the future, better annotations would be required and perhaps a presegmentation of the active cell area to avoid misaligned cropped regions interfering with the feature extraction and inference. For crack detection, more sophisticated feature extraction which is robust to changes in the wafer crystallinity (dark clusters of crystal dislocations were often confused as cracks in multicrystalline wafers) would help improve the classifier accuracy further. In addition, domain expertise could help solve the generalizability with either presenting more images spanning different types of solar cells for different types of defects. It may be useful to train separate models for each type of solar cell and then retrain if a new number of busbars is introduced or if the wafer material/crystallinity changes.