

Certificate of Inspection

SITE DETAILS	
Site Name:	Ocean Apartments
Site Address:	84 The Esplanade, Surfers Paradise QLD 4217

SYSTEM INFORMATION	
System Type	Industrial Rope Access & Fall Arrest
Inspected To	ISO 22846 Industrial Rope Access Systems AS/NZS 1891.4:2025 Industrial Fall Arrest Systems & Device
System Purpose	Rope Access Anchorage System for Window Cleaning

CERTIFIED COMPONENTS		FAILED OR EXCLUDED COMPONENTS	
The following components have been certified:		The following components have failed or been excluded from this inspection:	
Level 1: 2 x Chemically Set Anchors – 15kN (1,49) 45 x Friction Bolt Anchors – 15kN (3-45, 47, 48) 2 x SRA AA408 – Soffit Anchors – 15kN (50-52) Level 4, 5: 5 x Kattsafe Static Lines – (SL1-SL5) 11 x Kattsafe Post Anchors – 15kN (1-7, 3-11, 17) 6 x SRA AA408 Multi-fix anchors – 15kN (18, 26, 28-31) 2 x Ladder Brackets 2 x Steel Strops 7 x 3M rails – 15kN (RL1-RL7) Level 6: 61 x M16 Chemically Set Anchors - 15kN (1-61) 1 x Ladder Bracket 1 x Steel Strop Level 32: 116 x Cast-In soffit anchors - 15kN (1-1 – 16) 12 x Chemically Set Anchors - 15kN (117-128) 5 x Kattsafe Static Lines – Chemically Set (SL1-SL5) Level 76: 4 x Kattsafe Raptor Rails – Cast-in (RL1, RL2, RL3, RL5) 35 x Chemically Set Anchors - 15kN (1-6, 18-22, 30-35, 46-51, 63-68, 76-81) 4 x Cast-In Soffit Anchors - 15kN (82-85) Rooftop: 14 x Kattsafe Davit Bases – Chemically Set 37 x Kattsafe Needle Bases – Chemically Set 1 x Kattsafe Static Line – Chemically Set 64 x Chemically Set Anchors – 15kN (1-64) 12 x SRA AA408 Multifix Anchors – 15kN (66, 68, 69, 71, 74, 76, 77-82)		Level 1: 2 x Friction Bolt Anchors – 15kN (2, 46) – failed pull out test Level 4 & 5: 6 x Kattsafe Post Anchors – 15kN (8, 12-16) – unable to test 8 x SRA AA408 Multi-fix anchors – 15kN (19-25, 27) – unable to test Level 76: 1 x Kattsafe Raptor Rails – Cast-in (RL4) – improper installation 46 x Chemically Set Anchors - 15kN (7-17, 23-29, 36-45, 52-62, 69-75) – Excluded – installed for construction, not required for façade access Rooftop: 6 x SRA AA406 Multifix Anchors – 15kN (65, 67, 70, 72, 73, 75) – improperly installed 1 x Kattsafe Davit Base - DB-5 – Failed, bolt spinning, needs replacing	
Date of Inspection	08/04/2026	Certificate Expiry	08/04/2027

COMMENTS
All components found to be compliant during this inspection have been fitted with updated certification tags. Failed components have been tagged out of service. For further information on individual components, refer to system inspection report. Rope Access Technicians Pty Ltd takes no responsibility for any part of the system that is not listed in the inspection report. This inspection is not a comprehensive height safety audit and should not be relied upon as an exhaustive record of all possible height safety related risks or hazards that may exist or potential improvements that can be made. To remain compliant with Australian Standards, anchor points must be inspected by a height safety equipment inspector at intervals no greater than 12 months. Inspections must be documented. Installation and inspection documentation should be made readily available to all users of the system. Certification of the system does not absolve any persons of their obligations under the WH&S Act, relevant Regulations, Industry Codes or Australian Standards. This is not an operator's manual and as such is not providing details on the correct and safe use of the system.

AUTHORISED BY	SIGNATURE	DATE
---------------	-----------	------

Peter Knapp		07/04/2025
-------------	---	------------

2026 Inspection Report

Ocean Meriton – Surfers Paradise, QLD

Prepared By: Peter Knapp
Date: 08/04/2026
Document ID: IR 26042

Table of Contents

Certificate of Inspection	1
DISCLAIMER	4
Report Information	5
Inspection & Test Methodology	6
Inspection & Test Results	7
Testing Equipment - Calibration Certificate	28
Site Plan	31

DISCLAIMER

Rope Access Technicians believes the information contained within this report to be correct at the time of issue.

Rope Access Technicians was commissioned to undertake an inspection of height safety components at this site. This is not a comprehensive height safety audit and should not be relied upon as an exhaustive record of all possible height safety related risks or hazards that may exist or potential improvements that can be made.

Upon completion of this inspection, a certificate detailing the results shall be provided to the client. This certificate should be made readily available to users of the system.

Certification of the system does not absolve any persons of their obligations under the WH&S Act, relevant Regulations, Industry Codes or Australian Standards.

This is not an operator's manual and as such is not providing details on the correct and safe use of the system.

Report Information

Client:	Ocean 2 BMS CTS 721189441
Site Name:	Ocean Meriton
Address:	84 The Esplanade, Surfers Paradise QLD 4217
Site Contact:	Victor Joy – 0418 239 538
System Installed:	See First Page for Details
Component Manufacturers:	SRA, KattSafe, DBISala
Installed By:	Sky5
Installation Date:	Various - 2021
System Type:	Rope Access & Fall Arrest
System Location:	Levels: 1,4,5,6,32,76 and Rooftop. Soffit: 32, 76
System Rating:	Fall Arrest Components = 15 KN (1 anchor per person) Rope Access Components = 15 KN (2 anchors per person)
Inspection Completed by:	Brendan Farrell, Bruno Almeida
Inspection Date:	08/04/2026
System ID Sign:	Yes on rooftop door
Anchor Plan:	Yes in this report
User Manual Provided:	Yes
Test Equipment Used:	3 x Hydrajaws Model 2000
Test Equipment Calibration Date:	Gauge 09: 16/09/2025, Gauge 10: 22/04/2025, Gauge 11: 22/04/2025,
Test Exclusions:	Any other items not covered by this report
Report Written by:	Peter Knapp

Inspection & Test Methodology

Anchor Points

In accordance with Australian Standard 1891.4:2009 – Industrial fall-arrest systems and devices and AS4488.2:1997 – Industrial rope access systems, permanently installed anchor points are to be inspected at intervals not exceeding 12 months. The anchorages are visually inspected for signs of deterioration, which might make them unserviceable, together with any other requirements contained in manufacturers' instructions. The parent structure is also visually inspected for modifications or deterioration which might lead to loss of anchor strength. Drilled-in, glued-in and friction anchors are proof loaded by application of an axial pull-out force of 50% of the anchor's design load (this equates to 6kN for rope access, 7.5kN for fall-arrest).

Horizontal and Vertical Life Lines and Rails

In accordance with Australian Standard 1891.4:2009 – Industrial fall-arrest systems and devices, life lines of steel construction and rails are to be inspected by a height safety equipment inspector at intervals as recommendation by the manufacturer to a maximum of five-yearly. In the absence of such a recommendation, static lines are to be inspected on an annual basis. The inspection is carried out in accordance with the manufacturer's instructions. Line anchorage points and rail support anchorages are inspected as per the methodology for anchor points above. The parent structure is inspected for any modification or deterioration which might lead to a loss of anchorage strength. Cables terminations, line tensioners, fixings and other system components are inspected in accordance with AS1891.4 clause 9.3.5.

Important! Any system which has not been certified in over 12 months cannot be used. All inspections are to be documented. Upon completion of the annual testing regime, a certificate detailing the results of the inspection should be supplied to building management. This certificate and any installation documentation should be made readily available to users of the system.

Inspection & Test Results

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
Level 1								
1	MULTI	AP - C	Level 1	Good	Good	7.5kN	3 Min	PASS
2	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	FAIL
3	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
4	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
5	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
6	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
7	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
8	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
9	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
10	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
11	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
12	MULTI	AP - FR	Level 1	Good	Good	N/A	N/A	FAIL
13	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
14	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
15	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
16	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
17	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
18	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
19	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
20	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
21	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
22	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
23	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
24	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
25	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
26	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
27	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
28	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
29	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
30	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
31	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
32	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
33	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
34	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
35	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
36	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
37	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
38	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
39	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
40	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
41	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
42	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
43	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
44	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
45	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
46	MULTI	AP - FR	Level 1	Good	Insufficient	N/A	N/A	FAIL
47	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
48	MULTI	AP - FR	Level 1	Good	Good	7.5kN	3 Min	PASS
49	MULTI	AP - C	Level 1	Good	Good	7.5kN	3 Min	PASS
50	MULTI	AP - FR	Level 1	Good	Good	7.5kN/ Bolt	3 Min/ Bolt	PASS
51	MULTI	AP - FR	Level 1	Good	Good	7.5kN/ Bolt	3 Min/ Bolt	PASS
52	MULTI	AP - FR	Level 1	Good	Good	7.5kN/ Bolt	3 Min/ Bolt	PASS
Level 4 & 5								
1	MULTI	AP - C	Level 4	Good	Good	7.5 kN	3 Min	PASS
2	MULTI	AP - C	Level 4	Good	Good	7.5 kN	3 Min	PASS
3	MULTI	AP - C	Level 4	Good	Good	7.5 kN	3 Min	PASS
4	MULTI	AP - C	Level 4	Good	Good	7.5 kN	3 Min	PASS
5	MULTI	AP - C	Level 4	Good	Good	7.5 kN	3 Min	PASS
6	MULTI	AP - C	Level 4	Good	Good	7.5 kN	3 Min	PASS
7	MULTI	AP - C	Level 4	Good	Good	7.5 kN	3 Min	PASS

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
8	MULTI	AP - C	Level 4	Can't Test	Can't Test	N/A	N/A	FAIL
9	MULTI	AP - C	Level 4	Good	Good	7.5 kN	3 Min	PASS
10	MULTI	AP - C	Level 4	Good	Good	7.5 kN	3 Min	PASS
11	MULTI	AP - C	Level 4	Good	Good	7.5 kN	3 Min	PASS
12	MULTI	AP - C	Level 4	Can't Test	Can't Test	N/A	N/A	FAIL
13	MULTI	AP - C	Level 4	Can't Test	Can't Test	N/A	N/A	FAIL
14	MULTI	AP - C	Level 4	Can't Test	Can't Test	N/A	N/A	FAIL
15	MULTI	AP - C	Level 4	Can't Test	Can't Test	N/A	N/A	FAIL
16	MULTI	AP - C	Level 4	Can't Test	Can't Test	N/A	N/A	FAIL
17	MULTI	AP - C	Level 4	Good	Good	7.5 kN	3 Min	PASS
18	MULTI	AP - C	Level 5	Good	Good	7.5 kN	3 Min	PASS
19	MULTI	AP - C	Level 5	Can't Test	Can't Test	N/A	N/A	FAIL
20	MULTI	AP - C	Level 5	Can't Test	Can't Test	N/A	N/A	FAIL
21	MULTI	AP - C	Level 5	Can't Test	Can't Test	N/A	N/A	FAIL
22	MULTI	AP - C	Level 5	Can't Test	Can't Test	N/A	N/A	FAIL
23	MULTI	AP - C	Level 5	Can't Test	Can't Test	N/A	N/A	FAIL
24	MULTI	AP - C	Level 5	Can't Test	Can't Test	N/A	N/A	FAIL
25	MULTI	AP - C	Level 5	Can't Test	Can't Test	N/A	N/A	FAIL
26	MULTI	AP - C	Level 5	Good	Good	7.5 kN	3 Min	PASS
27	MULTI	AP - C	Level 5	Can't Test	Can't Test	N/A	N/A	FAIL
28	MULTI	AP - C	Level 5	Good	Good	7.5 kN	3 Min	PASS
29	MULTI	AP - C	Level 5	Good	Good	7.5 kN	3 Min	PASS
30	MULTI	AP - C	Level 5	Good	Good	7.5 kN	3 Min	PASS
31	MULTI	AP - C	Level 5	Good	Good	7.5 kN	3 Min	PASS
ST1	FA	ST	Level 5	Good	Good	Visual	Visual	PASS
ST2	FA	ST	Level 5	Good	Good	Visual	Visual	PASS
LB1	OTHER	LB-C	Level 5	Good	Good	Visual	Visual	PASS
LB2	OTHER	LB-C	Level 5	Good	Good	Visual	Visual	PASS
FL1	OTHER	FL	Level 5 to 4	Incorrect Installation	Good	Visual	Visual	FAIL
RL1	MULTI	RL-C	Level 5	Good	Good	7.5 kN/ Bolt	3 Min/ Bolt	PASS
RL2	MULTI	RL-C	Level 5	Good	Good	7.5 kN/ Bolt	3 Min/ Bolt	PASS

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
RL3	MULTI	RL-C	Level 5	Good	Good	7.5 kN/ Bolt	3 Min/ Bolt	PASS
RL4	MULTI	RL-C	Level 5	Good	Good	7.5 kN/ Bolt	3 Min/ Bolt	PASS
RL5	MULTI	RL-C	Level 5	Good	Good	7.5 kN/ Bolt	3 Min/ Bolt	PASS
RL6	MULTI	RL-C	Level 5	Good	Good	7.5 kN/ Bolt	3 Min/ Bolt	PASS
RL7	MULTI	RL-C	Level 5	Good	Good	7.5 kN/ Bolt	3 Min/ Bolt	PASS
SL1	FA	HL-CAST	Level 5	Good	Good	Visual	Visual	PASS
SL2	FA	HL-CAST	Level 5	Good	Good	Visual	Visual	PASS
SL3	FA	HL-C	Level 4	Good	Good	Visual	Visual	PASS
SL3 – End x 4	FA	End Stanchion	Level 4	Good	Good	7.5kN	3 min	PASS
SL3 – Int x 3	FA	Intermediate	Level 4	Good	Good	7.5kN	3 Min	PASS
SL4	FA	HL-C	Level 4	Good	Good	Visual	Visual	PASS
SL4 – End x 4	FA	End Stanchion	Level 4	Good	Good	7.5kN	3 min	PASS
SL4 – Int x 11	FA	Intermediate	Level 4	Good	Good	7.5kN	3 Min	PASS
SL5	FA	HL-C	Level 4	Good	Good	Visual	Visual	PASS
SL5 – End x 4	FA	End Stanchion	Level 4	Good	Good	7.5kN	3 min	PASS
SL5 – Int x 1	FA	Intermediate	Level 4	Good	Good	7.5kN	3 Min	PASS
Level 6								
1	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
2	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
3	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
4	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
5	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
6	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
7	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
8	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
9	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
10	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
11	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
12	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
13	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
14	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
15	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
16	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
17	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
18	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
19	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
20	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
21	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
22	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
23	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
24	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
25	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
26	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
27	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
28	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
29	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
30	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
31	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
32	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
33	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
34	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
35	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
36	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
37	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
38	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
39	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
40	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
41	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
42	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
43	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
44	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
45	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
46	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
47	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
48	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
49	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
50	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
51	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
52	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
53	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
54	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
55	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
56	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
57	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
58	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
59	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
60	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
61	MULTI	AP - C	Level 6	Good	Good	7.5 kN	3 Min	PASS
LB1	OTHER	LB-C	Level 6	Good	Good	Visual	Visual	PASS
SS1	OTHER	ST-C	Level 6	Good	Good	Visual	Visual	PASS
Level 32								
1	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
2	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
3	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
4	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
5	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
6	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
7	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
8	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
9	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
10	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
11	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
12	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
13	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
14	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
15	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
16	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
17	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
18	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
19	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
20	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
21	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
22	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
23	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
24	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
25	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
26	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
27	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
28	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
29	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
30	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
31	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
32	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
33	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
34	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
35	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
36	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
37	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
38	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
39	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
40	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
41	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
42	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
43	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
44	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
45	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
46	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
47	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
48	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
49	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
50	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
51	MULTI	AP - CAST	Level 32 - Soffit	Good	Cracked	7.5kN	3 Min	PASS
52	MULTI	AP - CAST	Level 32 - Soffit	Good	Cracked	7.5kN	3 Min	PASS
53	MULTI	AP - CAST	Level 32 - Soffit	Good	Cracked	7.5kN	3 Min	PASS
54	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
55	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
56	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
57	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
58	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
59	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
60	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
61	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
62	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
63	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
64	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
65	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
66	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
67	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
68	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
69	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
70	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
71	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
72	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
73	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
74	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
75	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
76	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
77	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
78	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
79	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
80	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
81	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
82	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
83	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
84	MULTI	AP - CAST	Level 32 - Soffit	Good	Cracked	7.5kN	3 Min	PASS
85	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
86	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
87	MULTI	AP - CAST	Level 32 - Soffit	Good	Cracked	7.5kN	3 Min	PASS
88	MULTI	AP - CAST	Level 32 - Soffit	Good	Cracked	7.5kN	3 Min	PASS
89	MULTI	AP - CAST	Level 32 - Soffit	Good	Cracked	7.5kN	3 Min	PASS
90	MULTI	AP - CAST	Level 32 - Soffit	Good	Cracked	7.5kN	3 Min	PASS
91	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
92	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
93	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
94	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
95	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
96	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
97	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
98	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
99	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
100	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
101	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
102	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
103	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
104	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
105	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
106	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
107	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
108	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
109	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
110	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
111	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
112	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
113	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
114	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
115	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
116	MULTI	AP - CAST	Level 32 - Soffit	Good	Good	Visual	Visual	PASS
117	MULTI	AP - C	Level 32	Good	Good	Visual	Visual	PASS
118	MULTI	AP - C	Level 32	Good	Good	Visual	Visual	PASS
119	MULTI	AP - C	Level 32	Good	Good	Visual	Visual	PASS
120	MULTI	AP - C	Level 32	Good	Good	Visual	Visual	PASS
121	MULTI	AP - C	Level 32	Good	Good	Visual	Visual	PASS
122	MULTI	AP - C	Level 32	Good	Good	Visual	Visual	PASS
123	MULTI	AP - C	Level 32	Good	Good	Visual	Visual	PASS
124	FA	AP-FR	Level 32	Good	Good	7.5 kN	3 Min	PASS
125	FA	AP-FR	Level 32	Good	Good	7.5 kN	3 Min	PASS
126	FA	AP-FR	Level 32	Good	Good	7.5 kN	3 Min	PASS
127	FA	AP-FR	Level 32	Good	Good	7.5 kN	3 Min	PASS
128	FA	AP-FR	Level 32	Good	Good	7.5 kN	3 Min	PASS
SL1	FA	HL	Level 32	Good	Good	Visual	Visual	PASS
END 1-2		FR	Level 32	Good	Good	7.5 kN / Bolt	3 Min / Bolt	PASS
INT 1-4		FR	Level 32	Good	Good	7.5 kN / Bolt	3 Min / Bolt	PASS
SL2	FA	HL	Level 32	Good	Good	Visual	Visual	PASS
END 1-2		FR	Level 32	Good	Good	7.5 kN / Bolt	3 Min / Bolt	PASS
INT 1-3		FR	Level 32	Good	Good	7.5 kN / Bolt	3 Min / Bolt	PASS
SL3	FA	HL	Level 32	Good	Good	Visual	Visual	PASS
END 1-2		FR	Level 32	Good	Good	7.5 kN / Bolt	3 Min / Bolt	PASS
INT 1-11		FR	Level 32	Good	Good	7.5 kN / Bolt	3 Min / Bolt	PASS

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
INT 12		2 x C	Level 32	Good	Good	7.5 kN / Bolt	3 Min / Bolt	PASS
SL4	FA	HL	Level 32	Good	Good	Visual	Visual	PASS
END 1		2 x FR 1 x C	Level 32	Good	Good	7.5 kN / Bolt	3 Min / Bolt	PASS
END 2		FR	Level 32	Good	Good	7.5 kN / Bolt	3 Min / Bolt	PASS
INT 1-4		FR	Level 32	Good	Good	7.5 kN / Bolt	3 Min / Bolt	PASS
SL5	FA	HL	Level 32	Good	Good	Visual	Visual	PASS
END 1-2		FR	Level 32	Good	Good	7.5 kN / Bolt	3 Min / Bolt	PASS
INT 1-6		FR	Level 32	Good	Good	7.5 kN / Bolt	3 Min / Bolt	PASS
ST1	FA	ST	Anchor 124	Good	Good	Visual	Visual	PASS
ST2	FA	ST	Anchor 125	Good	Good	Visual	Visual	PASS
ST3	FA	ST	Anchor 126	Good	Good	Visual	Visual	PASS
ST4	FA	ST	Anchor 127	Good	Good	Visual	Visual	PASS
ST5	FA	ST	Anchor 128	Good	Good	Visual	Visual	PASS
GR1	OTHER	GR-FR	Level 32	Good	Good	Visual	Visual	PASS
GR2	OTHER	GR-FR	Level 32	Good	Good	Visual	Visual	PASS
GR3	OTHER	GR-FR	Level 32	Good	Good	Visual	Visual	PASS
GR4	OTHER	GR-FR	Level 32	Good	Good	Visual	Visual	PASS
GR5	OTHER	GR-FR	Level 32	Good	Good	Visual	Visual	PASS
Level 76								
1	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
2	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
3	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
4	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
5	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
6	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
7	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
8	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
9	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
10	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
11	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
12	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
13	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
14	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
15	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
16	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
17	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
18	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
19	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
20	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
21	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
22	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
23	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
24	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
25	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
26	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
27	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
28	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
29	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
30	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
31	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
32	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
33	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
34	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
35	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
36	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
37	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
38	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
39	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
40	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
41	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
42	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
43	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
44	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
45	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
46	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
47	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
48	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
49	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
50	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
51	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
52	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
53	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
54	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
55	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
56	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
57	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
58	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
59	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
60	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
61	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
62	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
63	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
64	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
65	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
66	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
67	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
68	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
69	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
70	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
71	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
72	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
73	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
74	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
75	MULTI	AP - C	Level 76	Good	Good	N/A	N/A	EXCLUDED
76	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
77	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
78	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
79	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
80	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
81	MULTI	AP - C	Level 76	Good	Good	7.5 kN	3 Min	PASS
82	RA	AP-CAST	Level 76	Good	Good	Visual	Visual	PASS
83	RA	AP-CAST	Level 76	Good	Good	Visual	Visual	PASS
84	RA	AP-CAST	Level 76	Good	Good	Visual	Visual	PASS
85	RA	AP-CAST	Level 76	Good	Good	Visual	Visual	PASS
RL1	MULTI	RL-CAST	Level 76 - Soffit	Good	Good	Visual	Visual	PASS
RL2	MULTI	RL-CAST	Level 76 - Soffit	Good	Good	Visual	Visual	PASS
RL3	MULTI	RL-CAST	Level 76 - Soffit	Good	Good	Visual	Visual	PASS
RL4	MULTI	RL-CAST	Level 76 - Soffit	Poor	Good	Visual	Visual	FAIL
RL5	MULTI	RL-CAST	Level 76 - Soffit	Good	Good	Visual	Visual	PASS
GR1	OTHER	GR-FR	Level 76	Good	Good	Visual	Visual	PASS
GR2	OTHER	GR-FR	Level 76	Good	Good	Visual	Visual	PASS
GR3	OTHER	GR-FR	Level 76	Good	Good	Visual	Visual	PASS
GR4	OTHER	GR-FR	Level 76	Good	Good	Visual	Visual	PASS
GR5	OTHER	GR-FR	Level 76	Good	Good	Visual	Visual	PASS
GR6	OTHER	GR-FR	Level 76	Good	Good	Visual	Visual	PASS
Rooftop								
1	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
2	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
3	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
4	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
5	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
6	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
7	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
8	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
9	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
10	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
11	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
12	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
13	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
14	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
15	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
16	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
17	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
18	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
19	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
20	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
21	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
22	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
23	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
24	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
25	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
26	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
27	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
28	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
29	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
30	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
31	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
32	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
33	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
34	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
35	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
36	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
37	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
38	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
39	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
40	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
41	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
42	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
43	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
44	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
45	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
46	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
47	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
48	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
49	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
50	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
51	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
52	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
53	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
54	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
55	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
56	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
57	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
58	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
59	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
60	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
61	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
62	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
63	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
64	MULTI	AP - C	Rooftop	Good	Good	7.5 kN	3 Min	PASS
65	MULTI	AP - FR	Rooftop	Good	Insufficient	N/A	N/A	FAIL
66	MULTI	AP - FR	Rooftop	Good	Good	7.5kN/ bolt	3 Min/ Bolt	PASS
67	MULTI	AP – FR	Rooftop	Good	Insufficient	N/A	N/A	FAIL
68	MULTI	AP - FR	Rooftop	Good	Good	7.5kN/ bolt	3 Min/ Bolt	PASS
69	MULTI	AP - FR	Rooftop	Good	Good	7.5kN/ bolt	3 Min/ Bolt	PASS
70	MULTI	AP – FR	Rooftop	Good	Insufficient	N/A	N/A	FAIL
71	MULTI	AP - FR	Rooftop	Good	Good	7.5kN/ bolt	3 Min/ Bolt	PASS

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
72	MULTI	AP – FR	Rooftop	Good	Insufficient	N/A	N/A	FAIL
73	MULTI	AP – FR	Rooftop	Good	Insufficient	N/A	N/A	FAIL
74	MULTI	AP - FR	Rooftop	Good	Good	7.5kN/ bolt	3 Min/ Bolt	PASS
75	MULTI	AP – FR	Rooftop	Good	Insufficient	N/A	N/A	FAIL
76	MULTI	AP - FR	Rooftop	Good	Good	7.5kN/ bolt	3 Min/ Bolt	PASS
77	MULTI	AP - FR	Rooftop	Good	Good	7.5kN/ bolt	3 Min/ Bolt	PASS
78	MULTI	AP - FR	Rooftop	Good	Good	7.5kN/ bolt	3 Min/ Bolt	PASS
79	MULTI	AP - FR	Rooftop	Good	Good	7.5kN/ bolt	3 Min/ Bolt	PASS
80	MULTI	AP - FR	Rooftop	Good	Good	7.5kN/ bolt	3 Min/ Bolt	PASS
81	MULTI	AP - FR	Rooftop	Good	Good	7.5kN/ bolt	3 Min/ Bolt	PASS
82	MULTI	AP - FR	Rooftop	Good	Good	7.5kN/ bolt	3 Min/ Bolt	PASS
DB1	FA	DB-C	Rooftop	Good	Good	15kN / Bolt	3 Min / Bolt	PASS
DB2	FA	DB-C	Rooftop	Good	Good	15kN / Bolt	3 Min / Bolt	PASS
DB3	FA	DB-C	Rooftop	Good	Good	15kN / Bolt	3 Min / Bolt	PASS
DB4	FA	DB-C	Rooftop	Good	Good	15kN / Bolt	3 Min / Bolt	PASS
DB5	FA	DB-C	Rooftop	1 Bolt Spinning	Good	15kN / Bolt	3 Min / Bolt	FAIL
DB6	FA	DB-C	Rooftop	Good	Good	15kN / Bolt	3 Min / Bolt	PASS
DB7	FA	DB-C	Rooftop	Good	Good	15kN / Bolt	3 Min / Bolt	PASS
DB8	FA	DB-C	Rooftop	Good	Good	15kN / Bolt	3 Min / Bolt	PASS
DB9	FA	DB-C	Rooftop	Good	Good	15kN / Bolt	3 Min / Bolt	PASS
DB10	FA	DB-C	Rooftop	Good	Good	15kN / Bolt	3 Min / Bolt	PASS
DB11	FA	DB-C	Rooftop	Good	Good	15kN / Bolt	3 Min / Bolt	PASS
DB12	FA	DB-C	Rooftop	Good	Good	15kN / Bolt	3 Min / Bolt	PASS

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
DB13	FA	DB-C	Rooftop	Good	Good	15kN / Bolt	3 Min / Bolt	PASS
DB14	FA	DB-C	Rooftop	Good	Good	15kN / Bolt	3 Min / Bolt	PASS
DB15	FA	DB-C	Rooftop	Good	Good	15kN / Bolt	3 Min / Bolt	PASS
NB1	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB2	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB3	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB4	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB5	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB6	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB7	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB8	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB9	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB10	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB11	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB12	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB13	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB14	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB15	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB16	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB17	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB18	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
NB19	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB20	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB21	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB22	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB23	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB24	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB25	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB26	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB27	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB28	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB29	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB30	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB31	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB32	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB33	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB34	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB35	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB36	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
NB37	FA	NB-C	Rooftop	Good	Good	7.5kN /Bolt	3 Min	PASS
FL01	OTHER	FL-FR	Rooftop	Good	Good	Visual	Visual	PASS
FL02	OTHER	FL-FR	Rooftop	Good	Good	Visual	Visual	PASS
PL01	OTHER	FL-FR	Rooftop	Good	Good	Visual	Visual	PASS

ITEM ID	ITEM USE	ITEM TYPE	LOCATION	ITEM CONDITION	SUBSTRATE CONDITION	TEST LOAD	LOAD TIME	RESULT
PL02	OTHER	FL-FR	Rooftop	Good	Good	Visual	Visual	PASS
SL01	FA	HL-C	Rooftop	Good	Good	Visual	Visual	PASS
SL01 – END x 2	FA	End Stanchion	Rooftop	Good	Good	10.5kN	3 Min	PASS
SL01 – INT x 2	FA	Intermediate	Rooftop	Good	Good	7.5kN	3 Min	PASS
NEEDLE01	FA	Needle	Rooftop	Good	N/A	Visual	Visual	PASS
NEEDLE02	FA	Needle	Rooftop	Good	N/A	Visual	Visual	PASS
NEEDLE03	FA	Needle	Rooftop	Good	N/A	Visual	Visual	PASS
NEEDLE04	FA	Needle	Rooftop	Good	N/A	Visual	Visual	PASS
NEEDLE05	FA	Needle	Rooftop	Good	N/A	Visual	Visual	PASS
NEEDLE06	FA	Needle	Rooftop	Good	N/A	Visual	Visual	PASS
DAVIT01	FA	Davit Arm	Rooftop	Good	N/A	Visual	Visual	PASS
DAVIT02	FA	Davit Arm	Rooftop	Good	N/A	Visual	Visual	PASS
PONY1	RA	Pony	Rooftop	Rusting	N/A	Visual	Visual	PASS
PONY2	RA	Pony	Rooftop	Rusting	N/A	Visual	Visual	PASS
COMMENTS:			All anchors have been tested in accordance with and ISO 22846 & ASNZS 1891 and have passed unless listed otherwise above. All tested anchors have been tagged (unless listed otherwise above) and their locations clearly identified on the site plan section of this document. All other anchors not listed in these test results are excluded from this inspection. Level 76 - RL1 – Following review with the technical director for KattSafe it has been determined that RL1 is safe for use and has been certified. Anchor Failures: Level 1 - Anchor 2 – failed pull out test - Anchor 46 – unable to test due to installed balustrade glass Level 4 & 5: - Anchors 8, 12-16 – Due to installed flashing, these anchors cannot be tested - Anchors 19-25, 27 – Anchors buried in dirt, unable to test Level 76: - All excluded anchors on 76 are not needed for façade access. These were installed during building construction - RL4 – One hanger appears to be a chemset bolt and has insufficient thread engagement with the nut. Various joints have been installed with a gap greater than 4mm DB-5 – Failed as one bolt is spinning, requires replacement Rooftop: - Anchors 65, 67, 70, 72, 73, 75 – poorly installed with insufficient distance between anchors Ponies – These are showing signs of rusting and seizing. At this point they are structurally sound and usable, with some lubrication for the seized counterweight attachment points. We recommended additional maintenance to remove rusting, and recoat the rusted parts to prevent further damage and ongoing lubrication of any moving parts to reduce the likelihood of seizing.					

INSPECTION & TEST LEGEND

ITEM USE	FA – Fall Arrest / RA – Rope Access / DIV – Diversion / AID – Aid Climbing Point / MULTI – Fall Arrest & Rope Access / OTHER – Other	
ITEM TYPE	ITEM TYPE	AP – Anchor Point / HL – Horizontal Lifeline / VL – Vertical Lifeline / L – Ladder / LB – Ladder Bracket / ST – Strop / HAR – Harness / SRL – Self Retracting Lanyard / LAN – Lanyard / ROP – Rope / SD – Safety Device / CAR - Carabiner
	FIXING METHOD (Anchors Only)	C – Chemically Set / FR – Friction Anchor / TB – Through Bolt / PA – Purlin Anchor SM – Surface Mount Anchor / TR – Truss Mount Anchor

Testing Equipment - Calibration Certificate



OTTO INDUSTRIAL INSTRUMENTS

SALES - SERVICE - REPAIR - CALIBRATION

CALIBRATION REPORT

TEST PRESSURE GAUGE

FOR: Rope Access Technicians
Unit 11/80 Township Drive
Burleigh Heads QLD 4220

Date of Calibration: 16/09/2025

Report No: 32962

Job: 18746

Gauge Description

Maker: Hydrajaws
Serial No: 6494
Location: Oil Laboratory

Type: Analogue

Plant No: GAU 09

Range: 25 KN

Preliminary Inspection: Serviced Prior to Calibration.

Calibration: The Gauge was calibrated in a Vertical position over a series of three tests. AS 1349-1986 was used as the basis for this Calibration. Equipment used in this examination was a Digital Pressure Indicator.

A Traceable Standard: Nata Calibration Report No. NC15/0129 is part of the system.

The gauge was calibrated to meet the requirements of AS/NZS ISO 10012:2004 (Measurement Processes and Measuring Equipment).

The ambient temperature during calibration was 21 degrees Celsius.

Calibration Results: The mean values of the gauge indications at applied pressure are given in Table 1.

Signed: 
Allan Barber
For Otto Industrial Instruments

Date: 16/09/2025

Page 1 of 2

ABN 33 124 107 967
3 Commerce Street
Salisbury Qld. 4107
P.O. Box 25 Salisbury Q. 4107

Tel: (07) 3277 3971
Fax: (07) 3276 8889
info@ottoindustrial.com.au
www.ottoindustrial.com.au



OTTO INDUSTRIAL INSTRUMENTS

SALES - SERVICE - REPAIR - CALIBRATION

CALIBRATION REPORT

TEST PRESSURE GAUGE

FOR: Rope Access Technicians
Unit 1/11 Ramly Drive
Burleigh Heads QLD 4220

Date of Calibration: 22/04/2025

Report No: 32548

Job: 18539

Gauge Description

Maker: Hydrajaws

Type: Analogue

Serial No: 5404CYO5

Plant No: GAU 10

Location: Oil Laboratory

Range: 20 KN

Preliminary Inspection: Serviced Prior to Calibration

Calibration: The Gauge was calibrated in a Vertical position over a series of three tests. AS 1349-1986 was used as the basis for this Calibration. Equipment used in this examination was a Digital Pressure Indicator.

A Traceable Standard: Nata Calibration Report No. NC15/0129 is part of the system.

The gauge was calibrated to meet the requirements of AS/NZS ISO 10012:2004 (Measurement Processes and Measuring Equipment).

The ambient temperature during calibration was 21 degrees Celsius.

Calibration Results: The mean values of the gauge indications at applied pressure are given in Table 1.

Signed: 

Date: 22/04/2025

Allan Barber

For Otto Industrial Instruments

Page 1 of 2

ABN 33 124 107 967
3 Commerce Street
Salisbury Qld. 4107
P.O. Box 25 Salisbury Q. 4107

Tel: (07) 3277 3971
Fax: (07) 3276 8889
info@ottoindustrial.com.au
www.ottoindustrial.com.au



OTTO INDUSTRIAL INSTRUMENTS

SALES - SERVICE - REPAIR - CALIBRATION

CALIBRATION REPORT

TEST PRESSURE GAUGE

FOR: Rope Access Technicians
Unit 1/11 Ramtly Drive
Burleigh Heads QLD 4220

Date of Calibration: 22/04/2025

Report No: 32547
Job: 18539

Gauge Description

Maker: Hydrajaws
Serial No: 402232001
Location: Oil Laboratory

Type: Analogue
Plant No: GAU 11
Range: 15 KN

Preliminary Inspection: Serviced Prior to Calibration

Calibration: The Gauge was calibrated in a Vertical position over a series of three tests. AS 1349-1986 was used as the basis for this Calibration. Equipment used in this examination was a Digital Pressure Indicator.

A Traceable Standard: Nata Calibration Report No. NC15/0129 is part of the system.

The gauge was calibrated to meet the requirements of AS/NZS ISO 10012:2004 (Measurement Processes and Measuring Equipment).

The ambient temperature during calibration was 21 degrees Celsius.

Calibration Results: The mean values of the gauge indications at applied pressure are given in Table 1.

Signed: 
Allan Barber
For Otto Industrial Instruments


Date: 22/04/2025


Page 1 of 2

A.B.N 33 124 107 967
3 Commerce Street
Salisbury Qld. 4107
P.O. Box 25 Salisbury Q. 4107

Tel: (07) 3277 3971
Fax: (07) 3276 8889
info@ottoindustrial.com.au
www.ottoindustrial.com.au

Site Plan





Building: Oceans by Meriton

Address: 84 The Esplanade,
Surfers Paradise QLD 4217

Legend


Fall Arrest Anchor
Rope Access Anchor
Multi Use Anchor
Soffit Anchor
Steel Strop
Failed Anchor



Ladder Bracket
Gutter Bracket
Fixed Ladder
Walkway
Platform
Guardrail



Davit Base
Needle Base
Fall Arrest Rail
Rope Access Rail
Static Line



Level: 4 & 5




Building: Ocean by Meriton

Address: 84 The Esplanade
Surfers Paradise, QLD 4217

Legend

Fall Arrest Anchor
Rope Access Anchor
Multi Use Anchor
Soffit Anchor
Steel Strop
Failed Anchor



Ladder Bracket
Gutter Bracket
Fixed Ladder
Walkway
Platform



Davit Base
Fall Arrest Rail
Rope Access Rail
Static Line



Level: 6



Building: Oceans by Meriton
Address: 84 The Esplanade, Surfers Paradise QLD 4217

Level: 32

Legend

Fall Arrest Anchor
Rope Access Anchor
Multi Use Anchor
Soffit Anchor
Aid Anchor
Failed Anchor
Steel Stop

Ladder Bracket
Gutter Bracket
Fixed Ladder
Walkway
Platform
Guardrail
Stairs
Roof Hatch


Davit Base
Needle Base
Post Anchor
Fall Arrest Rail
Rope Access Rail
Static Line

ChemSet
ChemSet
ChemSet
ChemSet
ChemSet
ChemSet

Cast In
Cast In
Cast In
CastIn/ThruBolt
CastIn/ThruBolt
CastIn/ThruBolt

▲
▲
▲
→
→
→

Date Plan Created:
07/04/2026



**ROPE ACCESS
TECHNICIANS**
INSPECT | REPAIR | INSTALL | MAINTAIN

Building: Oceans by Meriton
Address: 84 The Esplanade,
Surfers Paradise QLD 4217

Legend

Fall Arrest Anchor
Rope Access Anchor
Multi Use Anchor
Soffit Anchor
Steel Strop
Failed Anchor




Ladder Bracket
Gutter Bracket
Fixed Ladder
Walkway
Platform
Guardrail



Davit Base
Needle Base
Fall Arrest Rail
Rope Access Rail
Static Line



Level: 76



ROPE ACCESS TECHNICIANS
 INSPECT | REPAIR | INSTALL | MAINTAIN

Building: Oceans by Meriton Address: 84 The Esplanade,
 Surfers Paradise QLD 4217

Legend

Fall Arrest Anchor
 Rope Access Anchor
 Multi Use Anchor
 Soffit Anchor
 Steel Strop
 Failed Anchor



Ladder Bracket
 Gutter Bracket
 Fixed Ladder
 Walkway
 Platform
 Guardrail



Davit Base
 Needle Base
 Fall Arrest Rail
 Rope Access Rail
 Static Line



Level: 77/Roof