Vehicle Condition Report

en de

POWERED BY PAVE

2019 PEUGEOT BOXER

VIN # **VF3YFANF*2***3062**

INSPECTION DATE:
March 20, 2026 @ 09:05 UTC

4
GOOD

Front Side: TOTAL GRADE SCORE	Back Side: TOTAL GRADE SCORE	Total Grade Score All Damages:
3	3	9
Left Side: TOTAL GRADE SCORE	**Right Side:** TOTAL GRADE SCORE	
0	3	

Vehicle Photos

ORIGINAL INSPECTION



Upload Photos

OPTIONAL

No photo

Exterior (3)

LEFT SIDE

Grade Score 1 Grade Score 4

RIGHT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
2 Rear Right Quarter Side Molding		Missing	Part is missing	Replace	3

FRONT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
1 Front Bumper Cover		Has Major Dent on Seam Line - Not Through Paint	Major dent 230mm to 255mm but on seam line	Replace	3

BACK SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
3 Rear Badge		Missing	Part is missing	Replace	3

WINDSHIELD

No damage