Vehicle Condition Report

en de

POWERED BY PAVE

2024 MERCEDES 315CDI L2 DIESEL RWD

VIN # **W1V3HBFZ*P***1460**

INSPECTION DATE:
March 04, 2026 @ 09:14 UTC

4
GOOD

Front Side: TOTAL GRADE SCORE	Back Side: TOTAL GRADE SCORE	Total Grade Score All Damages:
0	3	3
Left Side: TOTAL GRADE SCORE	**Right Side:** TOTAL GRADE SCORE	
0	0	

Vehicle Photos

ORIGINAL INSPECTION





Upload Photos

OPTIONAL

No photo

Exterior (2)

LEFT SIDE

Grade Score 1 Grade Score 4

RIGHT SIDE

Grade Score 1 Grade Score 4

FRONT SIDE



Grade Score 1 Grade Score 4

BACK SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
1 Rear Left Hatch Door		Has Major Dent on Seam Line - Not Through Paint	Major dent 230mm to 255mm but on seam line	Replace	3
2 Rear Left Hatch Door		Has Major Dent - Not Through Paint	230mm to 255mm	Replace	Included

WINDSHIELD

No damage