Vehicle Condition Report

en de

POWERED BY PAVE

2019 PEUGEOT BOXER

VIN # **VF3YFANF*2***8733

INSPECTION DATE:
March 20, 2026 @ 09:03 UTC

3
FAIR

Front Side: TOTAL GRADE SCORE	Back Side: TOTAL GRADE SCORE	Total Grade Score All Damages:
1	3	14
Left Side: TOTAL GRADE SCORE	**Right Side: TOTAL GRADE SCORE**	
4	6	

Vehicle Photos

ORIGINAL INSPECTION



Upload Photos

OPTIONAL

No photo

Exterior (7)

LEFT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
1 Left C-Pillar		Has Major Dent on Seam Line - Not Through Paint	Major dent 230mm to 255mm but on seam line	Replace	4
2 Left C-Pillar		Has Major Scrape	Scrape that is 300mm or longer or more than 70mm wide	Repair & Refinish	Included
3 Left C-Pillar		Has Major Dent on Seam Line - Not Through Paint	Major dent 230mm to 255mm but on seam line	Replace	Included

RIGHT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
5 Rear Right Quarter Side Molding		Has Major Dent - Not Through Paint	230mm to 255mm	Replace	3
4 Right C-Pillar		Has Major Scrape	Scrape that is 300mm or longer or more than 70mm wide	Repair & Refinish	3

FRONT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
6 Front Tow Hook		Missing	Part is missing	Replace	1

BACK SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
7 Rear Left Hatch Door		Has Major Dent - Not Through Paint	230mm to 255mm	Replace	3

WINDSHIELD

No damage