

Runway Surface Condition Report

Runway Surface Condition Report

Runway survey — UAV imagery, ~1.25 mm GSD · generated 2026-06-14 · detection confidence ≥ 0.10

274

frames analysed

1.82%

overall crack density

408

crack detections

207/274

crack-bearing frames

325

vegetation-gap detections

0

paint-marking detections


This report summarises an automated surface screening of the runway from drone imagery, performed by a custom YOLOv8 detection model. Findings are expressed as crack density (the share of surface covered by crack detections) and grouped into hot zones to prioritise inspection and maintenance, consistent with routine aerodrome pavement-condition monitoring under ICAO Annex 14 and CAA CAP 168.

Across 274 frames the model detected 408 cracks on 207 frames and 325 vegetation-gap features. The overall crack density is 1.82% of imaged surface, rising to 2.40% averaged over crack-bearing frames. Hot zones and per-class detail follow.

Limitations: crack density is a bounding-box-area proxy and over-states true crack area, so read it as a consistent relative index for ranking and trend tracking. Precision/recall are not quantified as no human-verified ground truth was available for this survey. Classes lacking training data for this domain (e.g. rubber deposits, band joints) are not assessed.



Crack-density profile along the runway

Capture order $\approx$ distance along the pass; shaded bands are hot zones.



Top hot zones (frame · density · cracks):

frame_000004.jpg	19.07%	6 cracks
frame_000003.jpg	18.27%	6 cracks
frame_000007.jpg	17.63%	5 cracks
frame_000002.jpg	14.01%	4 cracks
frame_000006.jpg	12.80%	4 cracks
frame_000005.jpg	12.48%	4 cracks
frame_000001.jpg	12.37%	3 cracks
frame_000008.jpg	11.81%	3 cracks
frame_000036.jpg	10.35%	2 cracks
frame_000009.jpg	9.61%	3 cracks



Class detail:


crack	408 dets	207/274 frames
gap_vegetation	325 dets	89/274 frames
spalling	1 dets	1/274 frames

Severity tiers by per-frame crack density:

high $\geq 4\%$	moderate 1–4%	low $< 1\%$	clean none
-----------------	---------------	-------------	------------


Cracks

detections: 408
frames affected: 207/274
box area px^2 – min 6202, median 65785,
mean 101156, max 499895
mean box: 122 × 736 px



Vegetation gaps

detections: 325
frames affected: 89/274
box area px^2 – min 2286, median 11151,
mean 23855, max 216877
mean box: 111 × 166 px



Paint markings

No paint-marking defects were detected by the model on this survey. Intact centreline/edge markings are present in the imagery but the model's paint classes target faded/damaged markings and did not fire; reliable paint-condition scoring would need dedicated training data for this runway.

red = crack · green = vegetation gap

frame_000004.jpg — 19.1% density · 6 cracks



frame_000003.jpg — 18.3% density · 6 cracks



red = crack · green = vegetation gap

frame_000007.jpg — 17.6% density · 5 cracks




frame_000002.jpg — 14.0% density · 4 cracks




red = crack · green = vegetation gap

frame_000006.jpg — 12.8% density · 4 cracks



frame_000005.jpg — 12.5% density · 4 cracks



Appendix — all detections

rows 1-92 of 734

frame	class	conf	cx,cy	w x h	frame	class	conf	cx,cy	w x h
frame_000001.jpg	crack	0.73	3490,1576	145x1166	frame_000012.jpg	crack	0.40	43,1070	86x2141
frame_000001.jpg	crack	0.68	294,1080	215x2160	frame_000012.jpg	crack	0.21	28,788	56x1576
frame_000001.jpg	crack	0.12	333,1080	180x2160	frame_000013.jpg	crack	0.73	3199,1056	153x1269
frame_000002.jpg	crack	0.73	3485,1576	148x1166	frame_000013.jpg	crack	0.17	3138,1925	92x468
frame_000002.jpg	crack	0.66	269,1083	216x2152	frame_000013.jpg	crack	0.11	26,744	52x1489
frame_000002.jpg	crack	0.46	1634,1997	367x324	frame_000014.jpg	crack	0.74	3176,1105	152x1271
frame_000002.jpg	crack	0.45	305,1080	187x2160	frame_000015.jpg	crack	0.72	3159,1199	145x1281
frame_000003.jpg	crack	0.72	3478,1571	145x1177	frame_000015.jpg	crack	0.22	3261,95	84x190
frame_000003.jpg	crack	0.60	259,1080	210x2158	frame_000015.jpg	crack	0.11	3287,93	124x187
frame_000003.jpg	crack	0.24	294,1080	166x2160	frame_000016.jpg	crack	0.65	3136,1345	148x1248
frame_000003.jpg	crack	0.21	228,1124	168x2071	frame_000016.jpg	crack	0.30	3700,1395	102x353
frame_000003.jpg	crack	0.18	1641,1983	362x353	frame_000016.jpg	crack	0.28	3256,163	97x327
frame_000003.jpg	crack	0.11	3587,354	111x471	frame_000017.jpg	crack	0.65	3219,245	105x475
frame_000004.jpg	crack	0.73	3474,1535	144x1231	frame_000017.jpg	crack	0.64	3101,1508	154x1279
frame_000004.jpg	crack	0.63	237,1126	200x2066	frame_000017.jpg	crack	0.22	3661,1566	109x370
frame_000004.jpg	crack	0.41	1642,1959	356x401	frame_000018.jpg	crack	0.62	3049,1605	148x1110
frame_000004.jpg	crack	0.39	209,1174	164x1971	frame_000018.jpg	crack	0.57	3167,448	109x492
frame_000004.jpg	crack	0.16	273,1121	142x2076	frame_000018.jpg	crack	0.21	3606,1763	108x362
frame_000004.jpg	crack	0.13	208,1397	149x1524	frame_000019.jpg	crack	0.60	3114,650	104x490
frame_000005.jpg	crack	0.74	211,1084	210x2152	frame_000019.jpg	crack	0.55	3133,460	138x856
frame_000005.jpg	crack	0.72	3454,1503	146x1313	frame_000019.jpg	crack	0.47	3007,1706	139x906
frame_000005.jpg	crack	0.30	3569,239	112x478	frame_000019.jpg	crack	0.23	3556,1975	118x368
frame_000005.jpg	crack	0.23	178,1138	163x2043	frame_000020.jpg	crack	0.62	3066,894	112x479
frame_000006.jpg	crack	0.73	185,1080	211x2160	frame_000020.jpg	crack	0.55	3084,701	147x860
frame_000006.jpg	crack	0.68	3427,1470	147x1380	frame_000020.jpg	crack	0.53	2973,1813	136x694
frame_000006.jpg	crack	0.35	3541,209	114x419	frame_000020.jpg	crack	0.15	3138,69	74x139
frame_000006.jpg	crack	0.19	154,1122	170x2074	frame_000020.jpg	crack	0.11	3070,809	114x651
frame_000007.jpg	crack	0.69	3410,1347	153x1316	frame_000021.jpg	crack	0.66	3045,982	146x852
frame_000007.jpg	crack	0.69	139,1087	217x2144	frame_000021.jpg	crack	0.48	2952,1957	102x405
frame_000007.jpg	crack	0.29	182,1080	186x2160	frame_000021.jpg	crack	0.38	3027,1172	110x490
frame_000007.jpg	crack	0.15	3529,165	122x331	frame_000022.jpg	crack	0.60	3011,1299	144x861
frame_000007.jpg	crack	0.12	103,1154	174x2011	frame_000022.jpg	crack	0.31	2996,1490	114x493
frame_000008.jpg	crack	0.73	3373,1257	155x1298	frame_000023.jpg	crack	0.68	2999,1648	148x877
frame_000008.jpg	crack	0.70	112,1085	211x2149	frame_000024.jpg	crack	0.65	2983,1865	138x588
frame_000008.jpg	crack	0.39	78,1128	156x2062	frame_000025.jpg	crack	0.23	2977,2048	85x222
frame_000009.jpg	crack	0.71	3330,1209	150x1304	frame_000025.jpg	crack	0.18	3113,184	102x368
frame_000009.jpg	crack	0.69	83,1086	167x2147	frame_000026.jpg	crack	0.41	1446,122	70x244
frame_000009.jpg	crack	0.29	59,1151	119x2016	frame_000028.jpg	crack	0.30	1428,146	58x292
frame_000010.jpg	crack	0.73	3295,1133	151x1302	frame_000028.jpg	crack	0.15	1359,857	88x356
frame_000010.jpg	crack	0.63	68,1084	137x2151	frame_000029.jpg	crack	0.20	1390,339	95x679
frame_000010.jpg	crack	0.12	32,1380	64x1558	frame_000030.jpg	crack	0.24	1380,243	97x486
frame_000011.jpg	crack	0.71	3259,1079	158x1303	frame_000030.jpg	crack	0.10	1255,1632	95x369
frame_000011.jpg	crack	0.43	45,1072	90x2144	frame_000031.jpg	crack	0.19	1233,1852	139x615
frame_000011.jpg	crack	0.17	36,779	73x1559	frame_000032.jpg	crack	0.26	3006,310	116x620
frame_000011.jpg	crack	0.17	3204,1937	92x445	frame_000033.jpg	crack	0.71	2996,503	134x994
frame_000012.jpg	crack	0.69	3227,1038	159x1273	frame_000034.jpg	crack	0.59	2974,684	185x1369

Appendix — all detections

rows 93-184 of 734

frame	class	conf	cx,cy	w x h	frame	class	conf	cx,cy	w x h
frame_000035.jpg	crack	0.45	2943,862	204x1722	frame_000060.jpg	crack	0.67	619,1785	123x661
frame_000035.jpg	crack	0.20	1235,1673	162x973	frame_000060.jpg	crack	0.59	2318,246	82x452
frame_000035.jpg	crack	0.12	2915,1096	153x1290	frame_000060.jpg	crack	0.26	114,509	106x613
frame_000036.jpg	crack	0.30	2904,1080	236x2118	frame_000060.jpg	crack	0.23	702,837	146x1056
frame_000036.jpg	crack	0.16	2879,1239	199x1802	frame_000061.jpg	crack	0.71	576,2012	80x283
frame_000037.jpg	crack	0.48	2856,1224	232x1864	frame_000061.jpg	crack	0.47	2314,103	54x207
frame_000038.jpg	crack	0.60	2797,1405	217x1509	frame_000061.jpg	crack	0.42	2258,666	78x426
frame_000038.jpg	crack	0.41	2927,152	89x304	frame_000061.jpg	crack	0.11	2329,104	80x208
frame_000038.jpg	crack	0.36	1286,267	96x535	frame_000062.jpg	crack	0.39	2286,308	108x616
frame_000039.jpg	crack	0.73	2846,336	114x672	frame_000062.jpg	crack	0.21	2214,1100	88x427
frame_000039.jpg	crack	0.66	2731,1577	180x1164	frame_000063.jpg	crack	0.47	2191,1531	81x438
frame_000040.jpg	crack	0.72	2756,645	118x749	frame_000063.jpg	crack	0.24	747,297	102x595
frame_000040.jpg	crack	0.52	2653,1757	158x805	frame_000064.jpg	crack	0.42	2184,1952	89x413
frame_000040.jpg	crack	0.19	2617,1755	228x808	frame_000064.jpg	crack	0.19	777,249	110x498
frame_000041.jpg	crack	0.76	2687,1028	113x707	frame_000064.jpg	crack	0.18	1443,106	93x212
frame_000041.jpg	crack	0.43	2602,1942	126x434	frame_000065.jpg	crack	0.52	1632,144	55x283
frame_000041.jpg	crack	0.18	2572,1940	185x438	frame_000066.jpg	crack	0.38	1625,544	64x316
frame_000042.jpg	crack	0.75	2653,1384	124x733	frame_000067.jpg	crack	0.53	1613,978	68x315
frame_000043.jpg	crack	0.75	2628,1762	119x681	frame_000068.jpg	crack	0.59	1585,1424	77x324
frame_000044.jpg	crack	0.52	1164,125	61x249	frame_000068.jpg	crack	0.44	876,228	87x456
frame_000044.jpg	crack	0.36	2619,1991	92x337	frame_000068.jpg	crack	0.17	752,1512	199x1295
frame_000045.jpg	crack	0.66	1163,348	102x672	frame_000069.jpg	crack	0.69	1541,1856	73x341
frame_000046.jpg	crack	0.11	1196,198	94x396	frame_000069.jpg	crack	0.55	732,1706	145x897
frame_000047.jpg	crack	0.22	678,81	56x162	frame_000069.jpg	crack	0.37	881,187	91x374
frame_000047.jpg	crack	0.11	1098,1160	107x664	frame_000069.jpg	crack	0.18	836,651	88x467
frame_000048.jpg	crack	0.40	1174,83	56x166	frame_000070.jpg	crack	0.58	703,1926	102x466
frame_000048.jpg	crack	0.23	1186,83	77x167	frame_000070.jpg	crack	0.41	859,399	131x799
frame_000048.jpg	crack	0.12	1037,1559	110x630	frame_000070.jpg	crack	0.14	2447,227	69x455
frame_000049.jpg	crack	0.16	1126,278	96x556	frame_000071.jpg	crack	0.48	2347,1153	79x381
frame_000051.jpg	crack	0.30	1066,168	66x336	frame_000072.jpg	crack	0.38	820,383	106x767
frame_000052.jpg	crack	0.14	1030,373	102x747	frame_000072.jpg	crack	0.26	2213,2005	90x303
frame_000055.jpg	crack	0.12	956,48	64x96	frame_000072.jpg	crack	0.17	2291,1566	81x387
frame_000056.jpg	crack	0.42	914,266	102x532	frame_000073.jpg	crack	0.75	2233,1970	80x372
frame_000057.jpg	crack	0.49	881,92	51x184	frame_000073.jpg	crack	0.43	2275,1420	86x494
frame_000057.jpg	crack	0.19	893,93	77x186	frame_000073.jpg	crack	0.12	805,111	69x222
frame_000057.jpg	crack	0.17	259,71	74x143	frame_000074.jpg	crack	0.27	2216,1852	85x468
frame_000057.jpg	crack	0.14	838,615	100x636	frame_000074.jpg	crack	0.21	667,1426	187x1449
frame_000058.jpg	crack	0.54	814,291	96x582	frame_000075.jpg	crack	0.67	631,1630	162x1059
frame_000058.jpg	crack	0.51	760,1002	113x640	frame_000076.jpg	crack	0.69	596,1840	125x639
frame_000058.jpg	crack	0.37	682,1774	134x771	frame_000077.jpg	crack	0.12	611,1699	161x921
frame_000058.jpg	crack	0.24	2396,174	70x348	frame_000078.jpg	crack	0.10	595,1904	117x511
frame_000059.jpg	crack	0.57	686,1386	114x640	frame_000079.jpg	crack	0.12	773,51	98x103
frame_000059.jpg	crack	0.50	763,484	137x969	frame_000080.jpg	crack	0.13	752,269	98x538
frame_000059.jpg	crack	0.47	623,1969	90x369	frame_000082.jpg	crack	0.58	763,287	84x502
frame_000059.jpg	crack	0.22	2323,523	75x413	frame_000082.jpg	crack	0.11	2330,259	89x518
frame_000059.jpg	crack	0.20	168,213	87x427	frame_000083.jpg	crack	0.47	744,756	89x468

Appendix — all detections

rows 185-276 of 734

frame	class	conf	cx,cy	w x h	frame	class	conf	cx,cy	w x h
frame_000083.jpg	crack	0.18	2231,1620	146x1079	frame_000119.jpg	crack	0.64	382,1948	131x421
frame_000084.jpg	crack	0.49	2224,1858	114x602	frame_000119.jpg	crack	0.19	2012,360	108x720
frame_000084.jpg	crack	0.32	720,1212	99x486	frame_000119.jpg	crack	0.11	2531,1130	63x277
frame_000084.jpg	crack	0.15	2274,1245	73x357	frame_000120.jpg	crack	0.66	481,769	112x628
frame_000085.jpg	crack	0.31	684,1804	109x710	frame_000121.jpg	crack	0.73	442,1102	112x623
frame_000085.jpg	crack	0.28	2370,225	76x451	frame_000121.jpg	crack	0.14	2000,130	86x260
frame_000086.jpg	crack	0.60	842,122	66x225	frame_000121.jpg	crack	0.13	524,175	97x350
frame_000086.jpg	crack	0.10	2347,522	98x874	frame_000121.jpg	crack	0.12	2437,1775	68x289
frame_000087.jpg	crack	0.28	692,1847	133x610	frame_000122.jpg	crack	0.61	398,1406	122x665
frame_000087.jpg	crack	0.18	2311,1013	113x839	frame_000122.jpg	crack	0.47	1971,307	109x615
frame_000087.jpg	crack	0.12	2397,57	56x114	frame_000122.jpg	crack	0.21	500,335	123x671
frame_000088.jpg	crack	0.42	2362,453	72x348	frame_000123.jpg	crack	0.67	361,1733	120x646
frame_000088.jpg	crack	0.17	2264,1513	91x863	frame_000123.jpg	crack	0.30	1976,197	83x395
frame_000089.jpg	crack	0.46	2312,933	87x408	frame_000124.jpg	crack	0.69	323,1959	114x394
frame_000089.jpg	crack	0.33	2228,1872	96x574	frame_000124.jpg	crack	0.11	1925,632	161x1265
frame_000089.jpg	crack	0.12	890,131	58x262	frame_000125.jpg	crack	0.15	1985,154	67x309
frame_000090.jpg	crack	0.60	2259,1454	77x368	frame_000126.jpg	crack	0.15	1960,336	94x672
frame_000090.jpg	crack	0.15	883,270	92x541	frame_000127.jpg	crack	0.10	1948,521	137x1043
frame_000091.jpg	crack	0.62	2216,1963	78x362	frame_000128.jpg	crack	0.50	1971,186	70x373
frame_000091.jpg	crack	0.34	2404,68	45x137	frame_000129.jpg	crack	0.54	1949,378	115x757
frame_000092.jpg	crack	0.71	2371,404	88x513	frame_000129.jpg	crack	0.28	506,142	58x284
frame_000093.jpg	crack	0.73	2328,918	95x518	frame_000130.jpg	crack	0.56	477,338	111x677
frame_000094.jpg	crack	0.73	2285,1432	93x511	frame_000130.jpg	crack	0.14	1913,573	147x1147
frame_000094.jpg	crack	0.25	2229,1960	94x398	frame_000131.jpg	crack	0.55	442,580	134x1010
frame_000095.jpg	crack	0.56	2242,1928	92x462	frame_000132.jpg	crack	0.35	409,1025	144x978
frame_000095.jpg	crack	0.46	2392,209	62x279	frame_000132.jpg	crack	0.24	491,96	49x193
frame_000096.jpg	crack	0.26	2407,108	63x217	frame_000133.jpg	crack	0.56	478,313	99x626
frame_000097.jpg	crack	0.46	2379,380	106x761	frame_000133.jpg	crack	0.40	364,1449	148x964
frame_000098.jpg	crack	0.25	2401,222	77x338	frame_000133.jpg	crack	0.13	1798,1678	150x963
frame_000104.jpg	crack	0.31	858,150	87x301	frame_000134.jpg	crack	0.56	323,1778	149x762
frame_000108.jpg	crack	0.39	2294,274	83x542	frame_000134.jpg	crack	0.45	436,747	102x634
frame_000108.jpg	crack	0.15	649,1852	133x615	frame_000135.jpg	crack	0.48	409,1198	109x607
frame_000109.jpg	crack	0.12	2253,503	129x1006	frame_000135.jpg	crack	0.16	314,2002	88x314
frame_000113.jpg	crack	0.11	3115,74	55x149	frame_000136.jpg	crack	0.45	379,1634	109x610
frame_000113.jpg	crack	0.10	722,93	91x186	frame_000137.jpg	crack	0.19	361,1969	87x377
frame_000114.jpg	crack	0.51	687,279	112x521	frame_000138.jpg	crack	0.30	1985,215	77x431
frame_000115.jpg	crack	0.74	626,659	120x458	frame_000141.jpg	crack	0.11	1864,1498	108x666
frame_000115.jpg	crack	0.10	2101,620	160x1241	frame_000142.jpg	crack	0.21	563,92	48x184
frame_000116.jpg	crack	0.71	570,997	122x452	frame_000143.jpg	crack	0.45	556,342	106x685
frame_000116.jpg	crack	0.62	2714,164	58x288	frame_000148.jpg	crack	0.40	1998,223	77x447
frame_000117.jpg	crack	0.63	510,1320	126x443	frame_000148.jpg	gap_vegetation	0.26	3766,81	55x100
frame_000117.jpg	crack	0.39	2651,490	56x267	frame_000148.jpg	gap_vegetation	0.12	3806,296	66x120
frame_000118.jpg	crack	0.61	450,1630	128x452	frame_000149.jpg	gap_vegetation	0.34	3712,569	55x91
frame_000118.jpg	crack	0.43	587,229	90x459	frame_000150.jpg	crack	0.13	599,83	60x166
frame_000118.jpg	crack	0.20	2591,814	60x266	frame_000150.jpg	gap_vegetation	0.40	3665,1058	53x95
frame_000119.jpg	crack	0.65	536,454	104x624	frame_000150.jpg	gap_vegetation	0.19	3734,1263	93x105

Appendix — all detections

rows 277-368 of 734

frame	class	conf	cx,cy	w x h	frame	class	conf	cx,cy	w x h
frame_000151.jpg	gap_vegetation	0.53	3608,1552	56x90	frame_000183.jpg	gap_vegetation	0.34	3082,586	154x312
frame_000151.jpg	gap_vegetation	0.35	3681,1751	105x113	frame_000183.jpg	gap_vegetation	0.25	3183,53	61x100
frame_000152.jpg	gap_vegetation	0.43	3547,2048	57x92	frame_000183.jpg	gap_vegetation	0.17	3066,678	110x112
frame_000154.jpg	crack	0.50	1930,257	105x515	frame_000183.jpg	gap_vegetation	0.13	3071,660	119x144
frame_000155.jpg	crack	0.34	1892,512	150x1024	frame_000183.jpg	gap_vegetation	0.10	3591,412	67x109
frame_000155.jpg	gap_vegetation	0.25	3783,929	107x237	frame_000184.jpg	crack	0.27	1411,110	51x221
frame_000155.jpg	gap_vegetation	0.12	3784,987	108x355	frame_000184.jpg	gap_vegetation	0.77	3123,222	210x422
frame_000156.jpg	gap_vegetation	0.41	3753,1566	172x424	frame_000184.jpg	gap_vegetation	0.62	3095,578	106x109
frame_000157.jpg	gap_vegetation	0.24	3715,2024	246x271	frame_000184.jpg	gap_vegetation	0.36	3783,125	103x137
frame_000157.jpg	gap_vegetation	0.23	3695,1623	91x162	frame_000184.jpg	gap_vegetation	0.36	3350,67	84x133
frame_000158.jpg	gap_vegetation	0.19	3749,1488	73x122	frame_000184.jpg	gap_vegetation	0.33	3048,943	142x297
frame_000159.jpg	gap_vegetation	0.14	3679,2002	64x106	frame_000184.jpg	gap_vegetation	0.32	3592,70	78x113
frame_000160.jpg	crack	0.21	456,106	64x212	frame_000184.jpg	gap_vegetation	0.14	3025,1037	94x101
frame_000161.jpg	crack	0.51	391,380	98x602	frame_000184.jpg	gap_vegetation	0.13	3150,346	72x148
frame_000162.jpg	crack	0.70	1608,1756	151x806	frame_000184.jpg	gap_vegetation	0.12	3784,129	107x203
frame_000162.jpg	crack	0.63	321,892	99x569	frame_000184.jpg	gap_vegetation	0.12	3551,774	71x109
frame_000163.jpg	crack	0.64	247,1320	102x532	frame_000185.jpg	crack	0.11	1437,80	72x160
frame_000163.jpg	crack	0.17	3710,201	258x107	frame_000185.jpg	gap_vegetation	0.79	3091,568	209x537
frame_000163.jpg	crack	0.14	355,261	82x523	frame_000185.jpg	gap_vegetation	0.66	3310,420	100x145
frame_000163.jpg	crack	0.10	3709,231	259x165	frame_000185.jpg	gap_vegetation	0.57	3065,944	111x119
frame_000164.jpg	crack	0.66	195,1776	111x608	frame_000185.jpg	gap_vegetation	0.53	3768,566	142x282
frame_000165.jpg	crack	0.29	3645,1077	389x108	frame_000185.jpg	gap_vegetation	0.40	3014,1308	139x304
frame_000165.jpg	crack	0.21	151,2021	86x276	frame_000185.jpg	gap_vegetation	0.35	3560,451	85x109
frame_000165.jpg	crack	0.15	3642,1102	393x154	frame_000185.jpg	gap_vegetation	0.22	3494,294	84x88
frame_000166.jpg	crack	0.27	3615,1508	448x138	frame_000185.jpg	gap_vegetation	0.19	3771,85	130x171
frame_000166.jpg	crack	0.19	3617,1539	445x208	frame_000185.jpg	gap_vegetation	0.14	3382,536	117x79
frame_000166.jpg	crack	0.12	3616,1585	446x295	frame_000185.jpg	gap_vegetation	0.13	3168,268	66x76
frame_000167.jpg	crack	0.17	332,274	94x549	frame_000185.jpg	gap_vegetation	0.12	3002,295	104x86
frame_000167.jpg	crack	0.14	3592,1942	495x195	frame_000185.jpg	gap_vegetation	0.11	3081,594	168x447
frame_000167.jpg	crack	0.13	3593,1912	492x139	frame_000186.jpg	crack	0.31	1422,262	99x525
frame_000167.jpg	crack	0.11	3593,1993	492x311	frame_000186.jpg	gap_vegetation	0.73	3069,952	208x520
frame_000168.jpg	crack	0.19	344,181	75x351	frame_000186.jpg	gap_vegetation	0.66	3288,794	91x143
frame_000169.jpg	crack	0.14	334,364	123x728	frame_000186.jpg	gap_vegetation	0.63	3042,1317	106x115
frame_000175.jpg	crack	0.42	1551,128	65x256	frame_000186.jpg	gap_vegetation	0.56	2993,1678	152x309
frame_000175.jpg	crack	0.20	1567,125	92x251	frame_000186.jpg	gap_vegetation	0.41	3757,940	162x309
frame_000176.jpg	crack	0.70	1484,302	85x545	frame_000186.jpg	gap_vegetation	0.23	3762,2068	144x172
frame_000177.jpg	crack	0.55	1427,594	84x495	frame_000186.jpg	gap_vegetation	0.22	3535,826	84x122
frame_000178.jpg	crack	0.49	1436,111	58x210	frame_000186.jpg	gap_vegetation	0.20	3755,405	168x303
frame_000178.jpg	crack	0.18	1376,875	86x516	frame_000186.jpg	gap_vegetation	0.15	3477,664	73x83
frame_000179.jpg	crack	0.44	1409,245	90x491	frame_000186.jpg	gap_vegetation	0.14	3080,89	55x76
frame_000182.jpg	gap_vegetation	0.23	3633,73	71x112	frame_000186.jpg	gap_vegetation	0.13	3451,160	75x64
frame_000182.jpg	gap_vegetation	0.19	3106,337	106x104	frame_000186.jpg	gap_vegetation	0.12	3138,642	73x75
frame_000182.jpg	gap_vegetation	0.13	3121,237	141x313	frame_000186.jpg	gap_vegetation	0.12	2975,662	105x85
frame_000182.jpg	gap_vegetation	0.13	3114,304	130x180	frame_000186.jpg	gap_vegetation	0.11	3357,913	124x86
frame_000183.jpg	crack	0.10	1402,269	99x538	frame_000186.jpg	gap_vegetation	0.11	3500,1528	81x126
frame_000183.jpg	gap_vegetation	0.61	3135,214	106x108	frame_000187.jpg	gap_vegetation	0.65	3027,1702	111x124

Appendix — all detections

rows 369-460 of 734

frame	class	conf	cx,cy	w x h	frame	class	conf	cx,cy	w x h
frame_000187.jpg	gap_vegetation	0.62	3268,1181	97x138	frame_000189.jpg	gap_vegetation	0.32	3477,2039	96x195
frame_000187.jpg	gap_vegetation	0.61	3052,1329	207x539	frame_000189.jpg	gap_vegetation	0.28	3726,1958	227x403
frame_000187.jpg	gap_vegetation	0.61	3542,160	209x295	frame_000189.jpg	gap_vegetation	0.24	3419,1847	70x90
frame_000187.jpg	gap_vegetation	0.51	3748,1308	182x365	frame_000189.jpg	gap_vegetation	0.23	3521,1792	77x159
frame_000187.jpg	gap_vegetation	0.40	2980,83	85x132	frame_000189.jpg	gap_vegetation	0.21	2939,853	87x209
frame_000187.jpg	gap_vegetation	0.39	3519,1207	87x132	frame_000189.jpg	gap_vegetation	0.16	3725,2082	225x151
frame_000187.jpg	gap_vegetation	0.30	3514,180	172x313	frame_000189.jpg	gap_vegetation	0.16	3299,2097	118x104
frame_000187.jpg	gap_vegetation	0.25	3742,814	194x362	frame_000189.jpg	gap_vegetation	0.14	3716,1786	248x652
frame_000187.jpg	gap_vegetation	0.18	2932,318	127x210	frame_000189.jpg	gap_vegetation	0.14	3462,974	192x332
frame_000187.jpg	gap_vegetation	0.17	2953,313	86x196	frame_000189.jpg	gap_vegetation	0.11	3380,1348	83x66
frame_000187.jpg	gap_vegetation	0.16	3451,1053	71x90	frame_000190.jpg	gap_vegetation	0.85	2863,1498	143x215
frame_000187.jpg	gap_vegetation	0.15	3425,545	81x67	frame_000190.jpg	gap_vegetation	0.73	3705,2005	268x309
frame_000187.jpg	gap_vegetation	0.14	3452,1826	133x305	frame_000190.jpg	gap_vegetation	0.63	3470,1349	227x355
frame_000187.jpg	gap_vegetation	0.12	2975,2070	142x178	frame_000190.jpg	gap_vegetation	0.59	2913,1268	82x136
frame_000187.jpg	gap_vegetation	0.11	2994,97	97x158	frame_000190.jpg	gap_vegetation	0.48	3723,1118	81x146
frame_000187.jpg	gap_vegetation	0.10	3329,1297	101x78	frame_000190.jpg	gap_vegetation	0.19	3435,1367	184x335
frame_000188.jpg	gap_vegetation	0.77	3029,1710	216x516	frame_000190.jpg	gap_vegetation	0.14	2917,1237	89x227
frame_000188.jpg	gap_vegetation	0.75	3254,1578	101x159	frame_000190.jpg	gap_vegetation	0.13	3349,1742	89x70
frame_000188.jpg	gap_vegetation	0.70	2908,724	130x210	frame_000191.jpg	crack	0.12	1398,1090	226x2135
frame_000188.jpg	gap_vegetation	0.56	2964,489	80x143	frame_000191.jpg	gap_vegetation	0.80	2842,1887	136x212
frame_000188.jpg	gap_vegetation	0.56	3521,553	221x353	frame_000191.jpg	gap_vegetation	0.57	3448,1736	231x355
frame_000188.jpg	gap_vegetation	0.53	3011,2098	119x122	frame_000191.jpg	gap_vegetation	0.52	2885,1657	87x139
frame_000188.jpg	gap_vegetation	0.41	3769,313	68x126	frame_000191.jpg	gap_vegetation	0.43	3694,1524	79x141
frame_000188.jpg	gap_vegetation	0.39	3737,1207	205x403	frame_000191.jpg	gap_vegetation	0.42	3410,1757	181x353
frame_000188.jpg	gap_vegetation	0.35	3739,1705	201x397	frame_000191.jpg	gap_vegetation	0.32	2891,1624	93x240
frame_000188.jpg	gap_vegetation	0.31	3483,578	175x336	frame_000191.jpg	gap_vegetation	0.18	2970,2090	73x136
frame_000188.jpg	gap_vegetation	0.22	3013,1775	200x507	frame_000191.jpg	gap_vegetation	0.17	3326,2128	81x63
frame_000188.jpg	gap_vegetation	0.19	3500,1618	78x111	frame_000191.jpg	gap_vegetation	0.12	3727,1939	158x124
frame_000188.jpg	gap_vegetation	0.18	3436,1457	76x95	frame_000192.jpg	crack	0.37	1398,1240	222x1838
frame_000188.jpg	gap_vegetation	0.17	3318,1695	111x84	frame_000192.jpg	crack	0.14	172,226	80x453
frame_000188.jpg	gap_vegetation	0.16	3404,957	86x72	frame_000192.jpg	gap_vegetation	0.81	3438,2049	227x220
frame_000188.jpg	gap_vegetation	0.13	3735,1610	208x652	frame_000192.jpg	gap_vegetation	0.47	3673,1916	77x141
frame_000188.jpg	gap_vegetation	0.12	3500,1638	88x148	frame_000192.jpg	gap_vegetation	0.34	2870,2012	104x241
frame_000188.jpg	gap_vegetation	0.11	3754,1204	170x335	frame_000192.jpg	gap_vegetation	0.34	2862,2034	90x127
frame_000188.jpg	gap_vegetation	0.11	2964,461	82x192	frame_000192.jpg	gap_vegetation	0.18	2871,2043	110x152
frame_000188.jpg	gap_vegetation	0.11	3741,1370	197x653	frame_000192.jpg	gap_vegetation	0.14	2977,807	48x111
frame_000188.jpg	gap_vegetation	0.11	3248,1424	90x79	frame_000193.jpg	crack	0.38	1389,1425	216x1469
frame_000188.jpg	spalling	0.17	3125,1790	452x739	frame_000193.jpg	crack	0.12	181,385	122x770
frame_000189.jpg	crack	0.16	1426,832	195x1664	frame_000193.jpg	gap_vegetation	0.22	2950,1188	47x108
frame_000189.jpg	gap_vegetation	0.83	2884,1109	141x211	frame_000194.jpg	gap_vegetation	0.14	2922,1568	46x101
frame_000189.jpg	gap_vegetation	0.65	3496,952	235x361	frame_000194.jpg	gap_vegetation	0.12	2890,2107	71x104
frame_000189.jpg	gap_vegetation	0.65	3016,1978	211x363	frame_000195.jpg	crack	0.14	1376,1807	152x706
frame_000189.jpg	gap_vegetation	0.64	3231,1972	87x154	frame_000195.jpg	gap_vegetation	0.17	3297,182	63x73
frame_000189.jpg	gap_vegetation	0.57	2936,876	80x146	frame_000195.jpg	gap_vegetation	0.13	3079,112	34x80
frame_000189.jpg	gap_vegetation	0.50	3725,1647	229x470	frame_000195.jpg	gap_vegetation	0.11	2916,1958	42x96
frame_000189.jpg	gap_vegetation	0.40	3745,719	71x128	frame_000196.jpg	gap_vegetation	0.26	3057,491	38x75

Appendix — all detections

rows 461-552 of 734

frame	class	conf	cx,cy	w x h	frame	class	conf	cx,cy	w x h
frame_000196.jpg	gap_vegetation	0.17	3275,556	66x86	frame_000220.jpg	gap_vegetation	0.26	3734,2069	182x170
frame_000196.jpg	gap_vegetation	0.15	3321,262	66x103	frame_000220.jpg	gap_vegetation	0.21	3752,2069	131x163
frame_000197.jpg	crack	0.39	265,213	82x426	frame_000220.jpg	gap_vegetation	0.15	3764,1134	148x166
frame_000197.jpg	gap_vegetation	0.15	3043,848	37x94	frame_000220.jpg	gap_vegetation	0.14	3765,2042	84x104
frame_000198.jpg	crack	0.23	272,388	116x776	frame_000220.jpg	gap_vegetation	0.14	3575,757	70x108
frame_000198.jpg	gap_vegetation	0.20	3232,1292	70x89	frame_000221.jpg	gap_vegetation	0.17	3722,1643	158x159
frame_000198.jpg	gap_vegetation	0.14	3019,1233	40x91	frame_000221.jpg	gap_vegetation	0.14	3524,1252	74x127
frame_000199.jpg	crack	0.13	265,575	134x1151	frame_000222.jpg	gap_vegetation	0.22	3482,1756	71x116
frame_000199.jpg	gap_vegetation	0.12	3012,1579	36x71	frame_000223.jpg	crack	0.29	869,128	60x257
frame_000199.jpg	gap_vegetation	0.11	3220,1642	73x88	frame_000223.jpg	gap_vegetation	0.14	3671,1932	70x100
frame_000199.jpg	gap_vegetation	0.10	3627,1872	62x90	frame_000224.jpg	crack	0.42	834,443	92x616
frame_000200.jpg	crack	0.11	243,931	134x1060	frame_000224.jpg	gap_vegetation	0.10	3174,381	45x78
frame_000200.jpg	gap_vegetation	0.26	3204,1998	68x82	frame_000225.jpg	crack	0.42	792,921	107x627
frame_000200.jpg	gap_vegetation	0.17	2987,1929	36x83	frame_000225.jpg	crack	0.13	338,361	109x723
frame_000200.jpg	gap_vegetation	0.11	2988,1918	40x108	frame_000225.jpg	gap_vegetation	0.23	3745,2016	69x104
frame_000201.jpg	crack	0.10	224,1263	139x1055	frame_000226.jpg	crack	0.33	744,1383	110x636
frame_000202.jpg	crack	0.14	194,1631	139x1053	frame_000227.jpg	crack	0.38	707,1849	110x595
frame_000202.jpg	gap_vegetation	0.12	3155,164	32x71	frame_000228.jpg	crack	0.47	203,1827	130x660
frame_000203.jpg	crack	0.51	175,1838	119x642	frame_000228.jpg	gap_vegetation	0.46	3073,272	56x149
frame_000203.jpg	crack	0.17	1535,1180	188x1942	frame_000229.jpg	gap_vegetation	0.57	3028,745	50x149
frame_000203.jpg	crack	0.12	152,1828	167x662	frame_000230.jpg	gap_vegetation	0.62	2981,1195	53x156
frame_000206.jpg	crack	0.48	1618,260	102x520	frame_000230.jpg	gap_vegetation	0.14	3672,140	52x65
frame_000206.jpg	crack	0.16	1650,258	152x516	frame_000231.jpg	gap_vegetation	0.61	2943,1627	55x143
frame_000207.jpg	crack	0.65	1599,439	114x879	frame_000232.jpg	gap_vegetation	0.46	2906,2060	55x162
frame_000208.jpg	crack	0.40	1582,621	151x1242	frame_000233.jpg	crack	0.11	403,211	76x408
frame_000208.jpg	gap_vegetation	0.15	3735,1983	63x96	frame_000233.jpg	gap_vegetation	0.22	3412,630	64x111
frame_000209.jpg	crack	0.60	1600,303	101x607	frame_000233.jpg	gap_vegetation	0.18	3722,957	149x136
frame_000210.jpg	crack	0.52	1563,480	118x954	frame_000234.jpg	gap_vegetation	0.17	3302,2103	53x92
frame_000210.jpg	gap_vegetation	0.10	3787,1617	101x193	frame_000234.jpg	gap_vegetation	0.14	3715,1383	109x127
frame_000211.jpg	gap_vegetation	0.24	3738,2015	119x218	frame_000234.jpg	gap_vegetation	0.13	3671,1651	59x73
frame_000211.jpg	gap_vegetation	0.13	3763,2023	116x234	frame_000234.jpg	gap_vegetation	0.11	3515,1897	61x80
frame_000212.jpg	crack	0.12	1508,880	171x1666	frame_000235.jpg	gap_vegetation	0.16	3681,1824	92x115
frame_000213.jpg	gap_vegetation	0.16	3622,258	77x80	frame_000236.jpg	crack	0.29	402,323	110x646
frame_000214.jpg	gap_vegetation	0.15	3582,676	73x89	frame_000236.jpg	crack	0.24	1625,188	62x376
frame_000215.jpg	crack	0.27	868,89	47x179	frame_000237.jpg	crack	0.36	1595,394	109x789
frame_000215.jpg	gap_vegetation	0.15	3710,997	75x97	frame_000237.jpg	crack	0.18	361,621	122x874
frame_000216.jpg	gap_vegetation	0.14	3796,1588	77x86	frame_000237.jpg	gap_vegetation	0.29	3212,231	68x121
frame_000217.jpg	crack	0.40	1587,210	90x420	frame_000238.jpg	crack	0.35	293,1038	128x855
frame_000217.jpg	crack	0.20	339,125	47x250	frame_000238.jpg	gap_vegetation	0.18	3147,645	67x128
frame_000217.jpg	gap_vegetation	0.33	3753,2030	77x80	frame_000239.jpg	crack	0.33	242,1459	133x852
frame_000217.jpg	gap_vegetation	0.17	3618,1868	67x96	frame_000239.jpg	gap_vegetation	0.40	3077,1070	82x137
frame_000217.jpg	gap_vegetation	0.16	3448,1969	73x100	frame_000240.jpg	crack	0.18	196,1805	113x709
frame_000218.jpg	crack	0.17	332,348	113x696	frame_000240.jpg	crack	0.13	1532,301	107x602
frame_000219.jpg	gap_vegetation	0.13	3624,274	63x90	frame_000240.jpg	gap_vegetation	0.36	3014,1487	76x138
frame_000219.jpg	gap_vegetation	0.12	3769,1342	137x213	frame_000240.jpg	gap_vegetation	0.10	3455,655	89x79
frame_000219.jpg	gap_vegetation	0.11	3766,1585	146x175	frame_000241.jpg	crack	0.18	157,2005	81x308

Appendix — all detections

rows 553-644 of 734

frame	class	conf	cx,cy	w x h	frame	class	conf	cx,cy	w x h
frame_000241.jpg	gap_vegetation	0.49	2974,1901	89x133	frame_000253.jpg	gap_vegetation	0.52	3655,1487	368x529
frame_000241.jpg	gap_vegetation	0.15	3656,611	91x111	frame_000253.jpg	gap_vegetation	0.48	3335,1564	88x89
frame_000241.jpg	gap_vegetation	0.13	3410,1087	96x118	frame_000253.jpg	gap_vegetation	0.30	3573,1895	174x112
frame_000241.jpg	gap_vegetation	0.12	3463,351	70x83	frame_000253.jpg	gap_vegetation	0.12	3755,1831	72x91
frame_000241.jpg	gap_vegetation	0.10	3404,1075	86x83	frame_000253.jpg	gap_vegetation	0.12	3803,84	66x117
frame_000242.jpg	gap_vegetation	0.11	3615,1046	95x105	frame_000253.jpg	gap_vegetation	0.11	3752,1669	176x466
frame_000243.jpg	gap_vegetation	0.14	3581,1459	98x108	frame_000254.jpg	crack	0.23	571,239	78x462
frame_000243.jpg	gap_vegetation	0.12	3326,1919	87x73	frame_000254.jpg	gap_vegetation	0.57	3299,1970	92x94
frame_000244.jpg	crack	0.21	351,212	83x412	frame_000254.jpg	gap_vegetation	0.57	3633,1894	413x524
frame_000244.jpg	gap_vegetation	0.18	3548,1869	96x109	frame_000254.jpg	gap_vegetation	0.39	3781,484	99x133
frame_000245.jpg	gap_vegetation	0.15	3337,2021	73x107	frame_000254.jpg	gap_vegetation	0.29	3732,1948	214x412
frame_000246.jpg	crack	0.57	401,235	97x471	frame_000255.jpg	gap_vegetation	0.67	3617,2085	344x148
frame_000247.jpg	crack	0.21	409,433	121x866	frame_000255.jpg	gap_vegetation	0.51	3737,895	104x131
frame_000248.jpg	crack	0.16	1659,297	91x595	frame_000255.jpg	gap_vegetation	0.23	3685,213	104x134
frame_000248.jpg	gap_vegetation	0.47	3673,121	119x166	frame_000255.jpg	gap_vegetation	0.17	3805,90	59x87
frame_000249.jpg	crack	0.36	1692,115	53x230	frame_000255.jpg	gap_vegetation	0.17	3705,200	64x106
frame_000249.jpg	gap_vegetation	0.56	3656,534	125x175	frame_000256.jpg	gap_vegetation	0.61	3702,1286	108x132
frame_000249.jpg	gap_vegetation	0.41	3641,211	197x111	frame_000256.jpg	gap_vegetation	0.47	3644,592	107x144
frame_000249.jpg	gap_vegetation	0.35	3663,213	148x102	frame_000256.jpg	gap_vegetation	0.19	3758,480	55x84
frame_000249.jpg	gap_vegetation	0.29	3658,602	141x327	frame_000256.jpg	gap_vegetation	0.12	3648,97	53x85
frame_000249.jpg	gap_vegetation	0.12	3657,570	130x248	frame_000256.jpg	gap_vegetation	0.12	3735,178	55x72
frame_000250.jpg	crack	0.50	1711,316	107x632	frame_000257.jpg	gap_vegetation	0.59	3669,1655	109x129
frame_000250.jpg	crack	0.24	530,140	52x281	frame_000257.jpg	gap_vegetation	0.58	3608,963	110x160
frame_000250.jpg	gap_vegetation	0.65	3700,251	279x494	frame_000257.jpg	gap_vegetation	0.26	3722,852	58x89
frame_000250.jpg	gap_vegetation	0.63	3603,635	240x118	frame_000257.jpg	gap_vegetation	0.20	3756,210	64x57
frame_000250.jpg	gap_vegetation	0.58	3635,966	126x175	frame_000257.jpg	gap_vegetation	0.17	3387,2072	130x165
frame_000250.jpg	gap_vegetation	0.44	3398,314	86x89	frame_000257.jpg	gap_vegetation	0.15	3698,539	52x70
frame_000250.jpg	gap_vegetation	0.18	3640,1031	147x326	frame_000257.jpg	gap_vegetation	0.13	3611,466	55x93
frame_000250.jpg	gap_vegetation	0.15	3739,239	200x479	frame_000258.jpg	gap_vegetation	0.56	3642,2019	113x127
frame_000250.jpg	gap_vegetation	0.14	3806,569	60x78	frame_000258.jpg	gap_vegetation	0.53	3582,1325	107x149
frame_000251.jpg	crack	0.40	1712,518	140x1037	frame_000258.jpg	gap_vegetation	0.32	3697,1221	63x92
frame_000251.jpg	gap_vegetation	0.54	3588,1065	238x113	frame_000258.jpg	gap_vegetation	0.19	3670,910	55x80
frame_000251.jpg	gap_vegetation	0.45	3385,739	91x90	frame_000258.jpg	gap_vegetation	0.17	3732,579	63x59
frame_000251.jpg	gap_vegetation	0.42	3624,1392	120x179	frame_000258.jpg	gap_vegetation	0.13	3742,579	87x64
frame_000251.jpg	gap_vegetation	0.36	3679,667	321x563	frame_000259.jpg	crack	0.30	597,124	54x240
frame_000251.jpg	gap_vegetation	0.30	3624,1460	138x328	frame_000259.jpg	gap_vegetation	0.62	3570,1677	111x150
frame_000251.jpg	gap_vegetation	0.10	3800,999	70x81	frame_000259.jpg	gap_vegetation	0.27	3678,1578	57x93
frame_000252.jpg	crack	0.17	1700,846	154x1207	frame_000259.jpg	gap_vegetation	0.15	3719,938	77x63
frame_000252.jpg	gap_vegetation	0.53	3667,1080	345x536	frame_000259.jpg	gap_vegetation	0.14	3723,942	102x74
frame_000252.jpg	gap_vegetation	0.52	3562,1482	248x117	frame_000260.jpg	crack	0.23	1783,104	52x209
frame_000252.jpg	gap_vegetation	0.47	3597,1803	133x180	frame_000260.jpg	gap_vegetation	0.54	3539,2018	115x140
frame_000252.jpg	gap_vegetation	0.38	3362,1150	83x89	frame_000260.jpg	gap_vegetation	0.29	3643,1916	63x88
frame_000252.jpg	gap_vegetation	0.28	3590,1483	186x107	frame_000260.jpg	gap_vegetation	0.19	3684,1280	82x59
frame_000252.jpg	gap_vegetation	0.26	3603,1873	161x345	frame_000260.jpg	gap_vegetation	0.11	3683,1314	120x130
frame_000252.jpg	gap_vegetation	0.10	3777,1420	77x89	frame_000261.jpg	crack	0.17	1773,246	89x492
frame_000253.jpg	gap_vegetation	0.57	3543,1892	236x125	frame_000261.jpg	gap_vegetation	0.17	3659,1594	80x59

Appendix — all detections

rows 645-734 of 734

frame	class	conf	cx,cy	w x h	frame	class	conf	cx,cy	w x h
frame_000261.jpg	gap_vegetation	0.13	3801,450	72x94	frame_000269.jpg	gap_vegetation	0.12	3606,108	63x81
frame_000261.jpg	gap_vegetation	0.11	3500,1829	57x99	frame_000269.jpg	gap_vegetation	0.12	3805,303	61x90
frame_000262.jpg	crack	0.24	1777,406	109x789	frame_000270.jpg	crack	0.71	1376,492	81x318
frame_000262.jpg	gap_vegetation	0.31	3631,1941	116x155	frame_000270.jpg	crack	0.70	1704,1774	117x759
frame_000262.jpg	gap_vegetation	0.25	3788,756	97x124	frame_000270.jpg	crack	0.57	1795,781	130x960
frame_000262.jpg	gap_vegetation	0.21	3633,1917	99x107	frame_000270.jpg	crack	0.15	1808,635	148x1250
frame_000262.jpg	gap_vegetation	0.10	3620,1968	83x109	frame_000270.jpg	gap_vegetation	0.61	3545,644	76x123
frame_000263.jpg	crack	0.20	1768,691	119x792	frame_000270.jpg	gap_vegetation	0.35	3738,1620	96x129
frame_000263.jpg	gap_vegetation	0.49	3766,1052	135x145	frame_000270.jpg	gap_vegetation	0.16	3766,463	86x62
frame_000263.jpg	gap_vegetation	0.10	3808,423	58x97	frame_000270.jpg	gap_vegetation	0.16	3582,284	63x72
frame_000264.jpg	crack	0.56	1759,916	116x783	frame_000270.jpg	gap_vegetation	0.14	3754,1087	69x76
frame_000264.jpg	crack	0.18	1821,200	86x401	frame_000270.jpg	gap_vegetation	0.11	3776,475	118x95
frame_000264.jpg	gap_vegetation	0.53	3755,1294	163x162	frame_000271.jpg	crack	0.61	1707,1815	104x688
frame_000265.jpg	crack	0.66	1819,295	111x590	frame_000271.jpg	crack	0.46	1378,594	76x301
frame_000265.jpg	crack	0.45	530,1778	135x750	frame_000271.jpg	crack	0.44	1810,689	141x1337
frame_000265.jpg	crack	0.32	1746,1095	111x748	frame_000271.jpg	crack	0.33	1795,826	123x1055
frame_000265.jpg	gap_vegetation	0.66	3752,1476	170x168	frame_000271.jpg	crack	0.30	1416,89	71x179
frame_000266.jpg	crack	0.69	1817,354	123x709	frame_000271.jpg	crack	0.16	1435,89	99x178
frame_000266.jpg	crack	0.46	519,1847	116x621	frame_000271.jpg	gap_vegetation	0.70	3532,750	85x137
frame_000266.jpg	crack	0.15	1706,1489	167x1340	frame_000271.jpg	gap_vegetation	0.25	3731,1716	100x136
frame_000266.jpg	gap_vegetation	0.56	3743,1620	186x160	frame_000271.jpg	gap_vegetation	0.13	3740,1182	70x88
frame_000266.jpg	gap_vegetation	0.11	3776,1011	77x98	frame_000271.jpg	gap_vegetation	0.12	3676,1855	57x77
frame_000267.jpg	crack	0.68	1815,416	133x832	frame_000271.jpg	gap_vegetation	0.10	3569,391	50x89
frame_000267.jpg	crack	0.59	512,1908	101x499	frame_000272.jpg	crack	0.57	1818,711	151x1414
frame_000267.jpg	crack	0.30	1712,1544	150x1173	frame_000272.jpg	crack	0.49	661,1119	161x2081
frame_000267.jpg	crack	0.28	1395,93	80x186	frame_000272.jpg	crack	0.45	1714,1839	96x640
frame_000267.jpg	crack	0.15	1378,94	108x189	frame_000272.jpg	gap_vegetation	0.27	3540,784	88x117
frame_000267.jpg	crack	0.10	1425,91	126x183	frame_000272.jpg	gap_vegetation	0.17	3698,1885	57x76
frame_000267.jpg	gap_vegetation	0.62	3744,1756	184x162	frame_000272.jpg	gap_vegetation	0.17	3747,1746	83x125
frame_000267.jpg	gap_vegetation	0.61	3590,169	77x115	frame_000272.jpg	gap_vegetation	0.16	3515,1461	78x122
frame_000267.jpg	gap_vegetation	0.14	3782,1142	90x107	frame_000273.jpg	crack	0.68	1721,1826	98x667
frame_000268.jpg	crack	0.69	1814,484	132x968	frame_000273.jpg	crack	0.57	1826,694	142x1360
frame_000268.jpg	crack	0.68	1386,165	76x297	frame_000273.jpg	crack	0.30	677,1087	147x2145
frame_000268.jpg	crack	0.59	1710,1616	137x1019	frame_000273.jpg	crack	0.20	1812,807	119x1124
frame_000268.jpg	crack	0.41	507,1979	85x360	frame_000273.jpg	gap_vegetation	0.67	3564,748	91x131
frame_000268.jpg	gap_vegetation	0.65	3751,1897	174x154	frame_000273.jpg	gap_vegetation	0.14	3752,1696	77x94
frame_000268.jpg	gap_vegetation	0.61	3594,306	81x124	frame_000273.jpg	gap_vegetation	0.10	3724,2061	75x84
frame_000268.jpg	gap_vegetation	0.16	3783,1289	90x108	frame_000274.jpg	crack	0.65	1727,1813	98x692
frame_000269.jpg	crack	0.67	1377,325	79x314	frame_000274.jpg	crack	0.55	1832,668	143x1315
frame_000269.jpg	crack	0.64	1800,619	137x1041	frame_000274.jpg	crack	0.16	669,1095	134x2128
frame_000269.jpg	crack	0.61	1707,1697	123x857	frame_000274.jpg	crack	0.14	1818,771	122x1105
frame_000269.jpg	crack	0.18	508,2051	69x217	frame_000274.jpg	crack	0.13	1429,61	71x123
frame_000269.jpg	gap_vegetation	0.68	3739,2069	190x171	frame_000274.jpg	gap_vegetation	0.67	3584,695	102x144
frame_000269.jpg	gap_vegetation	0.58	3565,480	86x129	frame_000274.jpg	gap_vegetation	0.28	3737,1813	61x86
frame_000269.jpg	gap_vegetation	0.23	3759,1461	82x117					
frame_000269.jpg	gap_vegetation	0.13	3677,630	78x73					