
Physical 3° step evidence — comparison at nearby, not identical poses
Continuous-follow smoothness and latency remain unverified
Previous measured run
Smoothness-first
Worst step overshoot (%)
Motor ID
Settling within ±0.5° (s)
Motor ID