

**Acuren Group Inc.**

2 - 240 Taiganova Crescent
Fort McMurray, AB, Canada T9K 0T4
www.acuren.com

Phone: 780.790.1776
Fax: 780.790.9061

Page 1 of 6

A Higher Level of Reliability

NONDESTRUCTIVE EXAMINATION

CLIENT: **Suncor Energy Inc.**
Suncor Oil Sands
Fort McMurray, AB

DATE: March 2, 2026

ACUREN JOB #: 272-J280794

REPORT #: **UT-AUTNAR-26-33**

CONTRACT/PO: SUENTQ00169932 WO: 300654572

WORK LOCATION: Plant 57

ATTENTION: **Condition Monitoring Group**

PROJECT: Corrosion 2026

ITEM(S) EXAMINED: **CML 1.02, 11.03**

PART #: See results MATERIAL: Carbon Steel THICKNESS: Various

SCOPE: Perform UT thickness scans as per request.

TYPE OF INSPECTION: Ultrasonic

TEST DETAILS:

ACCEPTANCE STANDARD: Client's information

REVISION: N/A

PROCEDURE/TECHNIQUE: CAN-UT-14T001

REVISION: 12

TYPE: Thickness

METHOD: Contact

INSTRUMENT: Olympus

MODEL: 38 DL Plus

S/N: 193347201

CAL DUE: February 15 2027

CAL. BLOCK: Step block

S/N: 21-1817 CS

CABLE-TYPE: Coaxial

LENGTH: 5ft

CAL. BLOCK:

S/N:

COUPLANT: Sono600

Probe & Technique Details:

	TEST ANGLE (°)	PROBE TYPE	CRYSTAL SIZE	FREQ. (MHZ)	SERIAL NUMBER	DAMPING Ω	TEST FROM	REFERENCE REFLECTOR	TRANSFER VALUE	REFERENCE		SCAN dB	RANGE
										dB	% FSH		
1	0	D799	3/8"	5	1566964	N/A	OD	Backwall	0	65	80	N/A	5.00"
2	0	D799	3/8"	5	1566949	N/A	OD	Backwall	0	65	80	N/A	5.00"
3													
4													

TEST SURFACE CONDITION: Rough

TEST SURFACE TEMPERATURE: 145°F

RESULTS:

Circuit:
57-008V 1-1
CML
1.02, 11.03

Client acknowledges receipt and custody of the report or other work ("Deliverable"). Client agrees that it is responsible for assuring that acceptance standards, specifications and criteria in the Deliverable and Statement of Work ("SOW") are correct. Client acknowledges that Acuren is providing the Deliverable according to the SOW, and not any other standards. Client acknowledges that it is responsible for the failure of any items inspected to meet standards, and for remediation. Client has 15 business days following the date Acuren provides the Deliverable to inspect it, identify deficiencies in writing, and provide written rejection, or else the Deliverable will be deemed accepted. The Deliverable and other services provided by Acuren are governed by a Master Services Agreement ("MSA"). If the parties have not entered into an MSA, then the Deliverable and services are governed by the SOW and the "Acuren Standard Service Terms" (www.acuren.com/service/terms) in effect when the services were ordered.

CLIENT:

CLIENT PRINTED NAME

Narciso Jr Auteda
Narciso Jr Auteda

ACUREN
TECHNICIAN:

1st Technician CGSB UT1
CGSB Reg. #30991

CLIENT SIGNATURE

ACCEPTED & ACKNOWLEDGED BY

Juniel Ballesteros
Juniel Ballesteros


2nd Technician CGSB UT1
CGSB Reg. #29240

DTR No.: N/A


REVIEWER:


Juniel Ballesteros
#29240

(Generated Using: CAN-QUA-02F007 R11 - 01/07/2026)



CML 1.02 & 11.03








A **6" x 6"** grid scan was performed on **CML 1.02 & 11.03**. Grid letters "**A to R**" starts at **North** and go **clockwise** with respect to flow. Grid Number "**1-29**" go with flow. See attached grid and photos for reference.

FLOW ↓	CML 1.02																			
	6" x 6"	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	
	INTRADOS					FLANGE										INTRADOS				
						EXTRADOS														
	1	0.380	0.379	0.384	0.387	0.382	0.377	0.374	0.361	0.358	0.367	0.364	0.369	0.371	0.386	0.388	0.381	0.375	0.379	
	2	0.381	0.379	0.383	0.389	0.391	0.383	0.378	0.370	0.364	0.370	0.370	0.371	0.382	0.391	0.390	0.387	0.376	0.379	
	3	0.382	0.381	0.388	0.391	0.392	0.384	0.378	0.371	0.365	0.372	0.375	0.375	0.383	0.397	0.394	0.388	0.381	0.378	
	4	0.373	0.385	0.389	0.394	0.393	0.387	0.383	0.375	0.368	0.370	0.377	0.373	0.380	0.394	0.394	0.387	0.381	0.376	
	5	0.373	0.387	0.389	0.393	0.391	0.387	0.380	0.372	0.373	0.373	0.377	0.378	0.382	0.390	0.395	0.388	0.386	0.372	
	6	0.368	0.390	0.394	0.393	0.392	0.385	0.379	0.375	0.373	0.378	0.379	0.383	0.384	0.391	0.395	0.390	0.385	0.373	
7	0.372	0.396	0.391	0.395	0.391	0.384	0.379	0.378	0.374	0.382	0.384	0.384	0.385	0.390	0.396	0.390	0.385	0.376		
8	0.374	0.398	0.390	0.395	0.392	0.385	0.381	0.379	0.375	0.385	0.385	0.387	0.388	0.395	0.394	0.393	0.387	0.377		
9	0.376	0.395	0.391	0.392	0.392	0.387	0.382	0.377	0.376	0.384	0.386	0.388	0.386	0.392	0.395	0.389	0.389	0.382		
10	0.377	0.391	0.395	0.391	0.393	0.387	0.384	0.378	0.372	0.384	0.383	0.391	0.387	0.389	0.395	0.390	0.388	0.380		
11	0.376	0.394	0.394	0.391	0.395	0.391	0.385	0.383	0.372	0.383	0.391	0.390	0.390	0.392	0.396	0.392	0.391	0.383		
12	0.381	0.398	0.395	0.392	0.396	0.392	0.387	0.381	0.380	0.386	0.389	0.389	0.385	0.396	0.392	0.388	0.388	0.382		
13	0.379	0.394	0.392	0.392	0.392	0.389	0.382	0.384	0.382	0.390	0.392	0.387	0.386	0.397	0.394	0.387	0.388	0.375		
14	0.377	0.389	0.389	0.393	0.392	0.388	0.385	0.380	0.383	0.393	0.390	0.381	0.388	0.395	0.395	0.386	0.387	0.374		
15	0.368	0.385	0.384	0.393	0.390	0.381	0.379	0.382	0.382	0.390	0.391	0.388	0.385	0.396	0.391	0.386	0.380	0.368		
16	0.367	0.381	0.380	0.388	0.390	0.384	0.380	0.381	0.381	0.392	0.389	0.385	0.388	0.396	0.391	0.382	0.374	0.367		
17	0.369	0.378	0.376	0.389	0.393	0.390	0.379	0.379	0.381	0.393	0.390	0.387	0.386	0.395	0.389	0.370	0.374	0.371		
18	0.365	0.373	0.371	0.381	0.386	0.385	0.383	0.387	0.385	0.382	0.394	0.386	0.380	0.380	0.378	0.372	0.371	0.366		
DOWNSTREAM WELD																				
FLOW ↓	CML 11.03																			
	BOTTOM				WEST				TOP				EAST				BOTTOM			
	19	0.380	0.379	0.384	0.386	0.382	0.374	0.380	0.377	0.381	0.384	0.386	0.391	0.390	0.376	0.378	0.383	0.378	0.381	
	20	0.386	0.387	0.389	0.386	0.386	0.377	0.385	0.388	0.388	0.389	0.396	0.397	0.393	0.390	0.389	0.390	0.385	0.391	
	21	0.388	0.388	0.390	0.387	0.385	0.383	0.386	0.389	0.388	0.387	0.397	0.399	0.396	0.389	0.390	0.389	0.387	0.391	
	22	0.388	0.389	0.391	0.387	0.383	0.380	0.386	0.388	0.387	0.382	0.393	0.396	0.395	0.388	0.388	0.389	0.384	0.393	
	23	0.385	0.389	0.391	0.387	0.385	0.384	0.387	0.384	0.384		0.384	0.390	0.395	0.390	0.388	0.388	0.385	0.392	
	24	0.387	0.390	0.390	0.388	0.385	0.382	0.385	0.384				0.392	0.391	0.392	0.389	0.388	0.384	0.395	
	25	0.380	0.388	0.392	0.390	0.386	0.378	0.377						0.384	0.388	0.388	0.387	0.385	0.393	
	26	0.374	0.387	0.389	0.386	0.385	0.377	0.378					0.383	0.384	0.384	0.385	0.385	0.380	0.385	
27	0.372	0.387	0.389	0.387	0.385	0.375	0.378	0.376	0.375		0.388	0.389	0.389	0.387	0.388	0.384	0.379	0.381		
28	0.369	0.379	0.390	0.389	0.386	0.379	0.385	0.381	0.377	0.378	0.387	0.394	0.394	0.389	0.389	0.384	0.381	0.390		
29	0.375	0.386	0.389	0.388	0.387	0.380	0.385	0.384	0.381	0.380	0.391	0.391	0.390	0.386	0.386	0.382	0.380	0.388		

A **3" x 3"** grid scan was performed on **CML 11.03 Branch Connection**. Grid letters "**A to Q**" starts at **North** and go **clockwise** with respect to flow. Grid Number "**1-2**" go with flow. See attached grid and photos for reference.

FLOW ↓	CML 11.03 BRANCH																	
	3" x 3"	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q
	1	0.351	0.348	0.333	0.334	0.344	0.359	0.340	0.337	0.343	0.357	0.338	0.342	0.342	0.361	0.339	0.350	0.356
	2			0.336	0.343	0.350	0.362	0.347	0.348	0.359	0.345			0.349	0.383	0.363	0.358	0.360

UT REPORT - ELBOW																																																																																																											
		DATE (MM/DD/YYYY): 3/2/2026		METHOD: Corrosion ☐ Erosion ☒																																																																																																							
		COMPANY: ACUREN		MATERIAL: Carbon Steel ☒ Stainless Steel ☐																																																																																																							
		TECHNICIAN: NARCISO JR AUTEDA		ADDITIONAL INFORMATION: SURFACE TEMP 145°F																																																																																																							
		ASSISTANT:																																																																																																									
PORT HOLES - CORROSION										FULL SCAN - EROSION																																																																																																	
																																																																																																											
<table border="1" style="width: 100%; border-collapse: collapse; font-size: 0.8em;"> <thead> <tr> <th rowspan="2">CIRCUIT</th> <th rowspan="2">CML</th> <th rowspan="2">SECTION</th> <th rowspan="2">DIAM.</th> <th colspan="5">PORT HOLES</th> <th colspan="4">FULL SCAN</th> <th rowspan="2">COMMENTS</th> </tr> <tr> <th>A</th> <th>B</th> <th>C</th> <th>D</th> <th>E</th> <th>NORTH</th> <th>SOUTH</th> <th>EAST</th> <th>WEST</th> <th>TOP</th> <th>BOTTOM</th> <th>CENTER</th> <th>HIGH</th> </tr> </thead> <tbody> <tr> <td rowspan="4">57-008V 1-1</td> <td rowspan="4">1.02</td> <td>1</td> <td>36"</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>"SEE GRID"</td> </tr> <tr> <td>2</td> <td>36"</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>0.358</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>3</td> <td>36"</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>0.374</td> <td></td> <td></td> </tr> <tr> <td>4</td> <td>36"</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>N/A, FLANGE</td> </tr> </tbody> </table>															CIRCUIT	CML	SECTION	DIAM.	PORT HOLES					FULL SCAN				COMMENTS	A	B	C	D	E	NORTH	SOUTH	EAST	WEST	TOP	BOTTOM	CENTER	HIGH	57-008V 1-1	1.02	1	36"														"SEE GRID"	2	36"										0.358					3	36"												0.374			4	36"														N/A, FLANGE
CIRCUIT	CML	SECTION	DIAM.	PORT HOLES					FULL SCAN				COMMENTS																																																																																														
				A	B	C	D	E	NORTH	SOUTH	EAST	WEST		TOP	BOTTOM	CENTER	HIGH																																																																																										
57-008V 1-1	1.02	1	36"														"SEE GRID"																																																																																										
		2	36"										0.358																																																																																														
		3	36"												0.374																																																																																												
		4	36"														N/A, FLANGE																																																																																										

UT REPORT - Connections																																													
		DATE (MM/DD/YYYY): 3/2/2026		METHOD: Corrosion ☐ Erosion ☒																																									
		COMPANY: ACUREN		MATERIAL: Carbon Steel ☒ Stainless Steel ☐																																									
		TECHNICIAN: Narciso Jr Auteda		ADDITIONAL INFORMATION: SURFACE TEMP 145°F																																									
		ASSISTANT:																																											
																																													
<table border="1" style="width: 100%; border-collapse: collapse; font-size: 0.8em;"> <thead> <tr> <th>CIRCUIT</th> <th>CML</th> <th>SECTION</th> <th>DIAM.</th> <th>NORTH</th> <th>SOUTH</th> <th>EAST</th> <th>WEST</th> <th>TOP</th> <th>BOTTOM</th> <th>HIGH</th> <th>COMMENTS</th> </tr> </thead> <tbody> <tr> <td rowspan="2">57-008V 1-1</td> <td rowspan="2">11.03</td> <td>1</td> <td>36"</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>0.369</td> <td></td> <td>"SEE GRID"</td> </tr> <tr> <td>2</td> <td>16"</td> <td>0.333</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>												CIRCUIT	CML	SECTION	DIAM.	NORTH	SOUTH	EAST	WEST	TOP	BOTTOM	HIGH	COMMENTS	57-008V 1-1	11.03	1	36"						0.369		"SEE GRID"	2	16"	0.333							
CIRCUIT	CML	SECTION	DIAM.	NORTH	SOUTH	EAST	WEST	TOP	BOTTOM	HIGH	COMMENTS																																		
57-008V 1-1	11.03	1	36"						0.369		"SEE GRID"																																		
		2	16"	0.333																																									