

Test Report

No.: CANEC24014498001

Date: Jul 17, 2024

Page 1 of 3

Client Name: DONGGUAN CITY KEDO SILICONE MATERIAL CO., LTD

Client Address: NO. 8 FANGZHONG 1ST ROAD, LIANGBIAN VILLAGE, LIAOBU TOWN, DONGGUAN CITY, GUANGDONG PROVINCE

Sample Name: KD-850

Model No.: KD-850

Client Ref. Information: KD-810(XX), KD-820(XX), KD-830(XX), KD-840(XX),
KD-850(XX), KD-860(XX), KD-870(XX), KD-880(XX),
KD-890(XX), KD-6021(XX), KD-6031(XX), KD-6041(XX),
KD-6051(XX), KD-6061(XX), KD-6071(XX), KD-6081(XX),
KD-6091(XX), KD-9021(XX), KD-9031(XX), KD-9041(XX),
KD-9051(XX), KD-9061(XX), KD-9071(XX), KD-9081(XX),
KD-9091(XX)

The above sample(s) and information were provided by the client.

SGS Job No.: SZP24-029501

Sample Receiving Date: Jul 04, 2024

Testing Period: Jul 04, 2024 ~ Jul 17, 2024

Test Requested: Select test(s) as requested by the client.

Test Method(s): Please refer to next page(s).

Test Result(s): Please refer to next page(s).

	Test Requirement	Conclusion
1	US FDA 21 CFR 177.2600 - Total Extractives	Pass

Signed for and on behalf of
SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch

Kim Cai

Kim Cai

Approved Signatory

scan to see the report



62CA5FEE



SGS-CSTC Standards Technical Services Co., Ltd.
Guangzhou Branch Technical Services Laboratory

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

No.198, Kezhu Road, Science City, Economic & Technological Development Area, Guangzhou, Guangdong, China 510663
中国·广东·广州高新技术产业开发区科学城科珠路198号 邮编: 510663

t (86-20) 82155555 www.sgsgroup.com.cn
t (86-20) 82155555 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

Test Report

No.: CANEC24014498001

Date: Jul 17, 2024

Page 2 of 3

Test Result(s):

Test Part Description:

SN ID	Sample No.	SGS Sample ID	Description	Material (claimed by the client)
SN1	A1	CAN24-0144980-0001.C001	Colorless transparent silicone sheet	Silicone

Remarks:

- (1) mg/dm² = milligram per square decimeter
mg/inch² = milligram per square inches
μg/cm² = microgram per square centimeter
mg/L = milligram per litre
mg/kg = milligram per kilogram
- (2) °C = degree Celsius
°F = degree Fahrenheit
- (3) <= less than
- (4) RL = Reporting Limit
- (5) ND = Not Detected (< RL).

US FDA 21 CFR 177.2600 - Total Extractives

Test Method: With reference to US FDA 21 CFR 177.2600.

Simulant used	Test Condition	Limit	Unit(s)	RL	A1	Comment
n-Hexane	Reflux Temperature 7.0 hrs	175	mg/inch ²	0.5	14.9	Pass
n-Hexane Succeeding extraction	Reflux Temperature 2.0 hrs	4	mg/inch ²	0.5	0.8	Pass
Distilled water	Reflux Temperature 7.0 hrs	20	mg/inch ²	0.5	ND	Pass
Distilled water Succeeding extraction	Reflux Temperature 2.0 hrs	1	mg/inch ²	0.5	ND	Pass

Unless otherwise stated, the decision rule for conformity reporting is based on Binary Statement for Simple Acceptance Rule (w=0) stated in ILAC-G8:09/2019.



SGS-CSI Standards Technical Services Co., Ltd.
Guangzhou Branch Technical Laboratory

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

No.198, Kezhu Road, Science City, Economic & Technological Development Area, Guangzhou, Guangdong, China 510663
中国·广东·广州高新技术产业开发区科学城科珠路198号 邮编: 510663

t (86-20) 82155555 www.sgsgroup.com.cn
t (86-20) 82155555 sgs.china@sgs.com

Member of the SGS Group (SGS SA)


Test Report

No.: CANEC24014498001

Date: Jul 17, 2024

Page 3 of 3

Sample Photo:



SGS authenticate the photo on original report only
*** End of Report ***



SGS-CSL Standards Technical Services Co., Ltd.
Guangzhou Branch, China Technical Laboratory

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

No.198, Kezhu Road, Science City, Economic & Technological Development Area, Guangzhou, Guangdong, China 510663
中国·广东·广州高新技术产业开发区科学城科珠路198号 邮编: 510663

t (86-20) 82155555 www.sgsgroup.com.cn
t (86-20) 82155555 sgs.china@sgs.com

Member of the SGS Group (SGS SA)