Inspection Checklist

Vehicle Details Company Info

Inspection Date: 10-Oct-2023 **Vehicle**

Year: 2023 Make: TOYOTA Model: Sienna Engine: 2GR-FKS

VIN: 2H7DHW9843J43D License: 5051-HC-100

AutoCoin 30 Đ. Đào Trí, Khu Phố 4, D7, HCMC,Vietnam Vietnam 72907

autofax@autocoin.sg

Inspection Results

Issues Found: 0

(items in Poor condition and have comments)

Client Information

Name: AutoFax Inspections

Phone:

Email: inspection@autocoin.ca

Address:

City: 30 D. Đào Trí, Khu Phố 4, D7, HCMC,

Vietnam, Hồ Chí Minh 72907


Summary:

Autocoin Inspection Disclaimer This inspection report, provided by Autocoin through its subsidiary AutoFax, is a non-certified suggestion based on our multi-point inspection. It is not suitable for vehicle registration purposes. While we strive for accuracy, it may not cover all aspects of the vehicle's condition. For official registration or compliance, please obtain a certified inspection from authorized agencies or professionals. Autocoin and AutoFax are not liable for any issues arising from the use of this report for legal purposes. This report is only valid for the inspection date and does not guarantee the vehicle's condition afterward. For questions, contact Autocoin or AutoFax.

autofax@autocoin.sg -

ENGINE	good	fair	poor	details
Engine Oil Level				
Oil Leaks				
Coolant Level				
Coolant Hoses				
Drive Belts				
Timing Belt/ Chain				
Exhaust System				
Engine Mounts				
Engine Wiring and Sensors				
Fluid Leaks				
TRANSMISSION	good	fair	poor	details
Fluid Level				
Transmission Fluid Leaks				
Transmission Pan				
Transmission Mounts				





Rear Left Brake Rotor Thickness				
Rear Right Brake Rotor Thickness				
BRAKE PADS	good	fair	poor	details
Front Left Brake Pad Thickness				
Front Right Brake Pad Thickness				
Rear Left Brake Pad Thickness				
Rear Right Brake Pad Thickness				
BRAKES	good	fair	poor	details
BRAKES HAND BRAKE	good	fair	poor	details
HAND	good	fair	poor	details
HAND BRAKE BRAKE	good	fair fair	poor	details
HAND BRAKE BRAKE FLUID	•			
HAND BRAKE BRAKE FLUID EXTERIOR- BODY/PAINT Paint	•			
HAND BRAKE BRAKE FLUID EXTERIOR- BODY/PAINT Paint Condition Dents and	•			
HAND BRAKE BRAKE FLUID EXTERIOR- BODY/PAINT Paint Condition Dents and Dings Rust and	•			
HAND BRAKE BRAKE FLUID EXTERIOR- BODY/PAINT Paint Condition Dents and Dings Rust and Corrosion Front	•			

Driver Door Rear				
Passenger Door Front				
Passenger Door Rear				
Driver Quarter Panel				
Passenger Quarter Panel				
Roof				
Windshield				
Sunroof				
Driver Window Front				
Passenger Window Passenger Front				
Rear Passenger Left				
Rear Passenger Right				
LIGHTS AND SIGNALS	good	fair	poor	details
Front				
Headlight Driver				
Headlight	•			

Passenger Taillight				
Fog Lights				
Reserve Lights				
Hazard Lights				
License Plate Lights				
Side View Mirrors				
INTERIOR	good	fair	poor	details
Driver Seat				
Passanger Seat				
Rear Seats				
Dashboard Condition				
Audio Controls				
Carpet				
Roof Liner				
Interior Lights				
Interior Trim				
Navigation System (Screen)				
Front Driver Seat Belt				

Front Passenger Seat Belt				
Rear Seat Belts				
Instrument Cluster Warnings				
Audio System				
HVAC SYSTEM	good	fair	poor	details
Air Conditioning				
Heater				
Front Air Vent Blowing				
Defrosters				
Rear Air Vent Blowing				
ELECTRICAL	good	fair	poor	details
Power Windows				
Power Locks				
Power Seats				
Cruise Control				
SAFETY INSPECTION	good	fair	poor	details
Driver Airbag				
Passanger Airbag				







Other Airbags





FRONT END OF VEHICLE IS IN GOOD CONDITION WITH MINOR BUMPER SCRATCHES









DAMAGE REPORTED TO REAR QUATER PANEL, PAINT READING SHOWING TWO PANELS PAINTED



80% TIRE LEFT/ MINOR CURB RASH



80% TIRE LEFT/ NO CURB RASH



70% TIRE LEFT/ MINOR CURB RASH



70% TIRE LEFT/ MINOR CURB RASH

